Site Audit Report 278_Northcote by Dr Ian Swane

WESTCONNEX STAGE 3A NORTHCOTE COMPOUND, HABERFIELD (AREA C3A)

Final | 28 NOVEMBER 2022



IAN SWANE & ASSOCIATES

Site Audit Report 278_Northcote by Dr Ian Swane

WESTCONNEX STAGE 3A NORTHCOTE COMPOUND, HABERFIELD (AREA C3A)

Document title: Site Audit Report 278_Northcote

Document no. 1

Revision: Final

Date: 28 November 2022

Prepared by: Dr Ian Swane

File name: SAR 278_Northcote

Ian Swane & Associates Pty Ltd ABN 51 102 396 565 PO Box 359 Mortdale NSW 2223 Australia

Tel: +61 (0) 418 867 112 Email: iswane@bigpond.com

COPYRIGHT: The concepts and information contained in this document are the property of Ian Swane & Associates Pty Ltd. Use or copying of this document in whole or in part without the written permission of Ian Swane & Associates Pty Ltd constitutes an infringement of copyright.

SAR 278_Northcote i

Contents

1.	Introduction	1
1.1	Background Information	1
1.2	Purpose and Scope of the Audit	6
1.2.1	Purpose	6
1.2.2	Scope of Work	8
1.3	Standards & Methodology	9
1.3.1	EPA Approved Guidelines	9
1.3.2	Decision Process	9
1.4	Data Quality Objectives	11
1.5	Information Reviewed	12
1.6	Chronology of Site Audit Program	13
1.7	Abbreviations	14
2.	Review of Site Conditions in 2019 Pre-ASBJV Work	19
2.1	Site Identification	19
2.2	Site History	20
2.3	Site Condition and Surrounding Environment	29
2.4	Preliminary Conceptual Site Model for Contamination	39
2.4.1	Potential Sources, Contaminants of Concern & APECs	39
2.4.2	Exposure Pathways and Potential Receptors	44
2.4.3	Preliminary Risk Assessment	44
2.5	Investigation Criteria	44
2.5.1	Aesthetic	44
2.5.2	Soil	45
2.5.3	Surface and Groundwater	46
2.5.4	Soil Vapour Criteria	48
2.6	Review of Investigation Data Quality	51
2.6.1	Overview	51
2.6.2	Documentation Completeness DQO	52
2.6.3	Data Completeness and Representativeness - Soils	53
2.6.4	Data Completeness and Representativeness – Surface Water	66
2.6.5	Data Completeness and Representativeness – Groundwater	66
2.6.6	Data Completeness and Representativeness – Ground Gas	69
2.6.7	Data Comparability	69
2.6.8	Precision & Accuracy	70
2.7	Aesthetic Issues	71
2.7.1	Extent of Fill	71
2.7.2	Type and Location of Aesthetic Impacts	71
2.8	Background Contaminant Levels	74
2.8.1	Soil	74
2.8.2	Groundwater	74

Append	dix E. Site Audit Statement and Interim Plan	112		
• •	dix D. Site Auditor Photographs			
	ppendix A. Figures & Tables from M4 East Work			
Annandiy A. Figurea 9. Tablea from M4 Foot Work				
5.	Other Relevant Information	105		
4.	Conclusions	104		
3.6	Review of LTEMP	100		
3.5	Final Site Condition			
3.4	Imported Fill			
3.3.3	Potential for Construction Activities to Have Contaminated the Site			
3.3.2	Environmental Management and Incidents			
3.3.1	Unexpected Finds			
3.3	Construction Activities at Site			
3.2	Compliance with EPA Notification Requirements			
3.1.3	Waste Management Plan			
3.1.2	Contaminated Land Management Sub-plan			
3.1.1	Site Environmental Management Plan			
3. 3.1	Review of Management Plans			
2.14 3.	Contamination Management During ASBJV Work			
2.13 2.14	Site Management Strategy			
2.12	Soil Vapours Ecological Risks			
2.11.2	Groundwater			
2.11.1	Surface Water			
2.11	Surface Water & Groundwater Contamination			
2.10	Chemical Mixtures			
2.9.4	Northcote Street at Site 046			
2.9.3	Other Former Commercial/Industrial Properties			
2.9.2	Former Service Station at Site 006			
2.9.1	Former Residential Properties			
2.9	Soil Contamination	75		

1. Introduction

1.1 Background Information

WestConnex is a 33 km predominately underground motorway scheme that encompassed widening of the M4 Western Motorway, an eastern extension of the M4 (M4 East), a new section for the M5 Motorway (New M5), and a new inner western bypass of the Sydney CBD connecting the M4 and New M5 (M4-M5 link). The WestConnex Stage 3A project consisted of a group of underground tunnels connecting the M4-M5 Link with Victoria Road (just east of the Iron Cove Bridge) and The Crescent, the Anzac Bridge, and the City West Link Figure 1-1).

There were four worksites / compounds where construction work for the WestConnex Stage 3A project occurred at the ground surface, these being:

- ➤ The St Peters Interchange (SPI) worksite (Area C10) at St Peters;
- ➤ The Pyrmont Bridge Road (PBR) worksite (Area C9) at Annandale;
- > The Parramatta Road East West (PREW) worksite (Areas C1b and C3b) at Ashfield; and
- > The Northcote Compound (Area C3a) at Haberfield.

The locations of these areas are shown in Figure 1-1.

The land at each of these worksite compounds was the subject of a <u>Statutory</u> Site Audit, as defined by the NSW Contaminated Lands Management (**CLM**) Act 1997. The outcome of the site audit for each property was documented in its own site audit report (**SAR**). This SAR documents the outcome of the site audit for the Northcote Compound, which consisted of one area (C3a) located on either side of Northcote Street in the Ashfield local government area (**LGA**). The total size of the Northcote Compound was 12,165 m² (1.2165 ha), with a layout plan provided in **Figure 1-2**.

The Northcote Compound was established by CPB Samsung John Holland as part of the WestConnex M4 East Project, which commenced several years before work on the WestConnex Stage 3A Project commenced. Fieldwork for a detailed site investigation (**DSI**) for the Northcote Compound was undertaken in 2016, with a draft report issued on 7/12/16.

The Northcote Compound consisted of 12 parcels of land, comprising:

- Site 006: 269 Parramatta Rd, Haberfield (Lots 63 & 64 in DP4612;
- Site 012: 2-4 Wattle Street, Haberfield (Lots 1 & 2 in DP239458);
- Site 026: 257 Parramatta Rd, Haberfield (Lots 51-52 in DP719977);
- Site 027: 255 Parramatta Rd, Haberfield (Lots 53 & 54 in DP719977);
- Site 028: 249-251 Parramatta Rd, Haberfield (Lots 56-58 in DP719977);
- > Site 046: Northcote Street
- Site 136: 3 Wolseley St, Haberfield (Lot 114 in DP4612);
- Site 137: 1 Wolseley St, Haberfield (Lot 115 in DP4612);
- Site 138: 4 Northcote St, Haberfield (Lot 1 in DP933407);
- Site 139: 2 Northcote St, Haberfield (Lot 1 in DP933225);
- Site 140: 1 Northcote St, Haberfield (Lot B in DP391272); and
- Site 141: 3 Northcote St, Haberfield (Lot A in DP391272).

Figure 1-1 Overview of WestConnex Stage 3A Project Footprint and Construction Ancillary Facilities




Figure 1-2 Location Plan for Northcote Compound (Site C3a)

(Source: Ref [50])



When the WestConnex M4 East Project was practically completed in 2019, responsibility for the Northcote Compound was transferred to the WestConnex Stage 3A Project. This meant that:

- > The DSI for the Northcote Compound was not conducted as part of this Project:
- > The Site Auditor this SAR was not involved in auditing the planning, conduct or documentation of the investigation; and
- The Site Auditor for this SAR was only able to review the DSI report after the Northcote Compound had been constructed and was being used by the WestConnex Stage 3A contractor.

The Site Auditor considered the delayed timing of the review of the DSI was not a significant matter for the purpose of this site audit because its purpose was to determine the suitability of the final condition of the Project site towards the end of the WestConnex Stage 3A Project.

The Northcote Compound was located on the corner of Wolseley Street and extended south along Parramatta Road, comprising partially of Northcote Street and finishing at the corner of Wattle Street. During construction of the M4 East Motorway, the Northcote Compound was used for a dive structure providing access for roadheaders, a laydown area, temporary ventilation plant, acoustic shed for stockpiled soils, water treatment plant, sedimentation pond, electrical and mechanical workshops, offices, and an electrical substation. This use was continued by ASBJV for the WestConnex Stage 3A project, with a layout plan of the Site for operations 2019 – 2022 provided in **Figure 1.3**.

The future use of the land was to be determined in accordance with the Residual Land Management Plan that was to be prepared for the project.

The audit was undertaken by Dr Ian Swane, a NSW Environment Protection Authority (**EPA**) Site Auditor Accreditation No. 9821. The audit was undertaken in accordance with the CLM Act. For annual return purposes to the EPA, the audit is number 278 in the records of the Site Auditor. The site audit was commissioned by from the Acciona Samsung Bouygues Joint Venture (**ASBJV**), formerly the Lendlease Samsung Bouygues Joint Venture (**LSBJV**) on 20/07/18. The audit was conducted in accordance with a proposal dated 15/07/18.

All site audit work reported in this SAR was undertaken by the Site Auditor, since all matters that needed to be audited and documented herein were within the expertise of the Site Auditor and no assistance was required from the Audit Support Team.

The Site Auditor checked the EPA website¹ at the beginning and during the audit and found that the Northcote Compound and land within 200 m of the Site were not recorded by the EPA as having been 'Declared' land or a notified site.

This report is the second statutory SAR/SAS issued for the Northcote Compound. The first SAR/SAS (Refs [55] and [56]) was issued by Brad Eismen, another EPA-accredited Site Auditor, from AECOM. The first SAR/SAS was dated 26/02/19, numbered BE136 and covered an area of only 0.14 ha in the central part of the Northcote Compound, which had a total area of 1.22 ha area. The land that was the subject of the Eismen site audit had the address of 257 Parramatta Road, which is referred to in this report to Site 026 as shown in **Figure 2-1**.

SAR 278 Northcote PAGE 4

-

¹ www.epa.nsw.gov.au/clm

Figure 1-3 WestConnex Stage 3A Layout for Northcote Compound (2019-2022)



1.2 Purpose and Scope of the Audit

1.2.1 **Purpose**

The purpose and scope of the site audit was based on requirements specified in three documents:

- A contract made on or about June 2018 between the ASBJV and the NSW Government, which required ASBJV to deliver most of the work required by the WestConnex Stage 3A Project as described in the Planning Consent. Some work required by the Planning Consent may also have been outside the scope of work to be undertaken by ASBJV;
- The Department of Planning Consent State Significant Infrastructure (SSI) 7485 ('Planning Consent') issued for the WestConnex Stage 3A Project on 17/04/18 (Ref [50]). The proponent for the Project was Transport for NSW (TfNSW) formerly Roads and Maritime Services from the NSW Government; and
- An Environmental Protection Licence (EPL).

Contractual Requirements

With regards to site contamination, the Site Auditor understood that ASBJV was responsible for:

- a) Complying with NSW Government environmental legislation regarding contaminated site and waste management;
- b) Managing contamination that ASBJV interfered or disturbed during the course of carrying out its work;
- Not generating contamination at the Project site or generating contamination that may cause an increase in contamination migrating from the Project site;
- d) Returning the Northcote Compound to a condition suitable for a road construction worksite; and
- e) Complying with EPL 21149 (Ref [52]).

With regards to site contamination, the Site Auditor understood that ASBJV was not responsible for engaging the Site Auditor to determine whether:

- Any part of the Project site had been remediated and made suitable for a specified use other than as a road construction worksite; and
- Contamination that existed at the Project site prior to the commencement of the Project continued to migrate off-site.

The Site Auditor was understood to be responsible for:

- h) Reviewing site environmental management plans that dealt with contamination at the Project site and to check whether these plans met Condition C22 of the Planning Consent as relevant to this site audit;
- Reviewing contamination assessments for the Project site and whether they met Condition E181 of the Planning Consent;
- Reviewing waste classifications and documentation on the management of waste removed from the Project site2;
- Reviewing reports on the management of contamination at the Project site throughout the period construction activities were undertaken by ASBJV and to determine whether:
 - i. No additional contamination was generated by the construction work;
 - ii. The land was maintained in a condition suitable for a road construction worksite and compliance was achieved with Conditions E182 to E185 of the Planning Consent;

² A requirement under Section 4.3.7, EPA (October 2017) Site Auditor Guidelines

- Waste generated by construction activities at the Project site was managed in accordance with iii. EPA guidance and Conditions E202 to E204 of the Planning Consent; and
- iv. The requirements of Conditions O5.10 and O5.11 of EPL 21149 were met.
- Notifying ASBJV, TfNSW and the EPA if the Site Auditor concluded that a part of the Project site should be notified to the EPA under the CLM Act3;
- m) Issuing a Section A site audit statement (SAS) for each part of the Project site where the ground surface was disturbed by construction work undertaken by ASBJV. Each SAS was to be issued at the completion of ASBJV sitework and needed to determine whether the land was suitable for a road construction worksite at the end of construction period and prior to landscaping by TfNSW.

With regards to site contamination, the Site Auditor understood that the NSW Government was responsible for separately engaging a Site Auditor to:

- n) Determine whether land within the Project site was suitable for a specified use other than as a road construction worksite at the end of construction and prior to landscaping by TfNSW;
- o) Review documentation prepared by environmental consultants that determined whether contamination migrating from the Project site not caused by ASBJV was posing an unacceptable risk to off-site receptors and needed to be remediated; and
- p) Review work undertaken at the Project site in addition to that required by the EPA under Conditions O5.10 and O5.11 of EPL 21149.

Interim advice report #19 containing the Site Auditor's understanding of the purpose and scope of the site audit, as described above, was issued to ASBJV on 26/11/18 (Appendix C).

Planning Consent

The site audit was undertaken in accordance with the requirements of the Conditions of Approval for the WestConnex M4-M5 Link SSI 7485 Project issued by the Department of Planning and Environment dated 17/04/18 (Ref [50]). Relevant conditions of the Planning Consent for the purpose of this site audit were:

Contaminated Sites

- A Site Contamination Report, documenting the outcomes of Phase 1 and Phase 2 contamination assessments of land upon which the Critical State Significance Infrastructure (CSSI) is to be carried out, that is suspected, or known to be, contaminated must be prepared by a suitably qualified and experienced person in accordance with guidelines made or approved under the Contaminated Land Management Act 1997 (NSW).
- E182 If a Site Contamination Report prepared under Condition E181 finds such land contains contamination, a site audit is required to determine the suitability of a site for a specified use. If a site audit is required, a Site Audit Statement and Site Audit Report must be prepared by a NSW EPA Accredited Site Auditor. Contaminated land must not be used for the purpose approved under the terms of this approval until a Site Audit Statement is obtained that declares the land is suitable for that purpose and any conditions on the Site Audit Statement have been complied with.
- A copy of the Site Audit Statement and Site Audit Report must be submitted to the Secretary and E183 relevant council for information no later than one (1) month prior to the commencement of operation.
- E184 An Unexpected Contaminated Land and Asbestos Finds Procedure must be prepared and must be followed should unexpected contaminated land or asbestos be excavated or otherwise discovered during construction.
- E185 The Unexpected Contaminated Land and Asbestos Finds Procedure must be implemented throughout construction.

PAGE 7 SAR 278 Northcote

³ A requirement under Sections 3.8.2, 4.3.11 & 4.3.12, EPA (October 2017) Site Auditor Guidelines

Waste

- E202 Waste generated during delivery of the CSSI is to be dealt with in accordance with the following priorities:
 - (a) waste generation is to be avoided and where avoidance is not reasonably practicable, waste generation is to be reduced;
 - (b) where avoiding or reducing waste is not possible, waste is to be re-used, recycled, or recovered; and
 - (c) where re-using, recycling or recovering waste is not possible, waste is to be treated or disposed of at a waste management facility or premise lawfully permitted to accept the materials or in accordance with a Resource Recovery Exemption or Order issued under the Protection of the Environment Operations (Waste) Regulation 2014, or to any other place that can lawfully accept such waste.
- E203 Waste generated outside the site must not be received at the site for storage, treatment, processing, reprocessing, or disposal on the site, except as expressly permitted by a licence or waste exemption under the Protection of the Environment Operations Act 1997, if such a licence is required in relation to that waste.
- E204 All waste generated during construction and operation must be classified in accordance with the EPA's Waste Classification Guidelines, with appropriate records and disposal dockets retained for audit purposes.

Environmental Protection Licence 21149

The EPA issued EPL 21149 for the WestConnex Stage 3A Project dated 9/10/19 (Ref [52]). Relevant conditions of the EPL for the purpose of the Project site audit were:

O5.11 Notwithstanding condition O5.10, construction activities may be undertaken following development of an Environmental Management Plan or similar, subject to written approval from a NSW EPA accredited site auditor.

1.2.2 Scope of Work

The scope of work undertaken for this SAR comprised the following tasks:

- Review a preliminary site investigation report (PSI) and a DSI prepared by environmental consultants engaged by the earlier WestConnex M4 East Project, which commenced several years before work on the WestConnex Stage 3A Project commenced;
- Review an earlier SAS/SAR prepared for a 0.14ha area of land at Site 026 located within the central part of the Northcote Compound;
- Review plans for the management of contamination during the period of construction work, provide interim advice (as may be required), and obtain additional information from the ASBJV environmental team;
- Inspect the Project site prior to, during and at the end of construction work and provide interim advice (as may be required);
- Review a close-out report prepared by ASBJV documenting the final site condition and how contamination was managed during the construction work; and
- Prepare a Section A SAS and SAR that determined whether the land disturbed by ASBJV was suitable for a road construction worksite at the end of the construction period and prior to landscaping by TfNSW.

1.3 Standards & Methodology

1.3.1 EPA Approved Guidelines

The site audit was undertaken in accordance with the provisions of the CLM Act and EPA requirements as specified in their endorsed documents as they existed at the time of this SAR, as listed on the EPA website⁴.

1.3.2 Decision Process

The EPA⁵ decision process for assessing the risks posed by ground contamination at an urban redevelopment site involved ten issues.

The first issue in the EPA decision process was that:

'all site assessment, remediation and validation reports follow applicable guidelines'.

The Data Quality Indicators (**DQI's**) and assessment criteria that the Site Auditor commonly adopted for environmental assessments conducted at an urban redevelopment site are summarised in **Table 1-1**. The Site Auditor used these DQI's and criteria to assess the reliability and adequacy of the data provided by Environmental Consultants and to identify documentation where the level of non-compliance was considered to be significant.

Table 1-1 Data Quality Indicators and Evaluation Criteria

DQI	Evaluation Criteria
Documentation completeness	 DQO process properly described Site properly identified Site history adequately known The conceptual site contamination model for the site is known to a high level of confidence The site conditions adequately known Completion of field calibration records, borehole logs, chain of custody documentation, laboratory test certificates from NATA-registered laboratories
Data completeness	 Sampling density comparison meets EPA (1996) 'Sampling Design Guidelines' for all potential contaminants of concern at all areas of environmental concern Use of systematic and judgemental sampling to provide sufficient data representative of all AECs
Data comparability	 Use of appropriate techniques for the sampling, storage and transportation of samples Use of NATA certified laboratory using NEPM procedures
Data representativeness	 Good sampling coverage of all areas of environmental concern at the site, and selection of representative samples Location, distribution & extent of samples appropriate to characterise contamination at all AECs
Precision and accuracy for sampling and analysis	 Use properly trained and qualified field personnel Blind field duplicates to be collected at a minimum rate of 1 in 10 RPD's < 30% for inorganic and 50% for organic analyses Acceptable levels for equipment rinsate blanks Achieve laboratory QC criteria

⁴ www.epa.nsw.gov.au/clm/guidelines.htm

Appendix A, EPA (October 2017) 'Contaminated Land Management, Guidelines for the NSW Site Auditor Scheme (3rd edition)'

The remaining issues in the EPA decision process were:

- 'any aesthetic issues relating to site soils have been adequately addressed';
- > soils have been assessed against relevant health-based investigation levels and potential for migration of contamination from soils to groundwater has been considered';
- groundwater (where relevant) has been assessed against relevant health-based investigation levels and, if required, any potential impacts to buildings and structures from the presence of contaminants considered.'
- hazardous ground gases (where relevant) have been assessed against relevant health-based investigation levels and screening values'
- any issues relating to local area background soil concentrations that exceed relevant investigation levels have been adequately addressed in the site assessment report(s);
- the impacts of chemical mixtures have been assessed;
- > any potential ecological risks have been assessed;
- > any evidence of, or potential for, migration of contaminants from the site has been appropriately addressed, including potential risks to off-site receptors, and reported to the site owner or occupier; and
- the site management strategy (where relevant) is appropriate including post-remediation environmental plans.'

The contract made between ASBJV and the NSW Government described the Northcote Compound as a road construction worksite. The Site Auditor considered this land use did not correspond to an urban redevelopment site as defined by the EPA (2017) Site Auditor Guidelines because:

- A road construction worksite did not correspond to one of the four land uses considered by the EPA 10step decision process;
- A road construction worksite is covered by permanent concrete pavements and structures so there is no significant physical contact with underlying soils or groundwater;
- Future activities at a road construction worksite would be managed in accordance with a site-specific management plan;
- > The contract only required the site audit to consider contamination risks where the ground surface was disturbed by construction work undertaken by ASBJV;
- > The Contract only required the site audit to consider contamination risks where the ground surface was disturbed by construction work undertaken by ASBJV;
- The Contract did not require ASBJV to remediate contamination but to undertake their work so that no additional contamination was generated by construction work;
- ➤ The migration of contamination from the Northcote Compound was not an issue if pre-construction levels were not increased; and
- The Northcote Compound was land owned by the NSW Government on which public infrastructure was to be constructed.

Given these circumstances, the Site Auditor applied the EPA decision process in a manner consistent with the ASBJB contractual requirements. This was done by adopting appropriate Data Quality Objectives (**DQOs**) that are described in the following section.

1.4 Data Quality Objectives

DQOs are performance and acceptance criteria developed during the planning of a site assessment. They are used to evaluate whether there is enough data of a high enough quality to support decision making⁶.

The DQO process is a seven-step systematic planning approach used to prepare plans for environmental data collection activities. The DQO process was specified in the NEPM and provides a systematic approach for defining the criteria that a data collection design should satisfy, including: when, where and how to collect samples or measurements; determination of tolerable decision error rates; and the number of samples or measurements that should be collected.

The Site Auditor assessed the appropriateness of the environmental site assessments (**ESAs**) using the following DQO process, which is considered to meet EPA requirements consistent with ASBJB contractual requirements:

- Step 1: State the Problem Contamination at the Northcote Compound needed to be managed consistent with its use as a road construction worksite in accordance with a contract between the ASBJV and the NSW Government.
- Step 2: Identify the Decisions These decisions reflect the purpose and scope of the site audit described in Section 1.2. These decisions were:
 - Determine if the Northcote Compound at the end of the construction period was suitable for a road construction worksite and compliance was achieved with Conditions E182 to E185 of the Planning Consent;
 - Determine whether ASBJV managed contamination it interfered or disturbed during the course of carrying out its work;
 - Determine whether operations at the Northcote Compound may have generated contamination or caused an increase in contamination migrating from the site;
 - Recommend management strategies which may be required at the Northcote Compound, including additional investigations and/or remediation works;
 - Determine whether there was sufficient information satisfying guidelines made or approved under the CLM Act to determine that implementation of the contamination management plan was feasible and would enable the specified use of the Northcote Compound and prevent an increase in contamination migrating from the site;
 - Assess compliance with Condition E181 of the Planning Consent and Condition O5.11 of EPL 21149 (Ref [52]) and NSW Government environmental legislation regarding contaminated site and waste management; and
 - Waste generated by construction activities at the Project site was to be managed in accordance with EPA guidance and Conditions E202 to E204 of the Planning Consent.

> Step 3: Identify Inputs to the Decisions – These included:

- Existing site information, site history, regional geology, topography, hydrogeology and background conditions;
- The use of proper investigation techniques;
- Data collected by investigations and monitoring programs implemented during the project;
- Development of an appropriate conceptual site model (CSM) for assessing contamination risks;
- The use of appropriate site assessment criteria and compare results as measured against these criteria; and
- The use of EPA-approved risk assessment methodologies.

⁶ Section 1.2, EPA (May 2020) 'Consultants reporting on contaminated land, Contaminated land guidelines'

- Step 4: Define the Study Boundaries As defined by the contract between ASBJV and the NSW Government comprising:
 - The boundaries of the Northcote Compound; and
 - The condition of the Northcote Compound at the end of the construction works.
- Step 5: Develop a Decision Rule The decision rules in characterising contamination at the Northcote Compound were:
 - Data used in contamination assessments were to be of a sufficient quality that allowed decisions to be made regarding contamination risks at the site and compliance with regulatory requirements;
 - Field and laboratory test results measured against EPA-approved criteria; and
 - The site was suitable for ongoing use as a road construction worksite if soil, groundwater and soil vapour contamination did not pose an unacceptable risk to users of the motorway, workers stationed at the facilities and maintenance workers.
- > Step 6: Specify Limits on Decision Errors These included:
 - The acceptable limits for inter/intra laboratory duplicate sample comparisons are laid out within the fieldwork protocols; and
 - The acceptable limits for laboratory quality assurance / quality control (QA/QC) parameters are based upon the laboratory reported acceptable limits and those stated within the NEPM 2013 guidelines.
- Step 7: Optimise the Design for Obtaining Data Identify the most resource-effective sampling and analysis design for general data that are expected to satisfy the DQOs. This may involve the use of field screening tests and use of biased sampling.

A summary of the DQI's for the field and laboratory testing programs are specified in **Table 1-1**.

1.5 Information Reviewed

The environmental reports reviewed for this audit (in approximate chronological order) comprised:

- 1. Transport for NSW (August 2017) "M4-M5 Link Environmental Impact Statement, WestConnex"
- 2. Ramboll (19 February 2019) "Northcote Compound, WestConnex M4 East, Phase 2 Environmental Site Assessment". Document No: 318000122_Final prepared for CPB Samsung John Holland
- 3. JM Environmental (4 March 2019) "JME18057-49 Preconstruction Land Condition Assessment, Northcote Street Compound Revision 2". Document No: JME18057-49 prepared for LSBJV
- 4. Ramboll (November 2016) "Underground Petroleum Storage System Validation Report, 269 Parramatta Road, Haberfield". Prepared for CPB Samsung John Holland

Other information reviewed for this audit comprised:

- 50. Department of Planning and Environment (17 April 2018) "Infrastructure Approval, Section 5.19 of the Environmental Planning & Assessment Act 1979, Application No: SSI 7485, Conditions of Approval for WestConnex M4-M5 Link SSI 7485". 76 pages
- 51. LSBJV (6 June 2018) PowerPoint Presentation "WestConnex Design and Construct, M4 M5 Link Main Tunnel Works, Compounds". 18 pages
- 52. NSW EPA (9 October 2018) 'Environmental Protection Licence Number 21149, WestConnex Stage 3A M4-M5 Mainline Tunnels, WestConnex between M4 East at Haberfield and the New M5 at St Peters, Marrickville NSW 2204'. 30 pages
- 53. Inner West Council (11 November 2016) "Land Zoning Map Sheet LZN_001, Ashfield Environmental Plan 2013 (Amendment No. 3)"
- 54. Higinbotham & Robinson (1889 1894) Map "Fivedock, Parish of Concord". Atlas of the Suburbs of Sydney, https://dictionaryofsydney.org/media/3907

- 55. AECOM (26 February 2019) "Site Audit Report, Northcote Compound, Site 026, WestConnex M4 East".

 Document No: 60437339 prepared by Brad Eismen for CPB Samsung John Holland JV
- 56. AECOM (26 February 2019) "Site Audit Statement, BE136 for Northcote Compound, Site 026, WestConnex M4 East". Prepared by Brad Eismen for CPB Samsung John Holland JV
- 57. LSBJV (10 October 2018) "Site Establishment Management Plan, M4-M5 Link Mainline Tunnels". Document No: M4M5-LSBJ-PRW-EN-MP01-PLN-0018-07
- 58. LSBJV (23 October 2018) "Appendix B, Contaminated Land Management Sub-plan, M4-M5 Link Mainline Tunnels". Document No: M4M5-LSBJ-PRW-EN-MP01-PLN-0021-01 Rev01
- 59. LSBJV (23 October 2018) "Unexpected Contaminated Land and Asbestos Finds Procedure, M4-M5 Link Mainline Tunnels". Appendix A of Ref [58]
- 60. LSBJV (17 April 2020) "Appendix B5, Soil and Surface Water Management Sub-plan, M4-M5 Link Mainline Tunnels". Document No: M4M5-LSBJ-PRW-EN-MP01-PLN-0005-09 Rev09
- 61. LSBJV (22 June 2020) "Appendix B9, Waste Management Sub-plan, M4-M5 Link Mainline Tunnels". Document No: M4M5-LSBJ-PRW-EN-MP01-PLN-0009-07 Rev08
- 62. LSBJV (28 April 2021) "Appendix B6 Groundwater Management Sub-plan, M4-M5 Link Mainline Tunnels". Document No: M4M5-LSBJ-PRW-EN-MP01-PLN-0006-13 Rev13 (revision 1 dated 17 September 2018)
- 63. ASBJV (27 June 2022) Drawings "M4M5 Link Main Tunnel Works, Package: Project Wide M4M5-RBGP-PRW-CIV-CW02-DPK-0001, Construction Site Reinstatement". 51 drawings prepared for Sydney Motorway Corporation WestConnex
- 64. PSM (9 April 2020) Drawings "M4-M5 Link Main Tunnel Works, Northcote Street Construction Access Backfill and Stub Wall". Document No: M4M5-PSML-NCS-STR-IS22-DPK-0001 comprising 14 drawings prepared for Sydney Motorway Corporation WestConnex

Additional information was obtained by the Site Auditor when a site inspection was conducted at the Northcote Compound on 2/06/21 and 4/11/22, with photographs taken by the Site Auditor provided in **Appendix D**.

1.6 Chronology of Site Audit Program

A chronology of the main activities relevant to the site audit work is provided below:

- ➤ 30 November 2016 A site remediation and validation report (SRVR) was issued by Ramboll for the removal of UPSS infrastructure at Site 006 (Ref [4]);
- ➤ December 2016 The fieldwork for the DSI at the Northcote Compound was undertaken by Ramboll for the WestConnex M4 East contractor and documented in a draft report;
- 20 July 2018 The Site Auditor for the WestConnex Stage 3A Project was engaged and issued formal notification for the commencement of the site audit to the EPA;
- > 19 February 2019 The Ramboll DSI report for the Northcote Compound was finalised (Ref [2]);
- → 4 March 2019 A preconstruction assessment of the Northcote Compound was issued by JM Environments to the ASBJV (Ref [3]);
- ➤ 2 June 2021 The Site Auditor inspected the Northcote Compound while it was being used by the WestConnex Stage 3A contractor, with copies of photos provided in **Appendix D**;
- ➤ 18 February 2022 The Site Auditor reviewed the available documentation on the Northcote Compound and issued a draft SAR to ASBJV that covered Sections 1 to 3. The draft SAR provided ASBJV with interim audit advice on contamination issues that needed to be addressed;
- ➤ 4 November 2021 The Site Auditor conducted a final site inspection of the Northcote Compound, with copies of photos provided in **Appendix D**;
- ➤ 28 November 2022 ASBJV approved the draft SAS / SAR and provided an interim environmental management plan (EMP) for contamination assessment work that needed to be completed prior to a

Section A2 SAS being issued for the Northcote Compound. The Site Auditor then finalised the documents and issued the signed Section B SAS and this SAR to ASBJV, TfNSW, the EPA and

Council. Copies of the Section B SAS and the interim plan are provided in Appendix E.

1.7 Abbreviations

ABC Ambient background concentration

ACL Added contaminant limit

ACM Asbestos containing material

ADWG Australian Drinking Water Guideline

AF Asbestos fines

AHD Australian Height Datum

ALF Alexandria Landfill

AMP Asbestos management plan

ANZECC Australia and New Zealand Environment and Conservation Council

ANZG Australian New Zealand 2018 water quality guidelines

APEC Area of potential environmental concern

ARIS Australian Soil Resource Information System
ASBJV Acciona Samsung Bouygues Joint Venture
ASRIS Australian Soil Resource Information System

ASS Acid sulphate soil

AST Above ground storage tank

B&D waste Building and demolition waste

BaP TEQ Benzo(a)pyrene toxicity equivalent

bgl Below ground level

BOM Bureau of Meteorology

BTEX Benzene, toluene, ethyl benzene, xylenes

BTEXN BTEX and naphthalene

C&D Construction and demolition
CCA Copper chrome arsenate
CEC Cation exchange capacity

CEMP Construction environmental management plan

CLM Act Contaminated Land Management Act 1997 (NSW)

CLMP Contaminated land management plan

COC Chain of custody

COV Coefficient of variation

CQA Construction quality assurance

CQAR Construction Quality Assurance Report

CS Characteristic gas situation

CSI Contaminated site investigation

IAN SWANE & ASSOCIATES

CSSI Critical State Significant Infrastructure

DBYD Dial-before-you-dig

DCP Development control plan

DEC Department of Environment and Conservation NSW

DECC Department of Environment and Climate Change NSW

DECCW Department of Environment, Climate Change and Water NSW

DOH Department of Health (WA)

DPE Department of Planning and Environment (NSW)

DQI Data quality indicator

DQO Data quality objective

DSI Detailed site investigation

EFCP Electrical friction cone penetrometer

EIL Ecological investigation level
EIS Environmental impact statement
EMP Environmental management plan

EPA Environment Protection Authority (NSW)

EPL Environmental Protection License

ERP Emergency response plan
ES Environmental Strategies

ESA Environmental site assessment

ESD Ecologically sustainable development

FA Fibrous asbestos

FSL Finished surface level

GIL Groundwater investigation level
GME Groundwater monitoring event

GPS Global positioning system

GSV Gas screening value GSW General Solid Waste

GTA Geotechnical Testing Authority

HAZMAT Hazardous materials assessment

HC Hydrocarbon

HDPE High density polyethylene

HEIC High energy impact compaction

HGG Hazardous ground gas

HGGRA Hazardous ground gas risk assessment

HHERA Human health and ecological risk assessment

HIL Health investigation level

ISEMP Interim Site Environmental Management Plan

IAN SWANE & ASSOCIATES

ITP Inspection and Test Plan

JME JM Environments

Kg Kilograms
L Litres

LCMP Landfill closure management plan

LCS Laboratory control sample

LFG Landfill gas

LFGMS Landfill gas mitigation system

LGA Local Government Area

LNAPL Light non-aqueous phase liquid

LOP Level of protection
LOR Limit of reporting

LSBJV Lendlease Samsung Bouygues Joint Venture

LTEMP Long Term Environmental Management Plan

M Metres

MAHs Monocyclic aromatic hydrocarbons

Mg Milligrams

MIP Membrane interface probe

nd Non-detectible

NEPM National Environment Protection Measure

NHMRC National Health and Medical Research Council

NIOSH National Institute for Occupational Safety and Health (USA)

NMOC Non-methane organic compounds

NRMMC Natural Resource Management Ministerial Council

NSW New South Wales

OCP Organochlorine pesticides

OHSP Occupational health and safety plan

OSD On-site detention basin

PAH Polycyclic aromatic hydrocarbons

PASS Potential acid sulphate soil

PBR Pyrmont Bridge Road

PCBs Polychlorinated Biphenyls

PCOC Potential contaminant of concern

PFAS Perfluoroalkyl and polyfluroalkyl substances

PID Photoionisation detector

POEO Protection of the Environment Operations (Act) 1997 (NSW)

PPE Personal Protective Equipment

ppm parts per million

IAN SWANE & ASSOCIATES

PQL Practical quantification limit

PREW Parramatta Road East West worksite, Ashfield

PSI Preliminary site investigation

QA Quality assurance

QC Quality control

QRA Qualitative risk assessment

RAC Remediation Acceptance Criteria

RAP Remediation Action Plan

RMS Roads and Maritime Services
RPD Relative percent difference

RL Reduced level

RRE Resource Recovery Exemption

RRO Resource Recovery Order

RSL US EPA Regional Soil Level

RSW Restricted Solid Waste
SAC Soil acceptance criteria

SAQP Sampling and analysis quality plan

SAR Site audit report

SAS Site audit statement
SD Standard deviation

SEARs Secretary's Environmental Assessment Requirements

SEMP Site Establishment Management Plan

SEPP State environment planning policy

SIL Soil investigation level

SMDD Standard maximum dry density

SOMC Standard optimum moisture content

SMF Synthetic mineral fibre SMP Site management plan

SOP Standard operating procedure

SPI St Peters Interchange

SPIR Submissions and Preferred Infrastructure Report

SRVR Site remediation and validation report

SSI State Significant Infrastructure
SVOCs Semi volatile organic compounds

SWL Standing water level

SWMP Soil and water management plan

SWMS Site work method statement

TCLP Toxicity Characteristic Leaching Procedure

IAN SWANE & ASSOCIATES

TDS Total dissolved solids

TfNSW Transport for NSW (formerly RMS)

TPH Total petroleum hydrocarbons
TRH Total recoverable hydrocarbons

TSEMP Task Specific Excavation Management Plan

TSS Total suspended solids

UCL Upper confidence limit

UFP Unexpected Finds Protocol

USA United States of America

US EPA United States Environmental Protection Agency

UST Underground storage tank

VB Vertical barrier

VENM Virgin excavated natural material VHCs Volatile halogenated compounds VMP Voluntary Management Proposal

VOCs Volatile organic compounds WCR Waste classification report

WCX M5 WestConnex New M5
WHS Worker health safety

WMP Waste management plan

μg micrograms

2. Review of Site Conditions in 2019 Pre-ASBJV Work

This section of the SAR assesses the adequacy of data provided by ESAs on the condition of the Northcote Compound and the contamination risks that existed in 2019 when the WestConnex Stage 3A Project took possession of the Site from the WestConnex M4 East contractor. The available ESAs were:

- > A DSI prepared by Ramboll dated 19/02/19 (Ref [2]);
- > A preconstruction land condition assessment prepared by JM Environments dated 4/03/19 (Ref [3]); and
- A validation report for the NW part of the Northcote Compound at 269 Parramatta Road (Site 006) prepared by Ramboll dated 30/11/16 (Ref [4]).

2.1 Site Identification

The Ramboll 2019 DSI subdivided the Northcote Compound into 12 sites numbered 006, 012, 026 – 028, 046, 136 – 141. A summary of the Northcote Compound location details provided by the Ramboll 2019 DSI is presented in **Table 2-1**. A plan showing the 12 sites that formed the Northcote Compound is provided in **Figure 2-1**. A Sixmaps subdivision plan for the Northcote Compound is provided in **Figure 2-2**, with an extract of the zoning map provided in **Figure 2-3**.

Table 2-1: Summary of Site Location Details

Site Location Detail	Detail	References
Site name	WestConnex Stage 3A site C3a	Ref [51]
Address/location	Site 006: 269 Parramatta Rd, Haberfield Site 012: 2-4 Wattle Street, Haberfield Site 026: 257 Parramatta Rd, Haberfield Site 027: 255 Parramatta Rd, Haberfield Site 028: 249-251 Parramatta Rd, Haberfield Site 046: Northcote Street Site 136: 3 Wolseley St, Haberfield Site 137: 1 Wolseley St, Haberfield Site 138: 4 Northcote St, Haberfield Site 139: 2 Northcote St, Haberfield Site 140: 1 Northcote St, Haberfield Site 141: 3 Northcote St, Haberfield	Sectn 3.1 & Appns B - F, Ref [2]
Legal property description	Site 006: Lots 63 & 64 DP4612 Site 012: Lots 1 & 2 DP239458 Site 026: Lots 51 – 52 DP719977 Site 027: Lots 53 & 54 DP719977 Site 028: Lot 56 - 58 DP719977 Site 046: Northcote Street Site 136: Lot 114 DP4612 Site 137: Lot 115 DP4612 Site 138: Lot 1 DP933407 Site 139: Lot 1 DP933225 Site 140: Lot B DP391272 Site 141: Lot A DP391272	Sectn 3.1 & Appns B - F, Ref [2]; Six Maps NSW
Local Government Area	Inner West Council	Appn B – F, Ref [2]; Ref [53]
Site area	Northcote Compound = 1.2165 ha Site 006: 0.13 ha Site 012: 0.059 ha Site 026: 0.14 ha Site 027: 0.12 ha Site 028: 0.20 ha	Sectn 3.1 & Appn B - F, Ref [2]; Ref [51]

Site Location Detail	Detail	References
Owner	TfNSW (formerly Roads and Maritime Services)	Sectn 1 & Appns B - F, Ref [2]
Contractor	ASBJV (formerly LSBJV)	Ref [3]
Past Zoning	Commercial/industrial zoning along Parramatta Road and Wattle Street; Low density residential for remainder	Sectn 3.1, Ref [2]; Ref [53]
Current zoning	B6 – Enterprise corridor for the sites adjacent to Parramatta Road and Wattle Street, namely, Sites 006, 012, 026 - 028	
	R2 – Low density residential for the other sites, namely, Sites 136 - 141	
Future zoning	No known change	
Surrounding land use	North: Wolseley Street then commercial/ industrial; East: Low density residential properties; South: Low density residential and commercial/industrial properties West Parramatta Road then commercial/ industrial	Sectn 4.3, Ref [3]

Legend:

Inadequate information provided in ESAs

The Site Auditor assessed the accuracy of the site location information provided in the ESAs by:

- Comparing the multiple lines of evidence provided by the source data;
- > Comparing the supplied data with other publicly available data obtained from NSW Government and other websites;
- > Examining Google and SixMaps aerial photos on several occasions throughout the audit period; and
- Inspecting the Northcote Compound throughout the audit period, with a photographic record provided in **Appendix D**.

The Site Auditor considered the information on site location details provided in the ESAs was close to meeting the documentation completeness DQO. One error in the Ramboll 2019 DSI was that Site 028 included not only Lot 56 but also Lots 57 and 58 in DP719977. The Site Auditor considered this error was not significant for the purpose of this SAR because the error was identified and it had no influence on the contamination risk assessment.

2.2 Site History

The Ramboll 2019 DSI⁷ advised that historical data on the land occupied by the Northcote Compound was provided by several reports. Copies of these reports were not available for this site audit, with the Ramboll 2019 DSI providing a summary of the available data, with a copy of this summary provided in **Table 2-2**. Additional historical information was provided for the five B6 Enterprise corridor zoned properties in Appendices B – F of the DSI.

⁷ Section 4, Ref [2]

Figure 2-1 Areas Forming the Northcote Compound


(Source: Figure 3, Ref [2])



Figure 2-2 Six Maps Subdivision Plan for Northcote Compound (Area C3a)



Figure 2-3 Land Zoning Plan for Northcote Compound (Area C3a) (Source: Ref [53])



PAGE 23 SAR 278_Northcote

(Source: Table 4-1, Ref [2])

Table 2-2 Summary of Historical Data Provided by Ramboll 2019 DSI

Site	GHD Risk	Review of Documents Completed	Revised Contamination Status	Notes
006	Low	Yes	High	The site was likely a former service station site based on the combination of historical aerial photographs and the historical title deeds indicating Amoco (Oil company) being a former site owner between the 1960-1980s.
012	Moderate	Yes	Moderate	The site was likely used as a mechanical workshop. Title search in GHD's EIS indicates former motor car dealer.
026	Moderate	Yes	Moderate	The site was likely used as a tyre workshop. Identified as potentially contaminated land in ENVIRON 2014 from use as a commercial/industrial property and potential fill. Detailed site inspection carried out by Ramboll 11/11/15, indicated minimal potential of contamination from current site use (no significant staining, USTs etc)
027	Moderate	Yes	Moderate	The site was likely a car yard and identified as potentially contaminated land in ENVIRON 2014 from use as a commercial/industrial property and potential fill.
028	Low	Yes	Moderate	The site was likely used as a liquor store. Detailed site inspection carried out by Ramboll 11/11/15, indicated no current contaminating activities (liquorland) for last 10 years at least. The additional information indicated that the site may have been potentially a former service station (site layout) which could pose a risk to construction workers through soil and groundwater vapour intrusion due to the potential of having onsite construction buildings. Also potential for contamination from uncontrolled filling including asbestos.
046	N/A	Yes	Low	Northcote Street. Initially classified as moderate because of potential filling beneath roadway and caryard to the north. Site 027 and Site 028 is already being investigated separately and migration of contamination unlikely unless significant. In addition, no excavation works are proposed for site 046 and review of historical aerials indicates long historical use of site as Northcote Street as far back as 1943. Re-classified from moderate to low risk as it is considered that investigation of adjacent sites 027 and 028 will be sufficiently representative of filling/regional contamination. Further investigation not considered necessary.
136	Low	Yes	Low	Residential property. Residential in 1943 photo.
137	Low	Yes	Low	Residential property. Residential in 1943 photo.
138	Low	Yes	Low	Residential property. Residential in 1943 photo.
139	Low	Yes	Low	Residential property. Historical Title Deeds from 1907-to present. Residential in 1943 photo.
140	Low	Yes	Low	Residential property.
141	Low	Yes	Low	Residential property. Residential in 1943 photo.

Additional historical information regarding underground storage tanks (USTs) and associated infrastructure at Site 006 (269 Parramatta Road) on the NW side of the Northcote Compound was provided in the Ramboll 2016 site remediation and validation report (**SRVR**), which is reviewed in **Section 2.3**.

The Site Auditor considered the historical data provided by the Ramboll 2019 DSI and Ramboll 2016 SRVR for the Northcote Compound did not meet the documentation completeness DQO as specified in the EPA (2020) reporting guidelines. The main data gaps included:

- Copies of aerial photographs;
- Data provided by former owners/tenants/local Council;
- Historic site layout plans;
- Sewer and underground service plans;
- Extent of any filling or dumping at the site;
- Copies of SafeWork NSW searches of the Stored Chemical Information Database;
- > Details and locations of former USTs and above ground storage tanks (ASTs) except for Site 006;
- Local site knowledge of residents and staff both present and former;
- > Summary of local literature about the site, including newspaper articles; and
- Details of building and related permits, licences, approval and trade waste agreements.

The Site Auditor sought to address these data gaps by reviewing historical data available from public sources. These included:

- ➤ Historical data provided in the 2017 Environmental Impact Statement (EIS)⁸, with a copy of the data provided in **Table 2-3**;
- ➤ The 1889 1894 Fivedock Map (Ref [54]), with an extract showing the Project site provided in **Figure 2-4**; and
- An extract of the 1943 aerial photo of the Project site available from the SixMaps NSW website (**Figure 2-5**).

Table 2-3 Historical Data Provided by 2017 EIS in Northcote Compound (C3a) (Source: Appn R, Ref [1])

Property	Site history summary	
C3a-A	The six houses appeared to be present since the 1930 historical aerial	
Six residential houses	photograph until 2016.	
С3а-В	The property was owned by various private owners (1907 to 1963 and 2000)	
Garden shop and service station	to 2015), Amoco Australia Pty Ltd (a petroleum company) (1963 to 1980) and Garden Art Foundations (1980 to 2000)	
	 Based on the historical aerials the property was formerly residential, and contained a corner shop or hotel which was demolished, and an Amoco service station constructed in the 1960s 	
	The service station was then used as a garden shop from 1980 until 2016.	

⁸ Section 4.3.3in Appendix R, Ref [1]

Table 2-3 (cont'd) Historical Data Provided by 2017 EIS in Northcote Compound (C3a)

able 2-3 (contra) Hist	torical Data Provided by 2017 EIS in Northcote Compound (C3a)
C3a-C Car Mechanic Workshop	 According to historical titles the property was previously owned by The Northcotstate Company Ltd (1907 to 1911), various private owners (1911 to 1973 and 1981 to 1998), Cousins Truck Sales (NSW) Pty Ltd, Moranda Pty Ltd (1979 to 1981) and Bill and Tina Hatzivasiloiou H Jax Quickfit Properties (1998 to 2015)
	Based on the historical aerials the property was previously three residential properties until they were demolished and a truck dealership constructed in the late 1970s/early 1980s
	The property was then used as a wheel alignment and tyre workshop until 2016.
C3a-D Car Dealership	 According to historical titles the property was previously owned by The Northcote Estate Company Ltd (1907 to 1914) and various private owners (1911 to 2015)
	Based on the historical aerials the property was previously two residential properties that were demolished and converted into a commercial business in the 1970s
	In the 1980s there was an additional commercial rectangular building in the centre of the site and cars parked across the site. The additional building
	was demolished by the mid-1990s
	Based on the historical aerials it appears that the site has been used as a car dealership and a possible mechanics until 2016.
C3a-E Liquor store	According to historical titles the property was owned by The Northcote Estate Company Ltd (1907 to 1911), various private owners (1907 to 1988), Pesutu Pty Ltd (liquor retailer) (1988 to 2009) and Reo Costi lease to Liquorland (2009 to 2015)
	Based on the historical aerials it appears that the site was formerly part of four residential houses that were demolished in the late 1960s/early 1970s. The site was then used as a liquor shop and car park since 1988
	The use of the property between the 1970s and 1988 is unknown
	The property was used as a Liquor store until 2016.
C3a-F Automotive Workshop	 According to historical titles the property was previously owned by The Northcote Estate Company Ltd (1910 to 1912), various private owners (1912 to 1965, 1970 to 1977 and 2011 to 2015), the Commissioner of Main Roads (1965 to 1970), and British and Continental Cars (Haberfield) Pty Ltd (1977 to 2011)
	Based on the historical aerials the property was previously part of three residential properties that were acquired and demolished for the widening of Wattle Street in the 1960s
	The property was then used as a car dealership until 2011 and was then converted for use as a mechanics workshop until 2016.

Figure 2-4 1889 – 1894 Fivedock Map

(Source: Ref [54])




Figure 2-5 1943 Historic Aerial Photo of Northcote Compound

(Source: Sixmaps NSW)

PAGE 28



SAR 278_Northcote

The Site Auditor considered the available historical data provided by the ESAs and publicly available sources was sufficient for developing a CSM for the Northcote Compound. This is because the available data showed:

- > The historical data provided by the Ramboll 2019 DSI was consistent with the data provided by the earlier 2017 EIS;
- The data provided by the 2017 EIS would have been reviewed by the EPA and DPE;
- ➤ A planning consent for construction work at the Northcote Compound was provided on 17/04/18 (Ref [50]);
- The data showed that the Northcote Compound land together with the surrounding area was used for low density residential use up to the 1940's; and
- ➤ After the 1940's, the part of the Northcote Compound land along Parramatta Road was redeveloped for a range of commercial / light industrial land uses mainly associated with car workshops / car yards (i.e. Sites 006, 012, 026 028, 046). Site 006 was a former service station site until 1980 when it's use changed to a garden shop. The land use across the remainder of the Site remained low density residential (i.e. Sites 136 141).

2.3 Site Condition and Surrounding Environment

During construction of the M4 East Motorway, the Northcote Compound was used for a dive structure providing access for roadheaders, a laydown area, temporary ventilation plant, acoustic shed for stockpiled soils, water treatment plant, sedimentation pond, electrical and mechanical workshops, offices and an electrical substation. A 2016 layout plan for the Northcote Compound that was to be constructed by the M4 East Motorway Project is provided in **Figure 2-6**. The uses of the Northcote Compound remained largely unchanged when the WestConnex Stage 3A Project took possession in March 2019, as shown by the layout plan in **Figure 2-7**.


A land condition assessment of the Northcote Compound was undertaken on 22/02/19 by JM Environments (**JME**) and documented in a report dated 4/03/19 (Ref [3]). The purpose of the assessment was to observe the condition of the Site just prior to the WestConnex Stage 3A project taking possession. The JME assessment consisted of a walkover inspection by an environmental consultant and the documentation of the site condition by 57 photos taken at various points across the Northcote Compound that were included in their report. The Site Auditor considered these photos showed the Northcote Compound was covered by recently constructed buildings, concrete ground slabs and tunnel excavations consistent with the layout plans in **Figure 2-6** and **2-7**. No physical evidence of contamination or stockpiled waste appeared to remain at the Northcote Compound.

The data on site conditions and the surrounding environment provided by the ESAs relevant to the assessment of contamination risks at the Northcote Compound are summarised below:

- ➤ **Topography**: The Northcote Compound area was generally flat with the ground surface ranging from 11 mAHD in the SE (towards Wolseley Street) to 9 mAHD to the NW (towards Parramatta Road).
- > On-site developments and surface conditions: Refer above description and Figures 2-6 and 2-7.
- ➤ USTs / ASTs: Site demolition and clearing work undertaken by the WestConnex M4 East Contractor identified two USTs at the former service station at Site 006 labelled UST1 and UST2 that were removed together with contaminated soil in the vicinity of the USTs as shown in Figure 2-8. The location of these USTs corresponded to the footprint of the tunnel dive structure subsequently constructed by the M4 East contractor prior to the commencement of the WestConnex Stage 3A project. The Ramboll 2019 DSI also considered there was a risk that Site 028 may also have been a service station that had USTs.

Figure 2-6 WestConnex M4 East Layout for Northcote Compound (2016-2019)

(Source: Figure 2, Ref [2])




SAR 278 Northcote

(Source: Ref [51])

Figure 2-7 WestConnex Stage 3a Layout for Northcote Compound (2019-2022)





- Physical evidence of contamination: Site demolition and clearing work undertaken by the WestConnex M4 East Contractor identified physical evidence of contamination at:
 - The backfill sands exposed when the two USTs were removed from the former service station at Site 006. Ramboll described the backfill sands as slightly odorous with no signs of free phase liquid. Two USTs (labelled UST1 and UST2) were identified and removed;
 - An ACM fragment in fill at borehole 026_GW001 (Site 026); and
 - Asbestos pipe at 0.5 mbgl⁹ at Site 027.
- ➤ **Geology and location and extent of fill**: The depth of fill varied considerably across the Site, but in general the geology encountered in the area consisted of:
 - Concrete or hardstand at ground level, then
 - FILL; gravelly silty clay, grey/brown, from ground level to a thickness of 0.25 0.7 m, underlain by,
 - SILTY CLAY/CLAY orange/brown (residual clay with traces of gravel) from 0.25 to 2.5 m thickness 1.1 to 1.9 m, underlain by,
 - Highly weathered SHALE orange/white mottled from 1.5 to 2.5 m thickness not determined, then
 - SANDSTONE, mostly white, medium grained from 2.3 m.
- Acid sulfate soil (ASS): The ASS risk map showed the Site was within Class 5 mapped land with Class 2 land located 150 m north and 430 m to the NE. Areas mapped as Class 5 had no known occurrence of ASS. Works within 500 m of adjacent Class 1, 2, 3 or 4 land below 1 mAHD presented an environmental risk if the water table was lowered.
- **Hydrogeology**: Shallow groundwater in the surrounding area was at between 2.5 and 5 mbgl in sandstone and weathered shale.

A search of the NSW Groundwater Database was undertaken by GHD on 26/05/15 and 9/09/14 and identified a registered groundwater well (GW112144) situated 200m NW of the Site. Fill was encountered from the ground surface to 2.2 mbgl then silty clay to 5.5 mbgl and sandstone to 57.1mbgl. GHD installed two groundwater wells in the general area. Well BH1365 was screened within the sandstone aquifer with a standing water level of 4.98 mbtoc¹⁰ and well BH1369 was screened within the weathered shale aquifer, with a standing water level of 2.595 mbtoc.

Based on local topography, groundwater was anticipated to flow in a northerly direction towards Iron Cove Creek.

- ➤ **Background water quality**: Slightly elevated metal concentrations associated with background water quality that were not considered to be of concern. The hydrogeology is dominated by shale and siltstone with salinity levels greater than 14,000 mg/L and low potential for groundwater movement.
- > Surrounding Land Use: (Refer Table 2-1).
- Local sensitive environments: Iron Cove Creek that flows into Iron Cove, which forms part of the Parramatta River. The Development Consent¹¹ also advised that the Project would have no impacts on biodiversity, soil and water.
- ➤ Nearest groundwater and surface water receptors: The nearest groundwater and surface water receptors were in Iron Cove Creek located 200 300 m to the north of the Site.
- > Surrounding areas that may pose a pollution hazard to the Site: Ramboll considered there was a risk that Site 505 to the SW of the Site may have been used as a service station, mechanical workshop and radiator manufacturing facility.

⁹ mbgl = metres below ground level

¹⁰ mbtoc = metres below top of collar (of the groundwater monitoring well)

¹¹ Condition C24, Ref [50]

The Site Auditor considered the weight of evidence supported these conclusions. This evidence included:

- Topographic plan of Sydney provided at topographic-map.com, with an extract of the contour plan for the Northcote Compound and surrounding area provided in **Figure 2-9**¹²;
- Logs of boreholes drilled in the area and provided in the Ramboll 2019 DSI;
- ➤ Geological cross-sections provided by the 2017 EIS¹³, with a copy of the cross section closest to the Northcote Compound provided in **Figure 2-10**;
- The ASS risk map provided in the EIS, which is copied in Figure 2-11;
- > Licensed groundwater bores provided by the NSW Water website as shown in Figure 2-12¹⁴;
- Interviews with employees at some of the properties that made up the Northcote Compound; and
- Information provided in the Development Consent.

The Site Auditor assessed the accuracy of the site condition assessment provided in the ESAs by:

- > Comparing the multiple lines of evidence provided by the source data;
- Comparing the supplied data with publicly available data provided by a topographical plan of the local area, the 1:100,000 geological map of Sydney¹⁵, the Australian Soil Resource Information System (ASRIS), the WaterNSW website for groundwater bore information¹⁶;
- Checking that the conclusions were consistent with the site history data (Section 2.2);
- Inspecting the Northcote Compound throughout the WestConnex Stage 3A project, with a photographic record provided in **Appendix D**; and
- There was a low risk of surrounding areas posing a pollution hazard to the Site because:
 - EPA databases showed there were no regulated or reported sites within 200 m of the Northcote Compound;
 - The closest petrol station was located to the north of Iron Cove Creek along Parramatta Road; and
 - Current land uses in the local area were commercial / light industrial along Parramatta Road, with low-density residential behind.

The Site Auditor considered the site condition and surrounding area data provided by the ESAs for the Northcote Compound generally met the documentation completeness DQO as specified in the EPA (2020) reporting guidelines. The main data gaps identified were:

- Flood potential;
- > Regional and site drainage patterns;
- Boundary fencing;
- Hazardous building materials;
- > Sewer and underground services; and
- Surrounding areas that may pose a pollution hazard to the site.

SAR 278_Northcote PAGE 34

-

¹² https://en-au.topographic-map.com/maps/janv/Sydney/

¹³ Appendix E, Ref [1]

¹⁴ https://realtimedata.waternsw.com.au/water.stm

https://gmaps.geoscience.nsw.gov.au/100K/Sydney/

https://realtimedata.waternsw.com.au/water.stm

Figure 2-9 Topographical plan of Northcote Compound and surrounding area

(Source: https://en-au.topographic-map.com/maps/janv/Sydney/)





Figure 2-10 Geological Cross Section along Tunnel Alignment Nearest Northcote Compound

(Source: Appn E, Ref [1])







Figure 2-11 ASS Risk Map for Northcote Compound

(Source: Appn E, Ref [1])



Figure 2-12 Licensed groundwater bore locations

(Source: WaterNSW website)



The Site Auditor addressed these data gaps by reviewing available data from public sources. This data indicated:

- Flood potential: The Development Consent¹⁷ advised that there was minimal environmental impact at the Northcote Compound from flooding;
- Regional and site drainage patterns: The topographical data indicated that surface water drainage from the Site was in a northerly direction via the local stormwater system to Iron Cove Creek;
- **Boundary fencing**: The Development Consent¹⁸ required boundary fencing to be constructed and maintained by the Project;
- ➤ Hazardous building materials: It was reasonable to conclude that all structures existing at the Northcote Compound prior to the commencement of the earlier WestConnex M4 East Project were demolished and hazardous building materials removed from the Site, since the work was subject to strict environmental controls and a statutory site audit; and
- > Sewer and underground services: It was reasonable to conclude that underground services existing at the Northcote Compound prior to the commencement of the WestConnex M4 East Project were removed and relocated where required prior to the commencement of construction work. However, there was a risk that underground services that did not need to be removed remained at the Site.

2.4 Preliminary Conceptual Site Model for Contamination

2.4.1 Potential Sources, Contaminants of Concern & APECs

The preliminary CSM provided by the Ramboll 2019 DSI¹⁹ identified main contamination risks at the Northcote Compound and Areas of Potential Environmental Concern (**APECs**) posed by the former activities as those listed in **Table 2-4**.

The Site Auditor considered the weight of evidence provided by the historical and site condition data reviewed in **Sections 2.2** and **2.3** supported the potential sources of contamination and the contaminants of potential concern (**CoPCs**) identified by the Ramboll 2019 DSI together with:

> All Sites:

- Potential for asbestos fragments to have been spilt on the ground and not removed when former structures were demolished in the early stage of the WestConnex M4 East Project; and
- Spraying of pesticides / herbicides to control termites and weeds.
- Site 012: Potential use of imported fill contaminated by metals, TPH/BTEX, OCPs/OPPs, PCBs, PAHs, asbestos.
- ➤ **Site 026**: Potential use of imported fill contaminated by metals, TPH, BTEX, OCPs/OPPs, PCBs, PAHs, asbestos.
- ➤ Site 028: Potential USTs that caused contamination by metals, TPH, BTEX, PAHs.

Site 046:

- The use by Council of coal tar to construct the road at Northcote Street
- Potential use of imported fill contaminated by metals, TPH, BTEX, OCPs/OPPs, PCBs, PAHs, asbestos.

The Site Auditor addressed these data gaps by amending the preliminary CSM to include these additional APECs and CoPCs.

¹⁷ Condition C24, Ref [50]

¹⁸ Condition C25, Ref [50]

¹⁹ Section 4.4, Ref [2]

(Source: Table 4-3, Ref [2])

Table 2-4 Potential Areas and Contaminants of Concern Identified by Ramboll

			` -
Site	Former Use	Potential Activities of Environmental Concern	Chemicals of Potential Concern (CoPC)
006	Garden sculpture shop (former service station)	Potential existing or former infrastructure associated with storage and distribution of fuels and/or oils (related to service station and/or possible vehicle maintenance) Potential use of imported fill on the site Potential off-site contamination source identified on adjacent buffer Site 505	Metals, TPH, BTEX, OCPs/OPPs, PCBs, PAHs, phenols, asbestos, solvents (VOCs)
012	Eurotech Automotive	Inspection of site during Land Condition Assessment identified a washdown bay with an in ground interceptor pit (at the same approximate location as the proposed Northcote Compound Mechanical/Welding workshop)	TRH, BTEX PAH, metals, asbestos, phenols, VOCs
026	Jax Tyres	Metals, TRH, BTEX, PAH, asbestos	
027	Ken Carroll Motors	Use of imported fill on site. Spillage and storage of waste oils, lubricants and various auto fluids in drums and tanks, Parts degreasing, Solvent based paints Potential off-site contamination source from Site 505.	Metals, TRH, BTEX, PAH, Phenols, asbestos SVOCs, VOCs
028	First Choice Liquor	There is potential for contamination from uncontrolled filling and asbestos from house demolition based on a review of historical aerial photographs. In addition, there is the potential for contamination from the use of the site historically as a service station and radio manufacturing.	TRH, BTEX PAH, PCBs, metals, asbestos, phenols, VOCs, SVOCs

Table 2-5 Exposure Pathways Assessment by Ramboll

(Source: Table 5-1, Ref [2])

Media	Potentially	Complete On-si	te ? (Y/N)	Justification
	Site¹ users	Construction workers ²	Ecological	
Soil				
Direct / Dermal contact	Y	Y	Y	Site end users may have contact with soils in residential areas and limited contact in commercial/industrial areas. Construction workers may have direct contact with soils during construction works. Ecological receptors within vegetated areas can contact soils.
Incidental ingestion / Plant uptake	Y	Y	Y	Site end users may incidentally ingest soils in residential areas but are unlikley to incidentally ingest soils under a commercial/industrial site end use. Construction workers may incidentally ingest soils during construction works. Ecological receptors within vegetated areas can incidentally ingest or uptake soils.
Outdoor inhalation of dust, vapours or fibres	Y	Y	Y	Site end users could inhale vapours, dust or fibres from surface soils in uncontrolled conditions. Construction workers could be exposed to dust, vapours and fibres during the construction activities. Ecological receptors within vegetated areas could be exposed to vapour in soils.
Indoor inhalation of vapours	Y	Y	n/a	Site end users could inhale indoor soil vapours depending on final site use (including retained structures). Construction workers could be exposed to soil vapours if temporary tunnel construction related buildings are proposed within the site footprint if slab on grade.
Groundwater				
Direct / Dermal contact	N	Y	Y	Site end users are unlikely to be able to contact groundwater. Construction workers may incidentally contact groundwater generated by construction works of the tunnel decline. Ecological receptors may uptake or incidentally ingest groundwater in landscaped areas if groundwater depth is less than 2.5m.

Table 2-5 (cont'd) Exposure Pathways Assessment by Ramboll

Media	Potentially	Complete On-si	te ? (Y/N)	Justification				
	Site¹ users	Construction workers ²	Ecological					
Incidental ingestion/ Plant Uptake	N	Y	Y	Site end users are unlikely to be able to ingest groundwater. Construction workers may incidentally ingest groundwater generated by construction works of tunnel decline. Ecological receptors may uptake or incidentally ingest groundwater in landscaped areas if groundwater depth is less than 2.5m bgl.				
Potable ingestion	n/a	n/a	n/a	Groundwater is not used for potable water.				
Outdoor inhalation of vapours	Y	Y	Y	Site end users could be exposed to outdoor vapours depending on final site use. Construction workers could be exposed to vapours during construction activities. Ecological receptors within vegetated areas could be exposed to vapour in soils.				
Indoor inhalation of vapours	Y	Y	n/a	Site end users could inhale indoor vapours depending on final site use. Construction workers could be exposed to indoor vapours related to temporary and permanant slab on grade buildings.				
Migration to surface water bodies	n/a	n/a	Y	Contaminated groundwater has the potential to migrate to Iron Cove Creek located approximately 300m north from the northern site compound boundary.				

^{1.} Includes all site occupants of post-construction land use.

^{2.} Includes road construction and future road maintenance workers.

Figure 2-13 Ramboll Risk Ranking of Northcote Compound Sites

(Source: Figure 4, Ref [2])



2.4.2 Exposure Pathways and Potential Receptors

The exposure pathways and potential human / ecological receptors identified by the Ramboll 2019 DSI are summarised in **Table 2-5**.

The Site Auditor considered the weight of evidence supported the exposure pathways and receptors identified by the Ramboll 2019 DSI. The Site Auditor considered the end users of the Northcote Compound needed to include:

- Commercial/industrial workers and trench workers at Sites 006, 012, 026, 027 and 028;
- Road maintenance and trench workers at Site 046; and
- ➤ Low density residential users at Sites 136 141.

2.4.3 Preliminary Risk Assessment

The Ramboll 2019 DSI made a preliminary assessment of potential contamination risks at the 12 sites making up the Northcote Compound, with the results shown in **Figure 2-13**. The Site Auditor considered the weight of evidence supported the sites identified by Ramboll as Moderate and High risk, together with Northcote Street (Site 046) that needed to be classified as having a Moderate risk due to potential coal tar contamination associated with historic road making practices as described in the RMS (2015) "*Technical Direction, Coal tar asphalt handling and disposal*".

In their 2015 Technical Direction, RMS advised that "Between about 1973 and 1977 coal tar was commonly used as a binder instead of bitumen in asphalt mixes, particularly in the Sydney and Newcastle areas. Coal tar continued to be used in roads in very small quantities up until about 1989 in some asphalt mixes and some precoated aggregate for sealing. It has also on occasions been inadvertently used in recycled asphalt mixes. Coal tar asphalts may still exist as a road surface layer but is more commonly found as a discreet subsurface layer overlaid by more modern bitumen asphalt."

2.5 Investigation Criteria

2.5.1 Aesthetic

The second check in the EPA decision process was that 'any aesthetic issues relating to site soils have been adequately addressed'.

NEPM 2013 further clarified that "Care should be taken to ensure adequate site characterisation, particularly when there is a diverse range of foreign material and associated fill and an appreciable risk inferred from site history (or lack thereof) for the presence of hazardous contaminants. For example, some ash fill may contain PAHs and metals, while other ash deposits may contain no contaminants of concern."

No aesthetic criteria were specified for the Northcote Compound by the ESAs. The Site Auditor addressed this data gap by reviewing the available data and identifying aesthetic criteria relevant to the preliminary CSM and a future land use as a road construction worksite. The Site Auditor considered the potential aesthetic issues for the Northcote Compound comprised:

- The presence of stained / discoloured, odorous soil conditions;
- Fill containing a significant amount of anthropogenic material;
- Visible ACM fragments in fill material; and
- ➤ The presence of buried putrescible waste that had the potential to degrade and generate methane and other types of hazardous gas.

Appropriate criteria that were adopted by the Site Auditor to assess these aesthetic issues comprised:

No odorous or stained materials were to remain near the groundsurface (say upper 0.3 m);

- Fill material remaining near the groundsurface (upper 0.3 m) was not to contain demolition rubble or other types of anthropogenic material greater than trace quantities (>5%). This criterion was considered to reflect a common condition placed in Development Consents²⁰, such as 'Contaminated soil, soil for which the contamination status is unknown, waste (including but not limited to concrete/bricks/ demolition material) is prohibited from being buried, capped, contained or similar onsite as part of any proposed Remediation Action Plan (including under public or private roads and land which will be dedicated or acquired for any other public purpose)'; and
- No visible asbestos was to remain near the groundsurface (upper 0.1 m), as specified by NEPM (2013) guidelines.

2.5.2 Soil

The third check in the EPA decision process was that 'soils have been assessed against relevant health-based investigation levels and potential for migration of contamination from soils to groundwater has been considered'.

The sixth check in the EPA decision process was that 'any issues relating to local area background soil concentrations that exceed relevant investigation levels have been adequately addressed in the site assessment report(s).'

The seventh check in the EPA decision process was that 'the impacts of chemical mixtures have been assessed'.

The Site Auditor reviewed contamination risks at the Northcote Compound using the NEPM (2013) guidelines, given that they provided the currently EPA-endorsed investigation levels. Where soil investigation levels (**SILs**) were not provided by these guidelines for potential contaminants of concern, reference was made to the CRC-CARE guidelines, the latest US EPA Regional Soil Levels (**RSLs**) or Canadian guidelines.

SILs were given in the NEPM (2013) guideline for four types of land uses:

- A residential with garden / accessible soil (home-grown produce < 10% of fruit and vegetable intake; no poultry), also includes children's day care centres, preschools and primary schools
- B residential with minimal opportunities for soil access includes dwellings with fully and permanently paved yard space such as high-rise buildings and flats
- C public open space such as parks, playgrounds, playing fields (e.g. ovals), secondary schools and footpaths. It does not include undeveloped public open space (such as urban bushland and reserves) which should be subject to a site-specific assessment where appropriate
- D commercial/industrial such as shops, offices, factories and industrial sites.

The land use considered most appropriate for a road construction worksite was Category D commercial/industrial.

The HILs and EILs provided by the Ramboll 2019 DSI were NEPM (2013) Category D commercial/industrial levels. The adopted soil properties for site soils used to derive the SILs were:

- Soil type: Coarse soil;
- Soil depth = 0 <1m;</p>
- \rightarrow pH = 5.1;
- Cation Exchange Capacity (CEC) = 5 cmol/kg;
- Average total organic carbon (TOC) = 0.085 %; and
- Clay content 1%.

²⁰ The Hills Shire Council (24 June 2019) 'Notice of Determination of a Development Application No: 2312/2018/ZB'

The Site Auditor considered these HILs / EILs were appropriate because:

- The criteria were consistent with the intended land use as a road construction worksite;
- They were derived in accordance with EPA guidance; and
- The soil specific parameters provided conservative criteria.

The Ramboll 2019 DSI did not derive background heavy metal concentrations to be used to define the EIL D criteria for chromium (III), copper, nickel and zinc at the Northcote Compound, as required by the NEPM (2013) guidelines. The Site Auditor addressed this data gap by deriving representative background concentrations based on the laboratory tests on natural soil samples collected and tested by the Ramboll 2019 DSI at Site 006. These concentrations and the resultant EILs are summarised in **Table 2-6**.

Table 2-6 Background Heavy Metal Concentrations in Natural Soils at Site 006 & EIL D

Sample Location	Depth (m)	Soil Type	Cr III	Cu	Ni	Zn
006 TP001	0.50	Clay	4	<5	<2	<5
000_17001	1.20	Clay	<2	<5	<2	<5
006 TD003	0.30	Sand	11	<5	<2	<5
006_TP003	0.60	Sand	4	<5	<2	<5
006_TP004	0.40	Clay	19	<5	<2	<5
000_17004	1.00	Clay	8	<5	<2	<5
006_GW005	0.70	Clay	2	<5	<2	<5
006_GW006	0.50	Clay	26	<5	2	6
	Background (Concentration	30	5	5	10
	Table 2-6 EIL D			150	60	300
	EIL	_ D	330	155	65	310

Units: mg/kg

Two amendments were made to the Ramboll 2019 DSI criteria, these being the use of:

- The HIL D F1 silt criteria of 250 mg/kg because it was slightly less than the F1 sand criteria of 260mg/kg; and
- ➤ The use of the NEPM (2013) EIL D criteria for BaP of 1.4 mg/kg, since it remains specified in the NEPM and the use of an alternate criteria needs more detailed justification than given by Ramboll.

A summary of the SILs used by the Site Auditor for assessing contamination risks at the Northcote Compound is provided in **Table 2-7**.

2.5.3 Surface and Groundwater

The fourth check in the EPA decision process was that 'groundwater (where relevant) has been assessed against relevant health-based investigation levels and, if required, any potential impacts to buildings and structures from the presence of contaminants considered.'

The ninth check in the EPA decision process was that 'any evidence of, or potential for, migration of contaminants from the site has been appropriately addressed, including potential risks to off-site receptors, and reported to the site owner or occupier'.

Table 2-7: Soil Investigation Levels for Northcote Compound

		HILs (mg/kg)		Commercial/					
Substances	Residential A	Recreational C	Commercial/ Industrial D	Industrial D EILs (mg/kg)					
	Metals / Me	talloids (in clay)							
Arsenic (total)	100	300	3,000	160					
Cadmium	20	90	900						
Chromium (III)				330					
Chromium (VI)	100	300	3,600						
Copper	6,000	17,000	240,000	155					
Lead	300	600	1,500	1,800					
Mercury (inorganic)	40	80	730						
Nickel	400	1,200	6,000	65					
Zinc	7,400	30,000	400,000	310					
	Othe	r Organics							
Aldrin + Dieldrin	6	10	45						
Chlordane	50	70	530						
Chlorpyriphos	160	250	2,000						
DDT+DDD+DDE	240	400	3,600	640					
Heptachlor	6	10	50						
PAHs (total)	300	300	4,000						
Benzo(a)pyrene	3	3	40	1.4 (1)					
	(BaP TEQ)	(BaP TEQ)	(BaP TEQ)						
Phenol	100	120	660						
(as pentachlorophenol)									
PCBs (total)	1	1	7						
	oleum Hydrocarbo		•	0.45					
TRH F1	4		250	215					
TRH F2	11		NL 0.500	170					
TRH F3	2,5		3,500	1,700					
TRH F4	6,300 ⁽²⁾	7,400 (2)	10,000	3,300					
Benzene	0.		3	75					
Toluene	16		NL	135					
Ethyl Benzene	5		NL	165					
Xylenes (total)	4		230	95					
Naphthalene	3		NL	370					
E10.15(1)	A	sbestos							
FA & AF (friable asbestos)	2.242/	0.001% w/w	0.050/						
Bonded ACM	0.01% w/w	0.02% w/w	0.05% w/w						
All forms of asbestos	No visib	No visible asbestos for surface soil							

Legend:

Applicable SILs for Northcote Compound

Notes:

- $(1) \ \ As \ given \ in \ NEPM \ erratum \ at \ \underline{http://nepc.gov.au/system/files/pages/622ffd38-f121-4daf-9ef3-ed7d40af68f2/files/asc-nepm-errata-30april2014.pdf}$
- (2) Direct contact criteria given in Table 4, CRC CARE Technical Report No. 10

The Ramboll 2019 DSI derived Groundwater Investigation Levels (**GILs**) to protect the following potential receptors:

- Marine aquatic ecosystems;
- Vapour intrusion for a commercial/industrial land use (Note: the Site Auditor reviews soil vapour criteria in Section 2.5.4); and

Recreational water use.

Drinking water criteria were not adopted since the area was supplied by potable water. The Site Auditor considered the potential receptors used by the Ramboll 2019 DSI for groundwater and surface water were generally appropriate for the end users of the land that made up the Northcote Compound. The Site Auditor also considered there was a future potential for groundwater to be used for irrigation water. The Site Auditor addressed this data gap by included long-term irrigation criteria in the assessment.

The Ramboll 2019 DSI derived GILs based on the:

- NEPM 2013 guidelines;
- National Health and Medical Research Council (**NHMRC**) 2011 Australian Drinking Water Guidelines 6, Version 3.2 Updated February 2016;
- NHMRC 2008 Guidelines for Managing Risks in Recreational Water; and
- ANZECC & ARMCANZ 2000 Australian and New Zealand Guidelines for Fresh and Marine Water Quality.

The Site Auditor considered the NEPM (2013) guidelines²¹ provided appropriate guidance with respect to groundwater contamination risks such as:

- "At the point of use or exposure, GILs may be considered as response levels: the response may include further investigation or management as appropriate. Contaminant levels marginally in excess of the GILs do not imply unacceptability or that a significant human health or ecosystem risk is likely to be present. The decision on whether clean-up is required (and, if so, to what extent) should be based on site-specific assessment. Risk assessment is one aspect of making the decision though other considerations such as practicality, timescale, effectiveness, cost, durability, relevant regulatory policy, and community acceptance are also important"; and
- Recreational water criteria are derived by multiplying the NHMRC (August 2018) Australian Drinking Water Guideline (**ADWG**) criteria by a factor of 10, as recommended by the NEPM (2013) guidelines²².

However, the criteria provided by the NEPM (2013) guidelines together with the other guidelines used by the Ramboll 2019 DSI had been superseded by the:

- Australian New Zealand 2018 water quality guidelines (ANZG) for fresh and marine water, which were published on the web and regularly updated;
- > The ADWG were updated in 2018 and then again in 2021; and
- ➤ US EPA RSLs provide criteria for some analytes not listed in Australian guidance, with these criteria being regularly updated.

The Site Auditor addressed this deficiency by adopting GILs based on the most recent criteria endorsed by the EPA at the time this SAR was prepared. A summary of the criteria used by the Site Auditor for assessing groundwater quality at the Northcote Compound is provided in **Table 2-8**. Note that freshwater criteria provided by the ANZG criteria were used where marine water criteria were not available.

2.5.4 Soil Vapour Criteria

The fifth check in the EPA decision process was that 'hazardous ground gases (where relevant) have been assessed against relevant health-based investigation levels and screening values.

The ninth check in the EPA decision process was that 'any evidence of, or potential for, migration of contaminants from the site has been appropriately addressed, including potential risks to off-site receptors, and reported to the site owner or occupier'.

²¹ Refer Section 3.5 in NEPM (2013) "Schedule B6 Guideline on The Framework for Risk-Based Assessment of Groundwater Contamination"

²² Section 2.8 in Schedule B1, NEPM (2013)

Table 2-8: Groundwater Investigation Levels

	Marine water		Recreational									
Substances	protection levels (1)	Irrigation criteria (6)	water criteria (5)									
Gubstances	(μg/L)	(μg/ L)	(μg/L)									
	Metals		(μg, –)									
Arsenic (V)	13	100	100									
Cadmium	0.7	100	20									
Chromium (III)	27		220,000 (3)									
Chromium (IV)	4.4	100	500									
Copper	1.3	200	20,000									
Lead	4.4	2,000	100									
Mercury (inorganic)	0.1	2	10									
Nickel	70	200	200									
Zinc	15	2,000	na									
	Petroleum Hydro	· ·										
TRH (C6-C9)												
TRH (C10-C36)	600 (2)											
Benzene	700		10									
Toluene	180		8,000									
Ethylbenzene	80		3,000									
Xylenes	75 - 350		6,000									
Aylenes	PAHs		0,000									
		T	(0)									
Naphthalene	70		1.2 (3)									
Anthracene	PQL (0.1)		18,000 ⁽³⁾									
Fluoranthene	1.0		8,000 (3)									
Phenanthrene	0.6		 DOL (0.04)									
Benzo(a)pyrene	0.1		PQL (0.01)									
Aldrin	Organochlorine P PQL (0.01)		PQL (0.01)									
Chlordane	PQL (0.01)		20									
DDT	PQL (0.01)		90									
Dieldrin	0.01		PQL (0.01)									
Heptachlor	PQL (0.01)		PQL (0.01)									
Пертастног	Organophosphate		FQL (0.01)									
Chlorpyrifos	PQL (0.01)		100									
Fenitrothion	PQL (0.01)		70									
Glyphosate	PQL (0.01)		10,000									
Malathion	0.05		700									
Parathion	PQL (0.01)		200									
. 3.3011011	Nutrients											
Ammonia (as NH3)	910		5,000									
Chlorine	na		6,000									
Nitrate	na		50,000									
Total phosphorus (2)	na											
	Other Chemi	cals										
PCBs	0.01-0.3		PQL (0.01)									
Chloroethylene (vinyl chloride)	100		0.19 (3)									
1,1,2-Trichloroethylene	330		4.9 (3)									
1,1,2,2-Tetrachloroethylene	70		110 (3)									

Notes

- (1) Marine water protection levels from ANZG guidelines wherever available, otherwise freshwater criteria were used
- (2) Dutch (2000) Intervention Level

- (3) US EPA (May 2021) RSLs tapwater criteria (with target cancer risk 1x10-6 and hazard quotient of 1) multiplied by
- (4) NHMRC (March 2021) drinking water criteria (health) used wherever possible. Aesthetic criteria not considered since the water use was recreational
- (5) Recreational criteria = ADWC x 10
- (6) ANZECC (2000) LTVs for long-term use (up to 100 years) used for irrigation water criteria where possible

The EPA endorsed the use of the soil vapour criteria provided in Schedule B1 of the NEPM (2013) guidelines. These guidelines provided a range of criteria for the four main land use types, comprising:

- Interim soil vapour HILs for volatile chlorinated organic compounds based on soil vapour measurements (NEPM Table 1A(2) in mg/m³);
- > Soil HSLs for vapour intrusion based on soil concentrations (NEPM Table 1A(3) in mg/kg);
- Groundwater HSLs for vapour intrusion based on groundwater concentrations (NEPM Table 1A(4) in mg/L); and
- Soil vapour HSLs for vapour intrusion based on soil vapour measurements (NEPM Table 1A(5) in mg/m^3).

The NEPM (2013) guidelines also referred to the CRC CARE source documents²³, which provided additional soil vapour criteria for protecting an intrusive maintenance worker in a shallow trench.

The vapour criteria provided by the Ramboll 2019 DSI were NEPM (2013) Category D commercial/industrial levels for petroleum hydrocarbons for sand and a groundwater depth of 2 to <4m. The Site Auditor considered these parameters were appropriate because:

- There was a low risk of petroleum hydrocarbon soil vapours at the R2 low density residential zoned land, with the main risk being at the B6 Enterprise corridor zoned land along Parramatta Road and Wattle Street; and
- > Sand and groundwater at the shallowest depth gives the lowest soil vapour criteria.

The Site Auditor identified errors in the groundwater vapour criteria presented in Table 7-6 in the Ramboll 2019 DSI, these being:

- The unit of measure should have been mg/L not mg/kg;
- Benzene = 5 mg/L not "Not Limiting" (NL); and
- \gt F1 = 6 mg/L not NL.

The Site Auditor addressed these errors by summarising the correct soil vapour criteria in Table 2-9, together with summaries of vapour criteria for direct measurement, soil and intrusive maintenance workers in a shallow trench.

PAGE 50 SAR 278 Northcote

²³ Friebel E and Nadebaum P (September 2011) "Technical report No. 10, Health screening levels for petroleum hydrocarbons in soil and groundwater, Part 1: Technical development document". CRC CARE

Table 2-9: Soil Vapour Criteria from NEPM & CRC CARE Guidelines

Contaminant	Commercial/ Industrial D	Intrusive Maintenance Worker (Shallow Trench)								
	Soil vapour (m	g/m³)								
Toluene	4,800	NL								
Ethylbenzene	1,300	NL								
Xylenes	840	NL								
Benzene	4	3,900								
Naphthalene	3	NL								
F1	680	NL								
F2	500	NL								
Soil (mg/kg)										
Toluene	NL	NL								
Ethylbenzene	NL	NL								
Xylenes	230	NL								
Benzene	3	77								
Naphthalene	NL	NL								
F1	250	NL								
F2	NL	NL								
	Groundwater (r	mg/L)								
Toluene	NL	NL								
Ethylbenzene	NL	NL								
Xylenes	NL	NL								
Benzene	5	NL								
Naphthalene	NL	NL								
F1	6	NL								
F2	NL	NL								

Legend: NL = No limit

2.6 Review of Investigation Data Quality

2.6.1 Overview

The Ramboll 2019 DSI advised that an intrusive site investigation was undertaken in May 2016 at the five properties zoned B6 Enterprise corridor, namely, Sites 006, 012, 026 – 028. The scope of field and laboratory work undertaken by the DSI is summarised in **Table 2-10**.

No investigations were undertaken for the five properties zoned R2 low density residential (Sites 136 – 141) and Northcote Street (Site 046). The Site Auditor has assessed the significance of this data gap in **Section 2.9.1**.

Site Audit Report 278_Northcote
WestConnex Stage 3A Northcote Compound
Area C3a

IAN SWANE & ASSOCIATES

(Source: Table 6-1, Ref

Table 2-10 Scope of Work for Ramboll 2016 Site Investigation [2])

Site	Fieldwork dates	Fieldwork completed	Investigations are in accordance with SAQP
006	4/5/2016 to 24/5/2016	6 Test pits 3 Boreholes converted into Groundwater wells	Yes.
012	10/5/2016 to 24/5/2016	1 Borehole converted into a Groundwater well	Yes.
026	4/5/2016 to 24/5/2016	1 Test pit 1 Borehole converted into a Groundwater well	Yes. A test pit was substituted for one groundwater well, as the installation of one well was considered to determine the groundwater conditions at the site and assess any up-gradient impact from Site 505. In addition, observation of the underlying geology and any CoPCs was able to be determined more accurately using a test pit.
027	4/5/2016 to 24/5/2016	2 Test pits 1 Borehole converted into a Groundwater well	Yes. Two test pits were substituted for two groundwater wells, as it was considered one groundwater well would be used to determine the groundwater conditions at the site and assess any up-gradient impact from Site 505. In addition, observation of the underlying geology and
			any CoPCs was able to be determined more accurately using a test pit.
028	5/5/2016	3 Test pits	Yes. The three soil bores were replaced with three test pits as no groundwater wells were to be installed onsite and the source of contamination was likely associated with the fill material onsite. Observation of the underlying geology and any CoPCs was able to be determined more accurately using a test pit.

2.6.2 Documentation Completeness DQO

Documentation provided in the Ramboll 2019 DSI regarding fieldwork and laboratory testing for the five B6 Enterprise corridor zoned sites was provided in Appendices B to F, I and J of their report. The documentation comprised:

- DQOs and DQIs;
- ➤ Site inspection conducted on 10 11/11/15 and photos taken;
- Soil and groundwater sample location plans;
- Description of field screening protocols for soil samples;
- Description of field screening protocols for groundwater samples;
- Soil investigation and sampling techniques; decontamination procedures; sample preservation methods; field QA/QC; sample management, use of a NATA-registered chemical laboratory/ies;
- Groundwater investigation and sampling techniques; decontamination procedures; sample preservation methods; field QA/QC; sample management, use of a NATA-registered chemical laboratory/ies;

- Borehole and well construction logs;
- LFG, PID and water quality calibration sheets;
- Groundwater testing field sheets;
- A copy of the chain-of-custody (COC) forms acknowledging receipt of date and time, and identity of samples included in shipments;
- Analytical test methods used by the NATA-registered laboratory; laboratory accreditation for analytical methods used; laboratory test certificates;
- ➤ QA/QC assessment of the field and laboratory data; description of the surrogates and spikes used; record of holding times and a comparison with method specifications (Section 7);
- > Summary of all soil chemical test results in a table that showed sample numbers, sample depth, soil assessment criteria;
- Summary of all groundwater test results; and
- DQO assessment.

Checkprints of the borelogs and figures provided in the Ramboll 2019 DSI were prepared by the Site Auditor to check the accuracy of the summarised data and no errors / omissions were identified.

The Site Auditor considered that the documentation provided by the Ramboll 2019 DSI met or was close to meeting the documentation completeness DQO for the 5 of 12 sites that made up the Northcote Compound and were zoned B6 Enterprise Corridor.

2.6.3 Data Completeness and Representativeness - Soils

The Ramboll 2019 DSI collected and chemically tested soil samples from 5 of the 12 sites that made up the Northcote Compound. These five sites corresponded to the properties zoned B6 Enterprise Corridor and were located along Parramatta Road and Wattle Street. The locations where soil samples were collected are shown in **Figures 2-14** to **2-18**.

Figure 2-14 Sample Locations at Site 006




Figure 2-15 Sample Locations at Site 012 (Source: Figure C-1, Ref [2]) Table 6-2 Soil Exceedances

Sample Location and Depth Con Concentration (mg/kg) 012_GW001_0.5 NEPM 2013 EIL D 420 mg/kg 300 mg/kg 012_GW001 Site 012 Site 028 Site Location Within Project Alignment Ramboll Environ Groundwater Well Ramboll Environ Test Pit Site Contamination Risk - Moderate

Figure 2-16 Sample Locations at Site 026

(Source: Figure D-1, Ref [2])




Figure 2-17 Sample Locations at Site 027

(Source: Figure E-1, Ref [2])



Figure 2-18 Sample Locations at Site 028

(Source: Figure F-1, Ref [2])



The Site Auditor summarised the laboratory test results conducted on soil samples according to the AECs included in the preliminary CSM reviewed in **Section 2.4**. These AECs comprised:

- Surface soils across all 12 sites: Potential for asbestos fragments to have been spilt by the demolition of buildings conducted by the WestConnex M4 East Project and the historic spraying of pesticides / herbicides. With the Northcote Compound having an area of 1.2165 ha, the EPA (Sept. 1995) 'Contaminated Sites Sampling Guidelines' recommended that contamination be characterised using a minimum of 23 sampling locations.
- Fill layer at the 5 sites zoned B6 Enterprise corridor: The EPA (Sept. 1995) 'Contaminated Sites Sampling Guidelines' recommended that contamination at each of these sites be characterised using the following number of sampling locations:
 - Site 006: 0.13 ha = 7 locations
 - Site 012: 0.059 ha = 6 locations
 - Site 026: 0.14 ha = 7 locations
 - Site 027: 0.12 ha = 9 locations
 - Site 028: 0.20 ha = 7 locations
- > Subbase and fill layer at Northcote Street: The EPA (Sept. 1995) 'Contaminated Sites Sampling Guidelines' recommended that contamination across a 0.145 ha area be characterised using a minimum of 7 sampling locations.
- ➤ Natural soils: Natural soils underlying the fill layer could be validated at a lower frequency than that given by the EPA (Sept. 1995) 'Contaminated Sites Sampling Guidelines' provided there was a low risk of migration of contamination from the overlying fill layer, no buried structures were present (e.g. USTs, buried pipes) that could be potential contaminant sources, and groundwater was not contaminated at levels that could impact soils.
- ➤ **USTs at Site 006 and possibly 028**: The EPA (April 2014) "*Technical Note Investigation of Service Station Sites*" recommended a minimum two samples per tank with samples taken from each tank wall and floor. Samples to be taken at or below the base of the tanks.
- ➤ **Dispenser at Sites 006 and possibly 028**: The EPA (April 2014) "*Technical Note Investigation of Service Station Sites*" recommended one sample per dispenser backfill and one per natural soil (if needed)
- ➤ Fuel feed lines to dispensers at Sites 006 and possibly 028: The EPA (April 2014) "Technical Note Investigation of Service Station Sites" recommended one sample every 5 m of line. The Ramboll 2019 DSI shows the fuel line at Site 006 was 30 m.
- Remote fill points at Site 006 and possibly 028: The EPA (April 2014) "Technical Note Investigation of Service Station Sites" recommended one sample per fill point.
- ➤ Below-ground waste oil/wastewater tank at Site 012: The EPA (April 2014) "Technical Note Investigation of Service Station Sites" recommended two samples per tank.
- Mechanical workshops at Sites 006, 012, 026 028: The EPA (April 2014) "Technical Note Investigation of Service Station Sites" recommended judgemental sampling in accordance with EPA (Sept. 1995) 'Contaminated Sites Sampling Guidelines'

Site 006

A summary of the laboratory tests conducted on fill and natural soil samples from Site 006 is provided in **Table 2-11**.

Table 2-11: Summary of Lab Tests on Soil Samples from Site 006 - Ramboll 2019 DSI

	-			_							
Location	Sample Depth (m)	Heavy metals ⁽¹⁾	TRH	ВТЕХ	PAHs	Phenois	OCPs	OPPs	PCBs	Asbestos	VOCs/VHCs
Site 006 - Fill											
006_TP001	0.20	✓	✓	✓	✓		✓	✓	✓	✓	
006_TP002	0.10, 0.70,	√	✓	✓	✓		√	√	✓	√	
006 TP003	1.20 0.10	✓	✓	✓	✓				√	✓	
006_TP003	0.10	✓	→	✓	✓		√	√	✓	✓	
006_TP005	0.20	, , , , , , , , , , , , , , , , , , ,	•		, , , , , , , , , , , , , , , , , , ,		•	,		, , , , , , , , , , , , , , , , , , ,	
006 TP006											
006_GW004/	0.20, 0.50,	✓	✓	✓	✓	✓			✓	✓	✓
006_QC004 006_GW005/	2.50	•				<u> </u>					•
006_GW003/	0.20, 0.60	✓	✓	✓	✓				✓	✓	✓
006_GW006	0.20	✓	✓	✓	✓				✓	✓	✓
ТОТА	LS	7	7	7	7	1	3	3	7	7	3
			5	Site 006	- Natura	al soil					
006_TP001	0.50, 1.20	✓	✓	✓	✓				✓		
006_TP003	0.30, 0.60	✓	✓	✓	✓				✓		
006_TP004	0.40, 1.00	✓	✓	✓	✓				✓		
006_GW005	0.70, 4.00	✓	✓	✓	√		✓	√	√		√
006_GW006	0.50	✓	✓	✓	✓		✓	✓	✓	✓	✓
ТОТА	LS	5	5	5	5		2	2	5	1	2
				ckpiled		n UST e	xcavati	ons			
006_GS001		√	√	✓	√					√	
006_GS002		√	√	√	✓					✓	
006_GS003		√	√	√	✓	√	√	✓	√	√	
006_GS004		√	√	✓	✓	✓	V	V	✓	✓	
006_GS005 006_GS006		V ✓	✓	✓	▼	✓	✓	√	✓	✓	
006_GS007		✓	✓	✓	✓	- •	<u> </u>	•	, ,	√	
006_GS008		√	✓	1	✓	√	✓	✓	√	√	✓
006_GS009		✓	✓	✓	✓					✓	
006_GS010		✓	✓	✓	✓	✓	✓	✓	✓	✓	
006_GS011/ 006_QC022		✓	✓	✓	✓					✓	
TOTA	LS	11	11	11	11	5	5	5	5	11	1
				Site 0	06 – US	T 1					
006_TP006											
TOTA	LS	0	0	0	0						
	ı			Site 0	06 – US	Т 2			T		
TOTA	LS	0	0	0	0						

Location	Sample Depth (m)	Heavy metals ⁽¹⁾	TRH	втех	PAHS	Phenois	OCPs	OPPs	PCBs	Asbestos	VOCs/VHCs
				Site 000	6 – Fuel	line					
006_TP002	0.10, 0.70, 1.20	✓	✓	✓	✓		✓	✓	✓	✓	
TOTA	LS	1	1	1	1		1	1	1	1	
	Site 006 - Dispenser										
			•		•	•					
TOTA	LS	0	0	0	0						

Legend:

Sampling frequency less than EPA guidance

The Site Auditor considered the available laboratory test data for Site 006 met or was close to meeting the minimum soil sampling requirements for:

- Fill layer: Fill was investigated and tested at 7 sample locations for the main contaminants of concern (metals, TRH, BTEX, PAHs, PCBs, asbestos), with the locations spread across the area;
- Natural soil: Natural soil was investigated and tested at 5 sample locations for the main contaminants of concern (metals, TRH, BTEX, PAHs), with the locations spread across the area; and
- ➤ <u>Stockpiled soil</u>: 11 samples of 275 m³ of stockpiled soil²⁴ was tested, which corresponded to a sampling frequency of 1 per 25 m³ that met EPA guidance as given by the NEPM (2013) guidelines.

The Site Auditor considered the available laboratory test data for Site 006 did not meet the minimum soil sampling requirements for:

- Fill layer: OCPs / OPPs were tested at only 3 locations, which was well below the 7 locations recommended by EPA guidance;
- <u>UST1 and UST2</u>: No samples were collected close to the USTs and tested for the contaminants of concern; and
- Dispenser and fuel line: No samples were collected from the soils along the dispenser or fuel line.

The Site Auditor assessed the significance of the deficiencies in soil sample testing when reviewing soil contamination risks in **Section 2.9.2**.

Site 012

A summary of the laboratory tests conducted on fill and natural soil samples from Site 012 is provided in **Table 2-12**.

²⁴ Section B-6.3, Ref [2]

Table 2-12: Summary of Lab Tests on Soil Samples from Site 012 - Ramboll 2019 DSI

Location	Sample Depth (m)	Heavy metals ⁽¹⁾	TRH	втех	PAHs	Phenois	OCPs	OPPs	PCBs	Asbestos	VOCs/ VHCs
	Site 012 - Fill										
012_GW001	0.2	✓	✓	✓	✓	✓				✓	✓
TOTAL	.S	1	1	1	1	1	0	0	0	1	1
			,	Site 012	- Natur	al soil					
012_GW001	0.5	✓	✓	✓	✓	✓				✓	✓
TOTAL	_S	1	1	1	1	1				1	1
	Site 012 – Interceptor pit / washdown bay										
012_GW001	0.2	✓	✓	✓	✓	✓				✓	✓
TOTAL	_S	1	1	1	1	1				1	1

Legend:

Sampling frequency less than EPA guidance

The Site Auditor considered the available laboratory test data for Site 012 met or was close to meeting the minimum soil sampling requirements for:

<u>Natural soil</u>: Natural soil was investigated and tested at 1 sample location for the main contaminants of concern (metals, TRH, BTEX, PAHs, phenols, asbestos, VOCs/VHCs), with the location targeting the interceptor pit / washdown bay.

The Site Auditor considered the available laboratory test data for Site 012 did not meet the minimum soil sampling requirements for:

- Fill layer: Fill was investigated and tested at only 1 sample location for the main contaminants of concern (metals, TRH, BTEX, PAHs, PCBs, asbestos, VOCs/VHCs), which was well below the 6 locations recommended by EPA guidance; and
- ➤ Interceptor pit / washdown bay: Near-surface soil was investigated and tested at only 1 sample location for the main contaminants of concern (metals, TRH, BTEX, PAHs, asbestos, VOCs/VHCs), which was well below the 2 locations recommended by EPA guidance.

The Site Auditor assessed the significance of the deficiencies in soil sample testing when reviewing soil contamination risks in **Section 2.9.3**.

Site 026

A summary of the laboratory tests conducted on fill and natural soil samples from Site 026 is provided in **Table 2-13**.

Table 2-13: Summary of Lab Tests on Soil Samples from Site 026 - Ramboll 2019 DSI

Location	Sample Depth (m)	Heavy metals ⁽¹⁾	TRH	втех	PAHS	Phenois	OCPs	OPPs	PCBs	Asbestos	VOCs/ VHCs
	Site 026 - Fill										
026_TP001/ 026_QC001	0.10, 0.50	✓	✓	✓	✓					✓	
026_GW001	0.20, 0.50	✓	✓	✓	✓					✓	
TOTAL	.s	2	2	2	2	0	0	0	0	2	0
	Site 026 - Natural soil										
026_TP001	1.00	✓	✓	✓	✓						
TOTAL	_S	1	1	1	1	0	0	0	0	0	0

Legend:

Sampling frequency less than EPA guidance

The Site Auditor considered the available laboratory test data for Site 026 met or was close to meeting the minimum soil sampling requirements for:

Natural soil: Natural soil was investigated and tested at 1 sample location for the main contaminants of concern (metals, TRH, BTEX, PAHs).

The Site Auditor considered the available laboratory test data for Site 026 did not meet the minimum soil sampling requirements for:

Fill layer: Fill was investigated and tested at only 2 sample locations for the main contaminants of concern (metals, TRH, BTEX, PAHs, asbestos), which was well below the 7 locations recommended by EPA guidance. No fill samples were tested for OCPs, OPPs and PCBs.

The Site Auditor assessed the significance of the deficiencies in soil sample testing when reviewing soil contamination risks in **Section 2.9.3**.

Site 027

A summary of the laboratory tests conducted on fill and natural soil samples from Site 027 is provided in **Table 2-14**.

Table 2-14: Summary of Lab Tests on Soil Samples from Site 027 - Ramboll 2019 DSI

Location	Sample Depth (m)	Heavy metals ⁽¹⁾	TRH	втех	PAHS	Phenois	OCPs	OPPs	PCBs	Asbestos	VOCs/ VHCs
Site 027 - Fill											
027_TP001	0.20, 0.50	✓	✓	✓	✓	✓	✓	✓	✓	✓	
027_TP002	0.15, 0.25	✓	✓	✓	✓					✓	
TOTALS		2	2	2	2	1	1	1	1	2	0
Site 027 - Natural soil											
027_GW003/ 027_QC001/ 027_QC002	0.20, 0.50, 1.00	✓	✓	✓	✓	✓				✓	✓
027_TP001	0.80	✓	✓	✓	✓						
027_TP002/	1.30	✓	\	✓	✓						
TOTALS		3	3	3	3	1	0	0	0	1	1

Legend:

Sampling frequency less than EPA guidance

The Site Auditor considered the available laboratory test data for Site 027 met or was close to meeting the minimum soil sampling requirements for:

Natural soil: Natural soil was investigated and tested at 3 sample locations for the main contaminants of concern (metals, TRH, BTEX, PAHs).

The Site Auditor considered the available laboratory test data for Site 027 did not meet the minimum soil sampling requirements for:

Fill layer: Fill was investigated and tested at only 2 sample locations for the main contaminants of concern (metals, TRH, BTEX, PAHs, asbestos), which was well below the 9 locations recommended by EPA guidance. Only one fill sample was tested for OCPs, OPPs and PCBs.

The Site Auditor assessed the significance of the deficiencies in soil sample testing when reviewing soil contamination risks in **Section 2.9.3**.

Site 028

A summary of the laboratory tests conducted on fill and natural soil samples from Site 028 is provided in **Table 2-15**.

The Site Auditor considered the available laboratory test data for Site 028 met or was close to meeting the minimum soil sampling requirements for:

Natural soil: Natural soil was investigated and tested at 3 sampling locations for the main contaminants of concern (metals, TRH, BTEX, PAHs), with the locations spread across the area.

Table 2-15: Summary of Lab Tests on Soil Samples from Site 028 - Ramboll 2019 DSI

Location	Sample Depth (m)	Heavy metals ⁽¹⁾	TRH	втех	PAHs	Phenois	OCPs	OPPs	PCBs	Asbestos	VOCs/VHCs
	Site 028 - Fill										
028_TP001/ 028_QC001 028_TP002	0.10, 0.50	✓ ✓	√	✓ ✓	✓ ✓	✓ ✓	√	✓ ✓	✓	✓ ✓	
028_TP003	0.40	✓	✓	✓	✓	✓	✓	✓		✓	
ТОТА	LS	3	3	3	3	3	3	3	1	3	0
Site 028 - Natural soil											
028_TP001	0.70, 0.90	✓	✓	✓	✓						
028_TP002	0.50, 1.00	✓	✓	✓	✓						
028_TP003	0.60	✓	✓	✓	✓						
TOTALS		3	3	3	3	0	0	0	0	0	0
Site 028 – Possible UST											
TOTA	TOTALS		0	0	0						
Site 028 – Possible Fuel line											
			-								
TOTALS		0	0	0	0						
Site 028 - Dispenser											
ТОТА	0	0	0	0							

Legend:

Sampling frequency less than EPA guidance

The Site Auditor considered the available laboratory test data for Site 028 did not meet the minimum soil sampling requirements for:

- Fill layer: Fill was investigated and tested at 3 sample locations for the main contaminants of concern (metals, TRH, BTEX, PAHs), which was well below the 7 locations recommended by EPA guidance; and
- <u>UPSS Infrastructure</u>: No investigation for potential USTs and other UPSS infrastructure was undertaken.

The Site Auditor assessed the significance of the deficiencies in soil sample testing when reviewing soil contamination risks in **Section 2.9.3**.

Site 046 (Northcote Street)

No soil samples were collected from the subbase, fill and natural soil underlying the asphalt pavement within Northcote Street. The Site Auditor considered there was a risk of contamination from Council's possible use of coal tar to construct the road, as well as contamination associated with imported fill.

The EPA (Sept. 1995) 'Contaminated Sites Sampling Guidelines' recommended that contamination across a 0.145 ha area be characterised using a minimum of 7 sampling locations. The Site Auditor assessed the significance of the deficiencies in soil sample testing when reviewing soil contamination risks in **Section 2.9.4**.

Sites 136 - 141 (Residential land use)

No soil samples were collected from near-surface soil and possible fill within the 5 residentially zoned properties forming the eastern part of the Site. The Site Auditor considered there was a risk of contamination from:

- Asbestos fragments split during demolition work undertaken by the WestConnex M4 East contractor near the beginning of the project; and
- Spraying of pesticides / herbicides to control termites and weeds.

The five residentially zoned properties had a combined area of 0.504 ha. The EPA (Sept. 1995) 'Contaminated Sites Sampling Guidelines' recommended that contamination across a 0.504 ha area be characterised using a minimum of 14 sampling locations. The Site Auditor assessed the significance of the deficiencies in soil sample testing when reviewing soil contamination risks in **Section 2.9.1**.

2.6.4 Data Completeness and Representativeness – Surface Water

No sampling or testing of surface water was undertaken by the Ramboll 2019 DSI since no surface water bodies were presence at or near the Northcote Compound.

2.6.5 Data Completeness and Representativeness – Groundwater


The Ramboll 2019 DSI conducted laboratory tests on samples of groundwater from 6 locations spread across the Northcote Compound, as shown in **Figure 2-19**. A summary of the number of groundwater samples (excluding QA samples) chemically tested by Ramboll is provided in **Table 2-16**.

Table 2-16: Summary of Lab Tests on Groundwater Samples

Site	Well	Sampling Date	Field parameters	Metals	TPH / BTEX	PAHs	Phenois	VOCs / VHCs	PCBs, OCPs, OPPs
006	006_GW004	24/05/16	✓	✓	✓	✓	✓	✓	✓
	006_GW005/ 006_QC100/ 006_QC101	24/05/16	✓	✓	✓	✓	✓	✓	✓
	006_GW006	24/05/16	✓	✓	✓	✓	✓	✓	✓
012	012_GW001	24/05/16	✓	✓	✓	✓	✓	✓	
026	026_GW001	24/05/16	✓	✓	✓	✓	✓	✓	
027	027_GW003	24/05/16	✓	✓	✓	✓	✓	✓	

Figure 2-19 Groundwater Monitoring Wells at Northcote Compound

(Source: Figure 3, Ref [2])



The Site Auditor considered the minimum sampling requirements meeting EPA guidance were:

- Installation of a sufficient number of monitoring bores (minimum of 3) to enable triangulation of water levels across the site;
- All bores should penetrate the regional water table to an extent that will allow representative discrete samples to be collected from both shallow and deep groundwater, due to the potential for DNAPLs to be present;
- A minimum of one well should be located up-gradient of potential contaminant sources in order to provide information on background conditions;
- A minimum of one well should be located at or immediately down-gradient of each likely contamination source in order to provide information on the groundwater quality at the likely contaminant source;
- A minimum of one well should be located down-gradient of the potential source zone and near the property boundary in order to provide information on migration potential of contamination, the quality of groundwater leaving the site and the likely presence of a groundwater plume;
- If contamination is found, then install and test a sufficient number of groundwater wells so that the extent of any groundwater plume can be defined;
- > Testing a minimum of one round of groundwater samples for the potential contaminants of concern. If contamination is found, then test a sufficient number of monitoring rounds to allow trends to be established for the potential contaminants of concern;
- If groundwater contamination is found and there is a risk to off-site receptors, then conduct sufficient testing to allow the risks to these receptors to be determined;
- Collect and test groundwater samples from a range of depths if a potential contaminant of concern has a density greater than water;
- ➤ If a fate-and-transport assessment is required for assessing contamination risks, additional sampling rounds tested over a sufficient period of time need to be undertaken to establish trends and the plume behaviour;
- > MNA parameters need to be tested to support a Monitored Natural Attenuation (MNA) assessment, if required; and
- > Field tests to determine the hydraulic properties of the strata that form the hydrogeological system.

The Site Auditor considered the test data from the Ramboll 2019 DSI met or was close to meeting the minimum sampling requirements for groundwater at Northcote Compound because:

- A sufficient number of wells (6) were installed across the area that allowed the extent of on-site plumes and groundwater levels to be defined, if present;
- > All wells penetrated the regional water table to an extent that allowed representative discrete samples to be collected;
- One well (012_GW001) was located up-gradient of potential contaminant sources and provided information on background conditions;
- Two wells (006_GW005 and 006_GW006) were located around and down-gradient of the UST located at Site 006 and along the down-gradient (northern) boundary;
- ➤ Three wells (006_GW004, 026_GW001, 027_GW003) were spread out in the main body of the Northcote Compound;
- > One sampling round was conducted for the potential contaminants of concern; and
- The monitoring found no evidence of groundwater contamination from on-site sources, which meant there was no need for additional testing.

2.6.6 **Data Completeness and Representativeness – Ground Gas**

The Ramboll 2019 DSI did not collect and test soil vapour samples from sampling locations at the Northcote Compound. The Site Auditor considered the absence of such testing was not a significant matter for the purpose of this site audit since the available data indicated there was a low risk of widespread volatile hydrocarbon contamination at the site. This is because:

- The borelogs reported no widespread odorous or stained soil, the few exceptions being:
 - 006 TP002: Very slight hydrocarbon odour in fill to the base of the test pit at 1.2 mbgl; and
 - 007 TP001: Very slight hydrocarbon odour in fill to 0.5 mbgl.
- PID headspace tests conducted in the field on soil samples measured low to non-detectible concentrations consistent with background conditions (i.e. <10 ppm) at all locations
- The investigation tested fill and natural soil samples across the B6 Enterprise corridor zoned land for TRH (C6-C9), BTEX, naphthalene, VHCs and other VOCs at 15 locations
- All soil samples measured volatile hydrocarbon concentrations at non-detectible concentrations
- The investigation tested groundwater for TRH (C6-C9), BTEX and naphthalene at 6 locations spread across the Northcote Compound
- All groundwater samples were described as having no sheen;
- All groundwater samples were recorded as showing no physical signs of petroleum hydrocarbon contamination; and
- All groundwater samples measured non-detectible volatile hydrocarbon concentrations.

The Ramboll 2019 DSI²⁵ advised that petroleum hydrocarbon vapours were subsequently encountered in backfill sand when the underground petroleum storage system (UPSS) was removed from Site 006. The data indicated:

- **UST 1**: PID readings ranged from 6.5 153.7 ppm. Strong hydrocarbon odours indicated a moderate potential for hydrocarbon contamination within the fill; and
- UST 2: PID readings ranged from 7.8 15.58 ppm. Moderately strong hydrocarbon odours indicated a moderate potential for hydrocarbon contamination within the fill: and
- Fuel Lines: PID readings were 0 ppm with no obvious signs of contamination in the excavation.

The Site Auditor has reviewed this remediation work in Section 2.9.2.

2.6.7 **Data Comparability**

Soils

The documentation provided in the Ramboll 2019 DSI indicated that the data comparability DQO was met or close to being met for the soil samples collected at the Northcote Compound because:

- Photographs were provided that showed the condition of the site at the time of the investigation;
- Boreholes and test pits were used to assess the fill stratigraphy, the extent of fill across the site, \triangleright physical presence of contamination including ACM fragments;
- The stratigraphic conditions at the sample locations were properly described by the test pit logs;
- Appropriate soil sampling method;
- \triangleright Appropriate containers (including preservation) used for soil samples;
- Appropriate sample storage and transportation;
- Appropriate management of chain of custody forms;

²⁵ Section B-6.1.2, Ref [2]

- Samples tested within recommended holding times;
- ➤ The laboratory test methods complied with NEPM (2013) guidelines; and
- > Appropriate PQL's for the analytes tested.

Groundwater

The documentation provided in the Ramboll 2019 DSI indicated that the data comparability DQO was met or close to being met for the groundwater samples collected at the Northcote Compound because:

- Groundwater well construction logs were provided that showed the wells installed by the investigation were likely to have been properly designed and constructed;
- Data provided by the groundwater sampling field sheets indicated that an appropriate groundwater sampling method was used;
- > Appropriate containers (including preservation) used for groundwater samples;
- Appropriate sample storage and transportation;
- Appropriate management of chain of custody forms;
- > Samples tested within recommended holding times;
- > The laboratory test methods complied with NEPM (2013) guidelines; and
- Appropriate PQL's for the analytes tested.

2.6.8 Precision & Accuracy

The Ramboll 2019 DSI²⁶ considered the results of the QA/QC programme provided an acceptable degree of confidence in the analytical program completed and that there were no issues that would preclude using the analytical data.

The documentation provided in the Ramboll 2019 DSI indicated that the precision and accuracy DQIs were met or close to being met for the soil and groundwater samples tested because:

- Use of properly trained and qualified field personnel;
- ➤ Blind field duplicate soil samples were inter- and intra-laboratory tested for the contaminants of concern, which was close to meeting the 10% sampling frequency;
- ➤ Blind field duplicate groundwater samples were inter- and intra-laboratory tested for the contaminants of concern, which met the 10% sampling frequency;
- > Trip blanks and rinsate blanks were tested;
- Laboratory QC criteria were achieved; and
- Field data was consistent with laboratory data.

²⁶ Section 8, Ref [2]

2.7 Aesthetic Issues

The second check in the EPA decision process was that 'any aesthetic issues relating to site soils have been adequately addressed'.

The Ramboll 2019 DSI provided no assessment of aesthetic issues relating to site soils. The Site Auditor addressed this data gap by reviewing the available data.

Data on the aesthetic condition of soils in the commercial/industrial part of the Northcote Compound was provided by the borehole and test pit logs undertaken in May 2016 prior to the commencement of the M4 East Project. This data was documented in the Ramboll 2019 DSI. A plot of this data is provided in **Figure 2-20** (extent of fill) and **Figure 2-21** (aesthetic impacts). No investigation was available for the former residential part along the eastern side of the Northcote Compound.

2.7.1 Extent of Fill

The data indicated that in 2016 prior to the commencement of the earlier M4 East Project, the fill layer in the commercial/industrial part of the Northcote Compound was generally thin and between 0 and 0.70 m. The exceptions were localised deeper fill at the two USTs at Site 006 and at other possible locations where unknown underground tanks / pits may be present. At these localised areas, the fill depth was likely to be between 1.0 and 3.0 m.

For the former residential part along the eastern side of the Northcote Compound, the Site Auditor considered it was reasonable to assume that the fill layer was likely to be thinner than at the

2.7.2 Type and Location of Aesthetic Impacts

The Site Auditor considered the data indicated that in 2016 prior to the commencement of the earlier M4 East Project, for the commercial/industrial part of the Northcote Compound:

- There was no evidence of broadscale aesthetic impacts in soil;
- > Two USTs and associated UPSS infrastructure was present at Site 006 that was removed in 2016;
- ➤ Localised aesthetic impacts were present in backfill sands at the two known USTs at Site 006, which was presumably removed in 2016;
- There was potential for unknown USTs to be present at Site 028 and pits in the commercial/industrial part of the Northcote Compound, as indicated by the historic and site condition data reviewed in **Sections 2.2** and **2.3**:
- There was potential for small quantities of ACM fragments to be present in the fill layer, as shown by the observation made at Sites 026 and 137 and the demolition of old structures that occurred as part of the M4 East early work;
- There was potential for buried asbestos pipes to be present, as shown by the buried pipe found at Site 027; and
- There was potential for localised areas of slag / building demolition waste in the fill layer, as shown by the observation made at Site 028.

Along the part of the Northcote Compound formed by Northcote Street (Site 047), the Site Auditor considered there was potential for odorous coal tar to be present in the subbase layer that formed the road pavement due to potential coal tar contamination associated with historic road making practices, as described in the RMS (2015) "Technical Direction, Coal tar asphalt handling and disposal".

For the former residential part along the eastern side of the Northcote Compound, the Site Auditor considered it was reasonable to assume there was a low risk of aesthetic impacts from contaminated soils prior to the commencement of the M4 East Project in 2016.

The Site Auditor further considered these issues in the review of the site management strategy in Section 2.14.

Figure 2-20 Depth (m) and Extent of Fill Along Western Part of Northcote Compound in 2016





Figure 2-21 Aesthetic Impacts in Soils along Western Part of Northcote Compound in 2016



2.8 Background Contaminant Levels

The sixth check in the EPA decision process was that 'any issues relating to local area background soil concentrations that exceed relevant investigation levels have been adequately addressed in the site assessment report(s).'

2.8.1 Soil

The Ramboll 2019 DSI provided no assessment of background contaminant levels for soils at the Northcote Compound in 2016 prior to the commencement of the M4 East Project. The Site Auditor addressed this deficiency by adopting the conservative assumption that all contamination at the Site was from past activities and needed to be considered in the contamination risk assessment.

The natural soil samples that were laboratory tested in 2016 were used to derive background heavy metal concentrations, with a summary of the data provided in **Table 2-6**. These background levels were used to derive the EILs adopted in **Table 2-7**.

2.8.2 Groundwater

The Ramboll 2019 DSI provided no assessment of background contaminant levels for groundwater at the Northcote Compound in 2016 prior to the commencement of the M4 East Project. The Site Auditor addressed this deficiency by reviewing the available data provided by the site condition data and the laboratory test results provided by the upgradient well sample 012_GW001 at Site 12.

Ramboll²⁷ advised that the geology of the Northcote Compound was dominated by shale and siltstone fractured rock aquifers that had salinity levels greater than 14,000 mg/L and a low potential for movement. The Site Auditor considered the published hydrogeological reported supported this conclusion.

The intrinsic groundwater quality data for the upgradient well 012_GW001 showed that in 2016:

- > pH measurements indicated slightly acidic conditions;
- > Electrical conductivity measurements indicated fresh water conditions;
- > Redox potential measurements indicated mildly oxidising conditions; and
- Dissolved oxygen measurements indicated slightly oxygenated water.

The Site Auditor considered this data indicated there was a low risk that the background quality of groundwater in the local area in 2016 was typical of groundwater in the local geology and was unlikely to have been impacted by hydrocarbon contamination.

The contaminant concentrations measured in the upgradient well 012 GW001 in 2016 were:

- Arsenic, chromium, copper and nickel <1 μg/L;</p>
- Mercury <0.1 μg/L;</p>
- Lead 84 μg/L (Marine GIL 4.4 μg/L);
- Zinc 554 μg/L (Marine GIL 15 μg/L); and
- > TRH, BTEX, PAHs, phenols, VOCs/VHCs non-detect.

The Site Auditor considered the available data indicated that the background quality of groundwater in the Northcote Compound in 2016 prior to the commencement of the M4 East Project was not contaminated by anthropogenic hydrocarbon compounds. Some heavy metals (e.g. lead, zinc and possibly copper) had elevated concentrations consistent with the urban environment of the local area, which needed to be considered when assessing contamination risks posed by past activities at the Northcote Compound prior to the commencement of the M4 East Project in 2016.

²⁷ Section 4.3, Ref [2]

2.9 Soil Contamination

The third check in the EPA decision process was that 'soils have been assessed against relevant health-based investigation levels and potential for migration of contamination from soils to groundwater has been considered'.

The Site Auditor reviewed the soil contamination data obtained in 2016 prior to the commencement of the M4 East Project by dividing the Northcote Compound into four areas based on their historical land use, these being:

- ➤ The six former residential properties on the eastern side of the Compound (Sites 136 141);
- > The former service station at Site 006;
- The other former commercial/industrial properties on the western side of the Compound (Sites 012, 026 028); and
- Northcote Street.

2.9.1 Former Residential Properties

No intrusive investigations were undertaken in 2016 for the six properties zoned R2 low density residential (Sites 136 – 141) that were located along the eastern side of Northcote Compound. The only investigation work undertaken by Ramboll was a site inspection, which found asbestos buried in building demolition rubble at Site 137, as shown in **Figure 2-22**.

The Site Auditor considered historical data supported the conclusion that there was a low risk of gross soil contamination from imported fill, chemical spills and leakage of fuels from USTs. However, there was a risk of contamination in shallow soils exceeding commercial/industrial SILs from:

- Spills of ACM fragments due to the likelihood that structures at the Site had used ACM building materials and likely historic demolition as indicated by the ACM fragment found at Site 137; and
- Abandoned buried services.

The Site Auditor assessed the significance of this contamination risk when reviewing the site management strategy in **Section 2.14**.

Risks posed by flaking lead-based paint due to the age of residential houses and spraying of OCPs to control termites / ants / weeds were considered to be low because the 2016 data provided by the Ramboll 2019 DSI found no evidence of elevated lead or OCPs in shallow soils.

2.9.2 Former Service Station at Site 006

Investigation Work

Investigations conducted by Ramboll in 2016 found evidence of petroleum hydrocarbon and heavy metal contamination at the former service station Site 006, as shown in **Figure 2-22**.


Remediation Work

In their 2016 SRVR, Ramboll²⁸ advised that the remediation of UPSS infrastructure at Site 006 involved:

- Underground utility clearance of the site;
- Disconnection of services at the property and associated UPSS;
- > Demolition and off-site disposal of all property structures and hardstand surfaces;
- ➤ Evacuation and disposal of all remaining liquids from the USTs and other fuel related infrastructure. Liquid waste was transported by Remondis to No Fuss Liquid Waste at Penrith;

28 Section 7.1, Ref [4]

Figure 2-22 Exceedances of SILs at Commercial/Industrial Land at Northcote Compound



Note: No intrusive investigations were undertaken by the Ramboll 2019 DSI at the six former residential properties

- Removal and disposal of two USTs and associated pipework. The USTs were degassed prior to their removal and transported to Fosters & Sons at Mortlake for disposal;
- Excavation and management of excavated tankpit backfill materials from around the UPSS infrastructure prior to their disposal at a licenced facility. Tank backfill sands were returned to the tank pit to await waste classification followed by off-site disposal to a licensed landfill; and
- Excavation and off-site disposal of backfill sands found to contain asbestos from the tankpit of UST2 by a licensed asbestos sub-contractor with appropriate disposal to landfill.

The Site Auditor considered the weight of evidence supported the conclusion that:

- The decommissioning and removal of the UPSS infrastructure was likely to have been undertaken in general compliance with EPA guidance;
- The former UPSS infrastructure at Site 006 was excavated and removed from the site; and
- > Asbestos contaminated UPSS tank pit backfill material was waste classified, excavated and then disposed off-site as asbestos waste.

This is because:

- > Ramboll advised that they observed the removal of the two USTs (i.e. UST 1 and UST 2) on 4/05/16;
- ➤ Liquid waste disposal dockets showed that 20,000 L of waste oil / hydrocarbon mixtures / emulsions in water were removed by the licensed liquid waste contractor Remondis on 10/05/16 and received by Worth Recycling South Windsor on the same day;
- ➤ Two USTs were received from the Northcote Compound by A.N.C. Forster on 14/05/16. The tanks were 15 kL and 2 kL in size;
- > Tip dockets from Dial a Dump Industries indicated at a total of 97.76 T of asbestos contaminated soil was received in four loads on 24 and 26/05/16;
- ➤ UPSS validation sampling was undertaken by Ramboll on 10/05/16;
- A copy of a waste classification report prepared by Ramboll was included in the report; and
- Site photos of the remediation work were provided.

The data indicated that:

- ➤ Contamination at UST 1 was remediated by excavation and off-site disposal of the excavated spoil. The excavation was 3.2 m deep and rectangular in shape measuring 6.5 x 7.1 m (147 m³ in-situ). The excavation pit was validated by two base samples (006_UST1_001 and 006-UST1_002) and four wall samples (one per side) taken at 2 mbgl (006_UST1_003 to 006_UST1_006);
- Contamination at UST 2 was remediated by excavation and off-site disposal of the excavated spoil. The excavation was 1.5 m deep and rectangular in shape measuring 3.7 x 5.4 m (30 m³ in-situ). Contamination was chased out in three stages, with the final set of validation samples comprising one base sample (006_UST2_001) and four wall samples (one per side) taken at 0.8 mbgl (006_UST2_003, 006_UST2_004, 006_UST2_008 and 006_UST2_009); and
- Contamination along the fuel lines was remediated by excavation and off-site disposal of the excavated spoil. The excavation was 0.5 m deep and rectangular in shape measuring 13.4 x 0.9 m (12 m³ insitu). The excavation was validated by two base samples (006 UST2 006, 006 UST2 007).

The total amount of excavated spoil that was meant to have been disposed off-site was 189 m³ or 340 t (1.8t/m³ unit weight). With 97.76 t of contaminated soil classified as asbestos waste, this meant that 242 t of petroleum hydrocarbon contaminated soil was meant to have been disposed off-site.

One data gap identified by the Site Auditor was that no copies of waste disposal dockets were provided for the petroleum hydrocarbon contaminated soil that was excavated and reported by Ramboll as having been disposed offsite. The Site Auditor considered this data gap was not significant for the purpose of this site audit because:

- Figures 2-6 and 2-7 show the UPSS infrastructure at Site 006 was located where the tunnel dive structure was excavated, which would have involved a large excavation down into bedrock;
- ➤ The 11 waste classification samples (006_GS001 to 006_GS011) measured low TRH and BTEX concentrations below the HIL D and EIL D criteria;
- There was a low risk that excavated spoil was backfilled at the Northcote Compound given the extremely large volume of materials that were excavated and removed from the Project site; and
- The Site Auditor for the earlier WestConnex M4 East Project was responsible for reviewing waste disposal and validation testing for the remediation of UPSS infrastructure at Site 006 in 2016.

Validation

Ramboll advised that validation soil sampling involved the collection of grab samples from an excavation bucket during the excavation of the UPSS infrastructure. The sample locations are shown in **Figure 2-23**, with a summary of the field data collected provided in **Table 2-17**. Ramboll²⁹ concluded that following the completion of the UPSS remediation work, Site 006 had been validated as suitable for use in the context of commercial/industrial use land use.

The Site Auditor considered the weight of evidence supported this conclusion because:

- > The validation sampling met or was close to meeting DQOs prepared in accordance with EPA guidance;
- > PID headspace results for the validation samples measured low concentrations below 10 ppm;
- Soil validation results were reported below the SILs;
- Groundwater in the vicinity of the site does not appear to have been impacted by historical operation of the UPSS; and
- ➤ The M4 East project involved the construction of a large tunnel dive structure, which would have resulted in the excavation of a large quantity of soil and rock from the former UST area and other parts of Site 006, as shown by **Figures 2-6** and **2-7**.

2.9.3 Other Former Commercial/Industrial Properties

The Ramboll 2019 DSI³⁰ concluded that in 2016 prior to the commencement of the M4 East Project there was a low risk of soil contamination exceeding commercial/industrial criteria at the other former commercial/industrial properties for most contaminants of concern. The one exception was asbestos.

The 2016 data provided by the Ramboll 2019 DSI showed that low to non-detectible concentrations of the contaminants of concern were measured in practically all fill, natural and excavated soil samples collected from the five sites zoned B6 Enterprise corridor. The main findings were:

- All samples measured concentrations below the HIL D criteria;
- Practically all samples measured concentrations below the EIL D criteria, with the few exceedances not representing hot-spots;
- > All 95% upper confidence limit (**UCL**) mean concentrations were below the HIL D and EIL D criteria.

SAR 278_Northcote PAGE 78

-

²⁹ Section 11, Ref [4]

³⁰ Sections 9 and 10, Ref [2]

Figure 2-23 Validation Sample Locations



Table 2-17 Summary of Validation Field Data

(Source: Appn B, Ref [4])

Area of Investigation	Sample ID	Sampling Rationale	Sample Depth (m bgl)	Sampling Date	QC Sample	PID (ppm)	Soil Description
UST1 Excavation	006_UST1_001	Tankpit NW base validation sample	3.2	24/05/2016	-	0.0	Weathered sandstone, no observed staining/odour/ACM
	006_UST1_002	Tankpit SE base validation sample	3.2	24/05/2016	006_QC024	1.2	Weathered sandstone, slight hydrocarbon odour, no observed staining or ACM
	006_UST1_003	Tankpit NE wall validation sample	2.0	24/05/2016		0.2	Weathered sandstone, very slight hydrocarbon odour, no observed staining or ACM
	006_UST1_004	Tankpit SE wall validation sample	2.0	24/05/2016	-	0.0	Weathered sandstone, no observed contamination (staining, odour or ACM)
	006_UST1_005	Tankpit SW wall validation sample	2.0	24/05/2016	e	0.7	Weathered sandstone, slight hydrocarbon odour, no observed staining or ACM
	006_UST1_006	Tankpit NW wall validation sample	2.0	24/05/2016	006_QC023	0.8	Weathered sandstone, slight hydrocarbon odour, no observed staining or ACM
UST2 Excavation	006_UST2_001	Tankpit base validation sample	1.5	10/05/2016	-	16.4	Weathered sandstone / dayey sand, orange and light grey, moderate hydrocarbon odour, no staining observed
	006_UST2_002	Tankpit E wall validation sample	0.8	10/05/2016	006_QC020 006_QC021	11.1	Weathered sandstone / dayey sand, orange and light grey, moderate hydrocarbon odour, no staining observed
	006_UST2_003	Tankpit S wall validation sample	0.8	10/05/2016	-	1.8	Sand (FILL), cream, loose, uniform, very moist, mild hydrocarbon odour, no staining observed. Unable to excavat beyond sand fill to natural on this wall as extends below concrete
	006_UST2_004	Tankpit W wall validation sample	0.8	10/05/2016	-	0.2	Weathered sandstone / dayey sand, very moist, medium dense, light grey, mild hydrocarbon odour, no staining observed
	006_UST2_005	Tankpit N wall validation sample	0.8	10/05/2016	127	0.1	Weathered sandstone, very mild hydrocarbon odour, no staining observed
	006_UST2_008	Tankpit wall validation sample	0.8	24/05/2016	-	0.0	Wearhered sandstone, mottled light grey and red/brown, no observed staining/odour/ACM
	006_UST2_009	Tankpit wall validation sample	0.8	24/05/2016	(4)	0.0	Wearhered sandstone, mottled light grey and red/brown, no observed staining/odour/ACM
Fuel Lines and Dispensing Pump	006_UST2_006	Fuel line trench and fuel pump base validation sample	0.5	10/05/2016	-	0.0	Weathered sandstone / clayey sand, light grey and orange brown, saturated, soft, no observed staining/odour/ACM
	006_UST2_007	Fuel line trench base validation sample	0.5	10/05/2016	12	0.0	Weathered sandstone / clayey sand, light grey and orange brown, saturated, soft, no observed staining/odour/ACM
	006_CS004	Backfill Waste Classification	n/a	10/05/2016	(5)	103.4	mix of sand and clayey sand (FILL), saturated, loose, medium grained, uniform, some bricks, wires, sandstone cobbles, timber, roots, PVC pipe, concrete pieces. Moderate hydrocarbon odour
	006_GS005	Backfill Waste Classification	n/a	10/05/2016	10	6.5	mix of sand and clayey sand (FILL), saturated, loose, medium grained, uniform, some bricks, wires, sandstone cobbles, timber, roots, PVC pipe, concrete pieces. Moderate hydrocarbon odour
UST1 Excavated Material	006_GS006	Backfill Waste Classification	n/a	10/05/2016	101	153.7	mix of sand and clayey sand (FILL), saturated, loose, medium grained, uniform, some bricks, wires, sandstone obbles, timber, roots, PVC pipe, concrete pieces. Strong hydrocarbon odour
	006_GS007	Backfill Waste Classification	n/a	10/05/2016	151	14.3	mix of sand and clayey sand (FILL), saturated, loose, medium grained, uniform, some bricks, wires, sandstone cobbles, timber, roots, PVC pipe, concrete pieces. Moderate hydrocarbon odour
	006_GS008	Backfill Waste Classification	n/a	10/05/2016	006_QC022	131.4	mix of sand and clayey sand (FILL), saturated, loose, medium grained, uniform, some bricks, wires, sandstone cobbles, timber, roots, PVC pipe, concrete pieces. Strong hydrocarbon odour
UST2 Excavated Material	006_CS001	Backfill Waste Classification	n/a	10/05/2016	10	7.8	Sand (FILL), cream, medium grained, uniform, loose, saturated, moderate hydrocarbon odour.
	006_GS002	Backfill Waste Classification	n/a	10/05/2016	-	9.4	Sand (FILL), cream, medium grained, uniform, loose, saturated, moderate hydrocarbon odour.
	006_GS003	Backfill Waste Classification	n/a	10/05/2016	1-	15.6	Sand (FILL), cream, medium grained, uniform, loose, saturated, strong hydrocarbon odour.
Fuel Line Trench Excavated Material	006_GS009	Backfill Waste Classification	n/a	10/05/2016	-	0.0	Silty Sand (FILL), brown, moist, uniform, includes some brick, concrete, wires, sandstone, no observed staining/odour/ACM
	006_GS010	Backfill Waste Classification	n/a	10/05/2016	-	0.0	Silty Sand (FILL), brown, moist, uniform, includes some brick, concrete, wires, sandstone, no observed staining/odour/ACM
	006_GS011	Backfill Waste Classification	n/a	10/05/2016	-	0.0	Silty Sand (FILL), brown, moist, uniform, includes some brick, concrete, wires, sandstone, no observed staining/odour/ACM

Notes

ppm = parts per million
m bgl = metres below ground level
ACM - asbestos containing materials
N - north, S - south, E - east, W - west
sample has been excavated and disposed of off site

For the contaminants of concern:

- ▶ Metals: Practically all samples measured concentrations consistent with typical background concentrations. A few isolated and minor exceedances of the EIL D criteria were measured, these being:
 - Fill sample 026_TP001_0.10: Nickel 119 mg/kg (EIL D 65 mg/kg);
 - Fill sample 028 TP001 0.50: Zinc 322 mg/kg (EIL D 310 mg/kg);
 - Natural soil sample 012_GW001_0.5: Zinc 420 mg/kg; and
 - Stockpiled soil sample 006_GS009: Zinc 398 mg/kg.
- > TRH: All samples measured non-detectible concentrations.
- BTEX: All samples measured non-detectible concentrations.
- PAHs: Practically all samples measured non-detectible concentrations, with the few detections at low concentrations well below the SILs.
- ➤ Other organics: Phenols, OCPs, OPPs, PCBs, VOCs/VHCs were measured at non-detectible concentrations in all samples.
- ➤ **Asbestos**: Isolated ACM fragments or buried pipes were found at a few locations, these being: Sample 006_GS001 lab test, Site 026 ACM fragment identified during drilling at 0.5 mbgl and in 026_GW001_0.5 lab test, Site 027: Asbestos pipe at 0.5 mbgl; Site 137 asbestos in buried demolition rubble.

The locations of these exceedances are shown in Figure 2-22.

For the other commercial/industrial zoned land at Northcote Compound, the Site Auditor identified data gaps in the 2016 soil investigation documented in the Ramboll 2019 DSI (**Sections 2.3 & 2.4.1**), these being:

> All Sites:

- Potential for asbestos fragments to have been spilt on the ground and not removed when former structures were demolished in the early stage of the WestConnex M4 East Project; and
- Spraying of pesticides / herbicides to control termites and weeds.
- > Site 012: Potential use of imported fill contaminated by metals, TPH/BTEX, OCPs/OPPs, PCBs, PAHs, asbestos.
- ➤ **Site 026**: Potential use of imported fill contaminated by metals, TPH, BTEX, OCPs/OPPs, PCBs, PAHs, asbestos.
- Site 028: Potential UST/s that caused contamination by metals, TPH, BTEX, PAHs.

In **Section 2.6.3**, the Site Auditor also considered that the Ramboll 2019 DSI did not meet the data completeness and data representativeness DQOs for the other commercial/industrial zoned land because:

> At Site 012:

- <u>Fill layer</u>: Fill was investigated and tested at only 1 sample location for the main contaminants of concern (metals, TRH, BTEX, PAHs, PCBs, asbestos, VOCs/VHCs), which was well below the 6 locations recommended by EPA guidance; and
- <u>Interceptor pit / washdown bay</u>: Near-surface soil was investigated and tested at only 1 sample location for the main contaminants of concern (metals, TRH, BTEX, PAHs, asbestos, VOCs/VHCs), which was well below the 2 locations recommended by EPA guidance.

> At Site 026:

- <u>Fill layer</u>: Fill was investigated and tested at only 2 sample locations for the main contaminants of concern (metals, TRH, BTEX, PAHs, asbestos), which was well below the 7 locations recommended by EPA guidance. No fill samples were tested for OCPs, OPPs and PCBs.

> At Site 027:

- <u>Fill layer</u>: Fill was investigated and tested at only 2 sample locations for the main contaminants of concern (metals, TRH, BTEX, PAHs, asbestos), which was well below the 9 locations recommended by EPA guidance. Only one fill sample was tested for OCPs, OPPs and PCBs.

At Site 028:

- <u>Fill layer</u>: Fill was investigated and tested at 3 sample locations for the main contaminants of concern (metals, TRH, BTEX, PAHs), which was well below the 7 locations recommended by EPA guidance; and
- <u>UPSS Infrastructure</u>: No investigation for potential USTs and other UPSS infrastructure was undertaken.

The Site Auditor considered the weight of evidence supported the conclusion that there was a low contamination risk from heavy metal contamination at the other commercial/industrial zoned land at the Northcote Compound because:

- The borehole / test pits investigated by Ramboll found no evidence of odorous, stained or soils with PID exceeding 10 ppm. The only locations where petroleum odours and elevated PID levels were found were in the UST backfill sand and stockpiled soil from the UST excavations made at Site 006; and
- > All 26 fill samples measured low heavy metal concentrations below the HIL A and D criteria, with practically all samples measuring concentrations below the EIL D criteria.

The Site Auditor considered the weight of evidence supported the conclusion that there was a low contamination risk from petroleum hydrocarbon contamination at the other commercial/industrial zoned land at the Northcote Compound because:

- > The borehole / test pits investigated by Ramboll found no evidence of odorous, stained or soils with PID exceeding 10 ppm;
- All 26 fill samples measured low TRH below the SILs, with all samples measured non-detectible BTEX concentrations; and
- > All groundwater samples from 6 wells measured non-detectible TRH and BTEX concentrations.

The Site Auditor considered the weight of evidence supported the conclusion that there was a low contamination risk from non-petroleum contaminants at the other commercial/industrial zoned land at the Northcote Compound because:

- The borehole / test pits investigated by Ramboll found no evidence of odorous, stained or soils with PID exceeding 10 ppm;
- All 12 fill samples measured non-detectible OCPs and OPPs concentrations;
- ➤ All 10 fill samples measured non-detectible phenol concentrations;
- All 14 fill samples measured non-detectible PCB concentrations;
- All 10 fill samples measured non-detectible phenol concentrations;
- All 5 fill samples measured non-detectible VOC/VHC concentrations;
- > All groundwater samples from 6 wells measured non-detectible phenol, VOC/VHC concentrations; and
- > All groundwater samples from 3 wells measured non-detectible OCP, OPP and PCB concentrations.

The Site Auditor considered the data provided by the Ramboll 2019 DSI indicated that the main contamination risks at the other commercial/industrial zoned land at the Northcote Compound were associated with:

- > The possibility of UPSS infrastructure at Site 028;
- > ACM fragments in fill across the Northcote Compound; and
- Abandoned buried services.

The Site Auditor assessed the significance of this contamination risk when reviewing the site management strategy in **Section 2.14**.

2.9.4 Northcote Street at Site 046

No intrusive investigation was undertaken at Northcote Street (Site 046) in 2016 and documented in the Ramboll 2019 DSI.

The Site Auditor considered the historical and site condition data (**Sections 2.2** and **2.3**) supported the conclusion that there was a risk of soil contamination in the Northcote Street road corridor from:

- > The use by Council of coal tar to construct the road pavement and subbase at Northcote Street;
- ➤ Potential use of imported fill contaminated by metals, TPH, BTEX, OCPs/OPPs, PCBs, PAHs and asbestos in the road subbase and subgrade; and
- Abandoned buried services/pits.

The Site Auditor assessed the significance of this contamination risk when reviewing the site management strategy in **Section 2.14**.

2.10 Chemical Mixtures

The seventh check in the EPA decision process was that 'the impacts of chemical mixtures have been assessed'.

The Ramboll 2019 DSI did not provide any assessment of risks posed by chemical mixtures. The main contaminants of concern, in terms of additive risks posed by chemical mixtures, were contaminants considered to be carcinogenic. These contaminants of concern at the Northcote Compound comprised benzene, PCBs, OCPs, PAHs (principally BaP) and chlorinated solvents.

The Site Auditor assessed the available data and considered there was a low risk of additional health risks posed by chemical mixtures because all samples measured low (below HIL D criteria) to non-detectible concentrations for these contaminants.

2.11 Surface Water & Groundwater Contamination

The fourth check in the EPA decision process was that 'groundwater (where relevant) has been assessed against relevant health-based investigation levels and, if required, any potential impacts to buildings and structures from the presence of contaminants considered.'

The ninth check in the EPA decision process was that 'any evidence of, or potential for, migration of contaminants from the site has been appropriately addressed, including potential risks to off-site receptors, and reported to the site owner or occupier'.

2.11.1 Surface Water

Contamination risks to surface water was not an issue for the Northcote Compound since no surface water bodies were located at or near the site.

2.11.2 Groundwater

Groundwater Levels & Flow Direction

The Ramboll 2019 DSI³¹ advised that:

➤ The average depth to groundwater was at 3 – 5 mbgl; and

³¹ Sections 4.3 and 9, Ref [2]

Groundwater flowed in a northerly to north-westerly direction towards Iron Cove Creek some 200 – 300m north of the Site.

The Site Auditor considered the weight of evidence supported this conclusion because of:

- > The topography of the Site;
- > The stratigraphic data provided by the Ramboll 2019 DSI; and
- The data provided by the groundwater monitoring undertaken by Ramboll. A plot of the groundwater equipotential data is provided in **Figure 2-24**.

Intrinsic Groundwater Quality

The Ramboll 2019 DSI measured field water quality parameters during well purging. The results at all wells indicated that:

- > pH measurements indicated slightly acidic conditions;
- > Electrical conductivity measurements indicated fresh to brackish water conditions;
- Redox potential measurements indicated mildly oxidising conditions; and
- Dissolved oxygen measurements indicated slightly oxygenated water.

The Site Auditor considered this data indicated there was a low risk that the groundwater quality at the Northcote Compound had been impacted by contamination above background conditions.

Groundwater Contamination

The Ramboll 2019 DSI³² concluded that:

- Groundwater in the vicinity of Site 006 did not appear to have been impacted by past operation of the service station and associated UPSS infrastructure; and
- Elevated heavy metal concentrations (i.e. copper, lead and zinc) above marine GILs was not considered to represent a risk to the environment as these were considered to be typical of elevated background conditions in the highly disturbed urban setting.

The Site Auditor considered the weight of evidence supported these conclusions because:

- ➤ The groundwater investigations undertaken by the Ramboll 2019 DSI met or was close to meeting the DQOs for the reasons given in **Section 2.6**;
- The intrinsic water quality data indicated there was a low risk that the groundwater quality at the Northcote Compound was impacted by contamination above background conditions;
- ➤ The contaminant concentrations measured in the groundwater monitoring wells were generally low. Hydrocarbon contaminants³³ were measured at non-detectible concentrations, with heavy metal concentrations consistent with background conditions;
- > The absence of any major physical evidence of gross contamination reported by the Ramboll 2019 DSI;
- > The fill layer at the Site was relatively thin in most places, so the volume of fill was not considered to be a potential large source of leachable contamination; and
- > The low permeability of natural soils and bedrock at and downgradient of the Site.

SAR 278_Northcote PAGE 84

_

³² Sections B-7.2, C-7.2, D-7.2 and E-7.2, Ref [2]

³³ TRH, BTEX, PAHs, phenols, VOCs/VHCs

Figure 2-24 Groundwater Equipotential Plot



2.12 Soil Vapours

The fifth check in the EPA decision process was that 'hazardous ground gases (where relevant) have been assessed against relevant health-based investigation levels and screening values.

The ninth check in the EPA decision process was that 'any evidence of, or potential for, migration of contaminants from the site has been appropriately addressed, including potential risks to off-site receptors, and reported to the site owner or occupier'.

In 2016 prior to the commencement of the M4 East Project, Ramboll³⁴ did not consider soil vapours posed a contamination risk for the future road construction worksite use of the Northcote Compound following removal of UPSS infrastructure at Site 006. The Site Auditor considered the weight of evidence supported this conclusion because:

- > The Ramboll 2019 DSI met most DQOs;
- There was no evidence of broadscale aesthetic impacts in soil at the Northcote Compound;
- The borehole / test pits investigated by Ramboll found no evidence of odorous, stained or soils with PID exceeding 10 ppm. The only locations where petroleum odours and elevated PID levels were found were in the UST backfill sand and stockpiled soil from the UST excavations made at Site 006;
- > Two USTs and associated UPSS infrastructure was present at Site 006 that needed to be removed;
- The investigation tested fill and natural soil samples for TRH (C6-C9), BTEX, naphthalene, VHCs and other VOCs at suspect areas across the site;
- Practically all soil samples measured volatile hydrocarbon concentrations at non-detectible concentrations, with the few detections having low concentrations well below HILs D criteria;
- > The investigation tested groundwater for TRH (C6-C9), BTEX, naphthalene and VOCs/VHCs at 6 locations spread across the Site;
- All groundwater samples were described as having no sheen;
- > All groundwater samples were recorded as showing no physical signs of petroleum hydrocarbon contamination; and
- > All groundwater samples from 6 wells measured non-detectible TRH and BTEX concentrations.

2.13 Ecological Risks

The eighth check in the EPA decision process was that 'any potential ecological risks have been assessed'.

The ecological risks posed by soil contamination are reviewed in **Section 2.9**, where they were assessed as low.

The ecological risks posed by groundwater contamination are reviewed in **Section 2.11**, where they were assessed as low.

³⁴ Sections 9 and 10, Ref [2]

2.14 Site Management Strategy

The tenth check in the EPA decision process was that 'the site management strategy (where relevant) is appropriate including post-remediation environmental plans.'

UPSS infrastructure and petroleum contaminated soil were removed from the former Service station land at Site 006 in 2016. The Ramboll 2019 DSI³⁵ considered the main contamination risk that remained at the Northcote Compound was asbestos contamination in fill and across the ground surface.

After the DSI fieldwork was completed by Ramboll in 2016, the Northcote Compound was constructed by the M4 East Project. Construction work for the Northcote Compound included, among other things:

- Demolition of above ground structures from across the Site;
- > The excavation and removal of the UPSS infrastructure at the northern end of the Site at Site 006;
- Deep and extensive excavations for the tunnel dive structure located at the northern end of the Site. This work would have resulted in the excavation of a large quantity of soil and rock from the former UST area and other parts of Site 006;
- The excavation and removal of the road pavement at Northcote Street;
- Cut to fill bulk earthworks to achieve final surface levels (FSLs); and
- Construction of thick reinforced concrete pavements across the Site.

The Northcote Compound was then used to support construction work for the M4 East Project between 2016 and 2019. When the Northcote Compound was handed over to the WestConnex Stage 3A project 2019, operations at the Site appeared to have remained largely unchanged, as shown by a comparison between site layouts in **Figures 2-6** and **2-7**.

The Site Auditor considered the weight of evidence provided in **Sections 2.7** and **2.9** supported the conclusion that unknown contamination risks remained at the Site when the Northcote Compound was constructed in 2016. These risks comprised:

- ➤ At the former residential properties (sites 136 141):
 - Spills of ACM fragments due to the likelihood that structures had used ACM building materials and likely historic demolition as indicated by the ACM fragment found at Site 137;
 - Flaking lead-based paint due to the age of residential houses;
 - Spraying of OCPs to control termites, ants and weeds; and
 - Abandoned buried services/pits.
- ➤ At the former commercial/industrial zoned properties (sites 006, 012, 026 028):
 - The possibility of UPSS infrastructure at Site 028;
 - ACM fragments in fill; and
 - · Abandoned buried services / pits.
- At the former Northcote Street road corridor (site 046):
 - The potential for coal tar to be present in the subbase layer that formed the road pavement;
 - Potential use of imported fill contaminated by metals, TPH, BTEX, OCPs/OPPs, PCBs, PAHs and asbestos in the road subbase and subgrade; and
 - Abandoned buried services / pits.

The Site Auditor understood that the strategy adopted by ASBJV to manage contamination risks at the Northcote Compound during the WestConnex Stage 3A project involved:

³⁵ Sections 9 and 10.1, Ref [2]

SAR 278_Northcote PAGE 87

25

- Maintain the integrity of the concrete ground slab covering the Site and prevent the exposure of underlying soils and infiltration of water into the ground;
- Operate the Site in a manner that would prevent interference or disturbance of contamination, if any, that remained below the concrete ground slab;
- > Operate the Site in a manner that would not generate contamination at the Site; and
- Returning the Site at the end of the Project to a condition suitable for a road construction worksite.

The Site Auditor has reviewed data on ASBJV operations at the Northcote Compound in Section 3.

3. Contamination Management During ASBJV Work

This section of the SAR reviews documentation provided by ASBJV concerning how contamination risks were managed by ASBJV at the Northcote Compound during the WestConnex Stage 3A Project. The reviews comprise:

- > Review of management plans (Section 3.1);
- Compliance with EPA notification requirements (Section 3.2);
- Construction activities at Site (Section 3.3);
- Imported fill (Section 3.4);
- > Final site condition (Section 3.5); and
- Review of LTEMP (Section 3.6).

3.1 Review of Management Plans

As previously discussed in Section 1.2.1, the Site Auditor understood that the site audit needed to review:

- Site environmental management plans that dealt with contamination at the Northcote Compound and to check whether these plans met the aspects of Condition C22 of the Planning Consent and Condition O5.11 of EPL 21149, as relevant to this site audit; and
- ➤ An Unexpected Contaminated Land and Asbestos Finds Procedure that met Condition E185 of the Planning Consent.

3.1.1 Site Environmental Management Plan

The documentation provided by ASBJV included a site environmental management plan (**SEMP**) prepared by LSBJV for the Project dated 10/10/18 (Ref [57]). The purpose of the plan was to describe how the Contractor proposed to manage site establishment works at the various surface area worksites. However, the SEMP was not relevant for the Northcote Compound since:

- > The Compound had already been established by the earlier M4 East Project; and
- ➤ The Northcote Compound was not identified as potentially contaminated land³⁶.

3.1.2 Contaminated Land Management Sub-plan

The documentation provided by ASBJV included a contaminated land management sub-plan (**CLMP**) prepared by LSBJV for the Project dated October 2018 (Ref [58]). The plan formed part of the Soil and Surface Water Management sub-plan (Ref [60]), which in turn formed Appendix B5 of the CEMP.

The purpose of the CLMP was to:

- Describe how the Contractor proposed to manage contaminated land during construction of the Project;
- Establish a set of best practice procedures for the identification and management of contaminated land and materials if encountered during construction work; and
- Address a contractual condition that required a CLMP to be included in the CEMP that needed to comply with the CLM Act, Roads and Maritime publication "Contaminated Land Management Guideline", Roads and Maritime "Environmental Incident Classification and Reporting Procedure", and EPA guidelines on contaminated land management.

The CLMP described:

³⁶ Sections 4.8.2 & 5.2.11, Ref [53]

- **Environmental requirements**: Relevant legislation and guidelines, Minister's Conditions of Approval, Revised environmental management measures;
- **Existing environment**: Previous investigations, further investigations;
- **Environmental aspects and impacts:** Construction activities, impacts;
- Management process: Phase 1 environmental site assessment, phase 2 sampling, analytical and quality plan, phase 2 environmental site assessment, remediation action plan, remediation validation report, long-term site environmental management plan, site audit report and site audit statements;
- > Environmental control measures:
- **Compliance management**: Roles and responsibilities; training, monitoring and inspections, auditing, reporting;
- > Review and improvement: Continuous improvement, CLMP update and amendment;
- > Unexpected contaminated lands and asbestos finds procedure (Ref [59]); and
- Asbestos management plan.

The Site Auditor considered the CLMP provided a comprehensive set of obligations and procedures capable of protecting the Northcote Compound from generating contamination and returning the Site at the end of the Project to a condition suitable for a road construction worksite.

3.1.3 Waste Management Plan

LSBJV prepared a waste management plan (**WMP**) for the project (Ref [61]). The purpose of the plan was to describe how LSBJV proposed to manage waste during construction of the Project. The Plan also explored relevant aspects of resource management and sustainability requirements for the Project. The plan was first issued on 25/07/18, with 8 revisions made up to 22/06/20.

The WMP³⁷ advised that its key objective was to ensure all planning conditions, licence and permit requirements relevant to waste management were described, scheduled and assigned responsibility as outlined in:

- ➤ The EIS prepared for WestConnex M4-M5 Link;
- > The Submissions and Preferred Infrastructure Report prepared for WestConnex M4-M5 Link;
- The Modification report for WestConnex M4-M5 Link Mainline Tunnel (September 2018);
- Conditions of Approval granted to the Project on 17 April 2018 and as modified on 25 February 2019;
- > Roads and Maritime Services (Roads and Maritime) QA Specifications G36 and G40;
- The Project's EPL; and
- > All relevant legislation and other requirements.

The WMP³⁸ advised that waste streams generated during construction of the Project were likely to include construction and demolition waste, vegetation waste, packaging materials and liquid wastes. There was the potential for special, hazardous and otherwise contaminated waste and spoil to be encountered during tunnelling and surface works. However, construction waste management activities were not considered likely to pose a significant risk to the environment or human health, with the implementation of standard mitigation and management measures.

The WMP advised that some 550,000 t of tunnel spoil was to be transported through the Northcote Compound but there was to be no waste generated by demolition or construction work at the Site since that work had been completed under the earlier M4 East Project.

SAR 278_Northcote PAGE 90

-

³⁷ Section 2.2, Ref [61]

³⁸ Section 5.1, Ref [61]

The Site Auditor considered the WMP provided a comprehensive set of obligations and procedures capable of protecting the Northcote Compound from generating contamination and returning the Site at the end of the Project to a condition suitable for a road construction worksite.

3.2 **Compliance with EPA Notification Requirements**

As previously discussed in Section 1.2.1, the Site Auditor understood that the site audit needed to determine whether contamination at the Northcote Compound was present and needed to be notified to ASBJV, TfNSW and the EPA under the CLM Act.

The Site Auditor considered that the available data indicated there was a low risk that contamination at the Site, if present, needed to be notified because:

- The available data indicated that all known contamination exceeding commercial/industrial criteria had been removed:
- There was a low risk of unknown contamination being present at the Site that needed to be notified;
- A concrete capping layer covered the Site.

3.3 Construction Activities at Site

3.3.1 **Unexpected Finds**

ASBJV³⁹ provided an Unexpected Finds register that recorded no unexpected finds during ASBJV activities at the Northcote Compound.

The Site Auditor considered the weight of evidence supported this outcome because:

- An Unexpected Finds Register was kept by the Project;
- ASBJV had an environmental professional manage environmental issues at each worksite;
- > The Site Auditor found the various worksites well managed and organised, as shown by the photos of the Northcote Compound in **Appendix D**; and
- The Site Auditor found no physical evidence of contamination at the Northcote Compound during site inspections.

3.3.2 **Environmental Management and Incidents**

Figures 2-6 and 2-7 show that most operational activities that occurred at the Northcote Compound during the earlier M4 East Project and the WestConnex Stage 3A Project posed a low contamination risk. The few exceptions were:

- Chemical storage and operations at the wastewater treatment plant; and
- Diesel tank and refuelling bay.

The Site Auditor considered that the weight of evidence indicated that environmental conditions at the Northcote Compound were likely to have been well managed and there was a low risk of environmental incidents having occurred that posed a contamination risk to the suitability of the Site for its intended road construction worksite land use. This is because:

- Construction activities at the Site were required to follow detailed environmental management plans that had been approved by independent environmental auditors and regulatory authorities;
- An extensive arrays of management plans and on-site training occurred as evidenced by the documentation provided to the Site Auditor for review and the protocols that the Site Auditor needed to follow when inspecting the Project site:

³⁹ ASBJ 18/11/22 email

- Construction activities at the Site were well managed by site personnel and the Site Auditor found no evidence of poor environmental management practices when inspecting the Site, as shown by photos provided in **Appendix D**;
- > Two annual reports that ASBJV issued to the EPA for the periods October 18-19 and October 19-20 recorded no significant environmental incidents;
- The Site was sealed by thick concrete slabs and most of the Site was covered by an enclosure that would have reduced risks posed by spills, leaks, accidents, etc;
- Construction activities at the Site did not involve the bulk storage of large quantities of fuel or chemicals, with tanks and chemicals used by the wastewater treatment plant contained within bunds; and
- > The Site Auditor received no complaints from regulatory authorities regarding construction activities that occurred at the Site during the period of the site audit.

To further support this conclusion, the Site Auditor considered that data needed to be provided on:

- Any environmental incidents that occurred at the Northcote Compound during the WestConnex Stage 3A project;
- Chemical storage and operations at the wastewater treatment plant; and
- Diesel tank and refuelling bay.

The Site Auditor addressed the need for this additional data by issuing a Section B SAS, which is further discussed in **Section 4**.

3.3.3 Potential for Construction Activities to Have Contaminated the Site

The Site Auditor considered the weight of evidence supported the conclusion that:

- ASBJV did not interfere or disturb contamination during the course of carrying out its work at the Northcote Compound during the WestConnex Stage 3A project;
- > Contamination was not generated by activities undertaken by ASBJV at the Northcote Compound; and
- > Contamination was not generated at the Northcote Compound that caused an increase in contamination migrating from the Project site.

This is because:

- ➤ The USTs and associated infrastructure and contaminated soils at the former service station property at Site 006 were reported to have been removed by the earlier M4 East Project in 2016;
- After the completion of bulk earthworks at the Site in 2016, the M4 East Project constructed a thick reinforced concrete slab across the Site that prevented further contact with the underlying soils and groundwater at the Site;
- Operations conducted at the Site by ASBJV did not involve interference or disturbance to soils or groundwater below the concrete ground slab;
- Environmental conditions at the Northcote Compound were likely to have been well managed and there was a low risk of environmental incidents having occurred that posed a contamination risk to the suitability of the Site for its intended road construction worksite land use for the reasons given in Section 3.3.2; and
- The Site Auditor found no physical evidence of contaminated soils or chemicals remaining at the Site at the end of the project.

3.4 Imported Fill

At the end of tunnelling work, the tunnel dive that occupied the northern part of the Northcote Compound needed to be backfilled with a large amount of soil that was to be geotechnically and environmentally acceptable, as shown in **Figure 3-1** and other plans in **Appendix B**. The specification required the fill to be:

- Inorganic, non-perishable;
- ➤ General filling: graded material from site, maximum particle size 50mm;
- ➤ Selected filling: Granular material, maximum particle size 50 mm, not more than 50% passing 0.075 mm sieve, Plasticity Index not greater than 14% and not less than 2%; CBR (4 day soaked) not less than 15%; and
- Fill subgrades: Use material in the top 150 mm which has a maximum particle size of 75 mm.

The design of the tunnel backfill at the PBR site is shown in Figure 3-2.

To facilitate ASBJV sourcing supplies of suitable material in an environmentally sustainable manner, on 24/12/21 the EPA issued 'The WestConnex imported tunnel backfill material exemption 2021' ('Backfill Exemption') and the 'The WestConnex imported tunnel backfill material order 2021' (Backfill Order') under a Resource Recovery Exemption under Part 9, Clauses 91 and 92 of the POEO (Waste) Regulation 2014. The Backfill Exemption applied to:

- ➤ The Northcote Ancillary Facility (Haberfield) 269 Parramatta Road, Haberfield;
- The PBR site 176 Parramatta Road, Annandale; and
- ➤ The SPI site 2 Albert Street, St Peters.

Some of the features of the Backfill Order were:

- The backfill material was to be naturally occurring rock and soil (including but not limited to materials such as sandstone, shale and clay) that:
 - had been excavated from the ground;
 - did not contain chlorinated hydrocarbons, OCPs, PFASs and PCBs;
 - contained at least 98% (by weight) natural material; and
 - · did not meet the definition of VENM
- The was not include material located in a hotspot; that had been processed; or that contained asbestos, ASS, PASS or sulfidic ores.
- ➤ The Backfill Order commenced on 24 December 2021 and was valid until 24 December 2023 or until revoked by the EPA by notice in writing at an earlier date.
- Prior to sampling the backfill material, the generator must:
 - Engage an environmental practitioner to undertake a desktop assessment of the source site in which the backfill material was generated to determine the likelihood for PCBs, PFASs, OCPS, and chlorinated hydrocarbons to be present; and
 - Where the environmental practitioner determined that there was a likelihood of PCBs, PFASs, OCPS, and chlorinated hydrocarbons being present at the source site, the backfill material must be sampled and tested for that contaminant.
- For backfill material in stockpiles, the number and type of samples and tested needing to be done by the generator were:
 - Composite samples for attributes 1 to 10 and 18 in Column 1 of Table 4;
 - Discrete samples for attributes 11 to 17 in Column 1 of Table 4;
 - The generator must carry out sampling in a way ensuring that the samples taken are representative of the material from the entire stockpile;



Figure 3-2 Design of Northcote Backfill and Stub Walls (sheet 1 of 2)





Figure 3-2 Design of Northcote Backfill and Stub Walls (sheet 2 of 2)

(Source: Ref [64]



TYPICAL TUNNEL PROFILE
REQUIREMENTS PRIOR TO BACKFILLING
NTS

- All parts of the stockpile must be equally accessible for sampling;
- For stockpiles greater than 4,000 t the number of samples described in Table 1 must be repeated.

Table 1

	Sampling of Stockpiled Material	
Column 1	Column 2	Column 3
Quantity (tonnes)	Number of samples	Validation
<500	3	
500 – 1,000	4	
1,000 – 2,000	5	Required
2,000 – 3,000	7	
3,000 – 4,000	10	

- > For sampling backfill material in-situ, the generator must:
 - Undertake sampling by collecting discrete samples. Compositing of samples was not permitted for in situ materials:
 - Undertake characterisation sampling for the range of chemicals and other attributes listed in Column 1 of Table 4 according to the requirements listed in Columns 1, 2 and 3 of Table 2.
 When the ground surface was not comprised of soil (e.g. concrete slab), samples must be taken at the depth at which the soil commenced;
 - Undertake sampling at depth according to Column 1 of Table 3;
 - Collect additional soil samples (and analyse them for the range of chemicals and other attributes listed in Column 1 of Table 4), at any depth exhibiting discolouration, staining, odour or other indicators of contamination inconsistent with soil samples collected at the depth intervals indicated in Table 3;
 - Segregate and exclude hotspots identified in accordance with Table 2, from material excavated for reuse; and
 - Subdivide sites larger than 50,000 m² into smaller areas and sample each area as per Table 2.
- Backfill material must not be supplied to WestConnex if:
 - A sample concentration exceeded the absolute maximum concentration or other value listed in Column 3 of Table 4; or
 - The average concentration exceeded the maximum average concentration or other value listed in Column 2 of Table 4.
- > The generator must keep a written record of the following for a period of six years:
 - the sampling plan required to be prepared;
 - all characterisation sampling results in relation to the WestConnex imported tunnel backfill material supplied;
 - the volume of detected hotspot material and the location;
 - the quantity of the WestConnex imported tunnel backfill material supplied; and
 - the name and address of each person to whom the generator supplied the WestConnex imported tunnel backfill material.

Table 2

	In	Situ Sampling at surface	<u> </u>	
Column 1	Column 2	Column 3	Column 4	Column 5 Validation
Size of in situ area (m²)	Number of systematic sampling points recommended	Distance between two sampling points (m)	Diameter of the hot spot that can be detected with 95% confidence (m)	
500	5	10.0	11.8	
1000	6	12.9	15.2	Required
2000	7	16.9	19.9	
3000	9	18.2	21.5	
4000	11	19.1	22.5	
5000	13	19.6	23.1	
6000	15	20.0	23.6	
7000	17	20.3	23.9	
8000	19	20.5	24.2	
9000	20	21.2	25.0	
10,000	21	21.8	25.7	
15,000	25	25.0	28.9	
20,000	30	25.8	30.5	
25,000	35	26.7	31.5	
30,000	40	27.5	32.4	
35,000	45	27.9	32.9	
40,000	50	28.3	33.4	
45,000	52	29.3	34.6	
50,000	55	30.2	35.6	

Table 2 has been taken from NSW EPA 1995, Contaminated Sites Sampling Design Guidelines, NSW Environment Protection Authority.

Table 3

In Situ Sampling at Depth	
Column 1	Column 2
Sampling Requirements *	Validation
1 soil sample at 1.0 m bgl from each surface sampling point followed by 1 soil sample for every metre thereafter.	
From 1.0 m bgl, sample at the next metre interval until the proposed depth of excavation of the material is reached. If the proposed depth of excavation is between 0.5 to 0.9 m after the last metre interval, sample at the base of the proposed depth of excavation.	Required if the depth of excavation is equal to or greater than 1.0 m bgl

^{*} Refer to Notes for examples

Table 4

Column 1	Column 2	Column 3	
Chemicals and other attributes	Maximum average concentration for characterisation (mg/kg 'dry weight' unless otherwise specified)	Absolute maximum concentration (mg/kg 'dry weight' unless otherwise specified)	
1. Mercury	1.0	1.5	
2. Cadmium	5	8	
3. Lead	300	500	
4. Arsenic	40	60	
5. Chromium (total)	75	150	
6. Copper	150	300	
7. Nickel	80	150	
8. Zinc	350	920	
9. Electrical Conductivity	N/A	N/A	
10. pH ¹	5 to 10	5 to 10	
11. Total Polycyclic Aromatic Hydrocarbons (PAHs)	40	80	
12. Benzo(a)pyrene	3	5	
13. Benzene	N/A	1	
14. Toluene	N/A	65	
15. Ethyl-benzene	N/A	25	
16. Xylene	N/A	15	
17. Total Recoverable Hydrocarbons (TRH) C6- C10 or F1 ^{2, 3}	N/A	50	
18. TRH C ₁₀ – C ₁₆ or F2 ^{2, 4}	100	185	
19. TRH C ₁₇ – C ₃₄ or F3 ²	200	380	
20. TRH C ₃₅ – C ₄₀ or F4 ²	270	380	
21. Asbestos	N/A	No asbestos found ⁵	
22. Foreign materials – Rubber, plastic, bitumen, paper, cloth, paint and engineered wood products and preservative treated or coated wood residues.	0.05%	0.1%	

Notes:

- 1. The ranges given for pH are for the minimum and maximum acceptable pH values in the material.
- The TRH test may include silica gel clean-up. The absolute maximum concentration and the maximum average concentration may include silica gel clean-up. TRH silica gel clean-up may be undertaken if the initial TRH test (without silica gel clean-up) exceeds the absolute maximum concentration or the maximum average concentration.
- To obtain F1, subtract the sum of BTEX concentrations from the F1 fraction. To obtain F2, subtract naphthalene from the F2 fraction.
- See test method.

Proposed landscaping works in the Northcote Street road corridor would also involve importing landscaping soils.

The Site Auditor considered that data on the type of fill used to backfill the tunnel decline and other parts of the Site needed to be provided so the Site Auditor could verify that the backfill was suitable for the intended road construction worksite land use.

The Site Auditor addressed the need for this additional data by issuing a Section B SAS, which is further discussed in **Section 4**.

3.5 Final Site Condition

ASBJV⁴⁰ design drawings show that final site conditions at the Northcote Compound would consist of:

- Demolition and removal of the acoustic shed, buildings, electrical substation, wastewater treatment plant, workshops and tunnel support infrastructure as shown in **Figure 3-3**;
- Landscaping of the former Northcote Street road corridor to include a grass verge, planter boxes and new pavements as shown in **Figure 3-4**; and
- New pavements as shown in Figures 3-1, 3-4 and 3-5.

Copies of final site condition design drawings are provided in **Appendix B**.

During the site inspection conducted on 4/11/22, demobilisation work was in its early stage, with the facilities still to be removed including the acoustic shed and the switchyard, as shown by photos in **Appendix D**.

The Site Auditor addressed the need for this additional construction work to be completed by issuing a Section B SAS, which is further discussed in **Section 4**.

3.6 Review of LTEMP

The Site Auditor considered the approach adopted by the ASBJV environment team for managing contamination at the Northcote Compound met the requirements of their contract, the planning consent and EPL, as described in **Section 1.2.1**, provided residual contamination risks were managed by a **LTEMP**. The contamination risks that remained at the Site (**Sections 2.7 & 2.9**) and required long-term management comprised:

- Unknown ACM fragments in fill;
- Unknown buried services/pits remaining at the Site;
- > The possibility of UPSS infrastructure at Site 028; and
- At the former Northcote Street road corridor (site 046): The potential for coal tar to be present in the subbase layer that formed the road pavement and the use of contaminated fill used when Council first constructed the road.

40 Refs [64] & [65]

Figure 3-3 General Arrangement for Reinstatement of Northcote Compound (Source: Drg No: M4M5 -RBGP-PRW- CIV - CW02-DRG- 1101, Ref [63]) EXISTING DRIVEWAY TO REMAIN AS PART OF THE NEW SITE LAYOUT 2 x 30kl RAINWATER TANKS TO BE REMOVED EXISTING HABERFIELD 2 FLOORS OFFICES TO BE REMOVED HOARDING TO BE RETAINED AND CONDITION TO PROPOSED NEW 6m SECURITY GATE TO WOLSELEYSTREET BE ASSESSED BEFORE HANDOVER BE INSTALLED AT THE BOUNDARY DECLINE PILING STRUCTURE M4E TO BE REMOVED WITH 1m OF FINAL SURFACE LEVEL AND BACKFILLED EXISTING PIT SURFACE LEVEL TO BE MODIFIED TO SUIT THE INVERT OF THE CONNECTING SWALE ELECTRICAL PLANTS TO BE REMOVED AND HARDSTAND TO RETAIN EXISTING PLANT YARD AND SECONDARY STOCKPILE TO BE REMOVED AND EXISTING HARDSTAND TO BE RETAINED PROPOSED STORMWATER NETWORK OFL 13.04X TO CONNECT INTO THE EXISTING PIT EXISTING RETAINING WALL TO BE RETAINED ON PARRAMATTA ROAD WITH MINIMUM ① FL 13.602 EXISTING STORMWATER PIT ON PARRAMATTA ⊕ FL 13:635 ROAD, IL TO BE CONFIRMED WITH ADDITIONAL SURVEY INFORMATION TO DETERMINE CONNECTION POINT REFER TO M4M5-RBGP-PRW-CIV-CW02-DRG-1102 FOR PROPOSED PEDESTRIAN LINK DESIGN EXISTING DRIVEWAY TO REMAIN AS PART OF THE NEW SITE LAYOUT PROPOSED NEW 6m SECURITY GATE TO BE INSTALLED AT THE BOUNDARY EXISTING RETAINING WALL TO BE RETAINED EXISTING WORKSHOPS TO BE REMOVED PROPOSED SO TYPE DISH DRAIN TO BE INSTALLED IN NOISE SHED PILING M4E TO BE CUT AND FLASHED WITH THE TOP OF WALL LEVEL ACCORDANCE WITH RMS STANDARD TO CAPTURE UPSTREAM SURFACE RUNOFF EXISTING GATE TO BE REMOVED O FL 16.04 EXISTING STORMWATER PIT TO RETAIN AND TO BE RE-COMMISSIONED FOR PEDESTRIAN LINKED DRAINAGE EXISTING SUBSTATION AND MECHANICAL EXISTING STORMWATER PIT ELECTRICAL WORKSHOP TO BE REMOVED, TO BE RECOMMISIONED HARDSTAND TO BE RETAINED FOR FUTURE AND MODIFIED TO SUIT THE DEVELOPMENT INVERT OF CONNECTING SWALE EXISTING KIOSK TO BE REMOVED THE FEED LOCATION TO BE RETAININED AND CAPPED AT BOUNDARY FOR FUTURE DEVELOPER PROPOSED 1.8m CHAIN-LINK SECURITY FENCE EXISTING WASHING BAYS TO BE REMOVED

EXISTING DRIVEWAY TO REMAIN

Figure 3-4 Reinstatement Design for Northcote Street

(Source: Drg No: M4M5 -RBGP-PRW- CIV - CW02-DRG- 1102, Ref [63])






Figure 3-5 Pavement Design Details for Reinstatement of Northcote Compound



CONCRETE RIGID PAVEMENT

NOT TO SCALE



FLEXIBLE PAVEMENT HARDSTAND NOT TO SCALE

(Source: Drg No: M4M5 -RBGP-PRW- CIV - CW02-DRG- 1103, Ref [63])

4. Conclusions

The Site Auditor considered the approach adopted by the ASBJV environment team for managing unknown contamination at the Northcote Compound met the requirements of their contract, the planning consent and EPL, as described in **Section 1.2.1**, for the reasons given in **Section 3**.

The Site Auditor considered that the weight of evidence supported the conclusions that:

- > ASBJV did not interfere or disturb contamination during the course of carrying out its work at the Northcote Compound during the WestConnex Stage 3A project;
- > Contamination was not generated by activities undertaken by ASBJV at the Northcote Compound;
- Contamination was not generated at the Northcote Compound that caused an increase in contamination migrating from the Project site;
- The Northcote Compound was returned to a condition suitable for a road construction worksite provided residual contamination risks were managed in accordance with an LTEMP prepared by an experienced environmental consultant that met EPA guidelines and was approved in writing by the Site Auditor and TfNSW; and
- The work generally complied with the requirements of EPL 21149 in relation to the management of site contamination.

The Site Auditor identified data gaps that needed to be addressed by ASBJV concerning:

- Operational information as described in Section 3.3.2, comprising:
 - Any environmental incidents that occurred at the Northcote Compound during the WestConnex Stage 3A project;
 - Chemical storage and operations at the wastewater treatment plant;
 - Operations of the diesel tank and refuelling bay.
- > The type of fill used to backfill the tunnel decline and other parts of the Site as described in Section 3.4
- Demobilisation work and reinstatement of the Northcote Compound to its final condition at hand over was a work-in-progress at the time this SAR was prepared, as described in **Section 3.5**.

The Site Auditor considered the issuing of a Section B SAS would allow these data gaps to be addressed prior to a Section A2 SAS being issued.

The contamination risks that remained at the Site and required long-term management by means of an LTEMP comprised:

- Unknown ACM fragments in fill;
- Unknown buried services/pits remaining at the Site;
- > The possibility of UPSS infrastructure at Site 028; and
- At the former Northcote Street road corridor (site 046): The potential for coal tar to be present in the subbase layer that formed the road pavement and the use of contaminated fill used when Council first constructed the road.

The Site Auditor addressed the need for an LTEMP to be prepared, for data gaps to be addressed, and for minor construction work to be completed at the Northcote Compound by:

- Having ASBJV issue an interim plan outlining the additional work that needed to be undertaken prior to the issuing of a Section A2 SAS; and
- Issuing a Section B SAS.

Copies of the Section B SAS and the ASBJV interim plan are provided in Appendix E.

5. Other Relevant Information

This SAR and the accompanying SAS relates to the WestConnex Stage 3A Northcote Compound (Area C3a). This SAR was prepared in accordance with the CLM Act 1997. Opinions and judgements expressed herein, which are based on our understanding and interpretation of current regulatory standards, should not be construed as legal opinions.

The audit report and statement have been prepared for ASBJV (the 'Client') for the purposes nominated in the audit report. It is acknowledged that the audit report and statement may be used by TfNSW, the Department of Planning and the EPA in reaching their conclusions about the Site. The scope of work performed in connection with the audit review may not be appropriate to satisfy the needs of any other person. Any other person's use of, or reliance on, the audit report and statement, or the findings, conclusions, recommendations or any other material presented in them, is at that person's sole risk.

The audit was, and this report is, limited by and relies on the scope of work undertaken for this audit, the information made available to the Site Auditor by the Client and their environmental consultants through the documents provided to us, and also on our observations of the site made during the audit period. The Site Auditor has taken this information to represent a fair and reasonable characterisation of the status of the land. Whilst all reasonable care was taken, to the extent practical under normal auditing procedures, to assure adequacy of the information, the Site Auditor and Ian Swane & Associates cannot warrant that this is the case. If the information is subsequently determined to be false, inaccurate or incomplete, it is possible that the Site Auditor's conclusions, as expressed in the audit report and statement may change.

This Site Audit applies to the condition of the Northcote Compound at the time the audit was undertaken. The Site Auditor and Ian Swane & Associates cannot be responsible for future activities that may result in changes to the site conditions. In the event that site conditions have since changed or are likely to change in the future, the Site Auditor recommends that the property owner engage an environmental consultant to confirm that the SPI site is being properly maintained to a condition suitable for its proposed land uses.

It must also be recognised that sub-surface conditions, including groundwater levels and contaminant concentrations, can change in a limited time. This should be borne in mind if the audit report and statement is used after a protracted delay.

There are always some variations in sub-surface conditions across a site that cannot be fully defined by investigation. No investigation, in practice, can be thorough enough to preclude the presence of materials on the subject property that presently, or in the future, may be considered hazardous. Hence it is possible that the measurements and values obtained from the sampling and testing presented do not represent the extremes of conditions which exist within the site.

Because regulatory evaluation criteria are constantly changing, concentrations of contaminants present and considered to be acceptable at the time of this audit report and statement, may in the future become subject to different regulatory standards and require reassessment. It is not possible in a Site Audit Report to present all data that could be of interest to all readers of this report. Readers are therefore referred to the referenced documentation for further data.

Yours faithfully

2022/2023 Mo. 1151





Dr Ian C Swane (CPEng, CEnvP & CSCS)

Accredited EPA Site Auditor Director, Ian Swane & Associates

Phone: 0418 867 112 Email: iswane@bigpond.com

SAR 278_Northcote PAGE 105

Site Audit Report 278_Northcote
WestConnex Stage 3A Northcote Compound
Area C3a

IAN SWANE & ASSOCIATES

Appendix A. Figures & Tables from M4 East Work


SAR 278_Northcote PAGE 106

Site Audit Report 278_Northcote
WestConnex Stage 3A Northcote Compound
Area C3a

IAN SWANE & ASSOCIATES

Ramboll (February 2019)
DSI

SAR 278_Northcote PAGE 107






RAMBOLL


DRAFTED BY: TP


Date: 2/11/2016 A3 SCALE 1:1000


Figure 2 Proposed Compound Layout Plan
Phase 2 ESA - Northcote Street Tunnel Compound Client: CPB
Samsung John Holland JV, WestConnex M4 East













Project No: AS121919 Client Name: CSJ Project Name: Phase 1 2 ESA

Project Site: 006

Well ID	Easting	Northing	Gauging	Total Well Depth	SWL	TOC Elevation	Groundwater Elevation
	3	3	Date	(m btoc)	(m btoc)	(mAHD)	(mAHD)
006_GW004	326965.04	6250050.50	24/05/2016	10.03	5.03	8.75	3.72
006_GW005	326947.55	6250064.53	24/05/2016	10.07	3.07	8.39	5.32
006_GW006	326967.92	6250079.60	24/05/2016	10.68	3.77	9.06	5.29

Notes

m = Metres

btoc = Below Top of Casing

SWL = Standing Water Level

TOC = Top of Casing

AHD = Australian Height Datum

Easting projection MGA94: Map Grid of Australia 1994



Project No: AS121919 Client Name: CSJ Project Name: Phase 1 2 ESA

Project Site: 006

Well ID	Purge Date	Purge Vol (L)	DO (ppm)	EC (µScm-¹)	рН	Eh (mV)	Temperature (°C)	Comments
006_GW004	24/05/2016	3.5	1.20	1107	5.16	108	21.0	moderately turbid, brown, no sheen, no odour, no PSH
006_GW005	24/05/2016	2.5	0.62	4350	5.34	136	22.0	slightly turbid, brown, no sheen, no odour, no PSH
006_GW006	24/05/2016	2.5	1.39	2180	5.85	74	22.5	slightly turbid, brown, no sheen, no odour, no PSH

Notes

L = Litre

DO = Dissolved Oxygen

ppm = parts per million

EC = Electrical Conductivity

 μ Scm-1 = microSiemens per centimetre

Eh = Redox

mV = milli Volts

											Sample Type	: 11	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL
											ALS Sample r Sample date:	number:	ES1609685001 04/05/2016	ES1609685002 04/05/2016	ES1609685003 04/05/2016	ES1609685004 04/05/2016	ES1609685005 04/05/2016	ES1609685006 04/05/2016	ES1609685007 04/05/2016	ES1609685008 04/05/2016	ES1609685009 04/05/2016	ES1609685010 04/05/2016	ES1609685011 04/05/2016	ES1609685012 04/05/2016	ES1610404001 11/05/2016	ES1610406011 11/05/2016	ES1610404002 11/05/2016	ES1610404004 11/05/2016	ES1610404005 11/05/2016	ES1610406010 11/05/2016	ES1610404006 11/05/2016	ES1610404007 11/05/2016	ES1610404008 11/05/2016	ES1610404009 10/05/2016	ES1610404010 10/05/2016
											Sample ID: Project Name Compound:	e:	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX		006_GW006_0.5 M4E-WCX Northcote Street
											Site:		Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Northcote Street Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006
	NEPM 2013 HIL D Commercial / Industrial	NEPM 2013 Soil Vapour Intrusion HSL D Sand ¹ 0-1m NEPM 2013 Soil Vapour Intrusion HSL D Sand ¹ 1-2m	NEPM 2013 Soil Vapour	NEPM 2013 Soil Vapour	NEPM 2013 EIL Commercial /	NEPM 2013 ESL ² Commercial /	NEPM 2013 Management Limits	CRC CARE 2011 Direct Contact ⁴	CRC CARE 2011 Direct Contact ⁴ HSL for	Vapour Intrusion HSL for Intrusive	Sampling Me		Test Pitting	Test Pitting	Test Pitting		Test Pitting	Test Pitting One wall of Test	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Drilling	Drilling	Drilling	Drilling	Drilling	Drilling	Drilling	Drilling	Drilling	Drilling	Drilling
	Industrial	Sand ¹ 0-1m Sand ¹ 1-2m	Sand ¹ 2-4m	Sand ¹ 4+m	Industrial	Industrial	Commercial/ Industrial ²	HSL D	Maintenance Workers	Maintenance Workers Sand 0- <2m ¹	Sample Desc		FILL; Silty sand,	Residual CLAY/highly	Residual CLAY/highly	FILL; Silty sand, possible backfill sands,	FILL; Gravelly	Pit becomes highly weathered sandstone/clayey		Clayey SAND; highly weathered	Clayey SAND; highly weathered	FILL: Gravelly clayey sand,	Gravelly SILT;												
													moist, medium grained, uniform, grey/brown, no observed	weathered sandstone; mottled grey/red	weathered sandstone; mottled grey/red	grey/orange, saturated, medium grained, perhaps very	sandy clay, saturated, orange/brown, ironstone gravels,	sand, white, loose, very moist, medium grained.	contains bricks, blue metal, lots of PVC conduits and wire and ag	medium stiff,	sandstone, orange/red, medium stiff, ironstone,	reworked natural with pieces of concrete, sandstone		Clayey SAND; highly weathered sandstone, orange	CLAY; red and	Duplicate of	CLAY; red and	SANDSTONE; light	FILL: Clayey sand, black, fine to	Duplicate of	FILL; Sandy clay with gravel, grey, low plasticity, wet (possible staining)	CLAY; red and	SANDSTONE	FILL; Clayey sand,	CLAY; brown with red (sandstone) mottling, low to
													contamination,	sands, soft-moist,	orange, moist, minor very fine sands, soft-moist	slight hydrocarbor	n soft, high	very slight hydrocarbon odour (other side	pipe, medium	high plasticity	high plasticity clay, sand is fine grained, no	mixed in,	ironstone, no observed contamination	and white, high plasticity, medium dense	plasticity, moist	006_GW004_0.2	plasticity, moist	mottled	medium grained, moist	006_GW005_0.2	low plasticity, wet (possible staining)	grey mottled, we	SANDSTONE	light brown, moist n	medium plasticity, moist
													rushed sandstone	no observed contamination	no observed contamination	asbestos containing material observed, brick	contamination	of wall still fill), keeps filling with	contaminatoin, broken glass	observed contamination	observed contamination	soft, no observed contamination													
Analyte grouping/Analyte											Units	LOR			ļ		1	irrigation water	-					-						-		-	#		
EA001: pH in soil using 0.01M CaCl extract pH (CaCl2)											pH units	0.1													4.2		3.8	4.3					4.6		
EA055: Moisture Content Moisture Content (dried @ 103°C)											96	- 1	7.9	15.2	14.4	13.3	14.6	14.8	8.9	14.1	17	11.5	16	12.2	10.8	11.3	13.2	3.6	27.4	17.6	17	21.4	10.4	11	16.7
ED006: Exchangeable Cations on Alkaline Soils Exchangeable Calcium												0.1	****												1.9		0.8	<0.1					0.2		
Exchangeable Magnesium Exchangeable Potassium Exchangeable Sodium												0.1 0.1 0.1															0.1 0.2	0.4 0.1 <0.1					1.1 <0.1 0.3		
Cation Exchange Capacity												0.1													10.8		4.2	0.7					1.7		
EP003: Total Organic Carbon (TOC) in Soil Total Organic Carbon											%		****												0.07		0.2	0.02					0.05		
EA200: AS 4964 - 2004 Identification of Asbestos in Soils Asbestos Detected Asbestos Type	+ +		-		-	-					g/kg	0.1	No -			No -	No -		No -			No -			No -	No -	No -		No -	No -	No -	No -		No -	No -
Sample weight (dry)											g	0.1	40.1			39.7	21.7		44.9	****	****	45.7			111	89.3	115	****	110	128	65.2	51.1		194	190
													Mid brown sandy soil.			Mid brown sandy soil with grey rocks	Mid brown clay soil with grey rocks.		Mid brown sandy soil.			Pale brown sandy soil.			Mid brown clay soil.	Pale brown clay soil.	Pale brown clay soil	а	Mid brown sandy soil.	Mid grey - brown sandy soil with gre rocks.	y Mid brown clay soil.	Pale brown clay so with grey rocks.	oil	Pale brown sandy soil.	Mid orange - brown clay soil with grey rocks.
Description APPROVED IDENTIFIER:													G.MORGAN			G.MORGAN	G.MORGAN		G.MORGAN		****	G.MORGAN			G.MORGAN	G.MORGAN	G.MORGAN	****	G.MORGAN	S.SPOONER	G.MORGAN	G.MORGAN		G.MORGAN	S.SPOONER
EG005T: Total Metals by ICP-AES Arsenic	3000			1	160							5	<5	<5	<5	46	<5	<5	<5	<5	<5	<5	<5	<5	<5	<5	<5	<5	<5	<5	6	<5	<5	13	6
Cadmium Chromium Copper	900 3600 240000				310 150						mg/kg mg/kg mg/kg	1 2 5	<1 4 7	<1 4 <5	<1 <2 <5	<1 19 20	<1 15 <5	<1 2 <5	<1 4 <5	<1 11 <5	<1 4 <5	<1 12 6	<1 19 <5	<1 8 <5	<1 6 <5	<1 11 <5	<1 3 <5	<1 14 <5	<1 21 12	<1 8 16	<1 69 24	<1 2 <5	<1 8 <5	<1 23 <5	<1 26 <5
Iron Lead	1500				1800						% mg/kg	0.005	22	6	 <5	39	11	9	13	6	10	10	6	6	0.076	6	0.138	0.64	21	31	33	10	0.749 10	14	12
Nickel Zinc	40000 400000				300							5	<2 46	<2 <5	<2 <5	228	<2 24	<2 <5	34	<2 <5	<2 <5	14	<2 <5	<2 <5	<2 <5	<2 <5	<2 <5	8	11 40	56	60 76	<2 <5	17	<2 10	6
EG035T: Total Recoverable Mercury by FIMS Mercury	730										mg/kg	0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1
EP066: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls	7										mg/kg	0.1	0.2			<0.1						<0.1			<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1
EP068A: Organochlorine Pesticides (OC) alcha-BHC			1	I	I	I						0.05	< 0.05			<0.05						<0.05			<0.05	<0.05					<0.05	<0.05	<0.05	<0.05	<0.05
alpha-BHC Hexachlorobenzene (HCB) beta-BHC	80										mg/kg mg/kg mg/kg	0.05	<0.05 <0.05 <0.05			<0.05 <0.05 <0.05		****				<0.05 <0.05			<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05 <0.05
gamma-BHC delta-BHC Heptachlor	50										mg/kg mg/kg	0.05	< 0.05 < 0.05			<0.05 <0.05						<0.05 <0.05 <0.05			<0.05 <0.05	<0.05 <0.05	<0.05 <0.05 <0.05	< 0.05 < 0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05 <0.05	< 0.05	<0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05
Aldrin Heptachlor epoxide Total Chlordane (sum)	530										mg/kg mg/kg mg/kg	0.05	<0.05 <0.05 <0.05			<0.05 <0.05 <0.05						<0.05 <0.05 <0.05			<0.05 <0.05 <0.05	< 0.05	< 0.05	< 0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	< 0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05
trans-Chlordane alpha-Endosulfan cis-Chlordane											mg/kg mg/kg mg/kg	0.05	<0.05 <0.05 <0.05			<0.05 <0.05 <0.05						<0.05 <0.05 <0.05			<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05 <0.05	<0.05 <0.05 <0.05		<0.05 <0.05 <0.05	<0.05 <0.05 <0.05
Dieldrin 4.4°-DDE Endrin	100										mg/kg mg/kg mg/kg	0.05 0.05 0.05	<0.05 <0.05 <0.05			<0.05 <0.05 <0.05						<0.05 <0.05 <0.05			<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	< 0.05	<0.05 <0.05	<0.05 <0.05	<0.05	<0.05 <0.05 <0.05	< 0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05 <0.05
Endrin Endosulfan (sum) beta-Endosulfan 4.4"-DDD	2000										mg/kg mg/kg mg/kg	0.05	<0.05 <0.05 <0.05			<0.05 <0.05 <0.05						<0.05 <0.05 <0.05			<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05 <0.05	<0.05 <0.05 <0.05 <0.05	<0.05 <0.05 <0.05
Endrin aldehyde Endosulfan sulfate 4.41-DDT					640						mg/kg mg/kg	0.05				<0.05 <0.05						<0.05 <0.05 <0.2			<0.05 <0.05	<0.05 <0.05			< 0.05	< 0.05		<0.05 <0.05 <0.2	< 0.05	<0.05 <0.05	<0.05 <0.05 <0.2
Endrin ketone Methoxychlor	2500				640						mg/kg mg/kg	0.2	<0.05 <0.2			<0.2 <0.05 <0.2						<0.05 <0.2			<0.2 <0.05 <0.2		<0.05 <0.2	<0.05	<0.05	<0.05 <0.2	<0.05 <0.2	<0.05 <0.2	<0.05 <0.2	<0.2 <0.05 <0.2	<0.05 <0.2
Sum of DDD + DDE + DDT Sum of Aldrin + Dieldrin	3600 45										mg/kg mg/kg	0.05	<0.05 <0.05			<0.05 <0.05						<0.05 <0.05			<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05
EP068B: Organophosphorus Pesticides (OP) Dichlorvos Demeton-S-methyl											mg/kg mg/kg	0.05	<0.05 <0.05			<0.05 <0.05						<0.05 <0.05			<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05
Monocrotophos Dimethoate Diazinon											mg/kg mg/kg	0.2	<0.2 <0.05 <0.05			<0.2 <0.05 <0.05						<0.2 <0.05 <0.05			<0.2 <0.05 <0.05	<0.2 <0.05	<0.2 <0.05	<0.2 <0.05	<0.2 <0.05	<0.2 <0.05	<0.2 <0.05	<0.2 <0.05	<0.2 <0.05	<0.2 <0.05	<0.2 <0.05
Chlorpyrifos-methyl Parathion-methyl											mg/kg mg/kg	0.05	<0.05 <0.2			<0.05 <0.2						<0.05 <0.2			<0.05 <0.2	<0.05 <0.2	<0.05 <0.2	<0.05 <0.2	<0.05 <0.2	<0.05 <0.2	<0.05 <0.2	<0.05 <0.2	<0.05 <0.2	<0.05 <0.05 <0.2	<0.05 <0.2
Malathion Fenthion Chlorpyrifos	2000										mg/kg mg/kg mg/kg	0.05	<0.05 <0.05 <0.05			<0.05 <0.05 <0.05						<0.05 <0.05 <0.05			~n ns		<0.05 <0.05 <0.05		<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05
Parathion Pirimphos-ethyl Chlorfenvinphos											mg/kg mg/kg mg/kg	0.05	<0.2 <0.05 <0.05	****		<0.2 <0.05 <0.05	****	****			****	<0.2 <0.05 <0.05 <0.05		****	<0.2 <0.05 <0.05	<0.2 <0.05 <0.05	<0.2 <0.05 <0.05	<0.2 <0.05 <0.05	<0.2 <0.05 <0.05	<0.2 <0.05 <0.05	<0.2 <0.05 <0.05	<0.2 <0.05 <0.05	<0.2 <0.05 <0.05	<0.2 <0.05 <0.05 <0.05	<0.2 <0.05 <0.05 <0.05
Bromophos-ethyl Fenamiphos Prothiofos											mg/kg mg/kg	0.05	< 0.05			<0.05 <0.05						<0.05 <0.05			<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05
Ethion Carbophenothion Azinphos Methyl				<u> </u>							mg/kg mg/kg mg/kg	0.05 0.05 0.05	<0.05 <0.05 <0.05 <0.05			<0.05 <0.05 <0.05 <0.05						<0.05 <0.05 <0.05			<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05	<0.05 <0.05 <0.05 <0.05 <0.05 <0.05	<0.05 <0.05 <0.05
EP075(SIM)A: Phenolic Compounds	240000																																		
Phenol 2-Chlorophenol 2-Methylphenol 3-8-4-Methylphenol											mg/kg	0.5	<0.5 <0.5 <0.5			<0.5 <0.5 <0.5						<0.5 <0.5 <0.5			<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5
3- & 4-Methylphenol 2-Nitrophenol 2.4-Dimethylphenol	25000										mg/kg mg/kg mg/kg	0.5 0.5	<0.5 <0.5 <0.5			<0.5 <0.5 <0.5		****	****			<0.5 <0.5 <0.5			<0.5 <0.5 <0.5	<1 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<1	<0.5 <0.5 <0.5	<1 <0.5 <0.5	<1	<1 <0.5 <0.5	<1	<1 <0.5 <0.5 <0.5	<1 <0.5 <0.5 <0.5
2.4-Dichlorophenol 2.6-Dichlorophenol 4-Chloro-3-methylphenol											mg/kg mg/kg mg/kg	0.5 0.5 0.5	<0.5 <0.5			<0.5 <0.5						< 0.5			<0.5 <0.5	<0.5 <0.5	< 0.5 < 0.5	<0.5							
4-Chloro-3-methylphenol 2.4.6-Trichlorophenol 2.4.5-Trichlorophenol Pentachlorophenol	660										mg/kg mg/kg mg/kg	0.5 0.5 2	<0.5 <0.5 <2			<0.5 <0.5 <2						<0.5 <0.5 <0.5 <2			<0.5 <0.5 <2	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5 <2	<0.5 <0.5 <2	<0.5 <0.5 <2	<0.5 <0.5 <2	<0.5 <0.5 <2	<0.5 <0.5 <0.5 <2	<0.5 <0.5 <0.5 <2
EP075(SIM)B: Polynuclear Aromatic Hydrocarbons		MI	a.r		275			*****	2000-							-0.5	1	0.5	25		1		25	0.5				<2							
Naphthalene Acenaphthylene Acenaphthene		NL NL	NL	NL	370			11000	29000	NL	mg/kg mg/kg mg/kg		<0.5 <0.5 <0.5	<0.5	<0.5 <0.5 <0.5	< 0.5	<0.5 <0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5	<0.5 <0.5 <0.5	< 0.5	< 0.5	<0.5 <0.5 <0.5	< 0.5	<0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	< 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5
Fluorene Phenanthrene											mg/kg	0.5	<0.5 <0.5 <0.5	< 0.5	<0.5 <0.5 <0.5 <0.5	< 0.5	< 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	< 0.5	< 0.5	< 0.5	< 0.5	<0.5 <0.5	<0.5	<0.5 <0.5	<0.5	<0.5 <0.5 <0.5	< 0.5	<0.5	<0.5 <0.5	<0.5 <0.5 <0.5
Anthracene Fluoranthene Pyrene											mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5 <0.5	<0.5	< 0.5	<0.5	< 0.5	< 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5 <0.5	< 0.5	< 0.5	<0.5 <0.5 <0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	<0.5 <0.5 <0.5	< 0.5	<0.5 <0.5
Benz(a)anthracene Chrysene											mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5	< 0.5	<0.5 <0.5 <0.5	<0.5	< 0.5	<0.5 <0.5	<0.5 <0.5	< 0.5	< 0.5	<0.5 <0.5 <0.5	< 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Benzo(b+j)fluoranthene Benzo(k)fluoranthene Benzo(a)pyrene						72					mg/kg	0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5				<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5	< 0.5	<0.5	<0.5	<0.5	<0.5 <0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5	< 0.5	<0.5 <0.5 <0.5	< 0.5	<0.5 <0.5 <0.5
Indeno(1.2.3.cd) pyrene Dibenz(a.h) anthracene											mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5	<0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5	< 0.5	< 0.5	< 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Benzo(g.h.i)perylene Sum of polycyclic aromatic hydrocarbons	4000										mg/kg mg/kg mg/kq	0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	< 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	< 0.5	<0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5
Benzo(a) pyrene TEQ (zero) Benzo(a) pyrene TEQ (half LOR) Benzo(a) pyrene TEQ (LOR)	40										mg/kg mg/kg	0.6 1.2	0.6 1.2	0.6	1.2	1.2	0.6	0.6 1.2	0.6	0.6	0.6 1.2	0.6	0.6 1.2	0.6	0.6 1.2	0.6 1.2	0.6	<0.5 0.6 1.2	0.6	0.6	0.6	0.6	0.6 1.2	0.6	0.6
EP080/071: Total Petroleum Hydrocarbons C6 - C9 Fraction				<u> </u>		<u> </u>					mg/kg	10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10
C10 - C14 Fraction C15 - C28 Fraction											mg/kg	50	<50	<50	<50	<50	<50 <100 <100	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50 <100 <100	< 50	<50 <100 <100
C29 - C36 Fraction C10 - C36 Fraction (sum)											mg/kg	50	<100 <50	<50	<50	<100 <50	<50	<100 <50	<100 <50	<100 <50	<100 <50	<100 <50	<100 <50	<50	<100 <50	<100 <50	<50	<100 <50	<100 <50	<50	<100 <50	<50	<100 <50	<100 <50	<100 <50
•		<u> </u>	*							- '																					*				

DAMBELL	ENTHRONI

												Sample Tune.	- 11	SOII	sou	SOLI	SOII	SOII	SOLI	SOII	SOIL	SOII	SOLI	SOLI	SOU	SOLI	SOU	SOII	SOLI	SOII	SOIL	SOU	SOLI	SOIL	sou	SOIL
												Sample Type: ALS Sample nu	mber:	ES1609685001	ES1609685002	ES1609685003	ES1609685004	ES1609685005	ES1609685006	ES1609685007	ES1609685008	ES1609685009	ES1609685010	ES1609685011	ES1609685012	ES1610404001	ES1610406011	ES1610404002	ES1610404004	ES1610404005	ES1610406010	SOIL ES1610404006 11/05/2016	ES1610404007	ES1610404008	ES1610404009	ES1610404010
												Sample date: Sample ID:		006_TP001_0.10	006_TP001_0.50	006_TP001_1.20	006_TP002_0.10	006_TP002_0.70	006_TP002_1.20	006_TP003_0.10	006_TP003_0.30	006_TP003_0.60	006_TP004_0.20	006_TP004_0.40	006_TP004_1.00	006_GW004_0.2	006_QC004	006_GW004_0.5	006_GW004_2.5	006_GW005_0.2	006_QC003	006_GW005_0.6	006_GW005_0.7	006_GW005_4.0	006_GW006_0.2	006_GW006_0.5
												Project Name: Compound:		M4E-WCX	M4E-WCX Northcota Street	M4E-WCX	M4E-WCX Northcote Street	M4E-WCX Northcoto Street	M4E-WCX	M4E-WCX	M4E-WCX Northcote Street	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX
														Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Northcote Street Tunnel Site Site 006	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site Site 006
		NEPM 2013 Soi	I NEPM 2013 Soi	II NEPM 2013 Soil	II NEPM 2013 Soil			NEPM 2013		CRC CARE 2011 Direct Contact ⁴	CRC CARE 2011 Vapour	Sampling Meth		Test Pitting			Test Pitting		Test Pitting		Test Pitting	Test Pitting		Test Pitting		Drilling	Drilling	Drilling	Drilling	Drilling		Drilling	Drilling	Drilling	Drilling	Drilling
	D Commercial /	Vapour Intrusion HSL I	Vapour Intrusion HSL D	Vapour D Intrusion HSL D	NEPM 2013 Soil Vapour D Intrusion HSL D Sand ¹ 4+m	Commercial /	NEPM 2013 ESL ² Commercial /	Limits Commercial	Direct Contact ⁴		Vapour Intrusion HSL for Intrusive Maintenance	Sample Descri	otion				FILL: Silty sand,		One wall of Test							,	-	,			-		,	,	,	
	maaamii	Sand ¹ 0-1m	Sand ¹ 1-2m	Sand ¹ 2-4m	Sand ¹ 4+m	maama	Industrial	Industrial 2	H3L D	Maintenance Workers	Workers Sand 0- <2m ¹			FILL: Silty sand,	Residual CLAV/blobby	Residual	possible backfill sands.	FILL; Gravelly	Pit becomes highly weathered sandstone/clayey		biobly weathered															
													- -	moist, medium grained, uniform,	CLAY/highly weathered sandstone:	CLAY/highly weathered sandstone:	grey/orange, saturated, medium grained.	sandy clay, saturated, orange/brown.			sandstone, orange/red, medium stiff.	sandstone, orange/red, medium stiff.	reworked natural with pieces of concrete.		Clayey SAND; highly weathered					FILL: Clavey sand.		FILL: Sandy clay				CLAY; brown with
														grey/brown, no observed contamination.	orange, moist,	orange, moist,	perhaps very slight hydrocarbon	ironstone gravels, soft, high	medium grained, very slight	blue metal, lots of PVC conduits and wire and ag pipe, medium	ironstone, high plasticity	ironstone, high plasticity	sandstone mixed in.	moist-moist, gravel is ironstone, no	sandstone, orange and white, high	grey mottled, low	Duplicate of 006_GW004_0.2	grey mottled, low	grey/orange	black, fine to medium grained,	Duplicate of 006_GW005_0.2	FILL; Sandy clay with gravel, grey, low plasticity, wet (possible staining)	CLAY; red and grey mottled, wet	SANDSTONE	FILL; Clayey sand, light brown, moist	mottling, low to
													- 11	contains srushed	minor very fine sands, soft-moist,	ands soft-moist	odour, loose, no asbestos	plasticity, no observed	hydrocarbon odour (other side	dense, no observed	clay, sand is fine grained, no	clay, sand is fine	orange/brown.	observed contamination	plasticity, medium dense	,		, , , , , , , , , , , , , , , , , , , ,		moist		(possible staining)				moist
													ll ^c	concrete, roots, crushed sandstone	no observed contamination	contamination	containing material	contamination	of wall still fill), keeps filling with	contaminatoin, broken glass	observed contamination	observed contamination	medium dense- soft, no observed contamination													
Analyte grouping/Analyte												Units	np				observed, brick		irrigation water																	
EP080/071: Total Recoverable Hydrocarbons - NEPM 2013 Fra	actione											Onits	Lon																							
C6 - C10 Fraction		260	370	630	NL		215	700	26000	82000	NL		10	<10 <10	<10 <10	<10	<10	<10 <10	<10	<10	<10 <10	<10 <10	<10	<10	<10 <10	<10	<10 <10	<10 <10	<10 <10	<10	<10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10
C6 - C10 Fraction minus BTEX (F1) >C10 - C16 Fraction		200	3,0	030			170	1000	20000	62000	NL	mg/kg	50	<50	<50	<10 <50	<50	<50	<50	<10 <50	<50	<50	<10 <50	<50	<50	<50	<50	<50	<50	<50	<10 <50	<50	<50	<50	<50	<50
>C16 - C34 Fraction (F3) >C34 - C40 Fraction (F4)							1700 3300	10000	27000 38000	120000		mg/kg	100	<100	<100 <100	<100	<100	<100	<100	<100 <100	<100	<100	<100	<100	<100 <100	<100	<100 <100	<100	<100 <100	<100	<100 <100	<100 <100	<100	<100 <100	<100	<100 <100
>C10 - C40 Fraction (sum) >C10 - C16 Fraction minus Naphthalene (F2)		NL	NL	NL	NL							mg/kg mg/kg	50 50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50	<50 <50
EPOBO: BTEXN																																				
Benzene Toluene		3 NL	3 NL	3 NL	3 NL		75 135		430 99000	1100 120000	77 NL	mg/kg mg/ka	0.2	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5
Ethylbenzene		NL	NL		NL		165		27000	85000	NL	mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5
meta- & para-Xylene ortho-Xylene		220	All	A.II	Nº		or.		91000	130000	NL	mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Total Xylenes Sum of BTEX		230	NL	NL	NL.		95		81000	130000			0.2	<0.5 <0.2	< 0.2	<0.5 <0.2	< 0.2	<0.5 <0.2	<0.5 <0.2	< 0.2	<0.5 <0.2	<0.5 <0.2	<0.5 <0.2	< 0.2	<0.5 <0.2	<0.5 <0.2	< 0.2	<0.5 <0.2	<0.5 <0.2	<0.5 <0.2	< 0.2	<0.5 <0.2	< 0.2	<0.5 <0.2	< 0.2	<0.5 <0.2
Naphthalene		NL	NL	NL	NL	370			11000	29000	NL.	mg/kg	1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1
EP074A: Monocyclic Aromatic Hydrocarbons Styrene												mg/kg mg/kg	0.5						****							<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5 <0.5	<0.5	<0.5	<0.5	<0.5
Isopropylbenzene n-Propylbenzene												mg/kg mg/kg	0.5													<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
1.3.5-Trimethylbenzene sec-Butylbenzene												mg/kg mg/kg	0.5													<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5	<0.5 <0.5
1.2.4-Trimethylbenzene tert-Butylbenzene												mg/kg mg/kg	0.5													<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	< 0.5	< 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
p-Isopropyltoluene												mg/kg		****				****							****	<0.5 <0.5		<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5		<0.5 <0.5
n-Butylbenzene EP074B: Oxygenated Compounds												mg/kg	0.3														10.5								40.5	
Vinyl Acetate												mg/kg	5														<5				<5	<5	<5			<5
2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK)													5													<5 <5	<5 <5	<5 <5	<5 <5	<5	<5 <5	<5 <5		<5 <5	<5 <5	<5 <5
2-Hexanone (MBK)												mg/kg	5											****		<5	<5	<5	<5	<5	<5	<5	<5	<5	<5	<5
EP074C: Sulfonated Compounds Carbon disulfide												mg/kg	0.5													<0.5	<0.5	< 0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
EP074D: Fumigants																																				
2.2-Dichloropropane 1.2-Dichloropropane												mg/kg mg/kg	0.5													<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	< 0.5	< 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
cis-1.3-Dichloropropylene												mg/kg	0.5					****								< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	<0.5 <0.5		< 0.5	< 0.5	< 0.5
trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB)													0.5													<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
EP074E: Halogenated Aliphatic Compounds					+ +								!																							
Dichlorodifluoromethane Chloromethane												mg/kg mg/kg	5													<5 <5	<5 <5	<5 <5	<5 <5	<5 <5	<5 <5	<5 <5	<5 <5	<5 <5	<5 <5	<5 <5
Vinyl chloride Bromomethane					 							mg/kg	5													<5 <5	<5 <5	<5 <5	<5 <5	<5 <5	<5	<5	<5 <5	<5 <5	<5 <5	<5 <5
Chloroethane Trichlorofluoromethane												mg/kg mg/kg	5	****		****	****	****		****	****	****	****	****	****	<5 <5	<5 <5	<5 <5	<5 <5	<5 <5	<5 <5	<5 <5	<5 <5	<5 <5	<5 <5	<5 <5
1.1-Dichloroethene Iodomethane												mg/kg	0.5													<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	< 0.5	<0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
trans-1.2-Dichloroethene												mg/kg	0.5					****				****				<0.5	< 0.5	< 0.5	<0.5	< 0.5	< 0.5	<0.5 <0.5	<0.5	< 0.5	< 0.5	< 0.5
1.1-Dichloroethane cis-1.2-Dichloroethene													0.5													<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	< 0.5	< 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
1.1.1-Trichloroethane 1.1-Dichloropropylene												mg/kg	0.5													<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	< 0.5		<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Carbon Tetrachloride 1.2-Dichloroethane												mg/kg mg/kg	0.5													<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Trichloroethene Dibromomethane			<u> </u>									mg/kg	0.5													<0.5 <0.5	<0.5 <0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	<0.5 <0.5	< 0.5	< 0.5
1.1.2-Trichloroethane												mg/kg	0.5													<0.5 <0.5	< 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5
1.3-Dichloropropane Tetrachloroethene												mg/kg	0.5													< 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5 <0.5	< 0.5	< 0.5	<0.5 <0.5	<0.5 <0.5
1.1.1.2-Tetrachloroethane trans-1.4-Dichloro-2-butene												mg/kg	0.5													<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	< 0.5	< 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
cis-1.4-Dichloro-2-butene 1.1.2.2-Tetrachloroethane												mg/kg mg/kg	0.5													<0.5 <0.5	<0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
1.2.3-Trichloropropane Pentachloroethane													0.5													<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5 <0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
1.2-Dibromo-3-chloropropane Hexachlorobutadiene			-									mg/kg mg/kg mg/kg	0.5													<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
EP074F: Halogenated Aromatic Compounds												- 3																								
Chlorobenzene												mg/kg														<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Bromobenzene 2-Chlorotoluene													0.5													<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
4-Chlorotoluene 1.3-Dichlorobenzene												mg/kg mg/kg														<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
1.4-Dichlorobenzene 1.2-Dichlorobenzene			 	 								mg/kg mg/kg	0.5													<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
1.2.4-Trichlorobenzene												mg/kg	0.5													< 0.5	<0.5 <0.5	< 0.5	<0.5	< 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
1.2.3-Trichlorobenzene EP074G: Trihalomethanes												mg/kg		-																						
Chloroform												mg/kg	0.5																			<0.5				
Bromodichloromethane Dibromochloromethane												mg/kg mg/kg	0.5													<0.5	<0.5	<0.5	<0.5	<0.5	<0.5		<0.5	<0.5	<0.5	<0.5
Bromoform												mg/kg	0.5													<0.5	<0.5	< 0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
EP074H: Naphthalene Naphthalene		NL	NL	NL	NL	370			11000	29000	NL	mg/kq	1													<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1
	_												- 1																		1	1				

files (Cd Indicates no criticion soviabile)

1.09 - Limit of Reporting

1.60 - Limit of Reporting

1.6 1

Z.\Projects\LSJH\Tables\Northcote Compound\AS121919_Northcote_Compound_Results Table_006_rev2_Not yet sentAS121919_Northcote_Compound_Results Table_006_rev2_Not yet sent



										Site 006											
					Sample T	ype: ole number:	SOIL ES1609685010	SOIL ES1609685011	SOIL ES1609685012	SOIL ES1610122001	SOIL ES1610122002	SOIL ES1610122003	SOIL ES1610122004	SOIL ES1610122005	SOIL ES1610122006	SOIL ES1610122007	SOIL ES1610122008	SOIL ES1610122009	SOIL ES1610122010	SOIL ES1610122011	SOIL ES1610122012
					Sample d	ate:	04/05/2016 006_TP004_0.20	04/05/2016	04/05/2016	10/05/2016	10/05/2016 006_GS002	10/05/2016 006_GS003	10/05/2016 006_GS004	10/05/2016 006_GS005	10/05/2016 006_GS006	10/05/2016 006_GS007	10/05/2016 006_GS008	10/05/2016 006_GS009	10/05/2016 006_GS010	10/05/2016 006_GS011	10/05/2016 006_QC022
					Project N		M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX
		NEPM 2013			Compoun	d:	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Tunnel Site	Northcote Street Tunnel Site	Tunnel Site	Northcote Street Tunnel Site	Tunnel Site
	NEPM 2013 HIL D	Management	CRC CARE 2011 Direct	CRC CARE 2011 Direct	Site:		Site 006	Site 006	Site 006	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class
	Commercial / Industrial	Limits Commercial/	Contact HSL D ⁴	Contact HSL for Workers ⁴	Sampling	Method:	Test Pitting	Test Pitting	Test Pitting	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands
	maasma	Industrial 3		IOI WOIKEIS			FILL; Gravelly clayey sand, reworked natural with pieces	Gravelly SILT;	Clayey SAND; highly												
							of concrete, sandstone	orange, slightly moist-moist, gravel	weathered sandstone, orange	orange/brown gravelly, sand clay	orange/brown gravelly, sand clay	orange/brown gravelly, sand clay	orange/brown gravelly, sand clay	orange/brown gravelly, sand clay	orange/brown gravelly, sand clay	orange/brown gravelly, sand clay	orange/brown gravelly, sand clay	Silty Sand (FILL),	Silty Sand (FILL),	Silty Sand (FILL),	Duplicate of
					Sample Des	cription	mixed in, orange/brown,	is ironstone, no observed	and white, high plasticity,	(Fill), medium grained, slightly moist	(Fill), medium grained, slightly moist	(Fill), medium grained, slightly moist	(Fill), soft, high plasticity	brown	brown	brown	006_GS008				
							medium dense-soft, no observed	contamination	medium dense	moist	moist	moist									
Analyte grouping/Analyte					Units	LOR	contamination														
EA001: pH in soil using 0.01M CaCl extract																					
pH (CaCl2)					pH units	0.1															
EA055: Moisture Content					II 04		II 44.5		10.0	40	40.7	45.7	44.0	44.0	10.6	47.6	04.0	10.0		10.1	10.0
Moisture Content (dried @ 103°C)					%		11.5	16	12.2	18	18.7	15.7	14.8	16.2	18.6	17.6	21.9	10.8	9.1	10.4	19.8
ED006: Exchangeable Cations on Alkaline Soils Exchangeable Calcium					meq/100g	0.1															
Exchangeable Magnesium					meq/100g	0.1															
Exchangeable Potassium Exchangeable Sodium					meq/100g meq/100g	0.1															
Cation Exchange Capacity					meq/100g	0.1															
EP003: Total Organic Carbon (TOC) in Soil		 	 	+	II 0/		· · · · · · · · · · · · · · · · · · ·			 									1	 	
Total Organic Carbon					%																
EA200: AS 4964 - 2004 Identification of Asbestos in bulk samp Asbestos Detected	oies				g/kg																
Asbestos Type Sample weight (dry)					 g																
Description APPROVED IDENTIFIER:																					
EA200: AS 4964 - 2004 Identification of Asbestos in Soils					<u> </u>																
Asbestos Detected					g/kg		No			Yes	No	No	No	No	No	No	No	No	No	No	
Asbestos Type Sample weight (dry)					 g		45.7			Ch 34.7	22.7	17.3	29.5	28.9	22.6	20.4	34.8	40.1	36.9	29.1	
										sandy soil with											
							Pale brown			red rocks plus one small	Mid brown sandy soil with	Mid brown sandy soil with	Mid brown sandy soil with	Mid brown sandy soil with	Mid brown sandy soil with	Pale brown sandy soil with	Mid brown sandy soil with	Mid brown sandy soil with	Mid brown clay soil with grey	Mid brown clay soil with grey	
							sandy soil.			friable asbestos fibre bundle	red rocks.	red rocks.	grey rocks.	grey rocks.	grey rocks.	grey rocks.	grey rocks.	grey rocks.	rocks.	rocks.	
Description										approx 3 x 1 x 1											
APPROVED IDENTIFIER:							G.MORGAN			C.OWLER	C.OWLER	C.OWLER	S.SPOONER	S.SPOONER	S.SPOONER	S.SPOONER	S.SPOONER	S.SPOONER	C.OWLER	C.OWLER	
EG005T: Total Metals by ICP-AES Arsenic	3000				mg/kg	5	<5	<5	<5	<5	<5	<5	5	6	<5	<5	<5	<5	<5	<5	7
Cadmium Chromium	900 3600				mg/kg mg/kg	2	<1 12	<1 19	<1 8	<1 <2	<1 <2	<1 <2	<1 7	<1 8	<1 6	< 1 4	<1 6	<1 5	<1 8	<1 8	<1 11
Copper Iron	240000				mg/kg	5 0.005	6	<5	<5	<5	<5	<5	8	12	10	<5	9	32	6	12	18
Lead Nickel	1500 6000				mg/kg mg/kg	5	10	6 <2	6 <2	<5 <2	<5 <2	<5 <2	26 2	26 3	18	8 <2	23	43 4	15 2	27 4	36 3
Zinc	400000				mg/kg	5	14	<5	<5	53	55	42	59	117	62	46	80	398	77	30	126
EG035T: Total Recoverable Mercury by FIMS																					
Mercury	730				mg/kg	0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	< 0.1	<0.1
EPO66: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls	7				mg/kg	0.1	<0.1					<0.1	<0.1		<0.1		<0.1		<0.1		
EP068A: Organochlorine Pesticides (OC)					II * *																
alpha-BHC Hexachlorobenzene (HCB)	90				mg/kg	0.05	<0.05					<0.05	<0.05		<0.05		<0.05		<0.05		
beta-BHC	80				mg/kg mg/kg	0.05 0.05	<0.05 <0.05					<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
gamma-BHC delta-BHC					mg/kg mg/kg	0.05	<0.05 <0.05					<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
Heptachlor Aldrin	50				mg/kg mg/kg	0.05	<0.05 <0.05					<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
Heptachlor epoxide Total Chlordane (sum)	530				mg/kg mg/kg	0.05 0.05	<0.05 <0.05					<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
trans-Chlordane alpha-Endosulfan					mg/kg	0.05 0.05	<0.05 <0.05					<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
cis-Chlordane					mg/kg mg/kg	0.05	< 0.05					< 0.05	< 0.05		< 0.05		< 0.05		< 0.05		
Dieldrin 4.4°-DDE					mg/kg mg/kg	0.05 0.05	<0.05 <0.05					<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
Endrin Endosulfan (sum)	100 2000				mg/kg mg/kg	0.05 0.05	<0.05 <0.05					<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
beta-Endosulfan 4.4`-DDD					mg/kg mg/kg	0.05	<0.05 <0.05					<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
Endrin aldehyde Endosulfan sulfate					mg/kg mg/kg	0.05 0.05	<0.05 <0.05					<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
4.4 - DDT Endrin ketone					mg/kg	0.2	<0.2 <0.05					<0.2 <0.05	<0.2 <0.05		<0.2 <0.05		<0.2 <0.05		<0.2 <0.05		
Methoxychlor	2500				mg/kg mg/kg	0.2	< 0.2					< 0.2	< 0.2		< 0.2		< 0.2		< 0.2		
Sum of DDD + DDE + DDT Sum of Aldrin + Dieldrin	3600 45				mg/kg mg/kg	0.05 0.05	<0.05 <0.05					<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
EP068B: Organophosphorus Pesticides (OP)																					
Dichlorvos Demeton-S-methyl					mg/kg mg/kg	0.05 0.05	<0.05 <0.05					<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
Monocrotophos Dimethoate					mg/kg mg/kg	0.2	<0.2 <0.05					<0.2 <0.05	<0.2 <0.05		<0.2 <0.05		<0.2 <0.05		<0.2 <0.05		
Diazinon					mg/kg	0.05	< 0.05					< 0.05	< 0.05		< 0.05		< 0.05		< 0.05		
Chlorpyrifos-methyl Parathion-methyl					mg/kg mg/kg	0.05	<0.05 <0.2					<0.05 <0.2	<0.05 <0.2		<0.05 <0.2		<0.05 <0.2		<0.05 <0.2		
Malathion Fenthion					mg/kg mg/kg	0.05 0.05	<0.05 <0.05					<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
Chlorpyrifos Parathion	2000				mg/kg mg/kg	0.05 0.2	<0.05 <0.2					<0.05 <0.2	<0.05 <0.2		<0.05 <0.2		<0.05 <0.2		<0.05 <0.2		
Pirimphos-ethyl Chlorfenvinphos					mg/kg mg/kg	0.05 0.05	<0.05 <0.05					<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
Bromophos-ethyl					mg/kg	0.05	< 0.05					< 0.05	< 0.05		< 0.05		< 0.05		< 0.05		
		i .	1	1	mg/kg	0.05	< 0.05					< 0.05	< 0.05		< 0.05		< 0.05		< 0.05		
Fenamiphos Prothiofos Ethion					mg/kg mg/kg	0.05	<0.05 <0.05					<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		



										Site 006											
					Sample Typ	pe:	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL
					ALS Sample Sample date		ES1609685010 04/05/2016	ES1609685011 04/05/2016	ES1609685012 04/05/2016	ES1610122001 10/05/2016	ES1610122002 10/05/2016	ES1610122003 10/05/2016	ES1610122004 10/05/2016	ES1610122005 10/05/2016	ES1610122006 10/05/2016	ES1610122007 10/05/2016	ES1610122008 10/05/2016	ES1610122009 10/05/2016	ES1610122010 10/05/2016	ES1610122011 10/05/2016	ES1610122012 10/05/2016
					Sample ID:	:	006_TP004_0.20	006_TP004_0.40	006_TP004_1.00	006_GS001	006_GS002	006_GS003	006_GS004	006_GS005	006_GS006	006_GS007	006_GS008	006_GS009	006_GS010	006_GS011	006_QC022
					Project Na		M4E-WCX Northcote Street	M4E-WCX Northcote Street	M4E-WCX Northcote Street	M4E-WCX Northcote Street	M4E-WCX Northcote Street	M4E-WCX Northcote Street	M4E-WCX Northcote Street	M4E-WCX Northcote Street	M4E-WCX Northcote Street	M4E-WCX Northcote Street	M4E-WCX Northcote Street	M4E-WCX Northcote Street	M4E-WCX Northcote Street	M4E-WCX Northcote Street	M4E-WCX Northcote Street
		NEPM 2013			Compound	:	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site
	PM 2013 HIL D	Management	CRC CARE 2011 Direct	CRC CARE 2011 Direct	Site:		Site 006	Site 006	Site 006	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class	Site 006 Waste Class
Com	nmercial /	Limits Commercial/	Contact HSL	Contact HSL	Sampling N	Method:	Test Pitting	Test Pitting	Test Pitting	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands
In	ndustrial	Industrial 3	D⁴	for Workers ⁴			FILL; Gravelly clayes sand, reworked	1													
							natural with pieces of concrete,	Gravelly SILT; orange, slightly	Clayey SAND; highly weathered	orange/brown	orange/brown	orange/brown	orange/brown	orange/brown	orange/brown	orange/brown	orange/brown				
					Sample Descr	iption	sandstone mixed in,	moist-moist, gravel is ironstone, no	sandstone, orange and white, high	gravelly, sand clay (Fill), medium	gravelly, sand clay (Fill), medium	gravelly, sand clay (Fill), medium	gravelly, sand clay (Fill), soft, high	Silty Sand (FILL), brown	Silty Sand (FILL), brown	Silty Sand (FILL), brown	Duplicate of 006_GS008				
							orange/brown, medium dense-soft,	observed contamination	plasticity, medium dense	grained, slightly moist	grained, slightly moist	grained, slightly moist	plasticity	plasticity	plasticity	plasticity	plasticity				
							no observed contamination														
Analyte grouping/Analyte		*			Units	LOR			•	!	•				· '	•					
Carbophenothion		T			mg/kg	0.05	<0.05					< 0.05	<0.05		< 0.05		<0.05		< 0.05		
Azinphos Methyl					mg/kg	0.05	<0.05					<0.05	<0.05	****	<0.05		< 0.05		<0.05		
EP075(SIM)A: Phenolic Compounds							Ш														
Phenol 2 2-Chlorophenol	240000				mg/kg mg/kg	0.5	<0.5 <0.5					<0.5 <0.5	<0.5 <0.5		<0.5 <0.5		<0.5 <0.5		<0.5 <0.5		
2-Methylphenol					mg/kg	0.5	< 0.5					< 0.5	< 0.5		< 0.5		< 0.5		< 0.5		
3- & 4-Methylphenol 2-Nitrophenol	25000				mg/kg mg/kg	0.5	<1 <0.5					<1 <0.5	<1 <0.5		<1 <0.5		<1 <0.5		<1 <0.5		
2.4-Dimethylphenol 2.4-Dichlorophenol					mg/kg	0.5 0.5	<0.5 <0.5					<0.5 <0.5	<0.5 <0.5		<0.5 <0.5		<0.5 <0.5		<0.5 <0.5		
2.6-Dichlorophenol					mg/kg mg/kg	0.5	< 0.5					< 0.5	< 0.5		<0.5		< 0.5		< 0.5		
4-Chloro-3-methylphenol 2.4.6-Trichlorophenol					mg/kg mg/kg	0.5	<0.5 <0.5					<0.5 <0.5	<0.5 <0.5		<0.5 <0.5		<0.5 <0.5		<0.5 <0.5		
2.4.5-Trichlorophenol	440				mg/kg	0.5	< 0.5					< 0.5	< 0.5		< 0.5		< 0.5		< 0.5		
Pentachlorophenol	660				mg/kg	2	<2					<2	<2		<2		<2		<2		
EP075(SIM)B: Polynuclear Aromatic Hydrocarbons Naphthalene			11000	29000	mg/kg	0.5	<0.5	< 0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	< 0.5	< 0.5
Acenaphthylene			11000	27000	mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Acenaphthene Fluorene					mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Phenanthrene					mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Anthracene Fluoranthene					mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Pyrene Benz(a)anthracene					mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Chrysene					mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Benzo(b+j)fluoranthene Benzo(k)fluoranthene					mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Benzo(a)pyrene					mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Indeno(1.2.3.cd)pyrene Dibenz(a.h)anthracene					mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Benzo(g.h.i)perylene Sum of polycyclic aromatic hydrocarbons	4000				mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Benzo(a)pyrene TEQ (zero)	4000				mg/kg mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Benzo(a)pyrene TEQ (half LOR) Benzo(a)pyrene TEQ (LOR)	40				mg/kg mg/kg	0.6 1.2	0.6	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2
EP080/071: Total Petroleum Hydrocarbons																					
C6 - C9 Fraction					mg/kg	10	<10	<10	<10	<10	<10	<10	<10	<10	21	<10	35	<10	<10	<10	56
C10 - C14 Fraction C15 - C28 Fraction					mg/kg mg/kg	50 100	<50 <100	<50 <100	<50 <100	250 360	250 390	310 420	<50 <100	<50 <100	<50 <100	<50 <100	60 <100	<50 <100	<50 <100	<50 <100	<50 <100
C29 - C36 Fraction					mg/kg	100	< 100	<100	<100	<100	< 100	<100	<100	<100	<100	< 100	< 100	<100	< 100	<100	< 100
C10 - C36 Fraction (sum)					mg/kg	50	<50	<50	<50	610	640	730	<50	<50	<50	<50	60	<50	<50	<50	<50
EP080/071: Total Recoverable Hydrocarbons - NEPM 2013 Fraction	is	700	26000	82000	mg/kg	10	<10	<10	<10	<10	<10	<10	<10	<10	30	<10	49	<10	<10	<10	70
C6 - C10 Fraction minus BTEX (F1)			20000	02000	mg/kg	10	<10	<10	<10	<10	<10	<10	<10	<10	30	<10	49	<10	<10	<10	70
>C10 - C16 Fraction >C16 - C34 Fraction (F3)		1000 3500	27000	85000 85000	mg/kg mg/kg	100	< 100	<50 <100	<50 <100	280	400 300	320	<50 <100	<50 <100	<50 <100	<50 <100	<100	<50 <100	< 100	<50 <100	<50 <100
>C34 - C40 Fraction (F4) >C10 - C40 Fraction (sum)		10000	38000	120000	mg/kg mg/kg	100 50	<100 <50	<100 <50	<100 <50	<100 660	<100 700	<100 790	<100 <50	<100 <50	<100 <50	<100 <50	<100 60	<100 <50	<100 <50	<100 <50	<100 <50
>C10 - C16 Fraction minus Naphthalene (F2)					mg/kg	50	<50	<50	<50	380	400	470	<50	<50	<50	<50	60	<50	<50	<50	<50
EP080: BTEXN					 		<u> </u>														
Benzene Toluene			430 99000	1100	mg/kg	0.2	<0.2	<0.2 <0.5	<0.2	<0.2	<0.2	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2	<0.2	<0.2	<0.2	<0.2	< 0.2	<0.2
Ethylbenzene			27000	120000 85000	mg/kg mg/kg	0.5	<0.5 <0.5	< 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	< 0.5	< 0.5	< 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
meta- & para-Xylene ortho-Xylene					mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Total Xylenes			81000	130000	mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Sum of BTEX Naphthalene			11000	29000	mg/kg mg/kg	0.2	<0.2 <1	<0.2 <1	<0.2 <1	<0.2 <1	<0.2 <1	<0.2 <1	<0.2 <1	<0.2 <1	<0.2 <1	<0.2 <1	<0.2 <1	<0.2 <1	<0.2 <1	<0.2 <1	<0.2 <1
EP074A: Monocyclic Aromatic Hydrocarbons																					
Styrene					mg/kg	0.5											<0.5				
Isopropylbenzene n-Propylbenzene					mg/kg mg/kg	0.5 0.5											<0.5 <0.5				
1.3.5-Trimethylbenzene sec-Butylbenzene			-		mg/kg mg/kg	0.5 0.5											<0.5 <0.5				
1.2.4-Trimethylbenzene					mg/kg	0.5											< 0.5				
tert-Butylbenzene p-Isopropyltoluene					mg/kg mg/kg	0.5											<0.5 <0.5				
n-Butylbenzene					mg/kg	0.5											< 0.5				
EP074B: Oxygenated Compounds					+ +																
Vinyl Acetate 2-Butanone (MEK)					mg/kg mg/kg	5 5											<5 <5				
4-Methyl-2-pentanone (MIBK)					mg/kg	5											<5				
2-Hexanone (MBK)					mg/kg	5											<5				
EP074C: Sulfonated Compounds Carbon disulfide					mg/kg	0.5											<0.5				
					23																
EP074D: Fumigants 2.2-Dichloropropane					mg/kg	0.5											<0.5				
2.2 Bidinoropropune		-	·		mg/kg	0.5 0.5											<0.5 <0.5				
1.2-Dichloropropane		1			mg/kg																
1.2-Dichloropropane cis-1.3-Dichloropropylene trans-1.3-Dichloropropylene					mg/kg	0.5											< 0.5				
1.2-Dichloropropane cis-1.3-Dichloropropylene					mg/kg mg/kg	0.5											<0.5 <0.5				
1.2-Dichloropropane cis-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB) EPO74E: Halogenated Aliphatic Compounds					mg/kg	0.5											<0.5				
1.2-Dichloropropane cis-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB) EPO74E: Halogenated Aliphatic Compounds Dichlorodifluoromethane Chloromethane					mg/kg mg/kg mg/kg	0.5 5 5											<0.5 <5 <5				
1.2-Dichloropropane cis-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB) EPO74E: Halogenated Aliphatic Compounds Dichlorodifluoromethane					mg/kg mg/kg	0.5											<0.5 <5				

TABLE 4: Risk to Construction Workers - Soil Sampling Results Northcote Compound Site 006



			Sample Type		SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL
			ALS Sample		ES1609685010	ES1609685011	ES1609685012	ES1610122001	ES1610122002	ES1610122003	ES1610122004	ES1610122005	ES1610122006	ES1610122007	ES1610122008	ES1610122009	ES1610122010	ES1610122011	ES1610122012
			Sample date		04/05/2016	04/05/2016	04/05/2016	10/05/2016	10/05/2016	10/05/2016	10/05/2016	10/05/2016	10/05/2016	10/05/2016	10/05/2016	10/05/2016	10/05/2016	10/05/2016	10/05/2016
			Sample ID:			006_TP004_0.40		006_GS001	006_GS002	006_GS003	006_GS004	006_GS005	006_GS006	006_GS007	006_GS008	006_GS009	006_GS010	006_GS011	006_QC022
			Project Nam	ie:	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX
			Compound:		Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	
	NEPM 2013	000 0105	Site:		Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006	Tunnel Site Site 006
NEPM 2013 HIL D	Management CRC CARE 2011 Direct	CRC CARE 2011 Direct	Site.		Site 666	Site 000	Site ooo	Waste Class	Waste Class	Waste Class	Waste Class	Waste Class	Waste Class	Waste Class	Waste Class	Waste Class	Waste Class	Waste Class	Waste Class
Commercial /	Limits Contact HSL		Sampling Me	ethod:	Test Pitting	Test Pitting	Test Pitting	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands	Backfill Sands
Industrial	Industrial 3 D4	for Workers ⁴			FILL; Gravelly clayey														
	muusman				sand, reworked	C	OL CAND LI-LL												1
					natural with pieces of concrete,	Gravelly SILT; orange, slightly	Clayey SAND; highly weathered	orange/brown	orange/brown	orange/brown	orange/brown	orange/brown	orange/brown	orange/brown	orange/brown				1
			Sample Descrip	tion	sandstone	moist-moist, gravel	sandstone, orange	gravelly, sand clay (Fill), medium	gravelly, sand clay (Fill), medium	gravelly, sand clay (Fill), medium	gravelly, sand clay	Silty Sand (FILL),	Silty Sand (FILL),	Silty Sand (FILL),	Duplicate of				
					mixed in, orange/brown,	is ironstone, no observed	and white, high plasticity,	grained, slightly	grained, slightly	grained, slightly	(Fill), soft, high plasticity	brown	brown	brown	006_GS008				
					medium dense-soft,	contamination	medium dense	moist	moist	moist	F	F	F	,	p				1
					no observed contamination														1
Analyte grouping/Analyte			Units	LOR	Jonathiandi		+		l .	+	+	<u> </u>	<u> </u>		l .	l .	<u> </u>	l .	
rinaryto grouping/Anaryto			Oints	LOK															
Trichlorofluoromethane			mg/kg	5											<5				
1.1-Dichloroethene			mg/kg	0.5											< 0.5				
lodomethane trans-1,2-Dichloroethene			mg/kg	0.5 0.5											<0.5 <0.5				
1.1-Dichloroethane			mg/kg mg/kg	0.5											< 0.5				
cis-1.2-Dichloroethene			mg/kg	0.5											< 0.5				
1.1.1-Trichloroethane			mg/kg	0.5											< 0.5				
1.1-Dichloropropylene			mg/kg	0.5											< 0.5				
Carbon Tetrachloride			mg/kg	0.5											< 0.5				
1.2-Dichloroethane			mg/kg	0.5											< 0.5				
Trichloroethene Dibromomethane			mg/kg mg/kg	0.5											<0.5 <0.5				
1.1.2-Trichloroethane			mg/kg	0.5											< 0.5				
1.3-Dichloropropane			mg/kg	0.5											< 0.5				
Tetrachloroethene			mg/kg	0.5											< 0.5				
1.1.1.2-Tetrachloroethane			mg/kg	0.5											< 0.5				
trans-1.4-Dichloro-2-butene			mg/kg	0.5											< 0.5				
cis-1.4-Dichloro-2-butene 1.1.2.2-Tetrachloroethane			mg/kg	0.5											<0.5 <0.5				
1.2.3-Trichloropropane			mg/kg mg/kg	0.5											<0.5				
Pentachloroethane			mg/kg	0.5											< 0.5				
1.2-Dibromo-3-chloropropane			mg/kg	0.5											< 0.5				
Hexachlorobutadiene			mg/kg	0.5											< 0.5				
EDOZIE Uzlanowała dowania Ozwania																			
EP074F: Halogenated Aromatic Compounds Chlorobenzene			mg/kg	0.5											< 0.5				
Bromobenzene			mg/kg	0.5											< 0.5				
2-Chlorotoluene			mg/kg	0.5											< 0.5				
4-Chlorotoluene			mg/kg	0.5											< 0.5				
1.3-Dichlorobenzene			mg/kg	0.5											< 0.5				
1.4-Dichlorobenzene			mg/kg	0.5											< 0.5				
1.2-Dichlorobenzene 1.2.4-Trichlorobenzene			mg/kg	0.5											<0.5 <0.5				
1.2.3-Trichlorobenzene			mg/kg mg/kg	0.5											<0.5				
T.E.O THORNOODOLLONG			.iig/kg	0.0											X 0.3				
EP074G: Trihalomethanes	<u> </u>	<u> </u>																	
Chloroform			mg/kg	0.5											< 0.5				
Bromodichloromethane			mg/kg	0.5											< 0.5				
Dibromochloromethane Promoform		1	mg/kg	0.5											< 0.5				
Bromoform			mg/kg	0.5											< 0.5				
EP074H: Naphthalene					<u> </u>		1			1	1								
Naphthalene	11000	29000	mg/kg	1											<1				

Blank Cell indicates no criterion available LOR = Limit of Reporting

CRC Care Technical Report 10, September 2011 Direct Contact (DC) Health Screening Levels 'D' (Commercial/Industrial)

National Environment Protection Council (2013) National Environmental Protection (Assessment of Site Contamination) Amendment Measure 2013 (No. 1) (NEPM).

(For soil texture classification undertaken in accord with AS 1726, the classifications of sand, silt and clay may be applied as coarse, fine with liquid limit <50% and fine with liquid limit 50% respectively, as the underlying properties to develop the HSLs may reasonably be selected to be similar. Where there is uncertainty, either a conservative approach may be adopted or laboratory analysis should be carried out.

² The most conservative ESL value has been adopted for all analytes

3 Management limits are applied after consideration of relevant ESLs and HSLs. Separate management limits for BTEX and naphthalene are not available hence these should not be subtracted from the relevant fractions to obtain F1 and F2.

⁴ Direct Contact are applied to surface soils or soils that could result in immediate contact.

Health Investigation Levels for chromium based on chromium (VI)

To obtain F1 subtract the sum of BTEX concentrations from the C6-C10 fraction.

To obtain F1 subtract the sum of BTEX concentrations from the C6-C10 fraction.

To obtain F2 subtract naphthalene from the >C10-C16 fraction.

Concentration in red font and grey box exceed the adopted health screening value

Concentration in blue font and grey box exceed the adopted management limits

Concentration in green and grey box exceed the direct contact for HSL D screening value

Concentration in light blue and grey box exceed the direct contact for workers screening value

concentrations in box exceed the screening value >2.5 times

Where there is one or more guideline value is exceeded, the highest guidleline value will be highlighted

Concentrations below the LOR noted as <value

'Ch' Chrysolic (white assessos)

'Ch' Chrysotile (white asbestos) 'Am' Amosite (brown asbestos)

Cr' Crocidolite (blue asbestos)

25/11/2016						Northcote C Site -						
	_					Sample Typ		Groundwater	Groundwater	Groundwater	Groundwater	Groundwater
						ALS Sample	e number:	ES1611420001	ES1611420002	ES1611420003	ES1611420007	S16-My28529 502339
	HSL D	– Comm	ercial/			Sample dat Sample ID:	e:	24/05/2016 006_GW004	24/05/2016 006_GW005	24/05/2016 006_GW006	24/05/2016 006_QC100	24/05/2016 006_QC101
		ndustria		95% Marine		Project Nar	ne:	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX
				Water	Recreational	Compound:		NORTHCOLE CTREET TUNNEL	NORTHCOLE	NORTHCOLE	NORTHCOLE	NORTHCOLE
				Protection for Aquatic	Health (10x ADWG 2011) ^c			STREET TUNNEL SITE GME	STREET TUNNEL SITE GME	STREET TUNNEL SITE GME	STREET TUNNEL SITE GME	STREET TUNNEL SITE GME
		1		Ecosystems ^B	1.5110 2011,	Site:	lathad.	SITE 006	SITE 006	SITE 006	SITE 006	SITE 006
	_					Sampling M Sample Des		Bailer	Bailer	Bailer	Bailer	Bailer
Guidelines	2 to <4m	4m to<8m	8m+					moderately turbid,	slightly turbid,	slightly turbid,	DUPLICATE OF	TRIPLICATE OF
Guidelines		tocom						brown, no sheen, no odour, no PSH	odour, no PSH	brown, no sheen, no odour, no PSH	006_GW005	006_GW005
One lade consuming (One lade						Units	1.00					
Analyte grouping/Analyte						Ollits	LOR					
EGO20T: Dissolved Metals by ICP-MS					T			1	T	ı		T
Arsenic Cadmium				2.3 0.7	100 20	μg/L μg/L	0.1	<1 <0.1	<1 <0.1	2 0.9	<1 <0.1	<1 0.2
Chromium				4.4	500	μg/L	1	<1	<1	<1	<1	<1
Copper Lead				1.3 4.4	20000 100	μg/L μg/L	1	2 14	<1 32	6 65	<1 33	1 30
Nickel				7	200	μg/L	1	<1	<1	<1	<1	<1
Zinc				15		μg/L	1	53	50	96	52	48
EG035F: Dissolved Mercury by FIMS												
Mercury				0.1	10	μg/L	0.1	<0.1	<0.1	< 0.1	< 0.1	<0.1
EP066: Polychlorinated Biphenyls (PCB)												
Total Polychlorinated biphenyls						μg/L	1	<1	<1	<1	<1	
EP068A: Organochlorine Pesticides (OC)												
alpha-BHC	Ĺ	L_				μg/L	0.5	<0.5	<0.5	< 0.5	<0.5	
Hexachlorobenzene (HCB)				-		μg/L	0.5	<0.5	<0.5	< 0.5	<0.5	
beta-BHC gamma-BHC		1			100	μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	
delta-BHC						μg/L	0.5	<0.5	< 0.5	< 0.5	<0.5	
Heptachlor Aldrin				0.0004 0.003	3	μg/L μg/l	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	
Heptachlor epoxide	<u>L</u> _	<u>L</u> _		0.003		μg/L μg/L	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	
trans-Chlordane				0.00		μg/L	0.5	< 0.5	<0.5	< 0.5	<0.5	
alpha-Endosulfan cis-Chlordane		1		0.0002		μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	
Dieldrin				0.01		μg/L	0.5	<0.5	<0.5	<0.5	<0.5	
4.4`-DDE Endrin	-	1		0.0005 0.008		μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	
beta-Endosulfan				0.007		μg/L	0.5	<0.5	<0.5	<0.5	<0.5	
4.4`-DDD						μg/L	0.5	<0.5	< 0.5	< 0.5	< 0.5	
Endrin aldehyde Endosulfan sulfate						μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	
4.4`-DDT				0.0004	90	μg/L	2	<2.0	<2.0	<2.0	<2.0	
Endrin ketone Methoxychlor				0.004	3000	μg/L μg/L	0.5 2	<0.5 <2.0	<0.5 <2.0	<0.5 <2.0	<0.5 <2.0	
^ Total Chlordane (sum)				0.001	20	μg/L	0.5	<0.5	<0.5	< 0.5	<0.5	
^ Sum of DDD + DDE + DDT ^ Sum of Aldrin + Dieldrin					3	μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	
A Sum of Alarin + Dielarin					3	μg/L	0.5	<0.5	<0.5	<0.5	<0.5	
EP068B: Organophosphorus Pesticides ((OP)				T = -					I		I
Dichlorvos Demeton-S-methyl				4	50	μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	
Monocrotophos				,		μg/L	2	<2.0	<2.0	<2.0	<2.0	
Dimethoate Diazinon				0.15 0.01	70 40	μg/L	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5	
Chlorpyrifos-methyl				0.01	40	μg/L μg/L	0.5 0.5	<0.5	<0.5	<0.5	<0.5 <0.5	
Parathion-methyl					7	μg/L	2	<2.0	<2.0	<2.0	<2.0	
Malathion Fenthion				0.05	700 70	μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	
Chlorpyrifos				0.009	100	μg/L	0.5	<0.5	<0.5	<0.5	<0.5	
Parathion Pirimphos-ethyl				0.004	200	μg/L μg/L	2 0.5	<2.0 <0.5	<2.0 <0.5	<2.0 <0.5	<2.0 <0.5	
Chlorfenvinphos					20	μg/L	0.5	<0.5	<0.5	<0.5	<0.5	
Bromophos-ethyl					5	μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	
Fenamiphos Prothiofos					5	μg/L μg/L	0.5	<0.5	<0.5	<0.5	<0.5	
Ethion					40	μg/L	0.5	< 0.5	<0.5	< 0.5	< 0.5	
Carbophenothion Azinphos Methyl				0.01	300	μg/L μg/L	0.5 0.5	<0.5 < 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	
				0.0.		pg/ L	0.0	1010	10.0	1010	10.0	
VOCs Styrene						μg/L	5	<5	<5	<5		
Isopropylbenzene						μg/L μg/L	5	<5	<5	<5		
n-Propylbenzene						μg/L	5	<5 <5	<5	<5		
1.3.5-Trimethylbenzene sec-Butylbenzene	<u>L</u>	L				μg/L μg/L	5 5	<5 <5	<5 <5	<5 <5		
1.2.4-Trimethylbenzene						μg/L	5	<5	<5	<5		
tert-Butylbenzene p-Isopropyltoluene						μg/L μg/L	5 5	<5 <5	<5 <5	<5 <5		
n-Butylbenzene						μg/L	5	<5	<5	<5		
Vinyl Acetate 2-Butanone (MEK)						μg/L μg/L	50 50	<50 <50	<50 <50	<50 <50		
4-Methyl-2-pentanone (MIBK)						μg/L	50	<50	<50	<50		
2-Hexanone (MBK) Carbon disulfide						μg/L	50 5	<50	<50 <5	<50		
2.2-Dichloropropane	<u>L</u> _	<u>L</u> _				μg/L μg/L	5	<5 <5	<5 <5	<5 <5		
1.2-Dichloropropane						μg/L	5	<5	<5	<5		
cis-1.3-Dichloropropylene trans-1.3-Dichloropropylene						μg/L μg/L	5 5	<5 <5	<5 <5	<5 <5		
1.2-Dibromoethane (EDB)						μg/L	5	<5	<5	<5		
Dichlorodifluoromethane Chloromethane						μg/L μg/L	50 50	<50 <50	<50 <50	<50 <50		
Vinyl chloride					3	μg/L μg/L	50	< 50	<50	<50		
Bromomethane Chloroethane		<u> </u>				μg/L	50 50	<50 <50	<50 <50	<50 <50		
Trichlorofluoromethane	<u>L</u>	L				μg/L μg/L	50 50	<50 <50	<50 <50	<50 <50		
					300	μg/L	5	<5	<5	<5		
1.1-Dichloroethene	1					μg/L μg/L	5 5	<5 <5	<5 <5	<5 <5		
Iodomethane						μg/L	5	<5	<5	<5		
lodomethane trans-1.2-Dichloroethene 1.1-Dichloroethane						ua/l	5	<5	<5	<5		
Iodomethane trans-1.2-Dichloroethene 1.1-Dichloroethane cis-1.2-Dichloroethene						μg/L						
lodomethane trans-1.2-Dichloroethene 1.1-Dichloroethane						μg/L μg/L	5	<5 <5	<5 <5	<5 <5		
Iodomethane trans-1.2-Dichloroethene 1.1-Dichloroethane cis-1.2-Dichloroethene 1.1.1-Trichloroethane 1.1-Dichloropropylene Carbon Tetrachloride						μg/L μg/L μg/L μg/L	5 5 5	<5 <5 <5	<5 <5 <5	<5 <5 <5		
Iodomethane trans-1.2-Dichloroethene 1.1-Dichloroethane cis-1.2-Dichloroethane 1.1.1-Trichloroethane 1.1-Dichloropropylene Carbon Tetrachloride 1.2-Dichloroethane					30	μg/L μg/L μg/L μg/L	5 5 5 5	<5 <5 <5 <5	<5 <5 <5 <5	<5 <5 <5 <5		
Iodomethane trans-1.2-Dichloroethene 1.1-Dichloroethane cis-1.2-Dichloroethene 1.1-Trichloroethane 1.1-Dichloropylene Carbon Tetrachloride 1.2-Dichloroethane Trichloroethene Dibromomethane					30	μg/L μg/L μg/L μg/L	5 5 5 5 5 5	<5 <5 <5 <5 <5 <5	<5 <5 <5 <5 <5 <5	<5 <5 <5 <5 <5 <5		
Iodomethane trans-1.2-Dichloroethene 1.1-Dichloroethane cis-1.2-Dichloroethene 1.1.1-Trichloroethane 1.1-Dichloropropylene Carbon Tetrachloride 1.2-Dichloroethane Trichloroethene Dibromomethane 1.1.2-Trichloroethane				1900	30	µg/L µg/L µg/L µg/L µg/L µg/L µg/L	5 5 5 5 5 5 5	<5 <5 <5 <5 <5 <5 <5 <5	<5 <5 <5 <5 <5 <5 <5	<5 <5 <5 <5 <5 <5 <5 <5		
Iodomethane trans-1.2-Dichloroethene 1.1-Dichloroethane cis-1.2-Dichloroethene 1.1-Trichloroethane 1.1-Dichloropropylene Carbon Tetrachloride 1.2-Dichloroethane Trichloroethene Dibromomethane				1900	30	µg/L µg/L µg/L µg/L µg/L	5 5 5 5 5 5	<5 <5 <5 <5 <5 <5	<5 <5 <5 <5 <5 <5	<5 <5 <5 <5 <5 <5		
Iodomethane trans-1.2-Dichloroethene 1.1-Dichloroethane cis-1.2-Dichloroethene 1.1.1-Trichloroethene 1.1.1-Trichloroethane 1.1-Dichloropropylene Carbon Tetrachloride 1.2-Dichloroethane Trichloroethene Dibromomethane 1.1.2-Trichloroethane 1.3-Dichloropropane Tetrachloroethene 1.1.1.2-Tetrachloroethane				1900		рд/L рд/L рд/L рд/L рд/L рд/L рд/L рд/L рд/L рд/L рд/L рд/L	5 5 5 5 5 5 5 5 5 5	<5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <	<5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <	<5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <		
Iodomethane trans-1.2-Dichloroethene 1.1-Dichloroethane cis-1.2-Dichloroethene 1.1-Trichloroethane 1.1-Trichloroethane 1.1-Dichloropropylene Carbon Tetrachloride 1.2-Dichloroethane Trichloroethene Dibromomethane 1.1.2-Trichloroethane 1.3-Dichloropropane Tetrachloroethene				1900		рд/L рд/L рд/L рд/L рд/L рд/L рд/L рд/L рд/L рд/L	5 5 5 5 5 5 5 5 5	<5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <	<5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <5 <	<5 <5 <5 <5 <5 <5 <5 <5 <5		



25/11/2016						Northcote C Site -						
						Sample Typ		Groundwater	Groundwater	Groundwater	Groundwater	Groundwater
						ALS Sample		 				S16-My28529
						Sample	, mannuel.	ES1611420001	ES1611420002	ES1611420003	ES1611420007	502339
						Sample dat	e:	24/05/2016	24/05/2016	24/05/2016	24/05/2016	24/05/2016
		– Comm	_			Sample ID:		006_GW004	006_GW005	006_GW006	006_QC100	006_QC101
	ı	ndustria	I ^A	95% Marine		Project Nar	ne:	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX
				Water	Recreational	Compound:		NORTHCOLE	NORTHCOLE	NORTHCOLE	NORTHCOLE	NORTHCOLE
				Protection for	Health (10x			STREET TUNNEL	STREET TUNNEL	STREET TUNNEL	STREET TUNNEL	STREET TUNNEL
				Aquatic	ADWG 2011) ^c	011		SITE GME	SITE GME	SITE GME	SITE GME	SITE GME
			1	Ecosystems ^B		Site:		SITE 006	SITE 006	SITE 006	SITE 006	SITE 006
						Sampling M		Bailer	Bailer	Bailer	Bailer	Bailer
		4m				Sample Des	scription	and a state of the	a 11 andre Administration (1.4)			
Guidelines	2 to <4m	to<8m	8m+					moderately turbid, brown, no sheen, no	slightly turbid, brown, no sheen, no	slightly turbid, brown, no sheen, no	DUPLICATE OF	TRIPLICATE OF
Guidennes								odour, no PSH	odour, no PSH	odour, no PSH	006_GW005	006_GW005
Analyte grouping/Analyte						Units	LOR					
	_											
1.2.3-Trichloropropane						μg/L	5	<5	<5	<5		
Pentachloroethane						μg/L	5	<5	<5	<5		
.2-Dibromo-3-chloropropane						μg/L	5	<5	<5	<5		
Hexachlorobutadiene						μg/L	5	<5	<5	<5		
Chlorobenzene				55	3000	μg/L	5	<5	<5	<5		
Bromobenzene						μg/L	5	<5	<5	<5		
2-Chlorotoluene						μg/L	5	<5	<5	<5		
I-Chlorotoluene						µg/L	5	<5	<5	<5		
1.3-Dichlorobenzene				260		µg/L	5	<5	<5	<5		
1.4-Dichlorobenzene				60	400	μg/L	5	<5	<5	<5		
1.2-Dichlorobenzene	1			160	15000	μg/L	5	<5	<5	<5		
1.2.4-Trichlorobenzene	 			20	300	μg/L μg/L	5	<5	<5 <5	<5		
1.2.3-Trichlorobenzene	1	1		3	300	μg/L μg/L	5	<5 <5	<5 <5	<5 <5		
				3	300			_				
Chloroform Bromodichloromethane	+			+	+	μg/L	5	<5	<5	<5		
Bromodichloromethane	1				-	μg/L	5 5	<5 .F	<5	<5 .F		
Dibromochloromethane						μg/L		<5	<5	< 5		
Bromoform	-		-		1	μg/L	5	<5	<5	<5		
laphthalene				50		μg/L	5	<5	<5	<5		
				<u> </u>	L	H		Ш				
EP075(SIM)A: Phenolic Compounds												
Phenol				400		μg/L	1	<1.0	<1.0	<1.0	<1.0	
2-Chlorophenol				340	3000	μg/L	1	<1.0	<1.0	<1.0	<1.0	
2-Methylphenol						μg/L	1	<1.0	<1.0	<1.0	<1.0	
- & 4-Methylphenol						μg/L	2	<2.0	<2.0	< 2.0	<2.0	
2-Nitrophenol				2		μg/L	1	<1.0	<1.0	<1.0	<1.0	
2.4-Dimethylphenol				2		μg/L	1	<1.0	<1.0	<1.0	<1.0	
2.4-Dichlorophenol				120	2000	μg/L	1	<1.0	<1.0	<1.0	<1.0	
2.6-Dichlorophenol				34		μg/L	1	<1.0	<1.0	<1.0	<1.0	
4-Chloro-3-methylphenol						µg/L	1	<1.0	<1.0	<1.0	<1.0	
2.4.6-Trichlorophenol				3	200	μg/L	1	<1.0	<1.0	<1.0	<1.0	
2.4.5-Trichlorophenol				4	200	μg/L	1	<1.0	<1.0	<1.0	<1.0	
Pentachlorophenol				22	100	μg/L	2	<2.0	<2.0	<2.0	<2.0	
						pg/ 2	_	12.0	12.0	12.0	12.0	
EP075(SIM)B: Polynuclear Aromatic Hy	drocarbo	ns					L	l I				
Naphthalene				50		μg/L	1	<1.0	<1.0	<1.0	<1.0	
Acenaphthylene						μg/L	1	<1.0	<1.0	<1.0	<1.0	
Acenaphthene						μg/L	1	<1.0	<1.0	<1.0	<1.0	
Fluorene						μg/L	1	<1.0	<1.0	<1.0	<1.0	
				0.4				_				
Phenanthrene				0.6		μg/L	1	<1.0	<1.0	<1.0	<1.0	
Anthracene				0.01		μg/L	1	<1.0	<1.0	<1.0	<1.0	
Fluoranthene				1		μg/L	1	<1.0	<1.0	<1.0	<1.0	
Pyrene	1			 	 	μg/L	1	<1.0	<1.0	<1.0	<1.0	
Benz(a)anthracene	1			ļ	ļ	μg/L	1	<1.0	<1.0	<1.0	<1.0	
Chrysene						μg/L	1	<1.0	<1.0	<1.0	<1.0	
Benzo(b+j)fluoranthene				ļ	ļ	μg/L	1	<1.0	<1.0	< 1.0	<1.0	
Benzo(k)fluoranthene				ļ	ļ	μg/L	1	<1.0	<1.0	< 1.0	<1.0	
Benzo(a)pyrene				0.1	0.1	μg/L	0.5	<0.5	<0.5	<0.5	<0.5	
ndeno(1.2.3.cd)pyrene						μg/L	1	<1.0	<1.0	<1.0	<1.0	
Dibenz(a.h)anthracene						μg/L	1	<1.0	<1.0	<1.0	<1.0	
Benzo(g.h.i)perylene						μg/L	1	<1.0	<1.0	<1.0	<1.0	
Sum of polycyclic aromatic hydrocarbons						μg/L	0.5	< 0.5	< 0.5	< 0.5	< 0.5	
Benzo(a)pyrene TEQ (zero)						μg/L	0.5	<0.5	< 0.5	< 0.5	<0.5	
EP080/071: Total Petroleum Hydrocarb	ons											
C6 - C9 Fraction						μg/L	20	<20	< 20	<20	<20	20
C10 - C14 Fraction						μg/L	50	<50	<50	<50	<50	
C15 - C28 Fraction						μg/L	100	<100	<100	<100	<100	
C29 - C36 Fraction	1					µg/L	50	<50	<50	<50	<50	
C10 - C36 Fraction (sum)						μg/L	50	<50	<50	<50	<50	
EP080/071: Total Recoverable Hydroca	rhons M	FPM 201	3 Fraction	ns								
C6 - C10 Fraction	DUTIS - IV	LFIVI 201.	o Fraction			μg/L	20	<20	<20	<20	<20	
C6 - C10 Fraction minus BTEX (F1)	6200	6300	6500			μg/L	20	< 20	<20	<20	<20	
>C10 - C16 Fraction						µg/L	100	<100	<100	<100	<100	
>C16 - C34 Fraction				1	1	μg/L	100	<100	<100	<100	<100	
>C34 - C40 Fraction	1					μg/L	100	<100	<100	<100	<100	
>C34 - C40 Fraction >C10 - C40 Fraction (sum)	1	1		†	 	μg/L μg/L	100	<100	<100	<100	<100	
>C10 - C40 Fraction (sum) >C10 - C16 Fraction minus Naphthalene (F2) NL	NL	NL			μg/L μg/L	100	<100	<100	<100	<100	
•	1					μg/ L	100	1100	100	100	1100	
EPO80: BTEXN	105-				2005							
Benzene	4900	5100	5400	500	8000	μg/L	1	<1	<1	<1	<1	<1
Toluene	NL	NL	NL	180	3000	μg/L	2	<2	<2	<2	<2	<1
Ethylbenzene	NL	NL	NL	5	8000	μg/L	2	<2	<2	<2	<2	<1
meta- & para-Xylene				275	ļ	μg/L	2	<2	<2	<2	<2	2
ortho-Xylene				350	ļ	μg/L	2	<2	<2	<2	<2	<1
Total Xylenes	NL	NL	NL		6000	μg/L	2	<2	<2	<2	<2	<3
Sum of RTEY	1		1		1	ua/I	1	-1	-1	-1	-1	

μg/L

Blank Cell indicates no criterion available

All results are in $\mu g/L$ unless stated

LOR = Limit of Reporting

Sum of BTEX

Naphthalene

NL

In instances where there was no marine guideline values, the freshwater guidelines have been adopted In instances where there was no health drinking water guideline value, the aesthetic value has been adopted Concentration in red font and grey box exceed the adopted ecosystem guideline value Concentration in orange font and grey box exceed the adopted recreational drinking water guideline value Concentrations in blue indicate the LOR is greater than the guideline value Concentrations below the LOR noted as <value

no HSL is presented for recreational use (HSL C) as all these chemicals are not limiting (NL)

A NEPM 2013 HSL 'D' (Commercial/Industrial) $^{\rm B}$ ANZECC 2000 % Protection Level for Receiving Water Type

On NAZECC 2000 % Protection Level for Receiving Water Type

NHMRC Australian Drinking Water Guidelines, 2011

ANZECC guidelines in Italics are low level reliability guidelines

ANZECC arsenic guideline based on As (III) for marine and As (V) for fresh, the lowest of presented guidelines.

NHMRC arsenic guidelines are based on total arsenic

ANZECC and NHMRC guidelines for chromium are based on Cr (VI)

ANZECC guidelines for mercury are based on inorganic mercury.

NHMRC guidelines for mercury are based on total mercury.



											Site 006									
	Sample Type:):	ALS	ALS		ALS	MGT		ALS	ALS		ALS	ALS		ALS	ALS		ALS	ALS	
	ALS Sample r		ES1609685004	ES1609685013		ES1609685004	S16-My06722		ES1609680002	ES1609680004		ES1609686002	ES1609686010		ES1610404001	ES1610406011		ES1610404005	ES1610406010	
	Sample date:	:	04/05/2016	04/05/2016		04/05/2016	499536 04/05/2016		04/05/2016	04/05/2016		05/05/2016	05/05/2016	-	11/05/2016	11/05/2016		11/05/2016	11/05/2016	-
	Sample ID:		006_TP002_0.10	006_QC001		006_TP002_0.10	006_QC002		026_TP001_0.50	026_QC001		028_TP001_0.50	028_QC001	_	006_GW004_0.2	006_QC004		006_GW005_0.2	006_QC003	1
	Project Name Compound:	e:	M4E-WCX Northcote Street	M4E-WCX Northcote Street	RPD	M4E-WCX Northcote Street	M4E-WCX Northcote Street	RPD	M4E-WCX Northcote Street	M4E-WCX Northcote Street	RPD	M4E-WCX Northcote Street	M4E-WCX Northcote Street	RPD	M4E-WCX Northcote Street	M4E-WCX Northcote Street	RPD	M4E-WCX Northcote Street	M4E-WCX Northcote Street	RPD
	Site:		Tunnel Site Site 006	Tunnel Site Site 006		Tunnel Site Site 006	Tunnel Site Site 006		Tunnel Site Site 026	Tunnel Site Site 026		Tunnel Site Site 028	Tunnel Site Site 028	-	Tunnel Site Site 006	Tunnel Site Site 006		Tunnel Site Site 006	Tunnel Site Site 006	4
	Sampling Met	thod:	Test Pitting	Test Pitting		Test Pitting	Test Pitting		Test Pitting	Test Pitting		Test Pitting	Test Pitting	1	Drilling	Drilling		Drilling	Drilling	-
	Sample Descr	ription		Duplicate of		-	Triplicate of			Duplicate of			Duplicate of	-		Duplicate of			Duplicate of	+
		-	PRIMARY	006_TP002_0.1		PRIMARY	006_TP002_0.1		PRIMARY	026_TP001_0.5		PRIMARY	028_TP001_0.5	L	PRIMARY	006_GW004_0.2		PRIMARY	006_GW005_0.2	
Analyte grouping/Analyte	Units	LOR																		
EA055: Moisture Content																				
Moisture Content (dried @ 103°C)	%		13.3	13.9	4.4	13.3			12.7	11.8		15.3	12.8	17.8	10.8	11.3	4.5	27.4	17.6	+
EA200: AS 4964 - 2004 Identification of Asbestos in Soils Asbestos Detected	g/kg		No.	No		No			No			No	No		No	No		No	No	
Asbestos Type Sample weight (dry)	 a		39.7	31.3		39.7			- 70			70.1	31.7		- 111	89.3		110	128	
Sample weight (dry)	g		Mid brown sandy soil			Mid brown sandy soil			Mid brown clay soil			Mid brown clay soil							Mid grey - brown	
Description			with grey rocks.	with grey rocks.		with grey rocks.			with grey rocks.			with grey rocks.	with grey rocks.		Mid brown clay soil.	Pale brown clay soil.		Mid brown sandy soil.	rocks.	
APPROVED IDENTIFIER:			G.MORGAN	G.MORGAN		G.MORGAN			G.MORGAN			G.MORGAN	G.MORGAN		G.MORGAN	G.MORGAN		G.MORGAN	S.SPOONER	
EG005T: Total Metals by ICP-AES Arsenic	mg/kg	5	46	32	35.9	46	36	24.4	16	14	13.3	18	6	100.0	<5	<5	nc	<5	<5	nc
Cadmium	mg/kg	1	<1	<1	nc	<1	< 0.4	nc	1	1	0.0	1	<1	nc	<1	<1	nc	<1	<1	nc 89.7
Chromium Copper	mg/kg mg/kg	5	19 20	14	71.4 35.3	19 20	10 13	62.1 42.4	24 20	26 28	33.3	30	20 25	40.0 24.6	- 6 <5	11 <5	58.8 nc	12	16	28.6
Lead Nickel	mg/kg mg/kg	5 2	39	47	18.6 0.0	39 4	42 < 5	7.4 nc	75 2	82 5	8.9 85.7	158	128	21.0 100.0	6 <2	6 <2	0.0 nc	21	31	38.5 58.8
Zinc	mg/kg	5	228	52	125.7	228	64	112.3	215	229	6.3	322	200	46.7	<5	<5	nc	40	56	33.3
EG035T: Total Recoverable Mercury by FIMS		0.5			e-		0.05			6.1			2.1							
Mercury	mg/kg	0.1	<0.1	<0.1	nc	<0.1	< 0.05	nc	0.1	<0.1	nc	<0.1	<0.1	nc	<0.1	<0.1	nc	<0.1	< 0.1	nc
EP066: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls	mg/kg	0.1	<0.1	<0.1	nc	<0.1	< 0.5	nc				<0.1	<0.1	nc	<0.1	<0.1	nc	<0.1	<0.1	nc
EP068A: Organochlorine Pesticides (OC)			I																	
alpha-BHC	mg/kg	0.05	<0.05	<0.05	nc	<0.05	<0.05	nc				<0.05	<0.05	nc	<0.05	<0.05	nc	<0.05	<0.05	nc
Hexachlorobenzene (HCB) beta-BHC	mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc				<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc
gamma-BHC delta-BHC	mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc				<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc
Heptachlor Aldrin	mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc				<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc
Heptachlor epoxide	mg/kg	0.05	< 0.05	< 0.05	nc	< 0.05	< 0.05	nc				< 0.05	< 0.05	nc	< 0.05	< 0.05	nc	< 0.05	< 0.05	nc
otal Chlordane (sum) rans-Chlordane	mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	< 0.1	nc 				<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc
alpha-Endosulfan cis-Chlordane	mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05	nc 				<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc
Dieldrin . 4`-DDE	mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc				<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc
Endrin	mg/kg	0.05	< 0.05	< 0.05	nc	< 0.05	< 0.05	nc				< 0.05	< 0.05	nc	< 0.05	< 0.05	nc	< 0.05	< 0.05	nc
Endosulfan (sum) peta-Endosulfan	mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc				<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc
4.4`-DDD Endrin aldehyde	mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc				0.06 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc
ndosulfan sulfate	mg/kg mg/kg	0.05	<0.05 <0.2	<0.05 <0.2	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc				<0.05 <0.2	<0.05 <0.2	nc nc	<0.05 <0.2	<0.05 <0.2	nc nc	<0.05 <0.2	<0.05 <0.2	nc nc
Endrin ketone	mg/kg	0.05	< 0.05	< 0.05	nc	< 0.05	< 0.05	nc				< 0.05	< 0.05	nc	< 0.05	< 0.05	nc	< 0.05	< 0.05	nc
Methoxychlor Sum of DDD + DDE + DDT	mg/kg mg/kg	0.2	<0.2 <0.05	<0.2 <0.05	nc nc	<0.2 <0.05	< 0.2	nc 				<0.2 0.06	<0.2 <0.05	nc nc	<0.2 <0.05	<0.2 <0.05	nc nc	<0.2 <0.05	<0.2 <0.05	nc nc
Sum of Aldrin + Dieldrin	mg/kg	0.05	<0.05	<0.05	nc	< 0.05						<0.05	< 0.05	nc	<0.05	< 0.05	nc	< 0.05	<0.05	nc
EPO68B: Organophosphorus Pesticides (OP) Dichlorvos	mg/kg	0.05	<0.05	<0.05	nc	<0.05	<0.2	nc				<0.05	<0.05	nc	<0.05	<0.05	nc	< 0.05	<0.05	nc
Demeton-S-methyl	mg/kg	0.05	< 0.05	< 0.05	nc	< 0.05	< 0.2	nc				< 0.05	< 0.05	nc	< 0.05	< 0.05	nc	< 0.05	< 0.05	nc
Monocrotophos Dimethoate	mg/kg mg/kg	0.2	<0.2 <0.05	<0.2 <0.05	nc nc	<0.2 <0.05	<2 <0.2	nc nc				<0.2 <0.05	<0.2 <0.05	nc nc	<0.2 <0.05	<0.2 <0.05	nc nc	<0.2 <0.05	<0.2 <0.05	nc nc
Diazinon Chlorpyrifos-methyl	mg/kg mg/kg	0.05 0.05	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.2 <0.2	nc nc				<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc
Arathion-methyl Malathion	mg/kg	0.2	<0.2 <0.05	<0.2 <0.05	nc nc	<0.2 <0.05	<0.2 <0.2	nc nc				<0.2 <0.05	<0.2 <0.05	nc nc	<0.2 <0.05	<0.2 <0.05	nc nc	<0.2 <0.05	<0.2 <0.05	nc nc
enthion	mg/kg mg/kg	0.05	< 0.05	< 0.05	nc	< 0.05	< 0.2	nc				< 0.05	< 0.05	nc	< 0.05	< 0.05	nc	< 0.05	< 0.05	nc
Chlorpyrifos Parathion	mg/kg mg/kg	0.05	<0.05 <0.2	<0.05 <0.2	nc nc	<0.05 <0.2	<0.2 <0.2	nc nc				<0.05 <0.2	<0.05 <0.2	nc nc	<0.05 <0.2	<0.05 <0.2	nc nc	<0.05 <0.2	<0.05 <0.2	nc nc
Pirimphos-ethyl Chlorfenvinphos	mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.2 <0.2	nc nc				<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc
gromophos-ethyl enamiphos	mg/kg mg/kg	0.05 0.05	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.2 <0.2	nc nc				<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc	<0.05 <0.05	<0.05 <0.05	nc nc
Prothiofos Pthion	mg/kg	0.05	< 0.05	< 0.05	nc nc	< 0.05	< 0.2	nc nc				< 0.05	< 0.05	nc nc	< 0.05	< 0.05	nc nc	< 0.05	< 0.05	nc nc
Carbophenothion	mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	nc	<0.05 <0.05	<0.2 <0.2	nc				<0.05 <0.05	<0.05 <0.05	nc	<0.05 <0.05	<0.05 <0.05	nc	<0.05 <0.05	<0.05 <0.05	nc
zinphos Methyl	mg/kg	0.05	<0.05	<0.05	nc	< 0.05	<0.2	nc				<0.05	<0.05	nc	< 0.05	<0.05	nc	< 0.05	<0.05	nc
PO75(SIM)A: Phenolic Compounds henol	mg/kg	0.5	<0.5	<0.5	nc	<0.5	<0.5	nc				<0.5	<0.5	nc	<0.5	<0.5	nc	<0.5	<0.5	nc
Chlorophenol Methylphenol	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc				<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
- & 4-Methylphenol	mg/kg	1	<1	<1	nc	<1	< 1	nc				<1	<1	nc	<1	<1	nc	<1	<1	nc
-Nitrophenol .4-Dimethylphenol	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc				<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
.4-Dichlorophenol .6-Dichlorophenol	mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5	nc				<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
-Chloro-3-methylphenol 4.6-Trichlorophenol	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc				<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
4.5-Trichlorophenol	mg/kg	0.5	< 0.5	< 0.5	nc	< 0.5	< 0.5	nc				< 0.5	< 0.5	nc	< 0.5	< 0.5	nc	< 0.5	< 0.5	nc
entachlorophenol	mg/kg	2	<2	<2	nc	<2	< 1	nc				<2	<2	nc	<2	<2	nc	<2	<2	nc
PO75(SIM)B: Polynuclear Aromatic Hydrocarbons aphthalene	mg/kg	0.5	<0.5	<0.5	nc	<0.5	< 0.5	nc	<0.5	<0.5	nc	<0.5	<0.5	nc	<0.5	<0.5	nc	<0.5	<0.5	nc
cenaphthylene cenaphthene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	< 0.5 < 0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
luorene	mg/kg	0.5	< 0.5	< 0.5	nc	< 0.5	< 0.5	nc	<0.5	< 0.5	nc	< 0.5	< 0.5	nc	< 0.5	< 0.5	nc	< 0.5	< 0.5	nc
henanthrene nthracene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	< 0.5 < 0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
luoranthene lyrene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	< 0.5 < 0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
enz(a)anthracene	mg/kg	0.5	< 0.5	< 0.5	nc	< 0.5	< 0.5	nc	< 0.5	< 0.5	nc	< 0.5	< 0.5	nc	< 0.5	< 0.5	nc	< 0.5	< 0.5	nc
hrysene enzo(b+j)fluoranthene	mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	< 0.5 < 0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
enzo(k)fluoranthene enzo(a)pyrene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	< 0.5 < 0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
ndeno(1.2.3.cd)pyrene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	< 0.5 < 0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
	. rig/ng	0.5	<0.5	< 0.5	nc	< 0.5	< 0.5	nc nc	< 0.5	<0.5 <0.5 <0.5	nc nc	<0.5 <0.5	< 0.5	nc nc	<0.5 <0.5	<0.5 <0.5 <0.5	nc nc	<0.5	< 0.5	nc nc
blenz(a.h)anthracene Senzo(g.h.i)perylene	mg/kg		-0.5	-0.5																
	mg/kg mg/kg mg/kg mg/kg	0.5 0.5 0.6	<0.5 <0.5 0.6	<0.5 <0.5 0.6	nc nc 0.0	<0.5 <0.5 0.6	< 0.5 < 0.5 0.6	nc 0.0	<0.5 <0.5 0.6	<0.5 0.6	nc 0.0	<0.5 <0.6	<0.5 <0.5 0.6	nc 0.0	<0.5 <0.6	<0.5 0.6	nc 0.0	<0.5 <0.5 0.6	<0.5 <0.5 0.6	nc 0.0



	Sample Type: ALS Sample number: Sample date: Sample ID:	ALS ES1609685004 04/05/2016 006_TP002_0.10	ALS ES1609685013 04/05/2016 006_QC001		ALS ES1609685004 04/05/2016 006_TP002_0.10	MGT S16-My06722 499536 04/05/2016 006_QC002		ALS ES1609680002 04/05/2016 026_TP001_0.50	ALS ES1609680004 04/05/2016 026_QC001		ALS ES1609686002 05/05/2016 028_TP001_0.50	ALS ES1609686010 05/05/2016 028_0C001		ALS ES1610404001 11/05/2016 006_GW004_0.2	ALS ES1610406011 11/05/2016 006_QC004		ALS ES1610404005 11/05/2016 006_GW005_0.2	ALS ES1610406010 11/05/2016 006_QC003	
	Project Name: Compound: Site: Sampling Method: Sample Description	M4E-WCX Northcote Street Tunnel Site Site 006 Test Pitting	M4E-WCX Northcote Street Tunnel Site Site 006 Test Pitting Duplicate of	RPD	M4E-WCX Northcote Street Tunnel Site Site 006 Test Pitting	M4E-WCX Northcote Street Tunnel Site Site 006 Test Pitting Triplicate of	RPD	M4E-WCX Northcote Street Tunnel Site Site 026 Test Pitting	M4E-WCX Northcote Street Tunnel Site Site 026 Test Pitting Duplicate of	RPD	M4E-WCX Northcote Street Tunnel Site Site 028 Test Pitting	M4E-WCX Northcote Street Tunnel Site Site 028 Test Pitting Duplicate of	RPD	M4E-WCX Northcote Street Tunnel Site Site 006 Drilling	M4E-WCX Northcote Street Tunnel Site Site 006 Drilling Duplicate of	RPD	M4E-WCX Northcote Street Tunnel Site Site 006 Drilling	M4E-WCX Northcote Street Tunnel Site Site 006 Drilling Duplicate of	RPD
EP080/071: Total Petroleum Hydrocarbons	Sample Bessi ipilon	PRIMARY	006_TP002_0.1		PRIMARY	006_TP002_0.1		PRIMARY	026_TP001_0.5		PRIMARY	028_TP001_0.5		PRIMARY	006_GW004_0.2		PRIMARY	006_GW005_0.2	
C6 - C9 Fraction C10 - C14 Fraction	mg/kg 10 mg/kg 50	<10 <50	<10 <50	nc nc	<10 <50	< 20 < 20	nc nc	<10 <50	<10 <50	nc nc	<10 <50	<10 <50	nc nc	<10 <50	<10 <50	nc nc	<10 <50	<10 <50	nc nc
C15 - C28 Fraction C29 - C36 Fraction	mg/kg 100	<100 <100	<100 <100	nc nc	<100 <100	<50 <50	nc nc	<100 <100	<100 <100	nc nc	<100 <100	<100 <100	nc nc	<100 <100	<100 <100	nc nc	<100 <100	<100 <100	nc nc
C10 - C36 Fraction (sum)	mg/kg 100 mg/kg 50	<50	< 50 < 50	nc	< 100 < 50	<50 <50	nc	< 100 < 50	< 100 < 50	nc	< 50 < 50	< 100 < 50	nc	<50 <50	<50	nc	< 100 < 50	< 50 < 50	nc
EP080/071: Total Recoverable Hydrocarbons - NEPM 2013																			
C6 - C10 Fraction C6 - C10 Fraction minus BTEX (F1)	mg/kg 10 mg/kg 10	<10 <10	<10 <10	nc nc	<10 <10	< 20 < 20	nc nc	<10 <10	<10 <10	nc nc	<10 <10	<10 <10	nc nc	<10 <10	<10 <10	nc nc	<10 <10	<10 <10	nc nc
>C10 - C16 Fraction >C16 - C34 Fraction (F3)	mg/kg 50 mg/kg 100	<50 <100	<50 <100	nc nc	<50 <100	< 50 < 100	nc nc	<50 <100	<50 <100	nc nc	<50 <100	<50 <100	nc nc	<50 <100	<50 <100	nc nc	<50 <100	<50 <100	nc nc
>C34 - C40 Fraction (F4) >C10 - C40 Fraction (sum)	mg/kg 100	<100	<100	nc	<100	< 100	nc	<100	<100	nc nc	<100	<100	nc nc	<100	<100	nc	<100	<100	nc nc
>C10 - C16 Fraction (sum)	mg/kg 50 mg/kg 50	<50 <50	<50 <50	nc nc	<50 <50	< 50	nc	<50 <50	<50 <50	nc	<50 <50	<50 <50	nc	<50 <50	<50 <50	nc nc	<50 <50	<50 <50	nc
EP080: BTEXN																			
Benzene Toluene	mg/kg 0.2 mg/kg 0.5	<0.2 <0.5	<0.2 <0.5	nc nc	<0.2 <0.5	< 0.1 < 0.1	nc nc	<0.2 <0.5	<0.2 <0.5	nc nc	<0.2 <0.5	<0.2 <0.5	nc nc	<0.2 <0.5	<0.2 <0.5	nc nc	<0.2 <0.5	<0.2 <0.5	nc nc
Ethylbenzene meta- & para-Xylene	mg/kg 0.5 mg/kg 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	< 0.1 < 0.2	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
ortho-Xylene Total Xylenes	mg/kg 0.5	<0.5 <0.5	<0.5 <0.5	nc	<0.5 <0.5	< 0.1 < 0.3	nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc
Sum of BTEX Naohthalene	mg/kg 0.2	< 0.2	< 0.2	nc nc	< 0.2		nc 	< 0.2	< 0.2	nc	< 0.2	< 0.2	nc	< 0.2	< 0.2	nc	< 0.2	< 0.2	nc nc
	mg/kg 1	<1	<1	nc	<1	<0.5	nc	<1	<1	nc	<1	<1	nc	<1	<1	nc	<1	<1	nc
EP074A: Monocyclic Aromatic Hydrocarbons Styrene	mg/kg 0.5													<0.5	< 0.5	nc	<0.5	< 0.5	nc
Isopropylbenzene n-Propylbenzene	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
1.3.5-Trimethylbenzene sec-Butylbenzene	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
1.2.4-Trimethylbenzene	mg/kg 0.5												****	< 0.5	< 0.5	nc	< 0.5	< 0.5	nc nc
tert-Butylbenzene p-Isopropyltoluene	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc	<0.5 <0.5	<0.5 <0.5	nc
n-Butylbenzene	mg/kg 0.5													<0.5	< 0.5	nc	<0.5	< 0.5	nc
EP074B: Oxygenated Compounds Vinyl Acetate	mg/kg 5													<5	<5	nc	<5	<5	nc
2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK)	mg/kg 5			****									****	<5 <5	<5 <5	nc nc	<5 <5	<5 <5	nc nc
2-Hexanone (MBK)	mg/kg 5 mg/kg 5													<5	<5	nc	<5	<5	nc
EP074C: Sulfonated Compounds Carbon disulfide EP074D: Fumigants	mg/kg 0.5													<0.5	<0.5	nc	<0.5	<0.5	nc
2.2-Dichloropropane	mg/kg 0.5													<0.5	<0.5	nc	<0.5	< 0.5	nc
1.2-Dichloropropane cis-1.3-Dichloropropylene	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB)	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
EP074E: Halogenated Aliphatic Compounds																			
Dichlorodifluoromethane Chloromethane	mg/kg 5 mg/kg 5												****	<5 <5	<5 <5	nc nc	<5 <5	<5 <5	nc nc
Vinyl chloride Bromomethane	mg/kg 5													<5	<5	nc	<5	<5	nc
Chloroethane	mg/kg 5 mg/kg 5													<5 <5	<5 <5	nc nc	<5 <5	<5 <5	nc nc
Trichlorofluoromethane 1.1-Dichloroethene	mg/kg 5 mg/kg 0.5													<5 <0.5	<5 <0.5	nc nc	<5 <0.5	<5 <0.5	nc nc
Iodomethane trans-1.2-Dichloroethene	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
1.1-Dichloroethane cis-1.2-Dichloroethene	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
1.1.1-Trichloroethane 1.1-Dichloropropylene	mg/kg 0.5													< 0.5	<0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc
Carbon Tetrachloride	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc	< 0.5	< 0.5	nc nc
1.2-Dichloroethane Trichloroethene	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
Dibromomethane 1.1.2-Trichloroethane	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
1.3-Dichloropropane Tetrachloroethene	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
1.1.1.2-Tetrachloroethane trans-1.4-Dichloro-2-butene	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
cis-1.4-Dichloro-2-butene 1.1.2.2-Tetrachloroethane	mg/kg 0.5													< 0.5	< 0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
1.2.3-Trichloropropane	mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc	< 0.5	< 0.5	nc
Pentachloroethane 1.2-Dibromo-3-chloropropane	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
Hexachlorobutadiene	mg/kg 0.5													<0.5	<0.5	nc	<0.5	<0.5	nc
EP074F: Halogenated Aromatic Compounds Chlorobenzene	mg/kg 0.5													<0.5	<0.5	nc	<0.5	<0.5	nc
Bromobenzene 2-Chlorotoluene	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
4-Chlorotoluene	mg/kg 0.5													< 0.5	< 0.5	nc	< 0.5	< 0.5	nc
1.3-Dichlorobenzene 1.4-Dichlorobenzene	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
1.2-Dichlorobenzene 1.2.4-Trichlorobenzene	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
1.2.3-Trichlorobenzene	mg/kg 0.5													<0.5	<0.5	nc	<0.5	<0.5	nc
EP074G: Trihalomethanes Chloroform	mg/kg 0.5													<0.5	<0.5	nc	<0.5	<0.5	nc
Bromodichloromethane Dibromochloromethane	mg/kg 0.5 mg/kg 0.5													<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
Bromoform	mg/kg 0.5													<0.5	<0.5	nc	<0.5	<0.5	nc
EP074H: Naphthalene		T	1		1			1			<u> </u>						I		
Naphthalene	mg/kg 1													<1	<1	nc	<1	<1	nc

March March Control	25/11/2016		Northcote Compound Site 006											
Column		1	i	1				S16-My28529				ALS ES1611421010		
Part		Sample dat	e:	24/05/2016	24/05/2016		24/05/2016	24/05/2016		23/05/2016	24/05/2016	24/05/2016		
Column				M4E-WCX	M4E-WCX		M4E-WCX	M4E-WCX		M4E-WCX	M4E-WCX	000_QA002 M4E-WCX		
Mary		Compound	:	STREET TUNNEL	STREET TUNNEL	RPD	STREET TUNNEL	STREET TUNNEL	RPD	STREET TUNNEL	STREET TUNNEL	NORTHCOLE STREET TUNNEL		
Part		Site:								SITE 006 / 012/	SITE 006 / 012/	SITE SITE 006 / 012/		
West														
Column	Analyte grouping/Analyte	_		PRIMARY			PRIMARY			TRIP SPIKE	TRIP BLANK	TRIP BLANK		
Service 1,00	EG020T: Dissolved Metals by ICP-MS													
March	Cadmium	μg/L		<0.1	<0.1	nc	< 0.1	0.2	nc					
Section 1982 1982 1982 1982 1982 1982 1982 1982														
1985 1985														
Company Comp	Zinc	μg/L	1	50	52	3.9	50	48	4.1					
College		μg/L	0.1	<0.1	<0.1	nc	<0.1	<0.1	nc					
State														
Fig. 1. Fig.	EP068A: Organochlorine Pesticides (OC)													
Service 160 15	Hexachlorobenzene (HCB)	μg/L	0.5	<0.5	<0.5	nc	< 0.5							
Second 196	gamma-BHC	μg/L	0.5	< 0.5	<0.5	nc	< 0.5							
Tacasta public 190 25 25 25 25 25 25 25 2	Heptachlor	μg/L	0.5	< 0.5	<0.5	nc	< 0.5							
Add			0.5	< 0.5	< 0.5		< 0.5							
Selection 100 55 75 75 75 75 75 75														
1 - 1707	Dieldrin	μg/L	0.5	< 0.5	<0.5	nc	< 0.5							
Service of the control of the contro		μg/L				nc								
Color		μg/L	0.5	< 0.5	<0.5		< 0.5							
4.4 COL	Endrin aldehyde	μg/L	0.5	< 0.5	<0.5	nc	< 0.5							
Management	4.4`-DDT	μg/L	2	2	2	nc	2							
Separation 1964	Methoxychlor ^ Total Chlordane (sum)	μg/L μg/L	2 0.5	2 <0.5	2 <0.5	nc nc	2 <0.5							
Commons	^ Sum of DDD + DDE + DDT	μg/L				nc								
Company										<u> </u>				
Commons	Demeton-S-methyl	μg/L	0.5	<0.5	<0.5	nc	<0.5							
Controlled 197	Dimethoate	μg/L	0.5	< 0.5	<0.5	nc	< 0.5							
Second	Chlorpyrifos-methyl	μg/L	0.5	<0.5	<0.5	nc	< 0.5							
Comparison	Malathion	μg/L	0.5	<0.5	<0.5	nc	< 0.5							
Company	Chlorpyrifos				<0.5		< 0.5							
Secretary (1971 1971 1971 1972														
Section 1,97														
Color	Prothiofos		0.5	< 0.5	<0.5		< 0.5							
Secretary Secr	Carbophenothion		0.5	<0.5	<0.5		< 0.5							
Section Sect		μg/L	0.5	<0.5	<0.5	nc	<0.5							
Proping processor 1946 5 15 15 15 15 15 15 15	Styrene													
100 100	n-Propylbenzene	μg/L	5	<5			<5							
June	sec-Butylbenzene	μg/L	5	<5			<5							
Contention	tert-Butylbenzene	μg/L	5	<5			<5							
Spingeres (MES)	n-Butylbenzene	μg/L	5	<5			<5							
2-bisotron (BIRD)	2-Butanone (MEK)	μg/L	50	< 50			<50							
2.2-Conforcerographic ppt 5	2-Hexanone (MBK)			< 50			< 50							
Self 3-DECRIFICATION 1984 5 5 5 5 5 5 5 5 5														
Page 1.5														
District Grant District Dis														
Signmentane														
Chiscoenhane	Vinyl chloride	μg/L	50 50	<50 <50			<50 <50							
13-Deciderorenthene	Trichlorofluoromethane	μg/L μg/L	50	<50			< 50							
Trans-1 2-Dichloroesthene	1.1-Dichloroethene	μg/L	5	<5 <5			<5							
18.1 2. Dischlaropethene 1981 5 5 5	trans-1.2-Dichloroethene	μg/L		<5			<5							
13-Delitroproprient	cis-1.2-Dichloroethene 1.1.1-Trichloroethane	μg/L	5	<5			<5							
1.2-Dichrosehane	1.1-Dichloropropylene Carbon Tetrachloride	μg/L	5	<5 <5			<5 <5							
11.2-Trichloroethane	Trichloroethene	μg/L μg/L	5	<5			<5							
Telephoropethene	1.1.2-Trichloroethane	μg/L	5	<5			<5							
Trans-14-Dichloro-2-butene	Tetrachloroethene	μg/L	5	<5			<5							
1.1.2.2-Tetrachioropetane	trans-1.4-Dichloro-2-butene	μg/L	5	<5			<5							
Pentachloroethane	1.1.2.2-Tetrachloroethane	μg/L	5	<5			<5							
Hexachtorobutadiene	Pentachloroethane	μg/L	5	<5			<5							
Bromolenzene	Hexachlorobutadiene	μg/L	5	<5			<5							
4-Chlorotolusne μg/L 5 <5 <5	Bromobenzene	μg/L	5	<5			<5							
1.4-Dichlorobenzene pg/L 5 <5 <5	4-Chlorotoluene	μg/L	5	<5			<5							
1.2.4-Trichlorobenzene	1.4-Dichlorobenzene	μg/L	5	<5			<5							
Chloroform Pig/L 5 S S S S S S S S S	1.2.4-Trichlorobenzene	μg/L	5	<5			<5							
Dibromochloromethane Pg/L 5 S S S S S S S S S	Chloroform	μg/L	5	<5			<5							
Naphthalene Pg/L 5 C5 C5	Dibromochloromethane	μg/L	5	<5			<5							
Phenol μg/L 1 <1.0 <1.0 nc <1.0														
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$		μg/L	1	<1.0	<1.0	nc	<1.0							
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	2-Chlorophenol 2-Methylphenol	μg/L μg/L	1	<1.0 <1.0	<1.0 <1.0	nc nc	<1.0 <1.0							
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	2-Nitrophenol	μg/L	1	<1.0	<1.0	nc	<1.0							
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	2.4-Dichlorophenol	μg/L		<1.0 <1.0	<1.0 <1.0	nc	<1.0							
2.4.5-Trichlorophenol µg/L 1 <1.0 <1.0 nc <1.0	2.6-Dichlorophenol 4-Chloro-3-methylphenol	μg/L μg/L	1 1	<1.0 <1.0	<1.0 <1.0	nc nc	<1.0 <1.0							
Pentachiorophenol µg/L 2 2 2 0.0 2	2.4.5-Trichlorophenol	μg/L	1	<1.0	<1.0	nc	<1.0							
	Pentachlorophenol	μg/L	2	2	2	0.0	2							


Table 6: QA/QC Groundwater Sampling Results Northcote Compound Site 006



Г	Sample Typ	ne:	ALS	ALS	ı	ALS	MGT	ı	ALS	ALS	ALS
	ALS Sample		ES1611420002	ES1611420007		ES1611420002	S16-My28529		ES1611420009	ES1611420010	ES1611421010
	Sample dat		24/05/2016	24/05/2016		24/05/2016	502339 24/05/2016	<u> </u>	23/05/2016	24/05/2016	24/05/2016
	Sample ID:		006_GW005	006_QC100		006_GW005	006_QC101	ł	000_QA003	000_QA004	000_QA002
	Project Na		M4E-WCX	M4E-WCX		M4E-WCX	M4E-WCX	t	M4E-WCX	M4E-WCX	M4E-WCX
	Froject ival	ille.	NORTHCOLE	NORTHCOLE	RPD	NORTHCOLE	NORTHCOLE	RPD	NORTHCOLE	NORTHCOLE	NORTHCOLE
	Compound	:	STREET TUNNEL SITE GME	STREET TUNNEL SITE GME	RPD	STREET TUNNEL SITE GME	STREET TUNNEL SITE GME	RPD	STREET TUNNEL SITE GME	STREET TUNNEL SITE GME	STREET TUNNEL SITE
	Site:		SITE 006	SITE 006		SITE 006	SITE 006		SITE 006 / 012/ 026/ 027	SITE 006 / 012/ 026/ 027	SITE 006 / 012/ 026/ 027
	Sampling N	/lethod:	Bailer	Bailer		Bailer	Bailer	†	020/ 02/	020/ 02/	020/ 02/
	Sample Des	scription	PRIMARY	DUPLICATE OF		PRIMARY	TRIPLICATE OF		TRIP SPIKE	TRIP BLANK	TRIP BLANK
Analyte grouping/Analyte	Units	LOR	1	006_GW005	l .	I.	006_GW005	l .	1		<u> </u>
ranalyte grouping/ranalyte	00	LOIN									
EP075(SIM)B: Polynuclear Aromatic Hyd	rocarbons										
Naphthalene	μg/L	1	<1.0	<1.0	nc	<1.0					
Acenaphthylene	μg/L	1	<1.0	<1.0	nc	<1.0					
Acenaphthene	μg/L	1	<1.0	<1.0	nc	<1.0					
Fluorene	μg/L	1	<1.0	<1.0	nc	<1.0					
Phenanthrene	μg/L	1	<1.0	<1.0	nc	<1.0					
Anthracene	μg/L	1	<1.0	<1.0	nc	<1.0					
Fluoranthene	μg/L	1	<1.0	<1.0	nc	<1.0					
Pyrene	μg/L	1	<1.0	<1.0	nc	<1.0					
Benz(a)anthracene	μg/L	1	<1.0	<1.0	nc	<1.0					
Chrysene Repro/h. influerenthene	μg/L	1	<1.0 <1.0	<1.0 <1.0	nc nc	<1.0 <1.0					
Benzo(b+j)fluoranthene Benzo(k)fluoranthene	μg/L μg/L	1	<1.0	<1.0	nc	<1.0					
Benzo(a)pyrene	μg/L	0.5	<0.5	<0.5	nc	<0.5					
Indeno(1.2.3.cd)pyrene	μg/L	1	<1.0	<1.0	nc	<1.0					
Dibenz(a.h)anthracene	μg/L	1	<1.0	<1.0	nc	<1.0					
Benzo(q.h.i)perylene	µg/L	1	<1.0	<1.0	nc	<1.0					
Sum of polycyclic aromatic hydrocarbons	μg/L	0.5	<0.5	<0.5	nc	< 0.5					
Benzo(a)pyrene TEQ (zero)	μg/L	0.5	< 0.5	< 0.5	nc	< 0.5					
EP080/071: Total Petroleum Hydrocarbo											
C6 - C9 Fraction	μg/L	20	20	20	0.0	20	20	nc	190	20	20
C10 - C14 Fraction	μg/L	50	< 50	<50	nc	<50				<50	
C15 - C28 Fraction	μg/L	100	<100	<100	nc	<100				<100	
C29 - C36 Fraction	μg/L	50	< 50	<50	nc	<50				<50	
C10 - C36 Fraction (sum)	μg/L	50	< 50	<50	nc	<50				<50	
EP080/071: Total Recoverable Hydrocart	bons - NEPM	2013 Fract	ions			<u> </u>	<u> </u>		<u> </u>		<u> </u>
C6 - C10 Fraction	µg/L	20	20	20	0.0	20			210	20	20
C6 - C10 Fraction minus BTEX (F1)	µg/L	20	20	20	0.0	20			130	20	20
>C10 - C16 Fraction	μg/L	100	<100	<100	nc	<100				<100	
>C16 - C34 Fraction	μg/L	100	<100	<100	nc	<100				<100	
>C34 - C40 Fraction	μg/L	100		<100						<100	
>C10 - C40 Fraction (sum)	μg/L	100		<100						<100	
>C10 - C16 Fraction minus Naphthalene (F2)	μg/L	100		<100						<100	
					L	L	L	L			L
EP080: BTEXN				1						1	
Benzene	μg/L	1		<1			<1		15	<1	<1
Toluene	μg/L	2		2			<1		14	2	2
Ethylbenzene	μg/L	2		_			<1		16	2	_
meta- & para-Xylene	μg/L μg/L	2		2			2 <1		16 16	2	2
ortho Vylono							< 1		10		
ortho-Xylene						1	- 3		22	2	2
ortho-Xylene Total Xylenes Sum of BTEX	µg/L µg/L	2		2 <1			<3		32 77	2 <1	2 <1

nc = not calculated since results < LOR
LOR = Laboratory Limit of Reporting
BOLD identifies where RPD results
Intralaboratory Interlaboratory
>50 >60 yeb







Project No: AS121919 Client Name: CSJ Project Name: Phase 2 ESA Project Site: 012

Well ID	Easting	Northing	Gauging	Total Well Depth	SWL	TOC Elevation	Groundwater Elevation
	3	3	Date	(m btoc)	(m btoc)	(mAHD)	(mAHD)
012_GW001	327076.13	6249959.79	5/24/2016	9.49	4.59	15.05	10.46

Notes

m = Metres

btoc = Below Top of Casing

SWL = Standing Water Level

TOC = Top of Casing

AHD = Australian Height Datum

Easting projection MGA94: Map Grid of Australia 1994



Project No: AS121919 Client Name: CSJ Project Name: Phase 2 ESA

Project Site: 012

Well ID	Purge Date	Purge Vol (L)	DO (ppm)	EC (mScm-1)	рН	Eh (mV)	Temperature (°C)	Comments
012_GW001	24/05/2016	2.5	0.37	5.78	5.35	90	20.7	moderately turbid, no observed contamination

Notes

L = Litre

DO = Dissolved Oxygen

ppm = parts per million

EC = Electrical Conductivity

mScm-1 = milliSiemens per centimetre

Eh = Redox

mV = milli Volts

					Site	012								
											Sample Type	: -	SOIL	SOIL
											ALS Sample I		ES1610404013 10/05/2016	ES1610404014 10/05/2016
											Sample ID:		012_GW001_0.2	012_GW001_0.5
	NEPM 2013	NEPM 2013	NEPM 2013	NEPM 2013	NEPM 2013	NEPM 2013	NEPM 2013	NEPM 2013		CRC CARE	Project Name Compound:	3 :	M4E-WCX Northcote Street	M4E-WCX Northcote Street
	HIL D	Soil Vapour	Soil Vapour Intrusion HSL	Soil Vapour	Soil Vapour	EIL	ESL ²	Management Limits	CRC CARE 2011 Direct	2011 Direct			Tunnel Site	Tunnel Site
	Commercial / Industrial		D Sand ¹ 1-2m	Intrusion HSL D Sand ¹ 2-4m	Intrusion HSL D Sand ¹ 4+m	Commercial / Industrial	Commercial / Industrial	Commercial/ Industrial ³	Contact HSL D⁴	Contact HSL for Workers ⁴	Site: Sampling Me	thod:	Site 012 Drilling	Site 012 Drilling
								industriai			Sample Desc		Drining	Drilling
												l	FILL; sandy clay,	CLAY, light brown/grey mottled,
													brown	low plasticity, dry
Analyte grouping/Analyte											Units	LOR	Щ	
EA055: Moisture Content											Omts	LOK		
Moisture Content (dried @ 103°C)											%		15.7	12.7
EA200: AS 4964 - 2004 Identification of Asbestos in Soils													Ш	
Asbestos Detected Asbestos Type											g/kg 		No	No -
Sample weight (dry)											g		209	173
													Mid brown clay soil with grey	Mid brown clay soil with grey
Description APPROVED IDENTIFIER:													rocks. S.SPOONER	rocks. S.SPOONER
													3.51 GOINEK	S.SI GOIVER
EG005T: Total Metals by ICP-AES Arsenic	3000					160					mg/kg	5	14	21
Cadmium Chromium	900 3600					310					mg/kg mg/kg	2	<1 29	<1 32
Copper Lead	240000 1500					150 1800					mg/kg mg/kg	5 5	21 228	153 438
Nickel	6000					60					mg/kg	2	5	6
Zinc	400000					30 0					mg/kg	5	66	420
EG035T: Total Recoverable Mercury by FIMS Mercury	730					1					mg/kg	0.1	<0.1	<0.1
	730										mg/kg	0.1	30.1	VO. 1
EP066: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls	7										mg/kg	0.1		
EP075(SIM)A: Phenolic Compounds														
Phenol 2-Chlorophenol	240000										mg/kg	0.5	<0.5 <0.5	<0.5 <0.5
2-Methylphenol											mg/kg mg/kg	0.5	< 0.5	< 0.5
3- & 4-Methylphenol 2-Nitrophenol	25000										mg/kg mg/kg	1 0.5	<1 <0.5	<1 <0.5
2.4-Dichlorophenol										_	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5
2.6-Dichlorophenol											mg/kg	0.5	< 0.5	< 0.5
4-Chloro-3-methylphenol 2.4.6-Trichlorophenol											mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5
2.4.5-Trichlorophenol Pentachlorophenol	660									_	mg/kg mg/kg	0.5	<0.5 <2	<0.5 <2
	990										mg/Kg		<u> </u>	<u> </u>
EP075(SIM)B: Polynuclear Aromatic Hydrocarbons Naphthalene		NL	NL	NL	NL	370			11000	29000	mg/kg	0.5	<0.5	<0.5
Acenaphthylene Acenaphthene				_				_			mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5
Fluorene											mg/kg	0.5	< 0.5	< 0.5
Phenanthrene Anthracene											mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5
Fluoranthene Pyrene											mg/kg mg/kg	0.5 0.5	<0.5 <0.5	1.2
Benz(a)anthracene Chrysene			-	-					-		mg/kg mg/kg	0.5 0.5	<0.5 <0.5	0.8
Benzo(b+j)fluoranthene											mg/kg	0.5	< 0.5	1
Benzo(k)fluoranthene Benzo(a)pyrene							72				mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 0.9
Indeno(1.2.3.cd)pyrene Dibenz(a.h)anthracene											mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5
Benzo(g.h.i)perylene											mg/kg	0.5	< 0.5	0.6
Sum of polycyclic aromatic hydrocarbons Benzo(a)pyrene TEQ (zero)	4000										mg/kg mg/kg	0.5 0.5	<0.5 <0.5	6.7 1.1
Benzo(a)pyrene TEQ (half LOR) Benzo(a)pyrene TEQ (LOR)	40										mg/kg mg/kg	0.6 1.2	0.6 1.2	1.4 1.7
EP080/071: Total Petroleum Hydrocarbons														
C6 - C9 Fraction											mg/kg	10	<10	<10
C10 - C14 Fraction C15 - C28 Fraction											mg/kg mg/kg	50 100	<50 <100	<50 <100
C29 - C36 Fraction C10 - C36 Fraction (sum)											mg/kg mg/kg	100 50	<100 <50	<100 <50
EP080/071: Total Recoverable Hydrocarbons - NEPM 2013 Frac	ctions												П	
C6 - C10 Fraction C6 - C10 Fraction minus BTEX (F1)		260	370	630	NII		215	700	26000	82000	mg/kg	10	<10 <10	<10 <10
>C10 - C16 Fraction		NL NL	NL	NL NL	NL NL		170	1000	20000	62000	mg/kg mg/kg	10 50	<50	<50
>C16 - C34 Fraction (F3) >C34 - C40 Fraction (F4)							1700 3300	3500 10000	27000 38000	85000 120000	mg/kg mg/kg	100 100	<100 <100	<100 <100
>C10 - C40 Fraction (sum) >C10 - C16 Fraction minus Naphthalene (F2)		NL	NL	NL	NL						mg/kg mg/kg	50 50	<50 <50	<50 <50
											g/kg			100
EPO80: BTEXN Benzene		3	NL	NL	NL		75		430	1100	mg/kg	0.2	<0.2	<0.2
Toluene Ethylbenzene		NL NL	NL NL	NL NL	NL NL		135 165		99000 27000	120000 85000	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5
meta- & para-Xylene ortho-Xylene							95					0.5	< 0.5	<0.5 <0.5
Total Xylenes		230	NL	NL	NL						mg/kg mg/ka	() 5	<0 F	
Sum of BTEX Naphthalene	 			IVL					81000	130000	mg/kg mg/kg	0.5	<0.5 <0.5	< 0.5
EP074A: Monocyclic Aromatic Hydrocarbons		NL	NL	NL	NL	370			81000 11000	130000	mg/kg			
		NL			NL	370					mg/kg mg/kg mg/kg mg/kg	0.5 0.2 1	<0.5 <0.2 <1	<0.5 <0.2 <1
Styrene Isopropylbenzene		NL			NL	370					mg/kg mg/kg mg/kg	0.5 0.2	<0.5 <0.2	<0.5 <0.2
Isopropylbenzene n-Propylbenzene		NL			NL	370					mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg	0.5 0.2 1 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene		NL			NL	370					mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kq mg/kq mg/kq mg/kq	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tet-Butylbenzene		NL			NL	370					mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kq mg/kq mg/kq	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene		NL			NL	370					mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.2 <1 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene		NL			NL	370					mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene EP074B: Oxygenated Compounds Vinyl Acetate		NL			NL	370					mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kq mg/kq mg/kq mg/kq mg/kq mg/kq mg/kg mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK)		NL			NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK)		NL			NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene sec-Butylbenzene sec-Butylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene EP074B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EP074C: Sulfonated Compounds		NL			NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide		NL			NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO74D: Fumigants 2.2-Dichloropropane		NL			NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene sec-Butylbenzene sec-Butylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene EP074B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EP074C: Sulfonated Compounds Carbon disulfide EP074D: Fumigants		NL			NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO74D: Fumigants 2.2-Dichloropropane 1.2-Dichloropropylene trans-1.3-Dichloropropylene		NL			NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene sec-Butylbenzene sec-Butylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene EP074B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EP074C: Sulfonated Compounds Carbon disulfide EP074D: Fumigants 2.2-Dichloropropane 1.2-Dichloropropylene trans-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB)		NL			NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butlylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO74D: Fumigants 2.2-Dichloropropane 1.2-Dichloropropane 1.2-Dichloropropape cis-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dichloropropophene 1.2-Dichloropropylene 1.2-Dichloroprophene		NL NL			NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO34D: Fumigants 2.2-Dichloropropane 1.2-Dichloropropane trans-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB) EPO74E: Halogenated Aliphatic Compounds Dichlorodifluoromethane Chloromethane		NL NL			NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butlylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO74D: Fumigants 2.2-Dichloropropane 1.2-Dichloropropane 1.2-Dichloropropape cis-1.3-Dichloropropylene trans-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB) EPO74E: Halogenated Aliphatic Compounds Dichlorodifluoromethane Chloromethane Vinyl chloride Bromomethane		NL NL			NL NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene P-Borropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO74D: Fumigants 2.2-Dichloropropane 1.2-Dichloropropane 1.2-Dichloropropane 1.2-Dichloropropylene trans-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB) EPO74E: Halogenated Aliphatic Compounds Dichlorodifluoromethane Chloromethane Vinyl chloride Bromomethane Chlorothane Trichlorofluoromethane Chlorotethane Trichlorofluoromethane		NL NL			NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO74D: Fumigants 2.2-Dichloropropane 1.2-Dichloropropane 1.2-Dichloropropylene trans-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB) EPO74E: Halogenated Aliphatic Compounds Dichlorodifluoromethane Chloromethane Vinyl chloride Bromomethane Chlorodethane		NL NL			NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene P-Borropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO74D: Fumigants 2.2-Dichloropropane 1.2-Dichloropropane 1.2-Dichloropropane 1.2-Dichloropropylene trans-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB) EPO74E: Halogenated Aliphatic Compounds Dichlorodifluoromethane Chloroethane Chloroethane Chloroethane Trichlorofluoromethane 1.1-Dichloroethene Indomethane Indom		NL NL			NL NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene P-Borropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO74D: Fumigants 2.2-Dichloropropane 1.2-Dichloropropane cis-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB) EPO74E: Halogenated Aliphatic Compounds Dichlorodifluoromethane Chloromethane Vinyl chloride Bromomethane Trichlorofluoromethane		NL NL			NL NL	370					mg/kg	0.5 0.2 1 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene P-Isopropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO74D: Fumigants 2.2-Dichloropropane 1.2-Dichloropropane cis-1.3-Dichloropropylene trans-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromethane (EDB) EPO74E: Halogenated Aliphatic Compounds Dichlorodifluoromethane Chloromethane Vinyl chloride Bromomethane Chloroethane Trichlorofluoromethane Chloroethane Trichlorofluoromethane In-Dichloroethene Iodomethane Itans-1.2-Dichloroethene Iodomethane Itans-1.2-Dichloroethene Iodomethane Itans-1.2-Dichloroethene In-Dichloroethane		NL			NL NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene p-Isopropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO74D: Fumigants 2.2-Dichloropropane 1.2-Dichloropropane cis-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB) EPO74E: Halogenated Aliphatic Compounds Dichlorodifluoromethane Vinyl chloride Bromomethane Vinyl chloride Bromomethane Trichlorofluoromethane Trichlorothane Trans-1.2-Dichloroethene 1.1-Dichloroethane T.1-Trichloroethane T.1-Trichloroethane T.1-Trichloroethane T.1-Trichloroethane T.1-Trichloroethane T.1-Trichloroethane T.1-Trichloroethane T.1-Trichloroethane T.1-Trichloroethane T.1-Dichloropropylene Tarbon Tetrachloride		NL NL			NL NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene P-Borpopyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO34D: Funigants 2.2-Dichloropropane 1.2-Dichloropropane 1.2-Dichloropropane trans-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB) EPO34E: Halogenated Aliphatic Compounds Dichlorodifluoromethane Chloromethane Trichlorofluoromethane Trichlorofluoromethane I-1-Dichloroprophene Icabene Indomethane Irin-Dichloroprophene Icabene Indomethane Irin-Dichloroprophene Icabene Indomethane Indomet		NL NL			NL NL	370					mg/kg	0.5 0.2 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene P-Borropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO74D: Fumigants 2.2-Dichloropropane 1.2-Dichloropropane 1.2-Dichloropropane 1.2-Dichloropropylene trans-1.3-Dichloropropylene trans-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB) EPO74E: Halogenated Aliphatic Compounds Dichlorodifluoromethane Chloroethane Chloroethane Chloroethane 1.1-Dichloroethene 1.1-Dichloroethene 1.1-Dichloroethene 1.1-Dichloroethene 1.1-Dichloroethene 1.1-Dichloroethane cls-1.2-Dichloroethene 1.1-Dichloroethane Trichloroethane		NL NL			NL NL	370					mg/kg	0.5 0.2 1 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene P-Borropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO74D: Fumigants 2.2-Dichloropropane 1.2-Dichloropropane cis-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB) EPO74E: Halogenated Aliphatic Compounds Dichlorodifluoromethane Chloromethane Vinyl chloride Bromomethane Trichlorofluoromethane 1.1-Dichloroethene 1.1-Dichloroethene Indomethane trans-1.2-Dichloroethene 1.1-Trichloroethene 1.1-Trichloroethene 1.1-Trichloroethene 1.1-Trichloroethene 1.1-Trichloroethene 1.1-Dichloropropylene Carbon Tetrachloride 1.2-Dichloroethene Dibromomethane Trichloroethene Dibromomethane		NL NL			NL NL	370					mg/kg	0.5 0.2 1 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene p-Isopropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO74D: Funigants 2.2-Dichloropropane 1.2-Dichloropropane 1.2-Dichloropropane 1.2-Dichloropropylene trans-1.3-Dichloropropylene trans-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB) EPO74E: Halogenated Aliphatic Compounds Dichlorodifluoromethane Chloroethane Chloroethane Chloroethane 1.1-Dichloroethene 1.1-Dichloroethene 1.1-Dichloroethene 1.1-Dichloroethene 1.1-Dichloroethene 1.1-Dichloroethane cis-1.2-Dichloroethene 1.1-Dichloroethane 1.1-Dichloroethane Trichloroethane		NL NL			NL NL	370					mg/kg	0.5 0.2 1 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<pre><0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5</pre>	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene P-Borropyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO74D: Fumigants 2.2-Dichloropropane 1.2-Dichloropropane 1.2-Dichloropropane 1.2-Dichloropropane 1.2-Dibromoethane (EDB) EPO74E: Halogenated Aliphatic Compounds Dichlorodifluoromethane Chloromethane Chloromethane Trichlorofluoromethane Trichlorofluoromethane Trichlorofluoromethane Trichlorofluoromethane Trichlorofluoromethane Trichlorofluoromethane Trichlorotluoromethane Trichlorotluoromethane Trichlorotluoromethane Trichlorotluoromethane Trichlorotluoromethane Trichlorotluoromethane Trichlorotluoromethane Trichlorotluoromethane Trichlorothane		NL NL			NL NL	370					mg/kg	0.5 0.2 1 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5
Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene sec-Butylbenzene 1.2.4-Trimethylbenzene tert-Butylbenzene p-Isopropyltoluene n-Butylbenzene P-Borpopyltoluene n-Butylbenzene EPO74B: Oxygenated Compounds Vinyl Acetate 2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK) EPO74C: Sulfonated Compounds Carbon disulfide EPO74D: Fumigants 2.2-Dichloropropane 1.2-Dichloropropylene trans-1.3-Dichloropropylene trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB) EPO74E: Halogenated Aliphatic Compounds Dichlorodifluoromethane Vinyl chloride Bromomethane Vinyl chloride Bromomethane Trichloroethene 1.1-Dichloroethene 1.1-Dichloroethene trans-1.2-Dichloroethene 1.1-Dichloroethane trans-1.2-Dichloroethene 1.1-Dichloroethane trans-1.2-Dichloroethene 1.1-Dichloroethene 0ibromomethane Carbon Tetrachloride 1.2-Dichloroethene 0ibromomethane Trichloroethene Dibromomethane Trichloroethene Dibromomethane Trichloroethene Dibromomethane Trichloroethene Dibromomethane Trichloroethene Dibromomethane Tichloroethene		NL NL			NL NL	370					mg/kg	0.5 0.2 1 1 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.2 <1 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5

TABLE 4: Commercial/Industrial D - Soil Sampling Results Northcote Compound Site 012



											Sample Type	: :	SOIL	SOIL
											ALS Sample	number:	ES1610404013	ES1610404014
											Sample date	:	10/05/2016	10/05/2016
											Sample ID:		012_GW001_0.2	012_GW001_0.5
								NEDM COAC			Project Nam	e:	M4E-WCX	M4E-WCX
	NEPM 2013	NEPM 2013	NEPM 2013	NEPM 2013	NEPM 2013	NEPM 2013	NEPM 2013	NEPM 2013	CRC CARE	CRC CARE	Compound:			Northcote Street
	HIL D	Soil Vapour	Soil Vapour	Soil Vapour	Soil Vapour	EIL	ESL ²	Management Limits	2011 Direct	2011 Direct			Tunnel Site	Tunnel Site
	Commercial /		Intrusion HSL			Commercial /	Commercial /	Commercial/	Contact HSL D ⁴	Contact HSL	Site:		Site 012	Site 012
	Industrial	D Sand ¹ 0-1m	D Sand ¹ 1-2m	D Sand ¹ 2-4m	D Sand ¹ 4+m	Industrial	Industrial	Industrial 3	COINACT TISE D	for Workers ⁴	Sampling Me	thod:	Drilling	Drilling
								maastriai			Sample Desc	ription		
												·	FILL; sandy clay, brown	CLAY, light brown/grey mottled, low plasticity, dry
Analyte grouping/Analyte											Units	LOR		
1.2-Dibromo-3-chloropropane											mg/kg	0.5	< 0.5	< 0.5
Hexachlorobutadiene											mg/kg	0.5	< 0.5	< 0.5
EP074F: Halogenated Aromatic Compounds				•					•				•	
Chlorobenzene											mg/kg	0.5	< 0.5	< 0.5
Bromobenzene											mg/kg	0.5	< 0.5	< 0.5
2-Chlorotoluene											mg/kg	0.5	< 0.5	< 0.5
4-Chlorotoluene											mg/kg	0.5	< 0.5	< 0.5
1.3-Dichlorobenzene											mg/kg	0.5	< 0.5	< 0.5
1.4-Dichlorobenzene											mg/kg	0.5	< 0.5	< 0.5
1.2-Dichlorobenzene											mg/kg	0.5	< 0.5	< 0.5
1.2.4-Trichlorobenzene											mg/kg	0.5	< 0.5	< 0.5
1.2.3-Trichlorobenzene											mg/kg	0.5	< 0.5	< 0.5
EP074G: Trihalomethanes		1	1		1		1							
Chloroform				I					I		mg/kg	0.5	<0.5	<0.5
Bromodichloromethane	+	 	 		 	<u> </u>	 	<u> </u>			mg/kg	0.5	<0.5	<0.5
Dibromochloromethane											mg/kg	0.5	<0.5	<0.5
Bromoform						†	1	†			mg/kg	0.5	<0.5	<0.5
Distribution	+	 	 		 	+	 	+			Hy/ky	0.5	<0.5	<0.5
EP074H: Naphthalene		L	L	l	L	<u>l</u>	L	<u>l</u>	l					
Naphthalene		NL	NL	NL	NL	370		1	11000	29000	ma/ka	1	<1	<1
naprimaiono	+	INL	IVL	INL	IVL	370		†	11000	27000	my/ky	- '		- ` -
	1	I	I		I	<u> </u>	I	<u> </u>			1		l .	

LOR = Limit of Reporting

CRC Care Technical Report 10, September 2011 Direct Contact (DC) Health Screening Levels 'D' (Commercial/Industrial)

National Environment Protection Council (2013) National Environmental Protection (Assessment of Site Contamination) Amendment Measure 2013 (No. 1) (NEPM).

¹ (For soil texture classification undertaken in accord with AS 1726, the classifications of sand, silt and clay may be applied as coarse, fine with liquid limit <50% and fine with liquid limit>50% respectively, as the underlying properties to develop the HSLs may reasonably be selected to be similar. Where there is uncertainty, either a conservative approach may be adopted or laboratory analysis should be carried out.

² The most conservative ESL value has been adopted for all analytes

³ Management limits are applied after consideration of relevant ESLs and HSLs. Separate management limits for BTEX and naphthalene are not available hence these should not be subtracted from the relevant fractions to obtain F1 and F2.

⁴ Direct Contact are applied to surface soils or soils that could result in immediate contact.

Health Investigation Levels for chromium based on chromium (VI) Chromium (III) EIL, based on a low clay content (% clay) of 1%

Site specific EILs for copper in Italics are based on the average of soil pH, cation exchange capacity and organic content

Site specific EILs for zinc in Italics are based on the average of soil pH and cation exchange capacity

To obtain F1 subtract the sum of BTEX concentrations from the C6-C10 fraction.

To obtain F2 subtract naphthalene from the >C10-C16 fraction.

Benzo(a)Pyrene ESL adopted values based on Canadian Council of Ministers of the Environment (CCME) 2008 guidelines developed using a species sensitivity distribution (SSD) for eco-toxicity data from five independent studies involving three soil invertebrate taxa and two plant taxa (14 endpoints) in preference to NEPM low reliability data.

Concentration in red font and grey box exceed the adopted health screening value

Concentration in orange font and grey box exceed the adopted ecological screening value

Concentration in **blue** font and grey box exceed the adopted management limits
Concentration in **green** and grey box exceed the direct contact for HSL D screening value

Concentration in light blue and grey box exceed the direct contact for workers screening value

concentrations in box exceed the screening value >2.5 times

Where there is one or more guideline value is exceeded, the highest guidleline value will be highlighted

Concentrations below the LOR noted as <value

'Ch' Chrysotile (white asbestos)

'Am' Amosite (brown asbestos) Cr' Crocidolite (blue asbestos)



						Site -		Groundwater
	_					ALS Sample		ES1611420006
	-					Sample da		24/05/2016
	HSL D	- Comm	ercial/	95% Marine		Sample ID:		012_GW001
	_	ndustria	l ^A	Water	Recreational	Project Na		M4E-WCX
				Protection for	Health (10x	Compound	:	NORTHCOTE STREET TUNNEL
	_			Aquatic Ecosystems ^B	ADWG 2011) ^c	4		SITE GME
			1	2000 you come		Site: Sampling N	Acthod:	SITE 012 micro purge pump
Guidelines	2 to <4m	4m	8m+			Sample De		Thicro purge purity
Cardennes		to<8m					•	PRIMARY
				Į.		11		4
Analyte grouping/Analyte						Units	LOR	
Thatyte grouping/Thatyte						Oillo	LOK	
EG020T: Dissolved Metals by ICP-MS								•
Arsenic				2.3	100	μg/L	1	<1
Cadmium Chromium				0.7 4.4	20 500	μg/L μg/L	0.1	0.6
Copper				1.3	20000	µg/L	1	<1
Nickel				7	200	μg/L	1	<1
Lead				4.4	100	μg/L	1	84
Zinc				15		μg/L	1	554
EG035F: Dissolved Mercury by FIMS	<u> </u>	<u> </u>	l			11	<u>. </u>	
Mercury				0.1	10	μg/L	0.1	<0.1
Waa								
VOCs Styrene	1		l	1	<u> </u>	μg/L	5	<5
Isopropylbenzene	<u> </u>	L	<u>L</u>			μg/L μg/L	5	<5 <5
n-Propylbenzene						μg/L	5	<5
1.3.5-Trimethylbenzene		<u> </u>				μg/L	5	<5 .F
sec-Butylbenzene 1.2.4-Trimethylbenzene	+	1				μg/L μg/L	5 5	<5 <5
tert-Butylbenzene	<u> </u>	L	<u>L</u>			μg/L μg/L	5	<5 <5
p-Isopropyltoluene						μg/L	5	<5
n-Butylbenzene	1					μg/L	5	<5
Vinyl Acetate 2-Butanone (MEK)	+	1				μg/L μg/L	50 50	<50 <50
4-Methyl-2-pentanone (MIBK)	1					μg/L	50	<50
2-Hexanone (MBK)						μg/L	50	<50
Carbon disulfide						μg/L	5	<5
2.2-Dichloropropane 1.2-Dichloropropane	+	 				μg/L μg/L	5 5	<5 <5
cis-1.3-Dichloropropylene	 					μg/L μg/L	5	<5 <5
trans-1.3-Dichloropropylene						μg/L	5	<5
1.2-Dibromoethane (EDB)		<u> </u>				μg/L	5	<5
Dichlorodifluoromethane Chloromethane	+	 				μg/L μg/L	50 50	<50 <50
Vinyl chloride					3	μg/L	50	< 50
Bromomethane						μg/L	50	<50
Chloroethane						μg/L	50	< 50
Trichlorofluoromethane 1.1-Dichloroethene	+	-			300	μg/L μg/L	50 5	<50 <5
Iodomethane	<u> </u>				300	μg/L μg/L	5	<5 <5
trans-1.2-Dichloroethene						μg/L	5	<5
1.1-Dichloroethane						μg/L	5	<5
cis-1.2-Dichloroethene 1.1.1-Trichloroethane						μg/L μg/L	5 5	<5 <5
1.1-Dichloropropylene						µg/L	5	<5
Carbon Tetrachloride						μg/L	5	<5
1.2-Dichloroethane					30	μg/L	5 5	<5 <5
Trichloroethene Dibromomethane						μg/L μg/L	5	<5 <5
1.1.2-Trichloroethane				1900		μg/L	5	<5
1.3-Dichloropropane						μg/L	5	<5
Tetrachloroethene 1.1.1.2-Tetrachloroethane		1			500	μg/L μg/L	5 5	<5 <5
trans-1.4-Dichloro-2-butene						μg/L μg/L	5	<5
cis-1.4-Dichloro-2-butene						μg/L	5	<5
1.1.2.2-Tetrachloroethane						μg/L	5	<5
1.2.3-Trichloropropane Pentachloroethane						μg/L μg/L	5 5	<5 <5
1.2-Dibromo-3-chloropropane						µg/L	5	<5
Hexachlorobutadiene						μg/L	5	<5
Chlorobenzene Bromobenzene				55	3000	μg/L	5 5	<5 <5
2-Chlorotoluene						μg/L μg/L	5	<5 <5
4-Chlorotoluene						µg/L	5	<5
1.3-Dichlorobenzene				260		μg/L	5	<5
1.4-Dichlorobenzene 1.2-Dichlorobenzene	+	1		60 160	400 15000	μg/L μg/L	5 5	<5 <5
1.2.4-Trichlorobenzene	 			20	300	μg/L μg/L	5	<5 <5
1.2.3-Trichlorobenzene				3	300	μg/L	5	<5
Chloroform Promodichloromethans		<u> </u>				μg/L	5	<5 .F
Bromodichloromethane Dibromochloromethane	+	1				μg/L μg/L	5 5	<5 <5
Bromoform Bromoform	L				<u> </u>	μg/L	5	<5
Naphthalene				50		μg/L	5	<5
EP075(SIM)A: Phenolic Compounds					<u> </u>			
Phenol				400		μg/L	1	<1.0
2-Chlorophenol				340	3000	μg/L	1	<1.0
2-Methylphenol						μg/L	1	<1.0
3- & 4-Methylphenol 2-Nitrophenol	+	1		2		μg/L	2	<2.0
2-Nitrophenol 2.4-Dimethylphenol	+	 		2		μg/L μg/L	1	<1.0 <1.0
2.4-Dichlorophenol	L			120	2000	μg/L	1	<1.0
2.6-Dichlorophenol				34		μg/L	1	<1.0
4-Chloro-3-methylphenol 2.4.6-Trichlorophenol	1	 		2	200	μg/L	1	<1.0
2.4.5-Trichlorophenol	1			3 4	200	μg/L μg/L	1	<1.0 <1.0
		1		22	100	μg/L	2	<2.0
Pentachlorophenol								
Pentachlorophenol								
Pentachlorophenol EP075(SIM)B: Polynuclear Aromatic Hy	drocarbo	ns		50	l	ug/I	1	~1 ∩
Pentachlorophenol	drocarbo	ns		50		μg/L μg/L	1 1	<1.0 <1.0
Pentachlorophenol EPO75(SIM)B: Polynuclear Aromatic Hy Naphthalene Acenaphthylene Acenaphthene	drocarbo	ns		50		μg/L μg/L	1	<1.0 <1.0
Pentachlorophenol EPO75(SIM)B: Polynuclear Aromatic Hy Naphthalene Acenaphthylene Acenaphthene Fluorene	drocarbo	ns				μg/L μg/L μg/L	1 1 1	<1.0 <1.0 <1.0
Pentachlorophenol EPO75(SIM)B: Polynuclear Aromatic Hy Naphthalene Acenaphthylene Acenaphthene	drocarbo	ns		0.6		µg/L µg/L µg/L µg/L	1 1 1 1	<1.0 <1.0 <1.0 <1.0
Pentachlorophenol EPO75(SIM)B: Polynuclear Aromatic Hy Naphthalene Acenaphthylene Acenaphthene Fluorene Phenanthrene	drocarbo	ns				μg/L μg/L μg/L	1 1 1	<1.0 <1.0 <1.0
Pentachlorophenol EP075(SIM)B: Polynuclear Aromatic Hy Naphthalene Acenaphthylene Acenaphthene Fluorene Phenanthrene Anthracene Fluoranthene Pyrene	drocarbo	ns		0.6 0.01		µg/L µg/L µg/L µg/L µg/L µg/L µg/L	1 1 1 1 1 1 1	<1.0 <1.0 <1.0 <1.0 <1.0 <1.0 <1.0 <1.0
Pentachlorophenol EP075(SIM)B: Polynuclear Aromatic Hy Naphthalene Acenaphthylene Acenaphthene Fluorene Phenanthrene Anthracene Fluoranthene Pyrene Benz(a)anthracene	drocarbo	ns		0.6 0.01		µg/L µg/L	1 1 1 1 1 1 1 1	<1.0 <1.0 <1.0 <1.0 <1.0 <1.0 <1.0 <1.0
Pentachlorophenol EPO75(SIM)B: Polynuclear Aromatic Hy Naphthalene Acenaphthylene Acenaphthene Fluorene Phenanthrene Anthracene Fluoranthene Pyrene Benz(a)anthracene Chrysene	drocarbo	ns		0.6 0.01		ру/L ру/L ру/L ру/L ру/L ру/L ру/L ру/L	1 1 1 1 1 1 1 1 1 1	<1.0 <1.0 <1.0 <1.0 <1.0 <1.0 <1.0 <1.0
Pentachlorophenol EP075(SIM)B: Polynuclear Aromatic Hy Naphthalene Acenaphthylene Acenaphthene Fluorene Phenanthrene Anthracene Fluoranthene Pyrene Benz(a)anthracene	drocarbo	ns		0.6 0.01		µg/L µg/L	1 1 1 1 1 1 1 1	<1.0 <1.0 <1.0 <1.0 <1.0 <1.0 <1.0 <1.0
Pentachlorophenol EPO75(SIM)B: Polynuclear Aromatic Hy Naphthalene Acenaphthylene Acenaphthene Fluorene Phenanthrene Anthracene Fluoranthene Pyrene Benz(a)anthracene Chrysene Benzo(b+j)fluoranthene Benzo(k)fluoranthene Benzo(a)pyrene	drocarbo	ns		0.6 0.01	0.1	ру/L ру/L ру/L ру/L ру/L ру/L ру/L ру/L	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 0.5	<1.0 <1.0 <1.0 <1.0 <1.0 <1.0 <1.0 <1.0
Pentachlorophenol EPO75(SIM)B: Polynuclear Aromatic Hy Naphthalene Acenaphthylene Acenaphthene Fluorene Phenanthrene Anthracene Fluoranthene Pyrene Benzo(a)anthracene Chrysene Benzo(b+j)fluoranthene Benzo(b)fluoranthene Benzo(a)pyrene Indeno(1.2.3.cd)pyrene	drocarbo	ns		0.6 0.01 1	0.1	рд/L рд/L рд/L рд/L рд/L рд/L рд/L рд/L	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	<1.0 <1.0 <1.0 <1.0 <1.0 <1.0 <1.0 <1.0
Pentachlorophenol EPO75(SIM)B: Polynuclear Aromatic Hy Naphthalene Acenaphthylene Acenaphthene Fluorene Phenanthrene Anthracene Fluoranthene Pyrene Benz(a)anthracene Chrysene Benzo(b+j)fluoranthene Benzo(k)fluoranthene Benzo(a)pyrene	drocarbo	ns		0.6 0.01 1	0.1	ру/L ру/L ру/L ру/L ру/L ру/L ру/L ру/L	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 0.5	<1.0 <1.0 <1.0 <1.0 <1.0 <1.0 <1.0 <1.0
Pentachlorophenol EPO75(SIM)B: Polynuclear Aromatic Hy Naphthalene Acenaphthylene Acenaphthene Fluorene Phenanthrene Anthracene Fluoranthene Pyrene Benz(a)anthracene Chrysene Benzo(b+j)fluoranthene Benzo(k)fluoranthene Benzo(a)pyrene Indeno(1,2,3,cd)pyrene Dibenz(a,h)anthracene	drocarbo	ns		0.6 0.01 1	0.1	ру/L ру/L ру/L ру/L ру/L ру/L ру/L ру/L	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	<1.0 <1.0 <1.0 <1.0 <1.0 <1.0 <1.0 <1.0

TABLE 5: Groundwater Sampling Results Northcote Compound Site - 012

Groundwater

Sample Type:



								Groundwater
						ALS Sample	e number:	ES1611420006
						Sample dat	e:	24/05/2016
	HSL D	- Commo	ercial/			Sample ID:		012_GW001
		ndustrial		95% Marine	B	Project Nar	ne:	M4E-WCX
		iluusti lai		Water Protection for	Recreational Health (10x	Compound		NORTHCOTE
				Aquatic	ADWG 2011) ^c			STREET TUNNE
				Ecosystems ^B	ADWG 2011)			SITE GME
				Ecosystems		Site:		SITE 012
						Sampling N		micro purge pun
Guidelines	2 to <4m	4m to<8m	8m+			Sample Des		
		to<8m						PRIMARY
Analyte grouping/Analyte					·	Units	LOR	
EP080/071: Total Petroleum Hydrocarbo	ons							
C6 - C9 Fraction						μg/L	20	<20
C10 - C14 Fraction						μg/L	50	<50
C15 - C28 Fraction						μg/L	100	<100
C29 - C36 Fraction						μg/L	50	< 50
C10 - C36 Fraction (sum)						μg/L	50	< 50
` ,						10		
EP080/071: Total Recoverable Hydrocar	bons - Ni	EPM 2013	3 Fraction	ns				
C6 - C10 Fraction						μg/L	20	<20
C6 - C10 Fraction minus BTEX (F1)	6200	6300	6500			μg/L	20	< 20
>C10 - C16 Fraction						μg/L	100	<100
>C16 - C34 Fraction						μg/L	100	<100
>C34 - C40 Fraction						μg/L	100	<100
>C10 - C40 Fraction (sum)						μg/L	100	<100
>C10 - C16 Fraction minus Naphthalene (F2)	NL	NL	NL			μg/L	100	<100
						F-9/-		
EP080: BTEXN			<u> </u>				<u> </u>	
Benzene	4900	5100	5400	500	8000	μg/L	1 1	<1
Toluene	NL	NL	NL	180	3000	μg/L	2	<2
Ethylbenzene	NL	NL	NL	5	8000	μg/L	2	<2
meta- & para-Xylene				275	5555	μg/L	2	<2
ortho-Xylene				350		µg/L	2	<2
Total Xylenes	NL	NL	NL		6000	μg/L	2	<2
,					5555			<1
	NII	NII	NII	50		P9'-		<5
Sum of BTEX Naphthalene	NL	NL	NL	50	333	µg/L	1 5	<

Blank Cell indicates no criterion available

All results are in µg/L unless stated LOR = Limit of Reporting

A NEPM 2013 HSL 'D' (Commercial/Industrial)

^B ANZECC 2000 % Protection Level for Receiving Water Type

^C NHMRC Australian Drinking Water Guidelines, 2011

ANZECC guidelines in $\it italics$ are low level reliability guidelines

 ${\tt ANZECC} \ arsenic \ guideline \ based \ on \ As \ (III) \ for \ marine \ and \ As \ (V) \ for \ fresh, \ the \ lowest \ of \ presented \ guidelines.$

NHMRC arsenic guidelines are based on total arsenic ANZECC and NHMRC guidelines for chromium are based on Cr (VI) ANZECC guidelines for mercury are based on inorganic mercury.

NHMRC guidelines for mercury are based on total mercury.

In instances where there was no marine guideline values, the freshwater guidelines have been adopted

In instances wehre there was no health drinking water guideline value, the aesthetic value has been adopted $\frac{1}{2}$

Concentration in **red** font and grey box exceed the adopted ecosystem guideline value

Concentration in orange font and grey box exceed the adopted recreational drinking water guideline

Concentrations in $\ensuremath{\textbf{blue}}$ indicate the LOR is greater than the guideline value

Concentrations below the LOR noted as <value

no HSL is presented for recreational use (HSL C) as all these chemicals are not limiting (NL)




	Sample Type	oe:	ALS	ALS	ALS
	ALS Sample	e number:	ES1611420009	ES1611420010	ES1611421010
	Sample dat	e:	23/05/2016	24/05/2016	24/05/2016
	Sample ID:		000_QA003	000_QA004	000_QA002
	Project Nar	ne:	M4E-WCX	M4E-WCX	M4E-WCX
	Compound	:	NORTHCOLE STREET TUNNEL SITE GME	NORTHCOLE STREET TUNNEL SITE GME	NORTHCOLE STREET TUNNEL SITE
	Site:		SITE 006/ 012 / 026 /027	SITE 006/ 012 / 026 /027	SITE 006/ 012 / 026 /027
	Sampling N	lethod:	026 /02 /	026 /02 /	026 /02 /
	Sample De		TRIP SPIKE	TRIP BLANK	TRIP BLANK
Analyte grouping/Analyte	Units	LOR	1		
ranaryto grouping/ranaryto	Oilito	LOIL			
EP080/071: Total Petroleum Hydrocarbo	ns				
C6 - C9 Fraction	μg/L	20	190	20	20
C10 - C14 Fraction	μg/L	50		<50	
C15 - C28 Fraction	μg/L	100		< 100	
C29 - C36 Fraction	μg/L	50		<50	
C10 - C36 Fraction (sum)	μg/L	50		<50	
EP080/071: Total Recoverable Hydrocart	ons - NEPM	2013 Fract	tions		
C6 - C10 Fraction	μg/L	20	210	20	20
C6 - C10 Fraction minus BTEX (F1)	μg/L	20	130	20	20
>C10 - C16 Fraction	μg/L	100		< 100	
>C16 - C34 Fraction	μg/L	100		< 100	
>C34 - C40 Fraction	μg/L	100		<100	
>C10 - C40 Fraction (sum)	μg/L	100		<100	
>C10 - C16 Fraction minus Naphthalene (F2)	μg/L	100		<100	
EP080: BTEXN			<u> </u>		
Benzene	μg/L	1	15	<1	<1
Toluene	μg/L	2	14	2	2
Ethylbenzene	μg/L	2	16	2	2
meta- & para-Xylene	μg/L	2	16	2	2
ortho-Xylene	μg/L	2	16	2	2
Total Xylenes	μg/L	2	32	2	2
Sum of BTEX	μg/L	1	77	<1	<1
Naphthalene	µg/L	5	17	<5	<5


nc = not calculated since results < LOR LOR = Laboratory Limit of Reporting BOLD identifies where RPD results

Intralaboratory	Interlaboratory	
>50	>60	where sample results are >10 x PQL
>75	>85	where sample results are > 5 to ≤10 x PQL
>100	>100	where sample results are >2 to ≤5 x PQL
AD>2.5 * PQL		where sample results are ≤2 x PQL

|AD>2.5 ^ PQL | Junete sample results are \$2 \text{ A FQL}|

Where results are within two of the above ranges the most conservative criteria have been used to assess duplicate performance.







Project No: AS121919 Client Name: CSJ Project Name: Phase 2 ESA

Project Site: 026

Well ID	Easting	Northing	Gauging	Total Well Depth	SWL	TOC Elevation	Groundwater Elevation
	3	3	Date	(m btoc)	(m btoc)	(mAHD)	(mAHD)
026_GW001	326968.70	6250035.60	24/05/2016	11.12	2.96	9.58	6.62

Notes

m = Metres

btoc = Below Top of Casing

SWL = Standing Water Level

TOC = Top of Casing

AHD = Australian Height Datum

Easting projection MGA94: Map Grid of Australia 1994



Project No: AS121919 Client Name: CSJ Project Name: Phase 2 ESA Project Site: 026

Well ID	Purge Date	Purge Vol (L)	DO (ppm)	EC (µScm-¹)	рН	Eh (mV)	Temperature (°C)	Comments
026_GW001	24/05/2016	3.0	1.33	1710	5.03	167	22.8	clear, no sheen, no odour

Notes

L = Litre

DO = Dissolved Oxygen

ppm = parts per million

EC = Electrical Conductivity

 μ Scm-1 = microSiemens per centimetre

Eh = Redox

mV = milli Volts

The content of the																					
Part	Sample Typ																	,	,	,	
March Marc			4									-	Sample Typ								
Part			4											number:							
			4																		11/05/2016
			4																		(ACM)
Control Cont			4											e:	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX
March Marc			4										Compound:	- 1	Northcote Street	Northcote Street					
March Marc			4								CRC CARE 2011			- 1	Tunnel Site	Tunnel Site					
Property of the property of		NEDM 2012 IIII					NEDM 2012 FIL	NEDM 2012 FEL 2	Management	CDC CADE 2011	Direct Contact		Site:		Site 026	Site 026					
Part		D Commercial /		Vapour	Vapour	Vapour			Limits	Direct Contact ⁴				thod-							
March Marc		Industrial					Industrial	Industrial	Commercial/	HSL D	Intrusive	Maintenance			Test Pitting	Test Pitting	Test Pitting	Test Pitting	Drilling	Drilling	Drilling
Company Comp			Sand: U-1m	Sand: 1-2m	Sand: 2-4m	Sand: 4+m			Industrial 2		Workers	Workers Sand 0-									
Company Comp			4									<2m 4		- 1							
Second Process			4											- 1		FILL; Silty clay, possibly					
Company of the comp			4											- 1	FILL; Sandy sitty graver, dank	reworked natural, most,	Duplicate of	Sity CLAY; orange with red			One piece of bonded
Marie Security Column Mari			4										Sample Desc	ription	moid medium density no	white norkets candstone		high nightfrity on			sheeting approximately
Marie Section Marie Ma			4											- 1	observed contamination			observed contamination	black	black	
Control Cont			4											- 1		observed contamination					
Control Cont			4											- 1							
Control Cont																					
Company Comp	Analyte grouping/Analyte												Units	LOR							
March Marc																					
The control of the																					
Marie	pH (CaCI2)												%								
Selection function fu					<u> </u>		<u> </u>		<u> </u>												
Company Control Andrew Service	EA055: Moisture Content																				
Scheller	Moisture Content (dried @ 103°C)					ļ							%		6.4	12.7	11.8	22.3	14.2	15.9	
Scheller					1																
Company Notices Company No	EDUUB: Exchangeable Cations on Alkaline Soils																				
Company			+		-												****				****
Company Comp			-		1																
Control	Exchangeable Potassium Evolvangeable Sodium														****	****	****	****	****	****	****
	Cation Eychange Canacity	l		 									_								
Table	Cutton Exchange Capacity		-		<u> </u>								1								****
Table	EPOOS: Total Organic Carbon (TOC) in Soil																				
Appendix	Total Organic Carbon												96								
April Debated																					
Absolute Image and property in the property	EA200: AS 4964 - 2004 Identification of Asbestos in bulk samp	les																			
September Sept	Asbestos Detected												g/kg			****	****				
Company Comp																****	****				
## Application Controlled ## Application Con	Sample weight (dry)												g		****	****	****	****	****	****	
Description Property Proper																					
Proceedings Process														- 1							
			'											- 1							
Appendix Company Com	Description.													- 1							
Appendix Appendix and Asheritan in South	Approved incorrector																				
Abbelle District Abbelle Dis	APPROVED IDENTIFIER.																****				N.WEBB
Abbelle District Abbelle Dis	EA200: AS 4964 - 2004 Identification of Achaetoe in Soile																				
According													g/kg		No	No			No	No	
															-					-	
Description	Sample weight (dry)												g		60.4	70			149	99.3	
Description			,												Mid brown clay soil	Mid brown clay soil					
APPROXITE	Description													- 1					Pale brown sandy soil.	Mid brown clay soil.	
Page	APPROVED IDENTIFIER:		-																G MORGAN	G MORGAN	
Asset Asse															U.montoret	U.MOROPEY			U.MOROPET	U.MONOPEY	
Asset Asse	EG005T: Total Metals by ICP-AES																				
Commiss	Arsenic	3000					160						mg/kg	5	<5	16	14	11	<5	<5	
Second S		900	-											1			1	1	<1	<1	****
Cooper C			-				310								12	24	26	42	9	6	****
1500 1600														2					13		
Note 100													mg/kg			75		18		6	
ECOSES 1018 ECOVERNIS 170			-				60							2					45		****
ECOUST: Total Recoverable Mercury by FIMS			-																		
No.	Zinc	400000													T						
Page	Zinc	400000									_					·	·				
EPOTSCHIDE: Polymerlear Aromatic Hydrocarbons NL NL NL NL 370 11000 29000 NL mg/kg 0.5	Zinc EG035T: Total Recoverable Mercury by FIMS	400000											ma/ka	0.1	<0.1	0.1					
Naghthatene NL NL NL NL 370 11000 29000 NL mg/kg 0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <											l	1						< 0.1	< 0.1	< 0.1	
Naghthatene NL NL NL NL 370 11000 20000 NL mg/kg 0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <																	<0.1	<0.1	<0.1	<0.1	
Nonaphthele	Mercury																<0.1	<0.1	<0.1	<0.1	****
Acceptables	Mercury EP075(SIM)B: Polynuclear Aromatic Hydrocarbons		NL NL	NL	NL	NL	370			11000	29000					<0.5					
Studente	Mercury EPO75(SIM)B: Polynuclear Aromatic Hydrocarbons Naphthalene		NL	NL	NL	NL	370			11000	29000		mg/kg	0.5 0.5	<0.5 <0.5		<0.5	<0.5	<0.5 <0.5	<0.5 <0.5	
Denathrone	Mercury EP075(SIM)B: Polynuclear Aromatic Hydrocarbons Naphibalene Aconaphitylene		NL NL	NL	NL	NL	370			11000	29000		mg/kg mg/kg	0.5 0.5	<0.5 <0.5	< 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	****
Administration Marking 0.5 0	Mercury EP075 (SIM)B: Polynuclear Aromatic Hydrocarbons Naphhalene Acenaphthylene Acenaphthylene		NL NL	NE	NL	NL	370			11000	29000		mg/kg mg/kg mg/kg	0.5 0.5 0.5	<0.5 <0.5 <0.5	<0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	****
Succeptible	Mercury EP075(SIM)8: Polynuclear Aromatic Hydrocarbons Uspithialere Aconsphityvien Aconsphityvien Aconsphitere		NL NL	NL NL	NL	NL	370			11000	29000		mg/kg mg/kg mg/kg mg/kg	0.5 0.5 0.5 0.5	<0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5	2000 2000 2000
Pyren	Hercury EP075 (SIM)B: Polynuclear Aromatic Hydrocarbons happhalene Aconaphhylene Fluorene Fluorene Phoenanthrone		NL.	NL	NL	NL	370			11000	29000		mg/kg mg/kg mg/kg mg/kg mg/kg	0.5 0.5 0.5 0.5 0.5	<0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5	
Sex (0.4 mg/kg 0.5	Mercury EPDTS(SIMM): Polynuclear Aromatic Hydrocarbons Naphthalene Acesaphthene Acesaphthene Dubrene Phenantivene Achtriscene		NL.	NL	NE.	NL	370			11000	29000		mg/kg mg/kg mg/kg mg/kg mg/kg	0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5	
Chrysne	Mercury EP075 (SIMIB: Polynuclear Aromatic Hydrocarbons Naphthalene Acenaphthylene Fluoren Fluorentene Anthracene Fluorantene		NL.	NL	NL	NL.	370			11000	29000		mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg	0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	
Bertz(0+) Nuoranthene	Decruy EPO75 (SIM)B: Polynusitear Aromatic Hydrocarbons Hagrihalene Acensaphhyene Acensaphhyene Electischinene		NL.	NL NL	NL	NL	370			11000	29000		mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg	0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	
	Hercury EP075 (SIM)B: Polynuclear Aromatic Hydrocarbons haphhalme Aconaphhylene Aconaphhylene Fluorene Phuranitrone Anthracone Fluoranitrone Pyrene Byrene Byrene Byrene		NL.	NL	NL.	NL.	370			11000	29000		mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg	0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	**************************************
	tercury EPOTS (SIM)B: Polynuclear Aromatic Hydrocarbons Inspithulene Acensachtheree Thocrees		NL NL	NL NL	NL NL	NL	370			11000	29000		mg/kg	0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	
	Netrous EPOTS (SIMIB: Polynuclear Aromatic Hydrocarbons Nagnthalene Aconaghthylene Aconaghthylene Pluorene		NL.	NL	NL.	NL NL	370			11000	29000		mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg	0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	
	Decruy EPOTS (SIM)B: Polynuclear Aromatic Hydrocarbons Insphthalme Accessfythlydene Accessfythlydene Fluorene Fluorene Fluorene Fluorene Elevationene Dycare Berva(Jaharthacene Chrysene Berva(Jaharthacene Berva(Jaharthacene Berva(Jaharthacene) Berva(Jaharthacene) Berva(Jaharthacene)		NL NL	NL	NL NL	NL.	370			11000	29000		mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg	0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	<0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	

												Sample Typ		SOIL	SOIL	ALS	SOIL	SOIL	SOIL	SOIL
												ALS Sample		ES1609680001	ES1609680002	ES1609680004	ES1609680003	ES1610406001	ES1610406002	ES1610406003
												Sample date	1	04/05/2016	04/05/2016	04/05/2016	04/05/2016	11/05/2016	11/05/2016	11/05/2016
												Sample ID:		026_TP001_0.10	026_TP001_0.50	026_QC001	026_TP001_1.00	026_GW001_0.2	026_GW001_0.5	026_GW001_0.5
												Project Nan	ne:	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX
												Compound:		Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street
										CRC CARE 2011	CRC CARE 2011			Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site
		NEPM 2013 Soil	NEPM 2013 Soil	NEPM 2013 Soil	NEPM 2013 Soil			NEPM 2013 Management	CRC CARE 2011	Direct Contact	Vapour	Site:		Site 026	Site 026	Site 026	Site 026	Site 026	Site 026	Site 026
	NEPM 2013 HIL D Commercial /	Vapour	Vapour	Vapour	Vapour	NEPM 2013 EIL Commercial /	NEPM 2013 ESL ² Commercial /	Limits	Direct Contact ⁴	HSL for	Intrusion HSL for Intrusive	Sampling M	ethod-	Jac 020	5110 020	Site 020	Disc 020	Sinc 020	Silc 020	Site 020
	Industrial	Intrusion HSL D	Intrusion HSL D		Intrusion HSL D	Industrial	Industrial	Commercial/	HSL D	Intrusive Maintenance	Maintenance	Juniping in	curou.	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Drilling	Drilling	Drilling
	_	Sand ¹ 0-1m	Sand ¹ 1-2m	Sand ¹ 2-4m	Sand ¹ 4+m			Industrial 2		Workers	Workers Sand 0-	_								-
											<2m 4									1
														FILL; Sandy silty gravel, dark	FILL; Silty clay, possibly reworked natural, moist,		Silty CLAY; orange with red			
														grey/brown, gravel is basalt,	erey/brown with orange and	Duplicate of	ironstone pockets, soft, moist.	FILL; Sandy Clay, light brown,		One piece of bonded asbestos cement
												Sample Des	cription	moist, medium density, no	white pockets, sandstone,	026_TP001_0.5	high plasticity, no	with cobbles, moist, becoming		sheeting approximately
														observed contamination	some charcoal inclusions, no		observed contamination	black	black	50 x 30 x 5mm
															observed contamination					1
												Units	LOR							
Analyte grouping/Analyte												Units	LUR							
Indeno(1.2.3.cd)pyrene												mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	<0.5	
Dibenz(a.h)anthracene												mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	
Benzo(q.h.i)perylene												mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	
Sum of polycyclic aromatic hydrocarbons	4000											mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	
Benzo(a)pyrene TEQ (zero)												mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	
Benzo(a)pyrene TEQ (half LOR)												mg/kg	0.6	0.6	0.6	0.6	0.6	0.6	0.6	
Benzo(a)pyrene TEQ (LOR)	40											mg/kg	1.2	1.2	1.2	1.2	1.2	1.2	1.2	
EP080/071: Total Petroleum Hydrocarbons			_																	
C6 - C9 Fraction												mg/kg	10	<10	<10	<10	<10	<10	<10	
C10 - C14 Fraction												mg/kg	50	<50	<50	<50	<50	<50	<50	
C15 - C28 Fraction												mg/kg	100	<100	<100	<100	<100	<100	<100	****
C29 - C36 Fraction												mg/kg	100	<100	<100	<100	<100	<100	<100	
C10 - C36 Fraction (sum)												mg/kg	50	<50	<50	<50	<50	<50	<50	
EP080/071: Total Recoverable Hydrocarbons - NEPM 2013 Fr	actions																			
C6 - C10 Fraction								700	26000	82000	NL	mg/kg	10	<10	<10	<10	<10	<10	<10	
C6 - C10 Fraction minus BTEX (F1)		260	370	630	NL		215					mg/kg	10	<10	<10	<10	<10	<10	<10	****
>C10 - C16 Fraction							170	1000	20000	62000	NL.	mg/kg	50	<50	<50	<50	<50	<50	<50	
>C16 - C34 Fraction (F3)							1700	3500	27000	85000		mg/kg	100	<100	<100	<100	<100	<100	<100	
>C34 - C40 Fraction (F4)							3300	10000	38000	120000		mg/kg	100	<100	<100	<100	<100	<100	<100	****
>C10 - C40 Fraction (sum)												mg/kg	50	<50	<50	<50	<50	<50	<50	****
>C10 - C16 Fraction minus Naphthalene (F2)	_	NL	NL	NL	NL							mg/kg	50	<50	<50	<50	<50	<50	<50	
		1						l		1				Ш		l				
EP080: BTEXN																				
Benzene		3	3	3	3		75		430	1100	77	mg/kg	0.2	< 0.2	<0.2	<0.2	<0.2	< 0.2	<0.2	****
Toluene		NL	NL	NL	NL		135		99000	120000	NL	mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	<0.5	
Ethylbenzene		NL	NL	NL	NL		165		27000	85000	NL	mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	<0.5	****
meta- & para-Xylene												mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	<0.5	
ortho-Xylene												mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	<0.5	****
Total Xylenes		230	NL	NL	NL		95		81000	130000	NL	mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	<0.5	
Sum of BTEX												mg/kg	0.2	< 0.2	< 0.2	< 0.2	<0.2	< 0.2	<0.2	
Naphthalene		NL	NL	NL	NL	370			11000	29000	NL	mg/kg	1	<1	<1	<1	<1	<1	<1	
		1			1	1	1	l	1	1			l	11	I	1	I		1	1

Black Cell Indicates no criterion available
LOR - Limit of Reporting
Residual Formation and Col 13 Maries of Environmental Protection (Assessment of Size Contamination) Amendment Measure 2013 (No. 1) (MEPM).
Restands Environment Protection (Col 2013 Maries of Environmental Protection (Assessment of Size Contamination) Amendment Measure 2013 (No. 1) (MEPM).
Restands Environment Protection (Assessment of Size Contamination) Amendment Measure 2013 (No. 1) (MEPM).
Restands Environment Protection (Assessment of Size Contamination) Amendment Measure 2013 (No. 1) (MEPM).

1 For all tecture Custodiction understates in accord with AS 1726, the classification of sand, six and city may be applied as coarse, free with liquid limit 450% and free with liquid limit 450% are question from the relevant fractions to citizen F1 and F2.

2 Portect Contact are applied to surface such or with the first contamination of size of protection of fractions and six and residual six and residual residual in the maximum allowable vapour risk for the given scenario.

3 Portect Contact are applied to surface such or with white the fractions as and vapour source controllation for a periodeum mixture could not exceed a level that sould result in the maximum allowable vapour risk for the given scenario.

3 Portect Contact are applied to surface such or with a series and an analysis and resident fractions to citizen F1 and F2.

3 Portect Contact are applied to surface such or with a series and an advantage applied protection of a resident for a series and an advantage applied protection of a resident for a series and an advantage applied protection of a relation as the based on the everage of only in a

TABLE 4: Groundwater Sampling Results Northcote Compound Site - 026



					Site - 026			
						Sample Typ	oe:	REG
						ALS Sample	e number:	ES1611420004
						Sample dat		24/05/2016
	HSL D	- Commo	ercial/			Sample ID:		026_GW001
		ndustrial				Project Na		M4E-WCX
	•	i idasti idi		95% Marine		Compound		NORTHCOTE
				Water	Recreational	-		STREET TUNNEL
				Protection for	Health (10x			SITE GME
				Aquatic	ADWG 2011) ^c	Site:		Site 026
				Ecosystems ^B		Sampling N	/lethod:	low flow micro-
						H <u> </u>		purge
	2 to <4m	4m	8m+			Sample De	scription	
Guidelines	2 10 (4111	to<8m	OIIIT					PRIMARY
Guidennes								
Analyte grouping/Analyte						Units	LOR	
EG020T: Dissolved Metals by ICP-MS								
Arsenic				2.3	100	μg/L	1 1	1
Cadmium				0.7	20	µg/L	0.1	0.3
Chromium				4.4	500	µg/L	1	<1
Copper				1.3	20000	µg/L	1	6
Nickel				7	200	µg/L	1	1
Lead				4.4	100		1	51
Zinc				15	100	μg/L μg/L	1	153
				10		μg/L	1	100
EGO35E: Dissolved Maroury by FIME	<u> </u>		<u> </u>	ļ	ļ	 		<u> </u>
EG035F: Dissolved Mercury by FIMS Mercury	1			0.1	10	110/1	0.1	-0.1
Mercury	+			0.1	10	μg/L	0.1	<0.1
VOCs		<u> </u>	<u> </u>			1 1	<u>. </u>	1
Styrene						μg/L	5	<5
Isopropylbenzene						μg/L	5	<5
n-Propylbenzene						μg/L	5	<5
1.3.5-Trimethylbenzene						μg/L	5	<5
sec-Butylbenzene						μg/L	5	<5
1.2.4-Trimethylbenzene						μg/L	5	<5
tert-Butylbenzene						μg/L	5	<5
p-Isopropyltoluene						μg/L	5	<5
n-Butylbenzene						μg/L	5	<5
Vinyl Acetate						µg/L	50	<50
2-Butanone (MEK)						µg/L	50	<50
4-Methyl-2-pentanone (MIBK)						μg/L	50	<50
2-Hexanone (MBK)						μg/L	50	<50
Carbon disulfide						μg/L	5	<5
2.2-Dichloropropane						μg/L	5	<5
1.2-Dichloropropane						μg/L	5	<5
cis-1.3-Dichloropropylene						μg/L	5	<5 <5
trans-1.3-Dichloropropylene						μg/L	5	<5
1.2-Dibromoethane (EDB)						μg/L	5	<5
Dichlorodifluoromethane						μg/L	50	<50
Chloromethane	+						50	<50 <50
					3	μg/L	ł — — — — — — — — — — — — — — — — — — —	
Vinyl chloride Bromomethane					3	µg/L	50 50	< 50 <50
						µg/L	ł — — — — — — — — — — — — — — — — — — —	
Chloroethane						μg/L	50	<50
Trichlorofluoromethane	_					μg/L	50	<50
1.1-Dichloroethene					300	μg/L	5	< 5
lodomethane						μg/L	5 5	<5 <5
trans-1.2-Dichloroethene						µg/L	ł — — — — — — — — — — — — — — — — — — —	1
1.1-Dichloroethane						μg/L	5	<5
cis-1.2-Dichloroethene						μg/L	5	< 5
1.1.1-Trichloroethane						µg/L	5	< 5
1.1-Dichloropropylene						µg/L	5	< 5
Carbon Tetrachloride					22	μg/L	5	<5
1.2-Dichloroethane				1	30	μg/L	5	<5
Trichloroethene						μg/L	5	< 5
Dibromomethane				4000		μg/L	5	< 5
1.1.2-Trichloroethane				1900		μg/L	5 5	<5
1.3-Dichloropropane Tetrachloroethene					500	μg/L	5	<5 <5
1.1.1.2-Tetrachloroethane				1	500	μg/L	5	<5 <5
trans-1.4-Dichloro-2-butene						μg/L	5	
						μg/L		<5
cis-1.4-Dichloro-2-butene						μg/L	5 5	<5 <5
1.1.2.2-Tetrachloroethane				1		μg/L		
1.2.3-Trichloropropane						μg/L	5	<5
Pentachloroethane						µg/L	5	< 5
1.2-Dibromo-3-chloropropane						μg/L	5	< 5
Hexachlorobutadiene Chlorobonzono					000-	µg/L	5	<5
Chlorobenzene				55	3000	μg/L	5	< 5
Bromobenzene				1		μg/L	5	< 5
2-Chlorotoluene						μg/L	5	<5
4-Chlorotoluene 1.3-Dichlorobenzene						μg/L	5	< 5
LL 3-DICDIOCODEDZEDE				260		μg/L	5	<5
				60	400	μg/L	5	<5
1.4-Dichlorobenzene				160	15000	μg/L	5	<5
1.4-Dichlorobenzene 1.2-Dichlorobenzene				20	300	μg/L	5	<5
1.4-Dichlorobenzene 1.2-Dichlorobenzene 1.2.4-Trichlorobenzene					300	μg/L	5	<5
1.4-Dichlorobenzene 1.2-Dichlorobenzene 1.2.4-Trichlorobenzene 1.2.3-Trichlorobenzene				3			1	
1.4-Dichlorobenzene 1.2-Dichlorobenzene 1.2.4-Trichlorobenzene 1.2.3-Trichlorobenzene Chloroform				3		μg/L	5	< 5
1.4-Dichlorobenzene 1.2-Dichlorobenzene 1.2.4-Trichlorobenzene 1.2.3-Trichlorobenzene Chloroform Bromodichloromethane				3		μg/L μg/L	5	<5
1.4-Dichlorobenzene 1.2-Dichlorobenzene 1.2.4-Trichlorobenzene 1.2.3-Trichlorobenzene Chloroform Bromodichloromethane Dibromochloromethane				3		μg/L μg/L μg/L	5 5	<5 <5
1.4-Dichlorobenzene 1.2-Dichlorobenzene 1.2.4-Trichlorobenzene 1.2.3-Trichlorobenzene Chloroform Bromodichloromethane Dibromochloromethane Bromoform						µg/L µg/L µg/L µg/L	5 5 5	<5 <5 <5
1.4-Dichlorobenzene 1.2-Dichlorobenzene 1.2.4-Trichlorobenzene 1.2.3-Trichlorobenzene Chloroform Bromodichloromethane Dibromochloromethane				50		μg/L μg/L μg/L	5 5	<5 <5
1.4-Dichlorobenzene 1.2-Dichlorobenzene 1.2.4-Trichlorobenzene 1.2.3-Trichlorobenzene Chloroform Bromodichloromethane Dibromochloromethane Bromoform Naphthalene						µg/L µg/L µg/L µg/L	5 5 5	<5 <5 <5
1.4-Dichlorobenzene 1.2-Dichlorobenzene 1.2.4-Trichlorobenzene 1.2.3-Trichlorobenzene Chloroform Bromodichloromethane Dibromochloromethane Bromoform Naphthalene EPO75(SIM)A: Phenolic Compounds				50		μg/L μg/L μg/L μg/L μg/L	5 5 5 5	<5 <5 <5 <5 <5
1.4-Dichlorobenzene 1.2-Dichlorobenzene 1.2.4-Trichlorobenzene 1.2.3-Trichlorobenzene Chloroform Bromodichloromethane Dibromochloromethane Bromoform Naphthalene					3000	µg/L µg/L µg/L µg/L	5 5 5	<5 <5 <5

TABLE 4: **Groundwater Sampling Results Northcote Compound** Site - 026

Sample Type:



						Sample Ty	<i>.</i>	REG
						ALS Sample	e number:	ES1611420004
						Sample dat	te:	24/05/2016
	Hei D	– Comm	orcial/			Sample ID:		026_GW001
						Project Na		M4E-WCX
	_	ndustria	ľ	OF9/ Marina				NORTHCOTE
				95% Marine Water	Recreational	Compound	·	STREET TUNNEL
				Protection for	Health (10x			SITE GME
				Aquatic	· · · · · · · · · · · · · · · · · · ·	Site:		
				Ecosystems ^B	ADWG 2011) ^c		Andread:	Site 026
				Ecosystems		Sampling N	nethod:	low flow micro-
	_					Camaria Da		purge
	2 to <4m	4m	8m+			Sample De	scription	
Guidelines	2 10 (4111	to<8m	OIIIT					PRIMARY
Guidennes								T TOTAL STATE
Analyte grouping/Analyte						Units	LOR	
3- & 4-Methylphenol						μg/L	2	<2.0
2-Nitrophenol				2		μg/L	1	<1.0
2.4-Dimethylphenol				2		1 1	1	<1.0
2.4-Dirherryphenol				1	2000	μg/L	H	
				120	2000	μg/L	1	<1.0
2.6-Dichlorophenol				34		μg/L	1	<1.0
4-Chloro-3-methylphenol						μg/L	1	<1.0
2.4.6-Trichlorophenol				3	200	μg/L	1	<1.0
2.4.5-Trichlorophenol				4		μg/L	1	<1.0
Pentachlorophenol				22	100	μg/L	2	<2.0
EP075(SIM)B: Polynuclear Aromatic Hy	ydrocarbo	ns						
Naphthalene				50		μg/L	1	<1.0
Acenaphthylene						μg/L	1	<1.0
Acenaphthene	1					µg/L	1	<1.0
Fluorene						μg/L	1	<1.0
	+			0.4		++	1	
Phenanthrene				0.6		μg/L	 	<1.0
Anthracene				0.01		μg/L	1	<1.0
Fluoranthene				1		μg/L	1	<1.0
Pyrene						μg/L	1	<1.0
Benz(a)anthracene						μg/L	1	<1.0
Chrysene						μg/L	1	<1.0
Benzo(b+j)fluoranthene						μg/L	1	<1.0
Benzo(k)fluoranthene						μg/L	1	<1.0
Benzo(a)pyrene				0.1	0.1	μg/L	0.5	<0.5
Indeno(1.2.3.cd)pyrene				0	<u> </u>	µg/L	1	<1.0
Dibenz(a.h)anthracene						µg/L	1	<1.0
Benzo(g.h.i)perylene						μg/L	1	<1.0
Sum of polycyclic aromatic hydrocarbons						μg/L	0.5	<0.5
Benzo(a)pyrene TEQ (zero)						μg/L	0.5	< 0.5
						ļ ļ	<u> </u>	
EP080/071: Total Petroleum Hydrocari	bons							
C6 - C9 Fraction						μg/L	20	<20
C10 - C14 Fraction						μg/L	50	<50
C15 - C28 Fraction						μg/L	100	<100
C29 - C36 Fraction						μg/L	50	<50
C10 - C36 Fraction (sum)						μg/L	50	<50
ere coorradion (sam)						P9'L	- 55	100
EP080/071: Total Recoverable Hydroca	arhons - A	IEDM 201	2 Eractio	nne				
C6 - C10 Fraction		ILFIVI 20 I	JITACIIC			119/1	20	+20
C6 - C10 Fraction minus BTEX (F1)	1000		(500			μg/L	20	<20
	6200	6300	6500			μg/L	20	<20
>C10 - C16 Fraction						μg/L	100	<100
>C16 - C34 Fraction						μg/L	100	<100
>C34 - C40 Fraction						μg/L	100	<100
>C10 - C40 Fraction (sum)						μg/L	100	<100
>C10 - C16 Fraction minus Naphthalene (F.	2 NL	NL	NL			μg/L	100	<100
EP080: BTEXN								
Benzene	4900	5100	5400	500	8000	μg/L	1	<1
Toluene	NL	NL	NL	180	3000	μg/L	2	<2
Ethylbenzene	NL	NL	NL	5	8000	µg/L	2	<2
meta- & para-Xylene	† · · · ·			275		µg/L	2	<2
ortho-Xylene				350		μg/L	2	<2
	NII	NL	NII.	330	4000	1 1	 	
Total Xylenes	NL	IVL	NL	1	6000	μg/L	2	<2
Sum of BTEX	 					μg/L	1 -	<1
Naphthalene	NL	NL	NL	50		μg/L	5	<5

Blank Cell indicates no criterion available

All results are in $\mu g/L$ unless stated

LOR = Limit of Reporting

ANZECC arsenic guideline based on As (III) for marine and As (V) for fresh, the lowest of presented guidelines. NHMRC arsenic guidelines are based on total arsenic

ANZECC and NHMRC guidelines for chromium are based on Cr (VI) ANZECC guidelines for mercury are based on inorganic mercury.

NHMRC guidelines for mercury are based on total mercury.

In instances where there was no marine guideline values, the freshwater guidelines have been adopted

In instances wehre there was no health drinking water guideline value, the aesthetic value has been adopted

Concentration in **red** font and grey box exceed the adopted ecosystem guideline value

Concentration in orange font and grey box exceed the adopted recreational drinking water guideline value Concentrations in blue indicate the LOR is greater than the guideline value

Concentrations below the LOR noted as <value

no HSL is presented for recreational use (HSL C) as all these chemicals are not limiting (NL)

^A NEPM 2013 HSL 'D' (Commercial/Industrial)

 $^{^{\}rm B}$ ANZECC 2000 % Protection Level for Receiving Water Type

 $^{^{\}rm C}$ NHMRC Australian Drinking Water Guidelines, 2011

ANZECC guidelines in *italics* are low level reliability guidelines



Sample Type:	ALS	ALS	
ALS Sample numb	ES1609680002	ES1609680004	
Sample date:	04/05/2016	04/05/2016	
Sample ID:	026_TP001_0.50	026_QC001	
Project Name:	M4E-WCX	M4E-WCX	
Compound:	Northcote Street Tunnel Site	Northcote Street Tunnel Site	RPD
Site:	Site 026	Site 026	
Sampling Method:	Test Pitting	Test Pitting	
Sample Description	PRIMARY	Duplicate of 026_TP001_0.5	

Analyte grouping/Analyte Mosture Content (incide © 103°C)							
Mosture Content (inted @ 103°C)	Analyte grouping/Analyte		Units	LOR			
Mosture Content (inted @ 103°C)	EAGES Malatura Contant	1					
Asserted Detected Qx No			0/		40.7	11.0	
Assertion Description	Moisture Content (dried @ 103°C)	4	%		12.7	11.8	
Assertion Description	FA200, AS 4064 2004 Identification of Ashestes in Sails			1 1	<u> </u>		
Assertion Type		-	a/ka	1 1	No		ı
Sample weight (dy)		#	g/kg	1	NO		
Description		+		1	70		
With grey rocks With grey	Sample weight (dry)	#	g	1	i i		
With grey rocks With grey					Mid brown clay soil		
APPROVED IDENTIFIER	Description				with grey rocks.		
Beautiful Beau		+		1	C MORCAN		
Arsenic mg/kg 5 16 14 13.3 Condmium mg/kg 1 1 1 1 0.0 Chromitim mg/kg 2 244 26 8.0 Copper mg/kg 5 20 28 33.3 Cold mg/kg 5 21 5 0 0 Cold mg/kg 5 21 5 0 0 Cold mg/kg 5 21 5 0 0 Cold mg/kg 5 21 5 Cold mg/kg 5 20 0 Cold mg/kg 5 20 0 Cold mg/kg 5 20 0 Cold mg/kg 5 20 5 Cold mg/kg 5 20 5 Cold mg/kg 5 0 5 Cold mg/kg 5 Cold mg/kg 5 0 5 Cold mg/kg 5 0 5 Cold mg/kg 5 Cold mg/kg 5 0 5 Cold mg/kg 5 Cold mg/	AFFROVED IDENTIFIER.	+		1	G.WORGAN		
Arsenic mg/kg 5 16 14 13.3 Condmium mg/kg 1 1 1 1 0.0 Chromitim mg/kg 2 244 26 8.0 Copper mg/kg 5 20 28 33.3 Cold mg/kg 5 21 5 0 0 Cold mg/kg 5 21 5 0 0 Cold mg/kg 5 21 5 0 0 Cold mg/kg 5 21 5 Cold mg/kg 5 20 0 Cold mg/kg 5 20 0 Cold mg/kg 5 20 0 Cold mg/kg 5 20 5 Cold mg/kg 5 20 5 Cold mg/kg 5 0 5 Cold mg/kg 5 Cold mg/kg 5 0 5 Cold mg/kg 5 0 5 Cold mg/kg 5 Cold mg/kg 5 0 5 Cold mg/kg 5 Cold mg/	EGOOET: Total Motals by ICB AES						
Cadmish			ma/ka	-	14	1.4	12.2
Coronian		+					
Copper		+				•	
Miscal		+					
Marked		+					
Re0357: Total Recoverable Mercury by FIMS		+					
Moreouty		+					
Marcury	LIIIC	+	mg/kg	5	210	229	0.3
Marcury	FG035T: Total Recoverable Mercury by FIMS	+					
Rep715 (SIM)B: Polynuclear Aromatic Hydrocarbons		+	ma/ka	0.1	0.1	-O 1	nc
Naphthalene	iwor cur y	+	mg/kg	U. I	∪.1	< U. I	IIC
Naphthalene	EBO75 (SIM) B. Bolynycloar Aromatic Hydrocarbons						
Acenaphthylene			ma/ka	0 = 1	-05	-0.5	no
Acenaphthene mg/kg 0.5 <0.5 <0.5 nc		+					
Fluorene mg/kg 0.5 <0.5 <0.5 c.0.5 nc		+					
Phenanthrene		+					
Marthracene Marka 0.5 <0.5 <0.5 <0.5 nc		+					
Fluoranthene		-					
Pyrene		+					
Benz(a)pyrene mg/kg		+					
mg/kg		-					
Benzo(b		#					
Benzo(k) Tuoranthene		+					
Benzo(a)pyrene mg/kg		-					
Indeno(1,2,3,cd)pyrene		+					
Dibenz(a,h)anthracene		<u> </u>					
Benzo(a),hi)perylene		-					
Sum of polycyclic aromatic hydrocarbons mg/kg 0.5 <0.5 <0.5 nc		-					
Benzo(a)pyrene TEO (zero)		+					
Benzo(a)pyrene TEQ (half LOR)		-					
Benzo(a)pyrene TEO (LOR)		-					
EP080/071: Total Petroleum Hydrocarbons		+					
Mg/kg	Benzo(a)pyrene TEQ (LOR)	+	mg/kg	1.2	1.2	1.2	0.0
Mg/kg	EDOGG (OZd. T-A-I D-II Ib-I				1		
C10 - C14 Fraction				100			w-
C15 - C28 Fraction		+					
C29 - C36 Fraction		+					
Mg/kg 50 <50 <50 nc		+					
PROBO/071: Total Recoverable Hydrocarbons - NEPM 2013 Fractions mg/kg		+					
C6 - C10 Fraction mg/kg 10 <10 nc C6 - C10 Fraction minus BTEX (F1) mg/kg 10 <10	CTO - CSO Fraction (Sum)	+	mg/kg	50	<50	<50	nc
C6 - C10 Fraction mg/kg 10 <10 nc C6 - C10 Fraction minus BTEX (F1) mg/kg 10 <10	EDOSO (074: Total Beautovable Hudrosovhova ALEDIA 2042 F	II		1 1			
C6 - C10 Fraction minus BTEX (F1) mg/kg 10 <10		LUUNS	ma er #1	10	.40	.10	l
SC10 - C16 Fraction		+					
SC16 - C34 Fraction (F3)		+					
SC34 - C40 Fraction (F4)		+					
C10 - C40 Fraction (sum) mg/kg 50 <50 <50 nc		+					
Post		+			< 100		
Benzene mg/kg 0.2 <0.2 <0.2 nc	> C10 - C46 Fraction minus Nanhthalana (E2)	+					
Benzene mg/kg 0.2 <0.2 <0.2 nc Toluene mg/kg 0.5 <0.5	2010 - CTO Fraction minus Naphithalene (F2)	+	mg/kg	50	<50	<50	nc
Benzene mg/kg 0.2 <0.2 <0.2 nc Toluene mg/kg 0.5 <0.5	EDOSO: RTEVN						
Toluene mg/kg 0.5 <0.5 <0.5 nc Ethylbenzene mg/kg 0.5 <0.5			ma/ka	0.2	-0.3	-0.2	no
Ethylbenzene mg/kg 0.5 <0.5 <0.5 nc meta- & para-Xylene mg/kg 0.5 <0.5		+					
meta- & para-Xylene mg/kg 0.5 <0.5 <0.5 nc ortho-Xylene mg/kg 0.5 <0.5		+					
ortho-Xylene mg/kg 0.5 <0.5 <0.5 nc Total Xylenes mg/kg 0.5 <0.5		+					
Total Xylenes mg/kg 0.5 <0.5 <0.5 nc Sum of BTEX mg/kg 0.2 <0.2		+					
Sum of BTEX mg/kg 0.2 <0.2 <0.2 nc		+					
		+					
марліпанене		+					
	парппанеле	+	mg/kg	1	<1	<1	nc
		11			L		l

nc = not calculated since results < LOR

LOR = Laboratory Limit of Reporting

BOLD identifies where RPD results

Intralaboratory	Interlaboratory	
>50	>60	where sample results are >10 x PQL
>75	>85	where sample results are > 5 to ≤10 x PQL
>100	>100	where sample results are >2 to ≤5 x PQL
AD>2.5 * PQL	•	where sample results are ≤2 x PQL
Where results are wassess duplicate per		es the most conservative criteria have been used to

Table 6: QA/QC Groundwater Sampling Results Site 026 Northcote Compound



	Sample Typ	e:	ALS	ALS	ALS
	ALS Sample		ES1611420009	ES1611420010	ES1611421010
	Sample dat	e:	23/05/2016	24/05/2016	24/05/2016
	Sample ID:		000_QA003	000_QA004	000_QA002
	Project Nar	ne:	M4E-WCX	M4E-WCX	M4E-WCX
	Compound:		NORTHCOLE STREET TUNNEL SITE GME	NORTHCOLE STREET TUNNEL SITE GME	NORTHCOLE STREET TUNNEL SITE
	Site:		SITE 006 / 012 / 026 / 027	SITE 006 / 012 / 026 / 027	SITE 006 / 012 / 026 / 027
	Sampling N	lethod:			
	Sample Des	scription	TRIP SPIKE	TRIP BLANK	TRIP BLANK
Analyte grouping/Analyte	Units	LOR			
EP080/071: Total Petroleum Hydrocarbo	ne				
C6 - C9 Fraction	μg/L	20	190	20	20
C10 - C14 Fraction	μg/L	50	170	<50	
C15 - C28 Fraction	μg/L	100		<100	
C29 - C36 Fraction	μg/L	50		<50	
C10 - C36 Fraction (sum)	μg/L	50		<50	
Carry (Carry	F-9-				
EP080/071: Total Recoverable Hydrocarl	ons - NEPM	2013 Fract	ions		
C6 - C10 Fraction	μg/L	20	210	20	20
C6 - C10 Fraction minus BTEX (F1)	μg/L	20	130	20	20
>C10 - C16 Fraction	μg/L	100		<100	
>C16 - C34 Fraction	μg/L	100		<100	
>C34 - C40 Fraction	μg/L	100		<100	
>C10 - C40 Fraction (sum)	μg/L	100		<100	
>C10 - C16 Fraction minus Naphthalene (F2)	μg/L	100		<100	
·					
EP080: BTEXN					
Benzene	μg/L	1	15	<1	<1
Toluene	μg/L	2	14	2	2
Ethylbenzene	μg/L	2	16	2	2
meta- & para-Xylene	μg/L	2	16	2	2
ortho-Xylene	μg/L	2	16	2	2
Total Xylenes	μg/L	2	32	2	2
Sum of BTEX	μg/L	1	77	<1	<1
Naphthalene	μg/L	5	17	<5	<5


nc = not calculated since results < LOR


LOR = Laboratory Limit of Reporting

BOLD identifies where RPD results

Intralaboratory	Interlaboratory	
>50	>60	where sample results are >10 x PQL
>75	>85	where sample results are > 5 to ≤10 x PQL
>100	>100	where sample results are >2 to ≤5 x PQL
AD>2.5 * PQL		where sample results are ≤2 x PQL

Where results are within two of the above ranges the most conservative criteria have been used to asset







Project No: AS121919 Client Name: CSJ Project Name: Phase 2 ESA Project Site: 027

Well ID	Easting	Easting Northing	Gauging	Total Well Depth	SWL	TOC Elevation	Groundwater Elevation
	J		Date	(m btoc)	(m btoc)	(mAHD)	(mAHD)
027_GW003			5/24/2016	10.67	2.825		

Notes

m = Metres

btoc = Below Top of Casing

SWL = Standing Water Level

TOC = Top of Casing

AHD = Australian Height Datum

Easting projection MGA94: Map Grid of Australia 1994



Project No: AS121919 Client Name: CSJ Project Name: Phase 2 ESA Project Site: 027

Well ID	Purge Date	Purge Vol (L)	DO (ppm)	EC (µScm-¹)	рН	Eh (mV)	Temperature (°C)	Comments
027_GW003	5/24/2016	3.0	0.75	1874	5.12	157	23.7	slightly turbid, no odour, sheen or PSH

Notes

L = Litre

DO = Dissolved Oxygen

ppm = parts per million

EC = Electrical Conductivity

 μ Scm- 1 = microSiemens per centimetre

Eh = Redox

mV = milli Volts

												Sample Typ	- I	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	ALS	MGT
												ALS Sample		ES1610406005	ES1610406006	ES1610406007	ES1609682001	ES1609682002	ES1609682003	ES1609682004	ES1609682005	ES1609682006	ES1610406012	S16-My15974
												Sample dat	in:	12/05/2016			04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	12/05/2016	500732 12/05/2016
												Sample ID:		027_GW003_0.2	027_GW003_0.5	027_GW003_1.0	027_TP001_0.20	027_TP001_0.50	027_TP001_0.80	027_TP002_0.15	027_TP002_0.25	027_TP002_1.30	027_QC001	027_QC002
												Project Nar	me:	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX
								NEPM 2013		CRC CARE 2011	CRC CARE 2011	Compound	.	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street
	NEPM 2013 HIL	NEPM 2013 Soil Vapour	NEPM 2013 Soil Vapour	NEPM 2013 Soil Vapour	NEPM 2013 Soil Vapour Intrusion HSL D Sand ¹ 4+m	NEPM 2013 EIL	NEPM 2013 ESL ² Commercial / Industrial	Management	CRC CARE 2011 Direct Contact ⁴ HSL D	Direct Contact ⁴ HSL for	Vapour Intrusion HSL for Intrusive Maintenance Workers Sand 0-			Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site
	D Commercial / Industrial	Intrusion HSL D	Intrusion HSL D	Intrusion HSL D	Intrusion HSL D	Industrial	Industrial	Management Limits Commercial/ Industrial ³	HSL D	Intrusive Maintenance Workers	Maintenance	Site:		Site 027	Site 027	Site 027	Site 027	Site 027	Site 027	Site 027	Site 027	Site 027	Site 027	Site 027
		Janu O-IIII	3810 1-211	300 2400	Jane 44111			Industrial 2		Workers	Workers Sand 0- <2m ³	Sampling N	netriod.	Drilling	Drilling	Drilling	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Drilling	Drilling
												Sample De	scription											
															C EX	C. IV	FLL; Clayey sit, grey with some dark grey pockets, pieces of bricks, medium plasticity, molet,	RLL; Clayey sit, grey with some dark grey pockets, pieces of bricks, possibly reworked natural, no	Sity CLAY; orange/red,	FLL; Builder's sand, cream, moist,	FILL; Clayey sit, grey/brown,	Sity CLAY; orange, moist-		
														Sandy CLAY, dark brown, low plasticity, wet	CLAY, orange/red/grey mottled, moist, low-med plasticity, becoming stiff	CLAY, orange/red/gray mottled, moist, low-med plasticity, becoming stiff	moderately stiff, perhaps very slight	anthrogogenic inclusions, no	Sity CLAY; orange/red, ironstone grawls, moist, medium-high plasticity, moist,	uniform, medium-grained, no observed contamination	moist-very moist, soft-moist, no anthropogenic inclusions	wery moist, soft, ironstone gravels, no observed	Duplicate of 027_GW003_0.2	Triplicate of 027_GW003_0.2
															pasters, seconing itin	pastery, becoming item	hydrocarbon odour, no ACM observed	observed contamination	no observed contamination	contamination	inclusions	contamination		
Analyte grouping/Analyte												Units	LOR											
EA001: pH in soil using 0.01M CaCl extract																								
pH (CaCl2)												%											****	
EA055: Moisture Content		<u> </u>	1	-	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·											<u> </u>							
Moisture Content (dried @ 103°C)												%		14	15.9	18.1	13.5	12.4	16.3		15.9	18	13.2	
EA200: AS 4964 - 2004 Identification of Asbestos in Soils																		1		1				
Asbestos Detected												g/kg		No	No	No	No	No		No	No		No	
Asbestos Type Sample weight (dry)												9	0.1	44.4	85.4	48.5	61.2	69.7		72.8	78		24.2	
														Pale brown clay	Pale orange -	Pale red clay soil	Mid brown day soil	Mid brown clay soil		Pale brown sandy	Mid brown clay		Mid brown clay soil	
Description												-		soil.	brown day soil with grey rocks.	with grey rocks.	with grey rocks.	with grey rocks.		soil.	soil.		with grey rocks.	
APPROVED IDENTIFIER:	 	—	—						 			H			S.SPOONER	1	G.MORGAN	G.MORGAN		G.MORGAN	G.MORGAN		G.MORGAN	
																							· ·	
EG005T: Total Metals by ICP-AES Arsenic	3000					160						mo/ke	5 1	10	<5	8	l 9	7	5		12	14	8	9.5
Arsenic Cadmium Chromium	900											mg/kg mg/kg	í	<1	<1	<1	1	<1	<1		1	<1	<1	< 0.4
Chromium	3600 240000					310 150			$\vdash =$			mg/kg	2	31	28 <5	33 <5	17 28	20 8	26 <5	-	38 <5	15 <5	22	28
Copper Lead	1500					1800						mg/kg mg/kg	5	38	11	17	158	37	13		14	16	7 39	21 120
Nickel	6000					60						mg/kg	2	<2	<2	<2	6	3	<2		<2	<2	<2	< 5
Zinc	400000					300						mg/kg	5	31	<5	<5	239	42	<5		<5	<5	41	140
EG035T: Total Recoverable Mercury by FIMS																		1		1				
Mercury	730											mg/kg	0.1	<0.1	< 0.1	< 0.1	<0.1	< 0.1	<0.1		< 0.1	< 0.1	<0.1	0.06
EP066: Polychlorinated Biphenyls (PCB)																								
Total Polychlorinated biphenyls	7											mg/kg	0.1				< 0.1						****	
EP068A: Organochlorine Pesticides (OC)			L																					
alpha-BHC												mg/kg	0.05	****			< 0.05				****			
Hexachlorobenzene (HCB) beta-BHC	80											mg/kg mg/kg mg/kg	0.05				< 0.05							
gamma-BHC																	<0.05 <0.05							
gamma-BHC delta-BHC	50											mg/kg	0.05	****	****	****	< 0.05	****	****	****	****	****	****	****
Heptachlor Aldrin	30											mg/kg mg/kg	0.05				<0.05 <0.05						****	
Heptachlor epoxide Total Chlordane (sum)	530											mg/kg	0.05	****	****	****	<0.05 <0.05	****	****	****	****	****	****	****
trans-Chlordane (sum)	530											mg/kg mg/kg	0.05				<0.05						****	
trans-Chlordane alpha-Endosulfan												mg/kg mg/kg	0.05				<0.05						****	****
cis-Chlordane Dieldrin												mg/kg mg/kg	0.05				<0.05 <0.05							
Dieldrin 4.4°-DDE	100											mg/kg mg/kg	0.05	****	****	****	<0.05 <0.05	****	****	****	****	****	****	****
Endrin Endosulfan (sum)	2000																< 0.05	****	****					
beta-Endosulfan 4.4'-DDD												mg/kg	0.05	****	****	****	< 0.05	****	****	****	****	****	****	
4.4°-DDD Endrin aldehvde	1		—									mg/kg mg/kg mg/kg mg/kg	0.05				<0.05 <0.05							
Endosulfan sulfate 4.4*-DDT												mg/kg	0.05		****		< 0.05	****	****	****			****	****
Endrin ketone	1	—		—		640						mg/kg mg/kg					<0.2 <0.05							
Methoxychlor Sum of DDD + DDE + DDT	2500											mg/kg	0.2		****		< 0.2						****	
Sum of DDD + DDE + DDT Sum of Aldrin + Dieldrin	3600 45	—		—								mg/kg mg/kg	0.05				<0.05 <0.05							
EP068B: Organophosphorus Pesticides (OP) Dichlorvos	T											mg/kg	0.05			T	<0.05							
Demeton-S-methyl												ma/ka	0.05				< 0.05							
Monocrotophos Dimethoate	_	<u> </u>		_	_	_	_		\vdash		_	mg/kg mg/kg	0.2				<0.2 <0.05							
Diazinon																	< 0.05							
Chlorpyrifos-methyl Parathion-methyl Malathion						_			-			mg/kg mg/kg	0.05				<0.05 <0.2							
Malathion												mg/kg	0.05				< 0.05	****						
Fenthion	2000	<u> </u>	H =						\vdash			mg/kg mg/kg	0.05				<0.05 <0.05							
Chlorpyrifos Parathion	2000											mg/kg	0.2				< 0.2							
Pirimphos-ethyl	1											mg/kg	0.05				< 0.05							
Chlorfenvinphos Bromophos-ethyl												mg/kg mg/kg	0.05				<0.05 <0.05							
Fenamiphos												mg/kg	0.05		****		< 0.05	****	****	****			****	****
Prothiofos Ethion	1			—								mg/kg mg/kg	0.05				<0.05 <0.05							
Carbophenothion												mg/kg	0.05		****		< 0.05	****	****	****			****	
Azinphos Methyl	1											mg/kg	0.05				< 0.05							
EP075(SIM)A: Phenolic Compounds	-															-	-	-	-	:				
Phenol 2-Chlorophenol	240000											mg/kg mg/kg	0.5	<0.5 <0.5	< 0.5 < 0.5	< 0.5 < 0.5	< 0.5 < 0.5						<0.5 <0.5	<0.5 <0.5
2-Methylphenol												mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5						<0.5	< 0.5
3- & 4-Methylphenol	25000								$\vdash \neg$			mg/kg mg/kg		<1 <0.5	<1 <0.5	<1 <0.5	<1 <0.5						<1	< 1
2.4-Dimethylphenol												mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5						<0.5 <0.5	<0.5 <0.5
2.4-Dichlorophenol												mg/kg mg/kg mg/kq	0.5	< 0.5	<0.5 <0.5 <0.5	< 0.5	< 0.5	****		****	****	****	<0.5	< 0.5
	1		—									mg/kg mg/kg	0.5	<0.5 <0.5	< 0.5	< 0.5	< 0.5						<0.5 <0.5	<0.5
4Chloro-3-methylohenol 2.4.6-Trichlorophenol 2.4.5-Trichlorophenol Pentachlorophenol												mg/kg mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5						< 0.5	< 0.5
2.4.5-Trichlorophenol Pentarhlorophenol	660											mg/kg mg/kg	0.5	<0.5 <2	<0.5 <2	<0.5 <2	<0.5						<0.5 <2	< 0.5
		_		_	_	_	_					Hop rod	-										5.4	

Column																									
Column														111				04/05/2016							500732
Column C												CRC CARE 2011	Sample ID: Project Name:	02	7_GW003_0.2 M4E-WCX	027_GW003_0.5 M4E-WCX	027_GW003_1.0 M4E-WCX	027_TP001_0.20 M4E-WCX	027_TP001_0.50 M4E-WCX	027_TP001_0.80 M4E-WCX	027_TP002_0.15 M4E-WCX	027_TP002_0.25 M4E-WCX	027_TP002_1.30 M4E-WCX	027_QC001 M4E-WCX	027_QC002 M4E-WCX
		NEPM 2013 HIL D Commercial /	NEPM 2013 Soil Vapour Intrusion HSL D	NEPM 2013 EIL Commercial /	NEPM 2013 ESL ² Commercial /	Management Limits	Direct Contact ⁴	CRC CARE 2011 Direct Contact ⁴ HSL for Intrusive	Vapour Intrusion HSL for Intrusive	Site:	- -	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site			
		-	Sand ¹ 0-1m	Sand ¹ 1-2m	Sand ¹ 2-4m	Sand ¹ 4+m	11001012		Industrial ³	1120	Maintenance Workers				Drilling	Drilling	Drilling			Test Pitting	Test Pitting	Test Pitting	Test Pitting	Drilling	Drilling
														Sandy	CLAY, dark brown, low planticity, wet	CLAY, crange/red/grey mottled, moist, low-med plasticity, becoming stiff	CLAY, orange/red/grey mottled, moist, low-med planticity, becoming stiff	dark grey pockets, pieces of bricks, medium plasticity, molet, moderately stiff, perhaps very slight	grey pockets, pieces of laricles, possibly reworked natural, no anthropogenic inclusions, no	Sity CLAY; orange/red, ironstone gravels, molet, medium-high plasticity, molet, no observed contamination	FEL; Builder's sand, cream, moist, uniform, medium grained, no observed contamination	FILL; Clayey sit, grey/brown, moist-very moist, soft-moist, no anthropogenic inclusions	very moist, soft, ironstone gravels, no observed	Duplicate of 027_GW003_0.2	Triplicate of 027_GW003_0.2
The column	Analyte grouping/Analyte												Units LC	OR				observed	contamination						
Column	Naphthalene		NL	NL	NL	NL	370			11000	29000	NL	mg/kg 0	0.5											
The column	Acenaphthene Fluorene												mg/kg 0 mg/kg 0	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	****	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Seminary Registration of the seminary Registration Registration of the seminary Registration Regist	Anthracene Fluoranthene												mg/kg 0 mg/kg 0	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	****	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Control Cont	Benz(a)anthracene Chrysene												mg/kg 0 mg/kg 0	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	****	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Column	Benzo(k)fluoranthene Benzo(a)pyrene							72					mg/kg 0 mg/kg 0	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	****	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	< 0.5 < 0.5
Column	Dibenz(a.h.)anthracene Benzo(g.h.i)perylene Sum of polycyclic aromatic hydrocarbons	4000											mg/kg 0 mg/kg 0 mg/kg 0	0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	****	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5
Charles	Benzo(a)pyrene TEQ (half LOR)	40											mg/kg 0 mg/kg 0	0.6						0.6	****			0.6	0.6
Column	C6 - C9 Fraction												mg/kg 1	10											
Column	C15 - C28 Fraction C29 - C36 Fraction												mg/kg 10 mg/kg 10	00	<100 <100	<100 <100	<100 <100	<100 140	<100 <100	<100 <100	****	<100 <100	<100 <100	<100 <100	<50 <50
March Marc	EP080/071: Total Recoverable Hydrocarbons - NEPM 2013 Fr.	actions							700	26000	82000	NL.	mg/kg 1	10	<10		<10	<10		<10					
Column	C6 - C10 Fraction minus BTEX (F1) >C10 - C16 Fraction >C16 - C34 Fraction (F3)		260	370	630	NL.		170 1700	1000 3500	20000 27000	62000 85000	NL.	mg/kg 1 mg/kg 5 mg/kg 1	10 50 00	<10 <50 <100	<10 <50 <100	<10 <50 <100	<10 <50 120	<10 <50 <100	<10 <50 <100		<10 <50 <100	<10 <50 <100	<10 <50 <100	< 20 < 50 < 100
The column The	>C34 - C40 Fraction (F4) >C10 - C40 Fraction (sum)		NL	NL.	NL.	NL		3300					mg/kg 10 mg/kg 5	50	<100 <50	<50	<50	300	<100 <50	<100 <50	****	<50	<50	<100 <50	****
The column	EPOSO: BTEXN Benzene												mg/kg 0	0.2		<0.2		<0.2			****	<0.2		<0.2	< 0.1
Series	Ethylbenzene meta- & para-Xylene											NL NL	mg/kg 0 mg/kg 0	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	****	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	< 0.1 < 0.2
	Total Xylenes Sum of BTEX						370	95					mg/kg 0 mg/kg 0	0.5	<0.5 <0.2	<0.5 <0.2	<0.5 <0.2	<0.5 <0.2	<0.5 <0.2	<0.5 <0.2	****	< 0.2	<0.5 <0.2	< 0.5	< 0.3
Company	EP074A: Monocyclic Aromatic Hydrocarbons Styrene												mg/kg 0	0.5	<0.5	<0.5	<0.5		****		****				<0.5
Company	Isopropylbenzene n-Propylbenzene 1.3.5-Trimethylbenzene												mg/kg 0 mg/kg 0	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	****	****		****	****	****	<0.5 <0.5	<0.5 <0.5
Amount	1.2.4-Trimethylbenzene tert-Butylbenzene												mg/kg 0 mg/kg 0	0.5	<0.5	< 0.5	< 0.5	****	****		****			<0.5 <0.5	<0.5 <0.5
Taken and the late of the late	n-Butylbenzene												mg/kg 0 mg/kg 0		<0.5 <0.5	<0.5 <0.5	<0.5 <0.5					****	****	<0.5 <0.5	<0.5 <0.5
Column	Vinyl Acetate 2-Butanone (MEK)												mg/kg !	5	<5	<5	<5							<5	<5
Company Comp	2-Hexanone (MBK)												mg/kg	5		<5	<5	****	****		****	****	****	<5	
	Carbon disulfide EP074D: Fumigants													!									****		
	1.2-Dichloropropane cis-1.3-Dichloropropylene												mg/kg 0 mg/kg 0	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	****	****		****	****	****	<0.5 <0.5	<0.5 <0.5
Seminorial III III III III III III III III III I	1.2-Dibromoethane (EDB)												mg/kg 0	0.5				****	****	****	****	****			<0.5
Company	Dichlorodifluoromethane Chloromethane												mg/kg	5	<5	<5	<5	****	****		****		****	<5	<5
Column	Bromomethane Chloroethane Trichlorofluoromethane												mg/kg mg/kg	5 5	<5 <5	<5 <5	<5 <5	****	****		****	****	****	<5 <5	<5 <5
ALMORPHICAL 1	Iodomethane trans-1.2-Dichloroethene												mg/kg 0 mg/kg 0	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	****	****		****	****	****	<0.5 <0.5	<0.5 <0.5
General Control Contro	cls-1.2-Dichloroethene 1.1.1-Trichloroethane												mg/kg 0 mg/kg 0	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	****	****	****	****	****	****	<0.5 <0.5	<0.5 <0.5
Company Comp	Carbon Tetrachloride 1.2-Dichloroethane												mg/kg 0 mg/kg 0	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	****	****		****			<0.5 <0.5	<0.5 <0.5
Company Comp	Dibromomethane 1.1.2-Trichloroethane												mg/kg 0 mg/kg 0	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	****	****		****	****	****	<0.5 <0.5	<0.5 <0.5
All All Martingers	Tetrachloroethene 1.1.1.2-Tetrachloroethane trans-1.4-Dichloro-2-butene												mg/kg 0 mg/kg 0 mg/kg 0	0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	****	****					<0.5 <0.5 <0.5	<0.5 <0.5 <0.5
Company Comp	cis-1.4-Dichloro-2-butene 1.1.2.2-Tetrachloroethane 1.2.3-Trichloropropane												mg/kg 0 mg/kg 0 mg/kg 0	0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5		****					<0.5 <0.5 <0.5	<0.5 <0.5 <0.5
Company Comp	Pentachloroethane 1.2-Dibromo-3-chloropropane												mg/kg 0 mg/kg 0	0.5	< 0.5				****		****			< 0.5	< 0.5 < 0.5
Company Comp	Chlorobenzene												mg/kg 0	0.5			<0.5 <0.5		****		****			<0.5	<0.5
14 Continuence	2-Chlorotoluene 4-Chlorotoluene												mg/kg 0 mg/kg 0	0.5	<0.5 <0.5	< 0.5	< 0.5		****		****		****	< 0.5	<0.5 <0.5
13 14 15 16 16 16 16 16 16 16	1.4-Dichlorobenzene 1.2-Dichlorobenzene 1.2.4-Trichlorobenzene												mg/kg 0 mg/kg 0 mg/kg 0	0.5	<0.5 <0.5 <0.5			****	****		****				<0.5 <0.5 <0.5
Second	1.2.3-Trichlorobenzene EP074G: Trihalomethanes												mg/kg 0	0.5	<0.5				****		****		****		<0.5
No. No. No. No. No. No. No. No. No. 1700 2000 50. 1000 2000 50. 1000 2000 50. 1000 2000 50. 1000 2000 50. 1000 2000	Bromodichloromethane Dibromochloromethane												mg/kg 0	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		****		****			<0.5 <0.5	<0.5 <0.5
Part	EP074H: Naphthalene		NI NI	MI	NI NI	NI NI	370			11000	29000	NL.		!		<0.5	<0.5							<0.5	
2-Chiesenphilates	EP075B: Polynuclear Aromatic Hydrocarbons									,,,,,,,,			mg/kg 0	0.5										<0.5	
	2-Chloronaphthalene N-2-Fluorenyl Acetamide 7.12-Dimethylbenz(a)anthracene												mg/kg 0 mg/kg 0 mg/kg 0	0.5		<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	****						<0.5 <0.5 <0.5	
Descript phthalists	3-Methylcholanthrene EP075C: Phthalate Esters		_										mg/kg 0	0.5		<0.5	<0.5		****		****			<0.5	
Security	Dimethyl phthalate Diethyl phthalate Di-n-butyl phthalate												mg/kg 0 mg/kg 0	0.5		<0.5 <0.5	<0.5 <0.5	****	****		****			<0.5 <0.5	
NAMPs consent fly definition in the Name of the Name o	bis(2-ethylhexyl) phthalate												mg/kg	5	****	<5.0	<5.0	****	****		****		****	<5.0	
Nationapprovides mg/kg 1 <10 <10 .	N-Nitrosomethylethylamine					-							mg/kg 0	0.5	****	<0.5 <0.5		****	****		****			<0.5 <0.5	
Nationappendates	N-Nitrosopyrrolidine N-Nitrosomorpholine N-Nitrosodi-n-propylamine												mg/kg 0 mg/kg 0	0.5	****	<1.0 <0.5 <0.5	<1.0 <0.5 <0.5	****						<1.0 <0.5 <0.5	
Methagrefries	N-Nitrosopiperidine N-Nitrosodibutylamine N-Nitrosodiphenyl & Diphenylamine												mg/kg 0 mg/kg 0 mg/kg	0.5 0.5	****	<0.5 <0.5 <1.0	<0.5 <0.5 <1.0	****	****	****	****	****	****	<0.5 <0.5 <1.0	
Mactodynamos	Methapyrilene EP075E: Nitroaromatics and Ketones												mg/kg 0	0.5		<0.5	<0.5							<0.5	
26.Digitatione	Acetophenone Nitrobenzene												mg/kg 0 mg/kg 0	0.5	****	<0.5 <0.5	<0.5 <0.5	****	****	****	****	****	****	<0.5 <0.5	
	2.6-Dinitrotoluene												ma/ka	1 II	****	<1.0	<1.0	****	****	****	****	****	****	<1.0	

												Sample Type:	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	ALS	MGT
												ALS Sample number	ES1610406005	ES1610406006	ES1610406007	ES1609682001	ES1609682002	ES1609682003	ES1609682004	ES1609682005	ES1609682006	ES1610406012	S16-My1597-
												Sample date:	12/05/2016	12/05/2016	12/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	12/05/2016	12/05/2016
												Sample ID:	027_GW003_0.2	027_GW003_0.5	027_GW003_1.0	027_TP001_0.20	027_TP001_0.50	027_TP001_0.80	027_TP002_0.15	027_TP002_0.25	027_TP002_1.30	027 00001	027_QC002
												Project Name:	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4F,WCX	M4F,WCX
	NEPM 2013 HIL	NEPM 2013 Soil Vapour	NEPM 2013 Soil	NEPM 2013 Soil Vapour	NEPM 2013 Soil Vapour	NEPM 2013 EIL		NEPM 2013 Management	CRC CARE 2011	CRC CARE 2011 Direct Contact ⁶ HSL for	Intrusion HSL	Compound:	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Stre Tunnel Site
	D Commercial /	Intrusion HSL D	Intrusion HSL D	Intrusion HSL D		Commercial /	Commercial /	Limits	Direct Contact ⁴	Intrusive	for Intrusive	Site:	Site 027	Site 027	Site 027	Site 027	Site 027	Site 027	Site 027	Site 027	Site 027	Site 027	Site 027
	Industrial	Sand ¹ 0-1m	Sand ¹ 1-2m	Sand ¹ 2-4m	Sand ¹ 4+m	Industrial	Industrial	Commercial/ Industrial ³	HSL D	Maintenance Workers	Maintenance Workers Sand 0- <2m ¹	Sampling Method:	Drilling	Drilling	Drilling	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Drilling	Drilling
												Sample Description	Sandy CLAY, dark brown, lo- plasticity, wet	CLAY, orange/ind/grey motified, maid, low-med plusticity, becoming stiff		Fit.: Clayer sit, gray with some dark gray pockets, pieces of bricks medium plasticity, molet, moderately stiff, perhaps very sligh hydrocarbon odour, no ACM observed	RLL: Clayey six, grey with some dark grey poolers, pieces of bricks, possibly neworked natural, no anthropogenic inclusions, no observed contamination	Silty CLAY; orange/red, itoestone grawls, moist, medium-high plasticity, moist, no observed contamination	Fit: Builder's sand, cream, moist, uniform, medium grained, no observed contamination	FILL; Clayey sit, grey/brown, moist-very moist, soft-moist, no anthropogenic inclusions	Sity CLAY, orange, moist- wey moist, soft, incedone gravels, no observed contamination	Duplicate of 027_GW003_0.2	Triplicate of 027_GW003_0
Analyte grouping/Analyte												Units LOR											
1-Naphthylamine												mg/kg 0.5		< 0.5	< 0.5	****		****	****	****		<0.5	
4-Nitroquinoline-N-oxide												mg/kg 0.5	****	< 0.5	< 0.5	****		****	****	****		<0.5	
5-Nitro-o-toluidine	_											mg/kg 0.5		< 0.5	< 0.5							<0.5	****
Azobenzene												mg/kg 1		<0.5	<0.5		****	****	****	****	****	<1	****
1.3.5-Trinitrobenzene												mg/kg 0.5					****		****	****	****	<0.5	****
Phenacetin												mg/kg 0.5		< 0.5	< 0.5							< 0.5	
4-Aminobiphenyl												mg/kg 0.5 mg/kg 0.5		<0.5	< 0.5			****	****			<0.5	
Pentachloronitrobenzene Pronamide	_					_			_			mg/kg 0.5		< 0.5	<0.5		****			****		< 0.5	
Pronamide Dimethylaminoazobenzene	_					_			_			mg/kg 0.5		< 0.5	< 0.5							<0.5	
Dimetriyiaminoazobenzene Chlorobenzilate					 							mg/kg 0.5		×0.5	< 0.5							< 0.5	

												Sample Ty	pe:	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	ALS	MGT \$16-Mv15974		
												ALS Sampl	le number:	ES1610406005	ES1610406006	ES1610406007	ES1609682001	ES1609682002	ES1609682003	ES1609682004	ES1609682005	ES1609682006	ES1610406012	516-My159 500732		
												Sample da	ite:	12/05/2016	12/05/2016	12/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	12/05/2016	12/05/20		
												Sample ID		027_GW003_0.2		027_GW003_1.0		027_TP001_0.50	027_TP001_0.80	027_TP002_0.15	027_TP002_0.25		027_QC001	027_QC0		
	-											Project Na	ime:	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WC		
								NEPM 2013		CRC CARE 2011	CRC CARE 2011 Vapour	Compound	:	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Street	Northcote Str		
	NEPM 2013 HIL			NEPM 2013 Soil Vapour	NEPM 2013 Soil Vapour	NEPM 2013 EIL	NEPM 2013 ESL ²	Management Limits	CRC CARE 2011	Direct Contact ⁴ HSL for	Intrusion HSL for Intrusive			Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site		
	D Commercial / Industrial	Intrusion HSL D Sand ¹ 0-1m	Vapour Intrusion HSL D Sand ¹ 1-2m	Vapour Intrusion HSL D Sand 12-4m	Vapour Intrusion HSL D Sand ¹ 4+m	Commercial / Industrial	Commercial / Industrial	Commercial/	Direct Contact ⁴ HSL D	Intrusive Maintenance	Maintenance	Site:		Site 027	Site 027	Site 027	Site 027	Site 027	Site 027	Site 027	Site 027	Site 027	Site 027	Site 027		
		Sand 0-1m	Sand 1-2m	Sand 2-4m	Sand 4+m			Industrial ³		Workers	Workers Sand 0- <2m ¹	Sampling I	Method:	Drilling	Drilling	Drilling	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Drilling	Drilling		
											<2m	Sample De	scription													
																	FEL; Clayey silt, grey with some dark grey pockets, pieces of bricks,	RLL; Clayey sit, grey with some dark grey pockets, pieces of bricks,	Sitty CLAY; orange/red,	FEL; Builder's sand, cream, moist,	FILL; Clayery sit, grey/brown,	Sity CLAY; orange, molet-				
												II		Sandy CLAY, dark brown, low	CLAY, orange/red/grey mottled, moist, low-med	CLAY, orange/red/grey mottled, moist, low-med	medium plasticity, molet, moderately stiff, perhaps very slight	possibly reworked natural, no	ironstone gravels, moist, medium-high plasticity, moist,	uniform, medium grained, no	moist-very moist, soft-moist,	very malst, soft, ironstone	Duplicate of	Triplicate o		
												II		plasticity, wet	plasticity, becoming stiff	plasticity, becoming stiff	hydrocarbon odour, no ACM	anthropogenic inclusions, no observed	no observed contamination	observed contamination	no anthropogenic inclusions	gravels, no observed contamination	027_GW003_0.2	027_GW003_		
												II .					abserved	contamination								
Analyte grouping/Analyte												Units	LOR													
EP075F: Haloethers Bis(2-chloroethyl) ether												mo/kn	0.5		<0.5	<0.5							<0.5			
Bis(2-chloroethoxy) methane												mg/kg	0.5		< 0.5	< 0.5							< 0.5			
4-Chlorophenyl phenyl ether												mg/kg	0.5		< 0.5	< 0.5		****					< 0.5	****		
4-Bromophenyl phenyl ether												mg/kg	0.5		< 0.5	< 0.5		****					<0.5			
EP075G: Chlorinated Hydrocarbons												Ш														
EP075G: Chlorinated Hydrocarbons 1.3-Dichlorobenzene	Paging 0.5 .															<0.5										
1.4-Dichlorobenzene	mpkg 0.5																									
1.2-Dichlorobenzene	mpkg 05																									
Hexachloroethane	mg/kg 0.5																									
1.2.4-Trichlorobenzene	mplg 05																									
Hexachloropropylene Hexachlorobutadlene	mpkg 0.5																									
Hexachlorocyclopentadiene Hexachlorocyclopentadiene	mg/kg 0.5																									
Pentachlor deyclopentaciene Pentachlorobenzene	mg/kg 0.5 <0.5 <0.5														<0.5											
Hexachlorobenzene (HCB)	mg/kg 0.5 <0.5 <0.5														<1.0											
	mglq 0.5																									
EP075H: Anilines and Benzidines Aniline	mg/kg 0.5 <0.5 <0.5																									
4-Chloroaniline	mg/kg 0.5 0.5 0.5														<0.5											
2-Nitroaniline	mg/kg 0.5 .0.5 .0.5														<1.0											
3-Nitroaniline															<1.0											
Dibenzofuran															<0.5											
4-Nitroaniline															<0.5	****										
Carbazole 3.3` -Dichlorobenzidine												mg/kg			<0.5	<0.5							<0.5			
3.5 -Dichloroberizidhe												IIIg/kg	0.3		10.3	10.3										
						•					-			-		•								•		
Blank Cell indicates no criterion available LOR = Limit of Reporting																										
National Environment Protection Council (2013) National Environmental Protection	rtinn (Assessment of	Site Contamination) Amondment Meas	ure 2013 (No. 1) (N	FPM																					
CRC Care Technical Report no.10, Health Screening Levels for petroleum hydr																										
¹ For soil texture classification undertaken in accord with AS 1726, the classifi				with liquid limit < 50	% and fine with line	uid limit >50% respect	tively as the underly	lvino oronarties to de	velon the HSI's ma	v reasonably be sele	rted to be similar. V	Mhore there is ur	nortainty													
either a conservative approach may be adopted or laboratory analysis should	be carried out.	na ciny may be appr	ING BY COM M, INN 1	min inquio initi 130	A and the will high	au mini zao a respec	inery, as the dident	iyang proper ses to de	nemap and risks may	y reasonably be also	CALC IO DE ATTIME. V	andre und e is di	Lucianity,													
² The most conservative ESL guideline value has been adopted for all analyter																										
³ Management limits are applied after consideration of relevant ESLs and HSL.	. Separate managem	ent limits for BTEX a	and naphthalene ar	e not available heno	e these should not b	be subtracted from th	e relevant fractions	to obtain F1 and F2.																		
⁴ Direct Contact are applied to surface soils or soils that could result in immed	ate contact.																									
NL = Non Limiting. No HSL is presented for these chemicals as a soil vapour s Health Investigation Levels for chromium based on chromium (VI)	ource concentration f	or a petroleum mixti	ture could not excee	d a level that would	result in the maxim	num allowable vapour	risk for the given so	cenario.																		
Chromium (III) Ell., based on a low clay content (% clay) of 1%																										
Site specific EILs for copper in italics are based on the average of soil pH, cati	on evrhanne ranarity	and organic content	e .																							
Site specific EILs for nickel in italics are based on the average of soil cation e																										
Site specific EILs for zinc in italics are based on the average of soil pH and ca		y																								
To obtain F1 subtract the sum of BTEX concentrations from the C6-C10 fraction	n.																									
To obtain F2 subtract naphthalene from the >C10-C16 fraction.																										
Benzo(a)Pyrene ESL adopted values based on Canadian Council of Ministers of Concentration in red font and grey box exceed the adopted HIL/HSL 'D' for co Concentration in orange font and grey box exceed the adopted EIL/ESL 'D' for	mmercial/industrial u	se	es developed using	a species sensitivity	distribution (SSD) f	for eco-toxicity data f	from five independen	nt studies involving t	three soil invertebra	ate taxa and two plan	nt taxa (14 endipoint	ts) in preference	to NEPM low	reliability data.												
	ct for commercial/ind	strial use																								
Concentration in blue font and grey box exceed the adopted management lim Concentration in green and grey box exceed the adopted HSL 'D' direct conta																										
Concentration in green and grey box exceed the adopted HSL 'D' direct conta Concentration in light blue and grey box exceed the adopted HSL direct cont	for Intrusive Mainten	ance Workers																								
Concentration in green and grey box exceed the adopted HSL 'D' direct conta Concentration in light blue and grey box exceed the adopted HSL direct cont Concentration in pink and grey box exceed the adopted HSL vapour intrusion																										
Concentration in green and grey box exceed the adopted HSL 'D' direct conta Concentration in light blue and grey box exceed the adopted HSL direct cont Concentration in jurks and grey box exceed the adopted HSL vapour intrusion Concentration in box exceed the screening value >2.5 times																										
Concentration in green and grey box exceed the adopted HSL. "Or direct control Concentration in light tiles and grey box exceed the adopted HSL direct cont Concentration in clink and grey box exceed the adopted HSL vapour intrusion Concentrations in box exceed the screening value > 2.5 times Where one or more guideline value is exceeded, the highest guideline value																										
concentration in green and grey box exceed the adopted HSL "D' direct conta- concentration in light bits and grey box exceed the adopted HSL direct cont- concentration in greet and grey box exceed the adopted HSL support intrusion concentrations in box exceed the screening value > 2.5 times. Where one or more guideline value is exceeded, the highest guideline value concentrations below the LOR noted as «value.																										
Concentration in green and grey box exceed the adopted HSL 'D' direct conta Concentration in light blue and grey box exceed the adopted HSL direct cont Concentration in jurks and grey box exceed the adopted HSL vapour intrusion Concentration in box exceed the screening value >2.5 times														Dates the LaC Product as - value (White Lace Code)												
Concentration in green and grey box exceed the adopted HSL TV direct context. Occorrelation in set bits and grey be exceed the adopted HSL direct cont Descentration in each and grey box exceed the adopted HSL support intrusion Concentrations in box exceed the streaming value > 2.5 times Where one or more guideline value is exceeded, the highest guideline value Concentrations below the LOR noted as value Chr. Chryscalie, lends associated.																										

		– Comm ndustria		95% Marine Water Protection for Aquatic Ecosystems ^B	Recreational Health (10x ADWG 2011) ^c	Sample Ty ALS Sample Sample da Sample ID Project Na Compound Site: Sampling I	e number: te: : me:	Groundwater ES1611420005 24/05/2016 027_GW003 M4E-WCX NORTHCOLE STREET TUNNEL SITE GME SITE 027 Bailer	Groundwater ES1611420010 24/05/2016 000_QA004 M4E-WCX NORTHCOLE STREET TUNNEL SITE GME SITE 027	Groundwater ES1611421010 24/05/2016 000_QA002 M4E-WCX NORTHCOLE STREET TUNNEL SITE SITE 027
Guidelines	2 to <4m	4m to<8m	8m+			Sample De		PRIMARY	TRIP BLANK	TRIP BLANK
Analyte grouping/Analyte						Units	LOR			
EG020T: Dissolved Metals by ICP-MS										
Arsenic Cadmium				2.3 0.7	100 20	μg/L μg/L	0.1	<1 0.1		
Chromium				4.4	500	μg/L	1	<1		
Copper Nickel				1.3 7	20000	μg/L μg/L	1	4		
Lead				4.4	100	μg/L	1	52		
Zinc				15		μg/L	5	118		
EG035F: Dissolved Mercury by FIMS										
Mercury				0.1	10	μg/L	0.1	<0.1		
VOCs			1		ı				I .	I .
Styrene Isopropylbenzene						μg/L μg/L	5 5	<5 <5		
n-Propylbenzene						μg/L μg/L	5	<5 <5		
1.3.5-Trimethylbenzene						μg/L	5	<5 <5		
sec-Butylbenzene 1.2.4-Trimethylbenzene						μg/L μg/L	5 5	<5 <5		
tert-Butylbenzene						μg/L	5	<5		
p-Isopropyltoluene n-Butylbenzene						μg/L μg/L	5 5	<5 <5		
Vinyl Acetate						μg/L	50	<50		
2-Butanone (MEK) 4-Methyl-2-pentanone (MIBK)						μg/L μg/L	50 50	<50 <50		
2-Hexanone (MBK)						μg/L	50	<50		
Carbon disulfide 2.2-Dichloropropane						μg/L μg/L	5	<5 <5		
1.2-Dichloropropane						μg/L	5	<5		
cis-1.3-Dichloropropylene trans-1.3-Dichloropropylene						μg/L	5	<5		
1.2-Dibromoethane (EDB)						μg/L μg/L	5 5	<5 <5		
Dichlorodifluoromethane						μg/L	50	<50		
Chloromethane Vinyl chloride					3	μg/L μg/L	50 50	<50 <50		
Bromomethane						μg/L	50	<50		
Chloroethane Trichlorofluoromethane						μg/L μg/L	50 50	<50 <50		
1.1-Dichloroethene					300	μg/L	5	<5		
Iodomethane trans-1.2-Dichloroethene						μg/L μg/L	5 5	<5 <5		
1.1-Dichloroethane						μg/L	5	<5		
cis-1.2-Dichloroethene 1.1.1-Trichloroethane						μg/L	5 5	<5 <5		
1.1-Dichloropropylene						μg/L μg/L	5	<5 <5		
Carbon Tetrachloride						μg/L	5	<5		
1.2-Dichloroethane Trichloroethene					30	μg/L μg/L	5 5	<5 <5		
Dibromomethane				1000		μg/L	5	<5		
1.1.2-Trichloroethane 1.3-Dichloropropane				1900		μg/L μg/L	5 5	<5 <5		
Tetrachloroethene					500	μg/L	5	<5		
1.1.1.2-Tetrachloroethane trans-1.4-Dichloro-2-butene						μg/L μg/L	5 5	<5 <5		
cis-1.4-Dichloro-2-butene						μg/L	5	<5		
1.1.2.2-Tetrachloroethane 1.2.3-Trichloropropane						μg/L μg/L	5 5	<5 <5		
Pentachloroethane						μg/L	5	<5		
1.2-Dibromo-3-chloropropane Hexachlorobutadiene						μg/L μg/L	5 5	<5 <5		
Chlorobenzene				55	3000	μg/L μg/L	5	<5		
Bromobenzene 2-Chlorotoluene						μg/L	5 5	<5 <5		
4-Chlorotoluene						μg/L μg/L	5	<5 <5		
1.3-Dichlorobenzene				260	400	μg/L	5	<5		
1.4-Dichlorobenzene 1.2-Dichlorobenzene				60 160	400 15000	μg/L μg/L	5 5	<5 <5		
1.2.4-Trichlorobenzene				20	300	μg/L	5	<5		
1.2.3-Trichlorobenzene Chloroform				3	300	μg/L μg/L	5 5	<5 <5		
Bromodichloromethane						μg/L	5	<5		
Dibromochloromethane Bromoform						μg/L μg/L	5 5	<5 <5		
Naphthalene				50		μg/L	5	<5		
EP075(SIM)A: Phenolic Compounds										
Phenol				400		μg/L	1	<1.0		
2-Chlorophenol 2-Methylphenol				340	3000	μg/L μg/L	1	<1.0 <1.0		
3- & 4-Methylphenol						μg/L	2	<2.0		
2-Nitrophenol 2.4-Dimethylphenol				2 2		μg/L μg/L	1	<1.0 <1.0		
2.4-Dichlorophenol				120	2000	μg/L μg/L	1	<1.0		
2.6-Dichlorophenol 4-Chloro-3-methylphenol				34		μg/L μg/l	1	<1.0		
2.4.6-Trichlorophenol				3	200	μg/L μg/L	1	<1.0 <1.0		
2.4.5-Trichlorophenol		_		4		μg/L	1	<1.0		

TABLE 4: **Groundwater Sampling Results** Northcote Compound Site - 027



						T I	1	1		
						Sample Typ	pe:	Groundwater	Groundwater	Groundwater
						ALS Sample	e number:	ES1611420005	ES1611420010	ES1611421010
						Sample dat	te:	24/05/2016	24/05/2016	24/05/2016
	HSL D	- Comm	ercial/			Sample ID:	:	027_GW003	000_QA004	000_QA002
		ndustria		95% Marine		Project Na	me:	M4E-WCX	M4E-WCX	M4E-WCX
	•	nuustiia	•	Water Protection for Aquatic	Recreational Health (10x	Compound		NORTHCOLE STREET TUNNEL	NORTHCOLE STREET TUNNEL	NORTHCOLE STREET TUNNEI
				Ecosystems ^B	ADWG 2011) ^c			SITE GME	SITE GME	SITE
						Site:		SITE 027	SITE 027	SITE 027
						Sampling N	/lethod:	Bailer		
Guidelines	2 to <4m	4m to<8m	8m+			Sample De	scription	PRIMARY	TRIP BLANK	TRIP BLANK
Analyte grouping/Analyte						Units	LOR			
Analyte grouping/Analyte						Ollits	LOR			
Pentachlorophenol				22	100	μg/L	2	<2.0		
EP075(SIM)B: Polynuclear Aromatic Hy	udrocarbo.	ns				Ш				
Naphthalene	, ar ocar bo			50		LIG/I	1	<1.0		
Acenaphthylene				30		μg/L	1	<1.0		
	1					μg/L	1			
Acenaphthene Fluorene	1	-				μg/L	1	<1.0		
				2.4		μg/L		<1.0		
Phenanthrene				0.6		μg/L	1	<1.0		
Anthracene				0.01		μg/L	1	<1.0		
Fluoranthene				1		μg/L	1	<1.0		
Pyrene						μg/L	1	<1.0		
Benz(a)anthracene						μg/L	1	<1.0		
Chrysene						μg/L	1	<1.0		
Benzo(b+j)fluoranthene						μg/L	1	<1.0		
Benzo(k)fluoranthene						μg/L	1	<1.0		
Benzo(a)pyrene				0.1	0.1	μg/L	0.5	<0.5		
Indeno(1.2.3.cd)pyrene						μg/L	1	<1.0		
Dibenz(a.h)anthracene						μg/L	1	<1.0		
Benzo(g.h.i)perylene						μg/L	1	<1.0		
Sum of polycyclic aromatic hydrocarbons						μg/L	0.5	<0.5		
Benzo(a)pyrene TEQ (zero)						μg/L	0.5	<0.5		
Benzo(a)pyrene TEQ (zero)						pg/L	0.5	V0.5		
EP080/071: Total Petroleum Hydrocark	oons									
C6 - C9 Fraction						μg/L	20	<20	<20	<20
C10 - C14 Fraction						μg/L	50	<50	<50	
C15 - C28 Fraction						μg/L	100	<100	<100	
C29 - C36 Fraction						μg/L	50	<50	<50	
C10 - C36 Fraction (sum)						μg/L	50	<50	<50	
ore coerraction (sam)						pg/ L	50	100	430	
EP080/071: Total Recoverable Hydroca	arbons - N	EPM 201	3 Fractio	ons					1	
C6 - C10 Fraction						μg/L	20	<20	<20	<20
C6 - C10 Fraction minus BTEX (F1)	6200	6300	6500			μg/L	20	<20	<20	<20
>C10 - C16 Fraction						μg/L	100	<100	<100	
>C16 - C34 Fraction						μg/L	100	<100	<100	
>C34 - C40 Fraction						μg/L	100	<100	<100	
>C10 - C40 Fraction (sum)						μg/L	100	<100	<100	
>C10 - C16 Fraction minus Naphthalene (F2	2 NL	NL	NL			μg/L	100	<100	<100	
EP080: BTEXN		<u> </u>								
Benzene	4900	5100	5400	500	8000	LIG/I	1	<1	<1	<1
Toluene	4900 NL	NL	NL	180	3000	μg/L				
						μg/L	2	<2	<2	<2
Ethylbenzene	NL	NL	NL	5	8000	μg/L	2	<2	<2	<2
meta- & para-Xylene		_		275		μg/L	2	<2	<2	<2
ortho-Xylene				350		μg/L	2	<2	<2	<2
Total Xylenes	NL	NL	NL		6000	μg/L	2	<2	<2	<2
Sum of BTEX						μg/L	1	<1	<1	<1
Nanhthalana	NII	NII	NII	50		1.1	5	5	-5	-5

Blank Cell indicates no criterion available

All results are in µg/L unless stated

LOR = Limit of Reporting

Naphthalene

ANZECC arsenic guideline based on As (III) for marine and As (V) for fresh, the lowest of presented guidelines.

NL

NL

NL

50

NHMRC arsenic guidelines are based on total arsenic

ANZECC and NHMRC guidelines for chromium are based on Cr (VI) ANZECC guidelines for mercury are based on inorganic mercury.

NHMRC guidelines for mercury are based on total mercury.

In instances where there was no marine guideline values, the freshwater guidelines have been adopted In instances wehre there was no health drinking water guideline value, the aesthetic value has been adopted

Concentration in red font and grey box exceed the adopted ecosystem guideline value

Concentration in orange font and grey box exceed the adopted recreational drinking water guideline value Concentrations in blue indicate the LOR is greater than the guideline value

Concentrations below the LOR noted as <value

no HSL is presented for recreational use (HSL C) as all these chemicals are not limiting (NL)

^A NEPM 2013 HSL 'D' (Commercial/Industrial)

 $^{^{\}rm B}$ ANZECC 2000 % Protection Level for Receiving Water Type

^c NHMRC Australian Drinking Water Guidelines, 2011

ANZECC guidelines in *italics* are low level reliability guidelines

				ī				
	Sample 1 ALS Sam	ype: ple number:	ALS ES1610406005	ALS ES1610406012		ALS ES1610406005	MGT S16-My15974 500732	•
	Sample of	late:	12/05/2016 027_GW003_0.2	12/05/2016 027_QC001		12/05/2016 027_GW003_0.2	12/05/2016 027_QC002	
	Project N Compour	lame:	M4E-WCX Northcote Street	M4E-WCX Northcote Street	RPD	M4E-WCX Northcote Street	M4E-WCX Northcote Street	RPD
	Site:	iu:	Tunnel Site Site 027	Tunnel Site Site 027		Tunnel Site Site 027	Tunnel Site Site 027	
	Sampling	Method:	Drilling	Drilling	-	Drilling	Drilling	:
	Sample I	Description	PRIMARY	Duplicate of 027_GW003_0.2		PRIMARY	Triplicate of 027_GW003_0.2	
Analyte grouping/Analyte	Units	LOR						
EA055: Moisture Content Moisture Content (dried @ 103°C)	%		14.0	13.2		14.0		
EA200: AS 4964 - 2004 Identification of Asbestos in Soils								
Asbestos Detected Asbestos Type Sample weight (dry)	g/kg g		No - 44.4	No - 24.2		No - 44.4		
Sample weight (dry)			Pale brown clay soil.	Mid brown clay soil		Pale brown clay soil.		
Description APPROVED IDENTIFIER:			G.MORGAN	with grey rocks. G.MORGAN		G.MORGAN		
EG005T: Total Metals by ICP-AES								
Arsenic Cadmium	mg/kg mg/kg	5	10	8 <1	22.2 nc	10	9.5	5.1 nc
Chromium Copper Lead	mg/kg mg/kg mg/kg	5 5	31 6 38	22 7 39	34.0 15.4 2.6	31 6 38	28 21 120	10.2 111.1 103.8
Nickel Zinc	mg/kg mg/kg	2 5	<2 31	<2 41	nc 27.8	<2 31	< 5 140	nc 127.5
EG035T: Total Recoverable Mercury by FIMS					2110			
Mercury	mg/kg	0.1	<0.1	<0.1	nc	<0.1	0.06	nc
EPO75(SIM)A: Phenolic Compounds Phenol	mg/kg	0.5	<0.5	<0.5	nc	<0.5	<0.5	nc
2-Chlorophenol 2-Methylphenol 3- & 4-Methylphenol	mg/kg mg/kg mg/kg	0.5 0.5	<0.5 <0.5 <1	<0.5 <0.5 <1	nc nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
2.4-Dimethylphenol	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	< 1 <0.5 <0.5	nc nc
2.4-Dichlorophenol 2.6-Dichlorophenol	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5	nc
4-Chloro-3-methylphenol 2.4.6-Trichlorophenol	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
2.4.5-Trichlorophenol Pentachlorophenol	mg/kg mg/kg	0.5	<0.5 <2	<0.5 <2	nc nc	<0.5 <2	<0.5 < 1	nc nc
EP075(SIM)B: Polynuclear Aromatic Hydrocarbons Vaphthalene	mg/kg	0.5	<0.5	<0.5	nc	<0.5	<0.5	nc
vapntnaiene Acenaphthylene Acenaphthene	mg/kg mg/kg mg/kg	0.5 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc
Fluorene Phenanthrene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
Anthracene Fluoranthene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
Pyrene Benz(a)anthracene Prysene	mg/kg mg/kg mg/ka	0.5 0.5 0.5	<0.5 <0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
Chrysene 3enzo(b+j)fluoranthene 3enzo(k)fluoranthene	mg/kg mg/kg mg/kg	0.5 0.5 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc nc	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc
senzo(s)nuoranmene Senzo(a)pyrene Indeno(1.2.3.cd)pyrene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5 <0.5	nc nc	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc
Dibenz(a.h) anthracene Benzo(g.h.i) perylene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
Sum of polycyclic aromatic hydrocarbons Benzo(a)pyrene TEO (zero)	mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
Benzo(a)pyrene TEO (half LOR) Benzo(a)pyrene TEO (LOR)	mg/kg mg/kg	0.6 1.2	0.6 1.2	0.6 1.2	0.0	0.6 1.2	0.6 1.2	0.0
EP080/071: Total Petroleum Hydrocarbons C6 - C9 Fraction	mg/kg	10	<10	<10	nc	<10	< 20	nc
210 - C14 Fraction C15 - C28 Fraction	mg/kg mg/kg	50 100	<50 <100	<50 <100	nc nc	<50 <100	< 20 <50	nc nc
C29 - C36 Fraction C10 - C36 Fraction (sum)	mg/kg mg/kg	100 50	<100 <50	<100 <50	nc nc	<100 <50	<50 <50	nc nc
EP080/071: Total Recoverable Hydrocarbons - NEPM 2013 Fractions Ch. C10 Fraction	ma/ka	40	<10	<10	nc	<10	< 20	nc
SG - CTO Fraction CG - CTO Fraction minus BTEX (F1) >CTO - CT6 Fraction	mg/kg mg/kg	10	<10 <10 <50	<10 <10 <50	nc nc	<10 <10 <50	< 20 < 20 < 50	nc nc
>C16 - C34 Fraction (F3) >C34 - C40 Fraction (F4)	mg/kg mg/kg	100	<100 <100	<100 <100	nc nc	<100 <100	< 100 < 100	nc nc
>C10 - C40 Fraction (sum) >C10 - C16 Fraction minus Naphthalene (F2)	mg/kg mg/kg	50 50	<50 <50	<50 <50	nc nc	<50 <50	< 50	nc
EPO80: BTEXN								
3enzene Foluene Ethylbenzene	mg/kg mg/kg mg/kg	0.2 0.5 0.5	<0.2 <0.5 <0.5	<0.2 <0.5 <0.5	nc nc nc	<0.2 <0.5 <0.5	< 0.1 < 0.1 < 0.1	nc nc
meta- & para-Xylene ortho-Xylene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.2 < 0.1	nc nc
Fotal Xylenes Sum of BTEX	mg/kg mg/kg	0.5 0.2	<0.5 <0.2	<0.5 <0.2	nc nc	<0.5 <0.2	< 0.3	nc
Naphthalene EP074A: Monocyclic Aromatic Hydrocarbons	mg/kg	1	<1	<1	nc	<1	<0.5	nc
Styrene sopropylbenzene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
n-Propylbenzene 1.3.5-Trimethylbenzene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
sec-Butylbenzene I.2.4-Trimethylbenzene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
ert-Butylbenzene Isopropyltoluene	mg/kg mg/kg	0.5 0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
n-Butylbenzene EP074B: Oxygenated Compounds	mg/kg	0.5	<0.5	<0.5	nc	<0.5	<0.5	nc
/inyl Acetate 2-Butanone (MEK)	mg/kg mg/kg	5 5	<5 <5	<5 <5	nc nc	<5 <5	<5 <5	nc nc
1-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK)	mg/kg mg/kg	5 5	<5 <5	<5 <5	nc nc	<5 <5	<5 <5	nc nc
EP074C: Sulfonated Compounds		0.5						
Carbon disulfide EP074D: Fumigants	mg/kg	0.5	<0.5	<0.5	nc	< 0.5	< 0.5	nc
2Dichloropropane .2-Dichloropropane	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
cis-1.3-Dichloropropylene rans-1.3-Dichloropropylene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
.2-Dibromoethane (EDB)	mg/kg	0.5	<0.5	<0.5	nc	<0.5	<0.5	nc
EP074E: Halogenated Aliphatic Compounds	mg/kg mg/kg	5	<5 <5	<5 <5	nc nc	<5 <5	<5 <5	nc nc
niorometrane inyl chloride kromomethane	mg/kg mg/kg mg/kg	5 5 5	<5 <5	<5 <5 <5	nc nc	<5 <5 <5	<5 <5 <5	nc nc
Chloroethane Frichlorofluoromethane	mg/kg mg/kg	5 5	<5 <5	<5 <5	nc nc	<5 <5	<5 <5	nc nc
.1-Dichloroethene odomethane	mg/kg mg/kg	0.5 0.5 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc
rans-1.2-Dichloroethene .1-Dichloroethane is-1.2-Dichloroethene	mg/kg mg/kg mg/kg	0.5 0.5 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc nc	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc
IS-1.2-Dicinioreurene .1.1-Trichloroethane .1-Dichloropropylene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc
Carbon Tetrachloride2-Dichloroethane	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
richloroethene Dibromomethane	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
.1.2-Trichloroethane .3-Dichloropropane etrachloroethene	mg/kg mg/kg mg/kg	0.5 0.5 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc nc	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc
etrachioroetnene 1, 1, 1, 2-Tetrachioroethane rans-1, 4-Dichloro-2-butene	mg/kg mg/kg mg/kg	0.5 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc
dis-1.4-Dichloro-2-butene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
.2.3-Trichloropropane tentachloroethane	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
.2-Dibromo-3-chloropropane lexachlorobutadiene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5	nc nc	<0.5 <0.5	<0.5 <0.5	nc nc
EP074F: Halogenated Aromatic Compounds Chlorobenzene	mg/kg	0.5	<0.5	<0.5	nc	<0.5	<0.5	nc
ntorobenzene tromobenzene Chlorotoluene	mg/kg mg/kg mg/kg	0.5 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc
-Chlorotoluene .3-Dichlorobenzene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5	nc 	<0.5 <0.5	<0.5 <0.5	nc nc
.4-Dichlorobenzene .2-Dichlorobenzene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5			<0.5 <0.5	<0.5 <0.5	nc nc
.2.4-Trichlorobenzene .2.3-Trichlorobenzene	mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5	nc	<0.5 <0.5	<0.5 <0.5	nc nc
EP074G: Trihalomethanes Shloroform	mg/kg	0.5	<0.5	< 0.5	nc	<0.5	<0.5	nc
thioroform tromodichloromethane Jibromochloromethane	mg/kg mg/kg mg/kg	0.5 0.5 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc nc	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	nc nc
Bromoform	mg/kg	0.5	<0.5	<0.5	nc	<0.5	<0.5	nc
EP074H: Naphthalene Naphthalene	mg/kg	1	<1			<1	<1	nc
		1	l .	1	1	I .	I	

11/8/2016										Site 027						
						Sample Typ	ne·	SOIL	SOIL	1	SOIL	SOIL		SOIL	SOIL	SOIL
						ALS Sample			ES1611420007			S16-My28529			ES1611420010	ES1611421010
						<u> </u>		ES1611420002			ES1611420002	502339		ES1611420009		
						Sample dat		24/05/2016	24/05/2016		24/05/2016	24/05/2016		23/05/2016	24/05/2016	24/05/2016
	HSL D = Co	mmercial/ In	dustrial			Sample ID: Project Na		006_GW005 M4E-WCX	006_QC100 M4E-WCX	1	006_GW005 M4E-WCX	006_QC101 M4E-WCX		000_QA003 M4E-WCX	000_QA004 M4E-WCX	000_QA002 M4E-WCX
	- 1.02.2 00			95% Marine		Compound		NORTHCOLE	NORTHCOLE	1	NORTHCOLE	NORTHCOLE		NORTHCOLE	NORTHCOLE	NORTHCOLE
				Water	Recreational		·	STREET TUNNEL	STREET TUNNEL	RPD	STREET TUNNEL	STREET TUNNEL	RPD	STREET TUNNEL	STREET TUNNEL	STREET TUNNEL
				Protection for	Health (10x	H		SITE GME	SITE GME		SITE GME	SITE GME		SITE GME	SITE GME	SITE
				Aquatic	ADWG 2011)	Site:	Analona di	SITE 006	SITE 006	-	SITE 006	SITE 006		SITE 006	SITE 006	SITE 006
				Ecosystems		Sampling N		Bailer	Bailer	1	Bailer	Bailer				
						Sample De	3CI IPTIOII		DUDI ICATE OF			TRIPLICATE OF				
Guidelines	2 to <4m	4m to<8m	8m+					PRIMARY	DUPLICATE OF 006_GW005		PRIMARY	006_GW005		TRIP SPIKE	TRIP BLANK	TRIP BLANK
Analyte grouping/Analyte						Units	LOR									
EGO20T: Dissolved Metals by ICP-MS	T		1		400									ı		
Arsenic Cadmium		+		2.3 0.7	100 20	μg/L μg/L	0.1	<1 <0.1	<1 <0.1	nc nc	<1 <0.1	<1 0.2	nc nc			
Chromium				4.4	500	μg/L	1	<1	<1	nc	<1	<1	nc			
Copper				1.3	20000	μg/L	1	<1	<1	nc	<1	1	nc			
Nickel				7	200	μg/L	1	<1	<1	nc	<1	<1	nc			
Lead	ļ	ļ		4.4	100	μg/L	1	32	33	3.1	32	30	6.5			
Zinc				15		μg/L	1	50	52	3.9	50	48	4.1			
EG035F: Dissolved Mercury by FIMS	<u> </u>					Ш		<u> </u>								
Mercury				0.1	10	μg/L	0.1	<0.1	<0.1	nc	<0.1	<0.1	nc			
EP066: Polychlorinated Biphenyls (PCB)	ļ	<u> </u>		<u> </u>		Щ	<u> </u>	<u> </u>		<u> </u>	<u> </u>			<u> </u>		
Total Polychlorinated biphenyls (PCB)	1			1		μg/L	1	<1	<1	nc	<1					
EP068A: Organochlorine Pesticides (OC))					P9'-	<u>' </u>	<u> </u>	<u> </u>	110	<u> </u>					
alpha-BHC	1			1		μg/L	0.5	<0.5	<0.5	nc	<0.5					
Hexachlorobenzene (HCB)						μg/L	0.5	<0.5	<0.5	nc	<0.5					
beta-BHC						μg/L	0.5	< 0.5	< 0.5	nc	< 0.5					
gamma-BHC					100	μg/L	0.5	< 0.5	<0.5	nc	< 0.5					
delta-BHC					_	μg/L	0.5	< 0.5	<0.5	nc	<0.5					
Heptachlor Aldrin		+		0.0004 0.003	3	μg/L μg/L	0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5					
Heptachlor epoxide				0.003		μg/L	0.5	<0.5	<0.5	nc	<0.5					
trans-Chlordane						μg/L	0.5	<0.5	<0.5	nc	<0.5					
alpha-Endosulfan				0.0002		μg/L	0.5	<0.5	<0.5	nc	<0.5					
cis-Chlordane						μg/L	0.5	< 0.5	< 0.5	nc	< 0.5					
Dieldrin				0.01		μg/L	0.5	<0.5	<0.5	nc	<0.5					
4.4`-DDE				0.0005		μg/L	0.5	<0.5	<0.5	nc	<0.5					
Endrin beta-Endosulfan				0.008 0.007		μg/L μg/L	0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5					
4.4`-DDD		†		0.007		μg/L	0.5	<0.5	<0.5	nc	<0.5					
Endrin aldehyde						μg/L	0.5	<0.5	<0.5	nc	<0.5					
Endosulfan sulfate						μg/L	0.5	< 0.5	< 0.5	nc	< 0.5					
4.4`-DDT				0.0004	90	μg/L	2	2	2	nc	2					
Endrin ketone	ļ					μg/L	0.5	<0.5	<0.5	nc	<0.5					
Methoxychlor	1	1	-	0.004	3000	μg/L	2	2	2	nc	2					
^ Total Chlordane (sum) ^ Sum of DDD + DDE + DDT	1		+	0.001	20	μg/L μg/L	0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5					
^ Sum of Aldrin + Dieldrin	1	<u> </u>	+		3	μg/L μg/L	0.5	<0.5	<0.5	nc	<0.5					
			上			1.3										
EP068B: Organophosphorus Pesticides ((OP)															
Dichlorvos	ļ				50	μg/L	0.5	<0.5	<0.5	nc	<0.5					
Demeton-S-methyl	1	1	-	4		μg/L	0.5	<0.5	<0.5	nc	<0.5					
Monocrotophos Dimethoate	 	-	-	0.15	70	μg/L	2	2	2	nc nc	2					
Diazinon			+	0.15	40	μg/L μg/L	0.5	<0.5 <0.5	<0.5 <0.5	nc	<0.5 <0.5					
Chlorpyrifos-methyl	1		1	5.07	.0	μg/L	0.5	<0.5	<0.5	nc	<0.5					
Parathion-methyl					7	μg/L	2	2	2	nc	2					
Malathion				0.05	700	μg/L	0.5	<0.5	< 0.5	nc	< 0.5					
Fenthion	ļ	<u> </u>	1		70	μg/L	0.5	<0.5	<0.5	nc	<0.5					
Chlorpyrifos	1		1	0.009	100	μg/L	0.5	<0.5	<0.5	nc	<0.5					
Parathion Pirimphos-ethyl	1		+	0.004	200	μg/L μg/l	0.5	2 <0.5	<0.5	nc nc	2 <0.5					
Chlorfenvinphos	 	+	+		20	μg/L μg/L	0.5	<0.5 <0.5	<0.5 <0.5	nc	<0.5 <0.5					
Bromophos-ethyl	1				20	μg/L	0.5	<0.5	<0.5	nc	<0.5					
Fenamiphos	İ				5	μg/L	0.5	<0.5	<0.5	nc	<0.5					
Prothiofos						μg/L	0.5	<0.5	<0.5	nc	<0.5					
Ethion	ļ	ļ			40	μg/L	0.5	<0.5	<0.5	nc	<0.5					
Carbophenothion	-					μg/L	0.5	<0.5	<0.5	nc	<0.5					
Azinphos Methyl	 	-	+	0.01	300	μg/L	0.5	<0.5	<0.5	nc	<0.5					
		ļ	1			l I										

Table 6: QA/QC Groundwater Sampling Results Northcote Compound Site 027

													1	1		
						Sample Ty		SOIL	SOIL		SOIL	SOIL		SOIL	SOIL	SOIL
						ALS Sampl	e number:	ES1611420002	ES1611420007		ES1611420002	S16-My28529 502339		ES1611420009	ES1611420010	ES1611421010
						Sample da	te:	24/05/2016	24/05/2016		24/05/2016	24/05/2016		23/05/2016	24/05/2016	24/05/2016
						Sample ID		006_GW005	006_QC100		006_GW005	006_QC101		000_QA003	000_QA004	000_QA002
	HSL D - Co	mmercial/ In	dustrial			Project Na		M4E-WCX	M4E-WCX		M4E-WCX	M4E-WCX		M4E-WCX	M4E-WCX	M4E-WCX
				95% Marine		Compound		NORTHCOLE	NORTHCOLE		NORTHCOLE	NORTHCOLE		NORTHCOLE	NORTHCOLE	NORTHCOLE
				Water	Recreational			STREET TUNNEL	STREET TUNNEL	RPD	STREET TUNNEL	STREET TUNNEL	RPD	STREET TUNNEL	STREET TUNNEL	STREET TUNNEL
				Protection for	Health (10x			SITE GME	SITE GME		SITE GME	SITE GME		SITE GME	SITE GME	SITE
				Aquatic	ADWG 2011)	Site:		SITE 006	SITE 006		SITE 006	SITE 006		SITE 006	SITE 006	SITE 006
				Ecosystems		Sampling N		Bailer	Bailer		Bailer	Bailer				
						Sample De	scription									
								PRIMARY	DUPLICATE OF		PRIMARY	TRIPLICATE OF		TRIP SPIKE	TRIP BLANK	TRIP BLANK
Guidelines	2 to <4m	4m to<8m	8m+					TRIMPICI	006_GW005		I KIWAKI	006_GW005		THE STIKE	TKII BEANK	TIKIT DEANK
VOCs						L										
Styrene						μg/L	5	<5			<5					
Isopropylbenzene	1					μg/L μg/L	5	<5			<5 <5					
n-Propylbenzene						μg/L	5	<5			<5					
1.3.5-Trimethylbenzene						μg/L	5	<5			<5					
sec-Butylbenzene						µg/L	5	<5			<5					
1.2.4-Trimethylbenzene						μg/L	5	<5			<5					
tert-Butylbenzene						μg/L	5	<5			<5					
p-Isopropyltoluene	1					μg/L	5	<5			<5					
n-Butylbenzene	1					μg/L	5	<5			<5					
Vinyl Acetate	1					μg/L	50	<50			<50					
2-Butanone (MEK)						μg/L	50	<50			<50					
4-Methyl-2-pentanone (MIBK)	1					μg/L	50	<50			<50					
2-Hexanone (MBK)						μg/L	50	<50			<50					
Carbon disulfide	1					μg/L	5	<5			<5					
2.2-Dichloropropane						μg/L	5	<5			<5					
1.2-Dichloropropane						μg/L	5	<5			<5					
cis-1.3-Dichloropropylene						μg/L	5	<5			<5					
trans-1.3-Dichloropropylene						μg/L	5	<5			<5					
1.2-Dibromoethane (EDB)						μg/L	5	<5			<5					
Dichlorodifluoromethane						μg/L	50	<50			<50					
Chloromethane						μg/L	50	<50			<50					
Vinyl chloride					3	μg/L	50	<50			<50					
Bromomethane						μg/L	50	<50			<50					
Chloroethane						μg/L	50	<50			<50					
Trichlorofluoromethane						μg/L	50	<50			<50					
1.1-Dichloroethene					300	μg/L	5	<5			<5					
Iodomethane						μg/L	5	<5			<5					
trans-1.2-Dichloroethene						μg/L	5	<5			<5					
1.1-Dichloroethane						μg/L	5	<5			<5					
cis-1.2-Dichloroethene						μg/L	5	<5			<5					
1.1.1-Trichloroethane						μg/L	5	<5			<5					
1.1-Dichloropropylene						μg/L	5	<5			<5					
Carbon Tetrachloride						μg/L	5	<5			<5					
1.2-Dichloroethane					30	μg/L	5	<5			<5					
Trichloroethene						μg/L	5	<5			<5					
Dibromomethane						μg/L	5	<5			<5					
1.1.2-Trichloroethane				1900		μg/L	5	<5			<5					
1.3-Dichloropropane						μg/L	5	<5			<5					
Tetrachloroethene					500	μg/L	5	<5			<5					
1.1.1.2-Tetrachloroethane						μg/L	5	<5			<5					
trans-1.4-Dichloro-2-butene						μg/L	5	<5			<5					
cis-1.4-Dichloro-2-butene						μg/L	5	<5			<5					
1.1.2.2-Tetrachloroethane	 					μg/L	5	<5 .F			<5					
1.2.3-Trichloropropane	 					μg/L	5	<5 .F			<5					
Pentachloroethane 1.2-Dibromo-3-chloropropane			 			μg/L	5	<5			<5					
Hexachlorobutadiene	+					μg/L	5	<5 <5			<5 <5					
Chlorobenzene				55	3000	μg/L μg/L	5	<5 <5			<5 <5					
Bromobenzene				- 55	3000	μg/L μg/L	5	<5 <5			<5 <5					
2-Chlorotoluene						μg/L	5	<5 <5			<5 <5					
4-Chlorotoluene						μg/L	5	<5			<5 <5					
1.3-Dichlorobenzene	1			260		μg/L	5	<5			<5					
1.4-Dichlorobenzene	1			60	400	µg/L	5	<5			<5					
1.2-Dichlorobenzene	1			160	15000	μg/L	5	<5			<5					
1.2.4-Trichlorobenzene				20	300	μg/L	5	<5			<5					
1.2.3-Trichlorobenzene				3	300	μg/L	5	<5			<5					
Chloroform						μg/L	5	<5			<5					
Bromodichloromethane						μg/L	5	<5			<5					
Dibromochloromethane						μg/L	5	<5			<5					
Bromoform						μg/L	5	<5			<5					
Naphthalene	1			50		μg/L	5	<5			<5					
						II					1					
EP075(SIM)A: Phenolic Compounds																
Phenol				400		μg/L	1	<1.0	<1.0		<1.0					
2-Chlorophenol				340	3000	μg/L	1	<1.0	<1.0		<1.0					
2-Methylphenol						μg/L	1	<1.0	<1.0		<1.0					
3- & 4-Methylphenol						μg/L	2	2	2		2					
2-Nitrophenol				2		μg/L	1	<1.0	<1.0		<1.0					
2.4-Dimethylphenol				2		μg/L	1	<1.0	<1.0		<1.0					
2.4-Dichlorophenol				120	2000	μg/L	1	<1.0	<1.0		<1.0					
2.6-Dichlorophenol				34		μg/L	1	<1.0	<1.0		<1.0					
4-Chloro-3-methylphenol						μg/L	1	<1.0	<1.0		<1.0					
2.4.6-Trichlorophenol				3	200	μg/L	1	<1.0	<1.0		<1.0					
2.4 E. Trichlorophonol				4		μg/L	1	<1.0	<1.0		<1.0					
2.4.5-Trichlorophenol								_			2					




										Site 027	7					
						Sample Ty	pe:	SOIL	SOIL		SOIL	SOIL		SOIL	SOIL	SOIL
						ALS Sampl	e number:	ES1611420002	ES1611420007		ES1611420002	S16-My28529 502339		ES1611420009	ES1611420010	ES16114210
	_					Sample da	te·	24/05/2016	24/05/2016		24/05/2016	24/05/2016		23/05/2016	24/05/2016	24/05/20
						Sample ID		006_GW005	006_QC100		006_GW005	006_QC101		000_QA003	000_QA004	000_QA0
	HSL D - Co	mmercial/ In	dustrial			Project Na		M4E-WCX	M4E-WCX		M4E-WCX	M4E-WCX		M4E-WCX	M4E-WCX	M4E-WC
				95% Marine		Compound		NORTHCOLE	NORTHCOLE		NORTHCOLE	NORTHCOLE		NORTHCOLE	NORTHCOLE	NORTHCO
				Water	Recreational	'		STREET TUNNEL	STREET TUNNEL	RPD	STREET TUNNEL	STREET TUNNEL	RPD	STREET TUNNEL	STREET TUNNEL	STREET TUI
				Protection for	Health (10x	Cite		SITE GME	SITE GME		SITE GME	SITE GME		SITE GME	SITE GME	SITE
				Aquatic	ADWG 2011)	Site: Sampling N	Mothod:	SITE 006 Bailer	SITE 006 Bailer		SITE 006 Bailer	SITE 006 Bailer		SITE 006	SITE 006	SITE 00
		1		Ecosystems		Sample De		Ballel	baller		ballel	baller				+
Guidelines	2 to <4m	4m to<8m	8m+			Sample De	Scription	PRIMARY	DUPLICATE OF 006_GW005		PRIMARY	TRIPLICATE OF 006_GW005		TRIP SPIKE	TRIP BLANK	TRIP BLA
						1	1							1	<u> </u>	Т
EP075(SIM)B: Polynuclear Aromatic Hy	drocarbons			I					1				I			
Naphthalene	1	1	<u> </u>	50	 	μg/L	1	<1.0	<1.0	nc	<1.0					
Acenaphthylene	1	1	<u> </u>		ļ	μg/L	1	<1.0	<1.0	nc	<1.0					
Acenaphthene	+	<u> </u>				μg/L	1	<1.0	<1.0 <1.0	nc	<1.0 <1.0					
Fluorene Phenanthrene	1	1	 	0.6	 	μg/L μg/L	1	<1.0 <1.0	<1.0 <1.0	nc nc	<1.0 <1.0					
Anthracene				0.8		μg/L μg/L	1	<1.0	<1.0	nc	<1.0					
Fluoranthene				1		μg/L	1	<1.0	<1.0	nc	<1.0					
Pyrene				· ·		μg/L	1	<1.0	<1.0	nc	<1.0					
Benz(a)anthracene						μg/L	1	<1.0	<1.0	nc	<1.0					
Chrysene						μg/L	1	<1.0	<1.0	nc	<1.0					
Benzo(b+j)fluoranthene						μg/L	1	<1.0	<1.0	nc	<1.0					
Benzo(k)fluoranthene						μg/L	1	<1.0	<1.0	nc	<1.0					
Benzo(a)pyrene				0.1	0.1	μg/L	0.5	< 0.5	<0.5	nc	< 0.5					
Indeno(1.2.3.cd)pyrene						μg/L	1	<1.0	<1.0	nc	<1.0					
Dibenz(a.h)anthracene						μg/L	1	<1.0	<1.0	nc	<1.0					
Benzo(g.h.i)perylene	+					μg/L	1	<1.0	<1.0	nc	<1.0					
Sum of polycyclic aromatic hydrocarbons Benzo(a)pyrene TEQ (zero)						μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5					
Benzo(a)pyrene 124 (zero)						μ9/ Ε	0.5	V0.3	V0.5	710	V0.3					
EP080/071: Total Petroleum Hydrocarb	ons															
C6 - C9 Fraction		<u> </u>	<u> </u>			μg/L	20	20	20	nc	20	20	nc	190	20	20
C10 - C14 Fraction	1	1	<u> </u>		 	μg/L	50	<50	<50	nc	<50				<50	
C15 - C28 Fraction	+	1	<u> </u>		-	μg/L	100	<100	<100	nc	<100				<100	
C29 - C36 Fraction C10 - C36 Fraction (sum)	1		-			μg/L μg/L	50 50	<50 <50	<50 <50	nc nc	<50 <50				<50 <50	
CTO - C30 FIACTION (SUIN)						µg/L	50	<50	<50	IIC .	< 50				<50	
EP080/071: Total Recoverable Hydroca	rbons - NEPM	2013 Fraction	าร													
C6 - C10 Fraction					ļ	μg/L	20	20	20	nc	20			210	20	20
C6 - C10 Fraction minus BTEX (F1)	6200	6300	6500		-	μg/L	20	20	20	nc	20			130	20	20
>C10 - C16 Fraction	1	1	<u> </u>		ļ	μg/L	100	<100	<100	nc	<100				<100	
>C16 - C34 Fraction >C34 - C40 Fraction	+	<u> </u>				μg/L	100	<100	<100	nc	<100				<100	
>C34 - C40 Fraction >C10 - C40 Fraction (sum)	1	1	 		 	μg/L μg/L	100 100	H	<100 <100						<100 <100	
>C10 - C40 Fraction (sum) >C10 - C16 Fraction minus Naphthalene (F2	2) NL	NL	NL			μg/L μg/L	100		<100						<100 <100	
,	,					13										
EPO80: BTEXN	4000	E100	E400	E00	9000	1.00/1	1	П						45	-1	- 1
Benzene Toluene	4900 NL	5100 NL	5400 NL	500 180	8000 3000	μg/L	2		<1			<1 <1		15 14	<1	<1
Ethylbenzene	NL NL	NL NL	NL NL	180	8000	μg/L μg/L	2		2			<1		16	2	2
meta- & para-Xylene	INL	INL	IVL	275	5500	μg/L μg/L	2		2			2		16	2	2
ortho-Xylene	1	1	1	350		μg/L	2		2			<1		16	2	2
Total Xvlenes	NL	NL	NL		6000	μg/L	2		2			<3		32	2	2
Sum of BTEX	1	1	T		1	μg/L	1		<1					77	<1	<1
Naphthalene	NL	NL	NL	50	1	μg/L	5		<5					17	<5	<5

All units in µg/L except trip spikes (%)
nc = not calculated since results < LOR
LOR = Laboratory Limit of Reporting
BOLD identifies where RPD results

DOLD Identii	ies where KFD i	esuits
Intralaborate	Interlaborator	_ 'y
>50	>60	where sample results are >10 x PQL
>75	>85	where sample results are > 5 to ≤10 x PQ
>100	>100	where sample results are >2 to ≤5 x PQL
AD>2.5 * PQL		where sample results are ≤2 x PQL

Where results are within two of the above ranges the most conservative criteria have been used to assess duplicate performance



	_											Sample T ALS Sample	ple number:	SOIL ES1609686001 05/05/2016	SOIL ES1609686002 05/05/2016	SOIL ES1609686010 05/05/2016	SOIL ES1609686003 05/05/2016	SOIL ES1609686004 05/05/2016	SOIL ES1609686005 05/05/2016	SOIL ES1609686006 05/05/2016	SOIL ES1609686007 05/05/2016	SOIL ES1609686008 05/05/2016	SOIL ES1609686009 05/05/2016
												Sample d Sample I Project N	D:	028_TP001_0.10 M4E-WCX	028_TP001_0.50 M4E-WCX	028_QC001 M4E-WCX	028_TP001_0.70 M4E-WCX	028_TP001_0.90 M4E-WCX	028_TP002_0.20 M4E-WCX	028_TP002_0.50 M4E-WCX	028_TP002_1.00 M4E-WCX	028_TP003_0.40 M4E-WCX	028_TP003_0.60 M4E-WCX
											CRC CARE 2011	Compoun		Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site
	NEPM 2013 HIL		NEPM 2013 Soil	NEPM 2013 Soil	NEPM 2013 Soil	NEPM 2013 EIL NE	PM 2013 ESL ²	NEPM 2013 Management		CRC CARE 2011 Direct Contact ⁴	Vapour Intrusion HSL	Site: Sampling	Method:	Site 028 Test Pitting	Site 028 Test Pitting	Site 028 Test Pitting	Site 028 Test Pitting	Site 028 Test Pitting	Site 028 Test Pitting	Site 028 Test Pitting	Site 028 Test Pitting	Site 028 Test Pitting	Site 028 Test Pitting
	D Commercial / Industrial		Vapour Intrusion HSL D Sand ¹ 1-2m		Intrusion HSL D	Commercial /	Commercial /		Direct Contact ⁴ HSL D	HSL for Intrusive Maintenance	for Intrusive Maintenance Workers Sand 0										Grading to extremely	FILL; Gravelly clayey silt,	1
								Industrial		Workers	<2m ¹			FILL, gravelly, silty Clay, dark	k FILL, gravelly, silty Clay, dark		Silty CLAY; orange, slightly		FILL; Gravelly clayey silt, gravel is ironstone,	Silty CLAY; orange, slightly moist-moist, soft, low		gravel is ironstone, stiff, dry- slightly moist, grey/brown,	
												Sample D	Description	brown, black staining, pieces of plastic,	brown, black staining, pieces of plastic,	Duplicate of 028_TP001_0.5	moist-moist, soft, low plasticity, some ironstone gravels, NOC	red/brown, ironstone cementing, low plasticity, slightly moist,	reworked natural (?), grey/brown, medium stiff, moist, high	plasticity, some ironstone gravels, no observed	ironstone cementing, low plasticity,	roots, pipe near surface, no observed contamination,	someironstone gravels, stiff, low plasticity,
																	g,	medium stiff, NOC	gravel content	contamination	slightly moist, medium stiff, no observed contamination	minor pockets of sand beneath concrete	no observed contamination
Analyte grouping/Analyte												Units	LOR										
EA055: Moisture Content																							
Moisture Content (dried @ 103°C)												%		13	15.3	12.8	15.8	19.1	12.8	23.6	17	7.9	16.1
EA200: AS 4964 - 2004 Identification of Asbestos in Soils Asbestos Detected												g/kg	0.1	No	No	No			No			No	
Asbestos Type Sample weight (dry)												g	0.1	51.9	70.1	31.7			43.7			61	
Description														Mid brown clay soil with grey rocks.	Mid brown clay soil with grey rocks.	Mid brown clay soil with grey rocks.			Mid brown sandy soil.			Pale brown clay soil with grey rocks.	
APPROVED IDENTIFIER:														G.MORGAN	G.MORGAN	G.MORGAN			G.MORGAN			G.MORGAN	
EG005T: Total Metals by ICP-AES Arsenic	3000					160						mg/kg	5	13	18	6 <1	<5 <1	9 <1	6 <1	8 <1	8 <1	9 <1	6 <1
Cadmium Chromium Copper	900 3600 240000					310 150						mg/kg mg/kg mg/kg	2	25 35	30 32	20	<1 33 <5	<1 33 <5	14 18	37 <5	<1 19 <5	26 <5	<1 29 <5
Lead Nickel	1500 6000					1800 60						mg/kg mg/kg	5 2	141	158 9	128 3	11 <2	17 <2	21	14 <2	19 <2	20 <2	19
Zinc	400000					300						mg/kg	5	226	322	200	6	<5	41	<5	<5	<5	<5
EG035T: Total Recoverable Mercury by FIMS Mercury	730											mg/kg	0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1
EP066: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls	7										I	ma/kc	0.1		<0.1	<0.1			<0.1			<0.1	
EP068A: Organochlorine Pesticides (OC)												mg/kg	0.1		X0.1	X0.1			X0.1			V0.1	
alpha-BHC Hexachlorobenzene (HCB)	80											mg/kg mg/kg	0.05 0.05		<0.05 <0.05	<0.05 <0.05			<0.05 <0.05			<0.05 <0.05	
beta-BHC gamma-BHC												mg/kg mg/kg	0.05 0.05		<0.05 <0.05	<0.05 <0.05			<0.05 <0.05			<0.05 <0.05	
delta-BHC Heptachlor	50											mg/kg mg/kg	0.05 0.05		<0.05 <0.05	<0.05 <0.05			<0.05 <0.05			<0.05 <0.05	
Aldrin Heptachlor epoxide	500											mg/kg mg/kg	0.05 0.05		<0.05 <0.05	<0.05 <0.05			<0.05 <0.05			<0.05 <0.05	
Total Chlordane (sum) trans-Chlordane alpha-Endosulfan	530											mg/kg mg/kg	0.05 0.05 0.05		<0.05 <0.05 <0.05	<0.05 <0.05 <0.05			<0.05 <0.05 <0.05			<0.05 <0.05 <0.05	
aipna-Endosulian cis-Chlordane Dieldrin												mg/kg mg/kg mg/kg	0.05 0.05		<0.05 <0.05	<0.05 <0.05			<0.05 <0.05 <0.05			<0.05 <0.05	
4.4°-DDE Endrin	100											mg/kg mg/kg	0.05 0.05		<0.05 <0.05	<0.05 <0.05			<0.05 <0.05			<0.05 <0.05	
Endosulfan (sum) beta-Endosulfan	2000											mg/kg mg/kg	0.05 0.05		<0.05 <0.05	<0.05 <0.05			<0.05 <0.05			<0.05 <0.05	
4.4`-DDD Endrin aldehyde												mg/kg mg/kg	0.05 0.05		0.06 <0.05	<0.05 <0.05			<0.05 <0.05			<0.05 <0.05	
Endosulfan sulfate 4.4`-DDT						640						mg/kg mg/kg	0.05 0.2 0.05		<0.05 <0.2 <0.05	<0.05 <0.2 <0.05			<0.05 <0.2 <0.05			<0.05 <0.2 <0.05	
Endrin ketone Methoxychlor Sum of DDD + DDE + DDT	2500 3600											mg/kg mg/kg mg/kg	0.05 0.2 0.05		<0.2 0.06	<0.05 <0.2 <0.05			<0.05 <0.2 <0.05			<0.05 <0.2 <0.05	
Sum of Aldrin + Dieldrin	45											mg/kg	0.05		<0.05	<0.05			<0.05			<0.05	
EP068B: Organophosphorus Pesticides (OP) Dichlorvos												mg/kg	0.05		<0.05	<0.05			<0.05			<0.05	
Demeton-S-methyl Monocrotophos												mg/kg mg/kg	0.2		<0.05 <0.2	<0.05 <0.2			<0.05 <0.2			<0.05 <0.2	
Dimethoate Diazinon												mg/kg mg/kg	0.05 0.05 0.05		<0.05 <0.05 <0.05	<0.05 <0.05 <0.05			<0.05 <0.05 <0.05			<0.05 <0.05 <0.05	
Chlorpyrifos-methyl Parathion-methyl Malathion												mg/kg mg/kg mg/kg	0.05		<0.2 <0.05	<0.2 <0.05			<0.2 <0.05			<0.2 <0.05	
Fenthion Chlorpyrifos	2000											mg/kg mg/kg	0.05 0.05		<0.05 <0.05	<0.05 <0.05			<0.05 <0.05			<0.05 <0.05	
Parathion Pirimphos-ethyl												mg/kg mg/kg	0.2 0.05		<0.2 <0.05	<0.2 <0.05			<0.2 <0.05			<0.2 <0.05	
Chlorfenvinphos Bromophos-ethyl												mg/kg mg/kg	0.05		<0.05 <0.05	<0.05 <0.05			<0.05 <0.05			<0.05 <0.05	
Fenamiphos Prothiofos Ethiop												mg/kg mg/kg	0.05 0.05 0.05		<0.05 <0.05 <0.05	<0.05 <0.05 <0.05			<0.05 <0.05 <0.05			<0.05 <0.05 <0.05	
Ethion Carbophenothion Azinphos Methyl												mg/kg mg/kg mg/kg	0.05 0.05 0.05		<0.05 <0.05 <0.05	<0.05 <0.05 <0.05			<0.05 <0.05 <0.05			<0.05 <0.05 <0.05	
EP075(SIM)A: Phenolic Compounds																							
Phenol 2-Chlorophenol	240000											mg/kg mg/kg	0.5		<0.5 <0.5	<0.5 <0.5			<0.5 <0.5			<0.5 <0.5	
2-Methylphenol 3- & 4-Methylphenol	25000											mg/kg mg/kg	0.5		<0.5 <1	<0.5 <1			<0.5 <1			<0.5 <1	
2.4-Dimethylphenol												mg/kg mg/kg	0.5 0.5 0.5		<0.5 <0.5 <0.5	<0.5 <0.5 <0.5			<0.5 <0.5 <0.5			<0.5 <0.5 <0.5	
2.4-Dichlorophenol 2.6-Dichlorophenol 4-Chloro-3-methylphenol												mg/kg mg/kg mg/kg	0.5 0.5		<0.5 <0.5 <0.5	<0.5 <0.5 <0.5			<0.5 <0.5 <0.5			<0.5 <0.5 <0.5	
2.4.6-Trichlorophenol 2.4.5-Trichlorophenol												mg/kg mg/kg			<0.5 <0.5	<0.5 <0.5			<0.5 <0.5 <0.5			<0.5 <0.5	
Pentachlorophenol	660											mg/kg	2		<2	<2			<2			<2	
EP075(SIM)B: Polynuclear Aromatic Hydrocarbons Naphthalene Acceptable		NL	NL	NL	NL	370			11000	29000	NL	mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Acenaphthylene Acenaphthene Fluorene												mg/kg mg/kg mg/kg	0.5 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5
Phenanthrene Anthracene												mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Fluoranthene Pyrene												mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Benz(a)anthracene Chrysene												mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Benzo(b+j)fluoranthene Benzo(k)fluoranthene							70					mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Benzo(a)pyrene Indeno(1.2.3.cd)pyrene Dibenz(a.h)anthracene							72					mg/kg mg/kg mg/kg	0.5 0.5 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5
Benzo(g.h.i)perylene Sum of polycyclic aromatic hydrocarbons	4000											mg/kg mg/kg	0.5 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	<0.5 <0.5	< 0.5	<0.5 <0.5 <0.5	< 0.5	<0.5 <0.5 <0.5	<0.5 <0.5 <0.5	< 0.5	< 0.5
Benzo(a)pyrene TEQ (zero)	1											mg/kg		<0.5	<0.5	<0.5	<0.5 <0.5	<0.5	<0.5 <0.5	<0.5	<0.5	<0.5 <0.5	<0.5 <0.5



												Sample Typ		SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL	SOIL
												ALS Sample		ES1609686001	ES1609686002	ES1609686010	ES1609686003	ES1609686004	ES1609686005	ES1609686006	ES1609686007	ES1609686008	ES1609686009
												Sample dat		05/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016
												Sample ID:		028_TP001_0.10	028_TP001_0.50	028_QC001	028_TP001_0.70	028_TP001_0.90	028_TP002_0.20	028_TP002_0.50	028_TP002_1.00	028_TP003_0.40	028_TP003_0.60
												Project Nar	me:	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX
												Compound	l:	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site
								NED11 0040		CRC CARE 2011	CRC CARE 2011	Site:		Site 028	Site 028	Site 028	Site 028	Site 028	Site 028	Site 028	Site 028	Site 028	Site 028
	NEPM 2013 HI	NEPM 2013 Soi	I NEPM 2013 Soil	NEPM 2013 Soil	II NEPM 2013 Soi	NEDM 2012 EII	NEPM 2013 ESL ²	NEPM 2013 Management	CRC CARE 2011	Direct Contact ⁴	Vapour Intrusion HSL	Sampling N	Method:	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Test Pitting	Test Pitting
	D Commercial Industrial	Vapour / Intrusion HSL I Sand 1 0-1m	Vapour D Intrusion HSL D Sand ¹ 1-2m	Vapour I Intrusion HSL D Sand ¹ 2-4m	Vapour D Intrusion HSL E Sand ¹ 4+m	Commercial / Industrial	Commercial / Industrial	Limits Commercial/ Industrial ³	Direct Contact ⁴ HSL D	HSL for Intrusive Maintenance Workers	for Intrusive Maintenance Workers Sand 0 <2m1	Sample De	escription	FILL, gravelly, sifty Clay, dar brown, black staining, pieces of plastic,	k FILL, gravelly, silty Clay, dark brown, black staining, pieces of plastic,	Duplicate of 028_TP001_0.5	Silty CLAY; orange, slightly moist-moist, soft, low plasticity, some ironstone gravels, NOC	Grading to weathered SHALE; light grey and red/brown, ironstone cementing, low plasticity, slightly moist medium stiff, NOC	FILL; Gravelly clayey silt, gravel is ironstone, reworked natural (?), grey/brown, medium stiff, moist, high gravel content	Silty CLAY; orange, slightly moist-moist, soft, low plasticity, some ironstone gravels, no observed contamination	Grading to extremely weathered SHALE; light grey and red/brown, ironstone cementing, low plasticity, slightly moist, medium stiff no observed contamination		slightly moist,
Analyte grouping/Analyte	,											Units	LOR	-					'				
Benzo(a)pyrene TEQ (half LOR)												mg/kg	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6
Benzo(a)pyrene TEQ (LOR)	40											mg/kg	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2
(2),,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,																							
EP080/071: Total Petroleum Hydrocarbons	<u> </u>					•				•				<u> </u>				•		•	<u>'</u>		
C6 - C9 Fraction												mg/kg	10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10
C10 - C14 Fraction												mg/kg	50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50
C15 - C28 Fraction												mg/kg	100	<100	<100	<100	<100	<100	<100	<100	<100	<100	<100
C29 - C36 Fraction												mg/kg	100	<100	<100	<100	<100	<100	<100	<100	<100	<100	<100
C10 - C36 Fraction (sum)												mg/kg	50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50
EP080/071: Total Recoverable Hydrocarbons - NEPM 2	2013 Fractions																						
C6 - C10 Fraction								700	26000	82000	NL	mg/kg	10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10
C6 - C10 Fraction minus BTEX (F1)		260	370	630	NL		215					mg/kg	10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10
>C10 - C16 Fraction							170	1000	20000	62000	NL	mg/kg	50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50
>C16 - C34 Fraction (F3)							1700	3500	27000	85000		mg/kg	100	<100	<100	<100	<100	<100	<100	<100	<100	<100	<100
>C34 - C40 Fraction (F4)							3300	10000	38000	120000		mg/kg	100	<100	<100	<100	<100	<100	<100	<100	<100	<100	<100
>C10 - C40 Fraction (sum)												mg/kg	50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50
>C10 - C16 Fraction minus Naphthalene (F2)		NL	NL	NL	NL							mg/kg	50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50
EP080: BTEXN			+	+	+	-	-							-	-		+	-	+	+	+	+	
Benzene		3	3	3	3		75		430	1100	77	mg/kg	0.2	< 0.2	<0.2	<0.2	< 0.2	< 0.2	<0.2	<0.2	< 0.2	<0.2	< 0.2
Toluene		NL	NL	NL	NL		135		99000	120000	NL NL	mg/kg	0.5	< 0.5	< 0.5	< 0.5	<0.5	< 0.5	<0.5	< 0.5	< 0.5	< 0.5	< 0.5
Ethylbenzene		NL	NL	NL	NL NL		165		27000	85000	NL	mg/kg	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	< 0.5	< 0.5	< 0.5
meta- & para-Xylene			1	1						1		mg/kg	0.5	< 0.5	<0.5	<0.5	< 0.5	< 0.5	<0.5	< 0.5	< 0.5	< 0.5	< 0.5
ortho-Xylene												mg/kg	0.5	<0.5	<0.5	<0.5	< 0.5	< 0.5	<0.5	< 0.5	< 0.5	<0.5	< 0.5
Total Xvienes		230	NL	NL	NL		95		81000	130000	NL	mg/kg	0.5	<0.5	<0.5	<0.5	< 0.5	< 0.5	<0.5	< 0.5	< 0.5	<0.5	<0.5
Sum of BTEX												mg/kg	0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Naphthalene		NL	NL	NL	NL	370			11000	29000	NL	mg/kg	1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1
•												11 22										1	+

Blank Cell indicates no criterion available

LOR = Limit of Reporting

National Environment Protection Council (2013) National Environmental Protection (Assessment of Site Contamination) Amendment Measure 2013 (No. 1) (NEPM). CRC Care Technical Report no.10, Health Screening Levels for petroleum hydrocarbons in soil and groundwater September 2011

¹ For soil texture classification undertaken in accord with AS 1726, the classifications of sand, silt and day may be applied as coarse, fine with liquid limit <50% and fine with liquid limit>50% respectively, as the underlying properties to develop the HSLs may reasonably be selected to be similar. Where there is uncertainty, either a conservative approach may be adopted or laboratory analysis should be carried out.

² The most conservative ESL guideline value has been adopted for all analytes

Amanagement limits are applied after consideration of relevant ESLs and HSLs. Separate management limits for BTEX and naphthalene are not available hence these should not be subtracted from the relevant fractions to obtain F1 and F2.

Direct Contact are applied to surface soils or soils that could result in immediate contact.

NL = Non Limiting. No HSL is presented for these chemicals as a soil vapour source concentration for a petroleum mixture could not exceed a level that would result in the maximum allowable vapour risk for the given scenario.

Health Investigation Levels for chromium based on chromium (VI)

Site specific EILs for copper in italics are based on the average of soil pH, cation exchange capacity and organic content

Site specific ELLs for nickel in fallics are based on the average of soil cation exchange capacity or Site specific ELLs for nickel in fallics are based on the average of soil pH and cation exchange capacity To obtain F1 subtract the sum of BTEX concentrations from the C6-C10 fraction.

To obtain F2 subtract he sum of BTEX concentrations from the C-C-10 fraction.

To obtain F2 subtract he path tack another the >C10-C-16 fraction.

Benzo(a)Pyrene ESL adopted values based on Canadian Council of Ministers of the Environment (CCME) 2008 guidelines developed using a species sensitivity distribution (SSD) for eco-toxicity data from five independent studies involving three soil invertebrate taxa and two plant taxa (14 endpoints) in preference to NEPM low reliability data. Concentration in red font and grey box exceed the adopted HIL/HSL 'D' for commercial/industrial use Concentration in blue fort and grey box exceed the adopted HIL first in the control of the control of the control of the control of the concentration in green and grey box exceed the adopted HISL 'D' direct contact for commercial/industrial use Concentration in light blue and grey box exceed the adopted HISL 'D' direct contact for intrusive Maintenance Workers Concentration in pink and grey box exceed the adopted HISL 'direct contact for intrusive Maintenance Workers Concentration in pink and grey box exceed the adopted HISL 'direct contact for intrusive Maintenance Workers Concentration in pink and grey box exceed the adopted HISL 'group intrusion for Intrusive Maintenance Workers Concentrations in box exceed the screening value > 2.5 times

Where one or more guideline value is exceeded, the highest guideline value will be highlighted Concentrations below the LOR noted as exceeding value is exceeded, the highest guideline value will be highlighted Concentrations and the properties of the LOR note as expected the properties of t

Concentrations below the LOR noted as <value

'Ch' Chrysotile (white asbestos)
'Am' Amosite (brown asbestos)

Cr' Crocidolite (blue asbestos)



		_			
	Sample ALS Sa	mple numb	ALS	ALS	
		-	ES1609686002	ES1609686010	
	Sample		05/05/2016	05/05/2016	
			028_TP001_0.50	028_QC001	
		Name:	M4E-WCX	M4E-WCX	RPD
	Compo	una:	Northcote Street Tunnel Site	Northcote Street Tunnel Site	
	Site:		Site 028	Site 028	
	Sampli	ng Method:	Test Pitting	Test Pitting	
	Sample	Description	PRIMARY	Duplicate of	
				028_TP001_0.5	
Analyte grouping/Analyte	Units	LOR			
EA055: Moisture Content Moisture Content (dried @ 103°C)	%		15.3	12.8	17.8
EA200: AS 4964 - 2004 Identification of Asbestos in Soils					
Asbestos Detected Asbestos Type	g/kg		No	No	
Sample weight (dry)	g		70.1	31.7	
			Mid brown clay soil	Mid brown clay soil	
Description			with grey rocks.	with grey rocks.	
APPROVED IDENTIFIER:			G.MORGAN	G.MORGAN	***
EG005T: Total Metals by ICP-AES	1				
Arsenic Cadmium	mg/kg mg/kg	5 1	18 1	6 <1	100.0 nc
Chromium	mg/kg	2	30	20	40.0
Copper	mg/kg	5	32	25	24.6
Lead Nickel	mg/kg mg/kg	2	158 9	128	21.0 100.0
Zinc	mg/kg	5	322	200	46.7
EG035T: Total Recoverable Mercury by FIMS					
Mercury	mg/kg	0.1	<0.1	<0.1	nc
EP075(SIM)A: Phenolic Compounds Phenol	mg/kg	0.5	<0.5	<0.5	nc
2-Chlorophenol	mg/kg	0.5	< 0.5	< 0.5	nc
2-Methylphenol	mg/kg	0.5	< 0.5	< 0.5	nc
3- & 4-Methylphenol 2-Nitrophenol	mg/kg mg/kg	0.5	<1 <0.5	<1 <0.5	nc nc
2.4-Dimethylphenol	mg/kg	0.5	< 0.5	< 0.5	nc
2.4-Dichlorophenol 2.6-Dichlorophenol	mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	nc nc
4-Chloro-3-methylphenol	mg/kg	0.5	<0.5	<0.5	nc
2.4.6-Trichlorophenol 2.4.5-Trichlorophenol	mg/kg	0.5	< 0.5	<0.5	nc nc
Pentachlorophenol	mg/kg mg/kg	2	<0.5 <2	<0.5 <2	nc
EP075(SIM)B: Polynuclear Aromatic Hydrocarbons					
Naphthalene Acenaphthylene	mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	nc nc
Acenaphthene	mg/kg	0.5	<0.5	<0.5	nc
Fluorene	mg/kg	0.5	< 0.5	<0.5	nc
Phenanthrene Anthracene	mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	nc nc
Fluoranthene	mg/kg	0.5	< 0.5	< 0.5	nc
Pyrene Benz(a)anthracene	mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	nc nc
Chrysene	mg/kg	0.5	<0.5	<0.5	nc
Benzo(b+j)fluoranthene Benzo(k)fluoranthene	mg/kg	0.5	< 0.5	<0.5 <0.5	nc nc
Benzo(k)fluoranthene Benzo(a)pyrene	mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	nc
Indeno(1.2.3.cd)pyrene	mg/kg	0.5	< 0.5	< 0.5	nc
Dibenz(a.h)anthracene Benzo(g.h.i)perylene	mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	nc nc
Sum of polycyclic aromatic hydrocarbons	mg/kg	0.5	< 0.5	< 0.5	nc
Benzo(a)pyrene TEQ (zero) Benzo(a)pyrene TEQ (half LOR)	mg/kg mg/kg	0.5	<0.5 0.6	<0.5 0.6	nc 0.0
Benzo(a)pyrene TEQ (LOR)	mg/kg	1.2	1.2	1.2	0.0
EP080/071: Total Petroleum Hydrocarbons	m = #-=	10			
C6 - C9 Fraction C10 - C14 Fraction	mg/kg mg/kg	10 50	<10 <50	<10 <50	nc nc
C15 - C28 Fraction	mg/kg	100	<100	<100	nc
C29 - C36 Fraction C10 - C36 Fraction (sum)	mg/kg mg/kg	100 50	<100 <50	<100 <50	nc nc
			.30		
EP080/071: Total Recoverable Hydrocarbons - NEPM 2013 Frac C6 - C10 Fraction	mg/kg	10	<10	<10	nc
C6 - C10 Fraction minus BTEX (F1)	mg/kg	10	<10	<10	nc
>C10 - C16 Fraction >C16 - C34 Fraction (F3)	mg/kg mg/kg	50 100	<50 <100	<50 <100	nc nc
>C34 - C40 Fraction (F4)	mg/kg	100	<100	<100	nc
>C10 - C40 Fraction (sum) >C10 - C16 Fraction minus Naphthalene (F2)	mg/kg mg/kg	50 50	<50 <50	<50 <50	nc nc
	gring	0	-200		
EPO80: BTEXN Benzene	mg/kg	0.2	<0.2	<0.2	nc
Toluene	mg/kg	0.5	< 0.5	< 0.5	nc
Ethylbenzene meta- & para-Xylene	mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	nc nc
ortho-Xylene	mg/kg	0.5	< 0.5	< 0.5	nc
			< 0.5	-0.5	nc
Total Xylenes Sum of BTEX	mg/kg mg/kg	0.5	<0.2	<0.5 <0.2	nc

nc = not calculated since results < LOR
LOR = Laboratory Limit of Reporting
ROLD identifies where RPD results

re sample results are >10 x PQL
re sample results are > 5 to ≤10 x PQL
re sample results are >2 to ≤5 x PQL
re sample results are ≤2 x PQL
1

Where results are within two of the above ranges the most conservative criteria have been used to assess duplicate performance




TABLE 1 Summary of Soil Sampling Results - Site 006 Underground Storage Tanks and Fuel Lines CSJ M4E WestConnex

	Ramboll Environ S	Sample ID						006_GS001	006_GS002	006_GS003	006_GS004	006_GS005	006_GS006	006_GS007	006_GS008	006_GS009	006_GS010	006_GS011	006_QC022	
	Location							UST 2	UST 2	UST 2	UST 1	UST 1	UST 1	UST 1	UST 1	Fuel Lines	Fuel Lines	Fuel Lines	Field duplicate of 006_GS008	RPD
	Laboratory Sample	e Description						Mid brown sandy soil with red rocks plus one small friable asbestos fibre bundle approx 3 x 1 x 1 mm.	Mid brown sandy soil with red rocks.	Mid brown sandy soil with red rocks.	Mid brown sandy soil with grey rocks.	Mid brown sandy soil with grey rocks.	Mid brown sandy soil with grey rocks.	Pale brown sandy soil with grey rocks.	Mid brown sandy soil with grey rocks.	Mid brown sandy soil with grey rocks.	Mid brown clay soil with grey rocks.	Mid brown clay soil with grey rocks.	****	RPD
					(2014) Waste															ļ.
	Units	Analyte	CT1	CT2	SCC1*	SCC2*	TCLP1* TCLP2*													
Asbestos	none	Asbestos **						Yes	No	No	No	No	No	No	No	No	No	No		
	none	Asbestos Asbestos Type						Ch****												
Metals		ASSESTED TYPE						Cii												
	mg/kg	Arsenic	100	400	500	2000		<5	<5	<5	5	6	<5	<5	<5	<5	<5	<5	7	nc
	mg/kg	Cadmium	20	80	100	400		<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	nc
	mg/kg	Chromium Total***						<2	<2	<2	7	8	6	4	6	5	8	8	11	58.8
-	mg/kg	Copper	100		4500	5000		<5	<5	<5	8	12	10	<5	9	32	6	12	18	66.7
-	mg/kg	Lead Nickel	100 40	400 160	1500 1050	6000 4200		<5 <2	<5 <2	<5 <2	26 2	26 3	18	8 <2	23	43	15 2	27 4	36 3	44.1 40.0
	mg/kg mg/kg	Zinc	40	100	1030	4200		53	55	42	59	117	62	46	80	398	77	30	126	44.7
	mg/kg	Mercury						<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	nc
BTEX	<u></u>																			
	mg/kg	Benzene	10	40	18	72		<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	nc
<u> </u>	mg/kg	Toluene	288	1150	518	2070		<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	nc
<u> </u>	mg/kg	Ethylbenzene	600	2400	1080	4320		<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	nc
-	mg/kg mg/kg	meta- & para-Xylene ortho-Xylene	1000	4000	1800	7200		<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	nc nc
	mg/kg	Total Xylenes	1000	4000	1800	7200		<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	nc
	mg/kg	Sum of BTEX						<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	nc
	mg/kg	Naphthalene						<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	nc
TPH (NEP																				
	mg/kg	C6 - C9 Fraction	650	2600	650	2600		<10	<10	<10	<10	<10	21	<10	35	<10	<10	<10	56	46.2
	mg/kg	C10 - C14 Fraction						250 360	250	310	<50 <100	<50	<50	<50	60	<50	<50	<50	<50 <100	nc
	mg/kg mg/kg	C15 - C28 Fraction C29 - C36 Fraction						<100	390 <100	420 <100	<100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100	nc nc
	mg/kg	C10 - C36 Fraction (sum)	10000	40000	10000	40000		610	640	730	<50	<50	<50	<50	60	<50	<50	<50	<50	nc
TRH (NEP	M Amendment 2013	3)																		
	mg/kg	C6 - C10 Fraction						<10	<10	<10	<10	<10	30	<10	49	<10	<10	<10	70	35.3
	mg/kg	C6 - C10 Fraction minus BTEX (F1)						<10	<10	<10	<10	<10	30	<10	49	<10	<10	<10	70	35.3
-	mg/kg	>C10 - C16 Fraction						380 280	400 300	470 320	<50	<50 <100	<50 <100	<50 <100	60 <100	<50 <100	<50 <100	<50	<50 <100	nc
	mg/kg mg/kg	>C16 - C34 Fraction >C34 - C40 Fraction						<100	<100	<100	<100 <100	<100	<100	<100	<100	<100	<100	<100 <100	<100	nc nc
	mg/kg	>C10 - C40 Fraction (sum)						660	700	790	<50	<50	<50	<50	60	<50	<50	<50	<50	nc
	mg/kg	>C10 - C16 Fraction minus Naphthalene (F2)						380	400	470	<50	<50	<50	<50	60	<50	<50	<50	<50	nc
PAHs																				
	mg/kg	Naphthalene						<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	nc
-	mg/kg mg/kg	Acenaphthylene Acenaphthene						<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	nc
	mg/kg	Fluorene						<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	nc nc
	mg/kg	Phenanthrene						<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	nc
	mg/kg	Anthracene						<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	nc
	mg/kg	Fluoranthene						<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	nc
-	mg/kg	Pyrene						<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	nc
-	mg/kg mg/kg	Benz(a)anthracene Chrysene	+				+	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	nc nc
	mg/kg	Benzo(b+j)fluoranthene						<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	nc
	mg/kg	Benzo(k)fluoranthene			<u></u>			<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	nc
	mg/kg	Benzo(a)pyrene	0.8	3.2	10	23		<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	nc
	mg/kg	Indeno(1.2.3.cd)pyrene						<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	nc
	mg/kg	Dibenz(a.h)anthracene						<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5	<0.5 <0.5	<0.5 <0.5	nc
-	mg/kg mg/kg	Benzo(g.h.i)perylene Sum of polycyclic aromatic hydrocarbons	1		1			<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5 <0.5	<0.5	<0.5	nc nc
	mg/kg	Benzo(a)pyrene TEQ (zero)						<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	nc
	mg/kg	Benzo(a)pyrene TEQ (half LOR)						0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	
	mg/kg	Benzo(a)pyrene TEQ (LOR)						1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	
Phenols				4		20														
—	mg/kg mg/kg	Phenol 2-Chlorophenol	288	1150	518	2070				<0.5 <0.5	<0.5 <0.5		<0.5 <0.5		<0.5 <0.5		<0.5 <0.5			
-	mg/kg	2-Methylphenol	4000	16000	7200	28800				<0.5	<0.5		<0.5		<0.5		<0.5			
	mg/kg	3- & 4-Methylphenol	1		1					<1	<1		<1		<1		<1			
	mg/kg	2-Nitrophenol								<0.5	<0.5		<0.5		<0.5		<0.5			
	mg/kg	2.4-Dimethylphenol								<0.5	<0.5		<0.5		<0.5		<0.5			
	mg/kg	2.4-Dichlorophenol	<u> </u>		1					<0.5	<0.5		<0.5		<0.5		<0.5			
-	mg/kg	2.6-Dichlorophenol 4-Chloro-3-methylphenol	-	-	-					<0.5 <0.5	<0.5 <0.5		<0.5 <0.5		<0.5 <0.5		<0.5 <0.5			
 	mg/kg mg/kg	2.4.6-Trichlorophenol	40	160	72	288				<0.5 <0.5	<0.5		<0.5		<0.5 <0.5		<0.5			
	mg/kg	2.4.5-Trichlorophenol	8000	32000	14400	57600				<0.5	<0.5		<0.5		<0.5		<0.5			
	mg/kg	Pentachlorophenol								<2	<2		<2		<2		<2			
-	-	•	•	•	•			•			•	•	•			•	•			-

TABLE 1 Summary of Soil Sampling Results - Site 006 Underground Storage Tanks and Fuel Lines CSJ M4E WestConnex

	Ramboll Environ	Sample ID						006_GS001	006_GS002	006_GS003	006_GS004	006_GS005	006_GS006	006_GS007	006_GS008	006_GS009	006_GS010	006_GS011	006_QC022	
	Location							UST 2	UST 2	UST 2	UST 1	UST 1	UST 1	UST 1	UST 1	Fuel Lines	Fuel Lines	Fuel Lines	Field duplicate of 006_GS008	RPD
	Laboratory Samp	ole Description						Mid brown sandy soil with red rocks plus one small friable asbestos fibre bundle approx 3 x 1 x 1 mm.	Mid brown sandy soil with red rocks.	Mid brown sandy soil with red rocks.	Mid brown sandy soil with grey rocks.	Mid brown sandy soil with grey rocks.	Mid brown sandy soil with grey rocks.	Pale brown sandy soil with grey rocks.	Mid brown sandy soil with grey rocks.	Mid brown sandy soil with grey rocks.	Mid brown clay soil with grey rocks.	Mid brown clay soil with grey rocks.		KPD
				NSW FPA	(2014) Waste	Classification	Guidelines	A 2 111111												
	Units	Analyte	CT1	CT2	SCC1*	SCC2*	TCLP1* TCLP2	k												
PCBs	Onits	Paralyte	C12	CIE	3001	JCCE	ICEI I ICEI Z													
PCDS	ma/lea	PCBs (Total)	50			50				<0.1	<0.1		<0.1		<0.1		<0.1			
D41 -1 -1 -	mg/kg	PCBS (Total)	30	50	50	50				V0.1	V0.1		V0.1		V0.1		V0.1			
Pesticide	_	D. 1.1																		
	mg/kg	Dichlorvos								<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	Demeton-S-methyl								<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	Monocrotophos								<0.2	<0.2		<0.2		<0.2		<0.2			
	mg/kg	Dimethoate								< 0.05	< 0.05		< 0.05		< 0.05		< 0.05			
	mg/kg	Diazinon								<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	Chlorpyrifos-methyl								<0.05	<0.05		<0.05		< 0.05		< 0.05			
	mg/kg	Parathion-methyl								<0.2	<0.2		<0.2		<0.2		<0.2			
	mg/kg	Malathion				1				<0.05	<0.05		<0.05		<0.05		< 0.05			
	mg/kg	Fenthion								<0.05	<0.05		<0.05		<0.05		< 0.05			
	mg/kg	Chlorpyrifos	4	16	7.5	30				<0.05	<0.05		<0.05		< 0.05		<0.05			
	mg/kg	Parathion		10	7.5	30				<0.2	<0.2		<0.2		<0.2		<0.2			
		Pirimphos-ethyl								<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg			-							<0.05		<0.05		<0.05					
	mg/kg	Chlorfenvinphos								<0.05							<0.05			
	mg/kg	Bromophos-ethyl								<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	Fenamiphos								<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	Prothiofos								<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	Ethion								<0.05	< 0.05		< 0.05		<0.05		< 0.05			
	mg/kg	Carbophenothion								<0.05	< 0.05		< 0.05		<0.05		< 0.05			
	mg/kg	Azinphos Methyl								< 0.05	< 0.05		< 0.05		< 0.05		< 0.05			
	mg/kg	alpha-BHC								< 0.05	< 0.05		< 0.05		<0.05		< 0.05			
	mg/kg	Hexachlorobenzene (HCB)								< 0.05	< 0.05		< 0.05		< 0.05		< 0.05			
	mg/kg	beta-BHC								< 0.05	<0.05		<0.05		< 0.05		< 0.05			
	mg/kg	gamma-BHC								<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	delta-BHC		+						<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	Heptachlor								<0.05	<0.05		<0.05		<0.05		<0.05			
		Aldrin		-						<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg				-							1		1				+ + + + + + + + + + + + + + + + + + + +	+	
-	mg/kg	Heptachlor epoxide								<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	Total Chlordane (sum)								<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	trans-Chlordane								<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	alpha-Endosulfan		1	1	ļ				<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	cis-Chlordane			1					<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	Dieldrin				<u> </u>				<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	4.4`-DDE								<0.05	< 0.05		< 0.05		<0.05		< 0.05			
	mg/kg	Endrin								<0.05	<0.05		<0.05		<0.05		< 0.05			
	mg/kg	Endosulfan (sum)	60	240	108	432				<0.05	<0.05		<0.05		<0.05		< 0.05			
	mg/kg	beta-Endosulfan	 	†	† <u></u>	T				<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	4.4`-DDD	+	1	†	l .				<0.05	<0.05		<0.05		<0.05		<0.05			
\vdash	mg/kg	Endrin aldehyde	+	1	†	 	 			<0.05	<0.05		<0.05		<0.05		<0.05			
—		Endosulfan sulfate	+	+	+	1	 			<0.05	<0.05		<0.05		<0.05			+		
—	mg/kg		+	1	1	 	 										<0.05			
	mg/kg	4.4`-DDT		1	-					<0.2	<0.2		<0.2		<0.2		<0.2			
	mg/kg	Endrin ketone		_		ļ				<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	Methoxychlor			1	ļ				<0.2	<0.2		<0.2		<0.2		<0.2			
	mg/kg	Sum of DDD + DDE + DDT			1					<0.05	<0.05		<0.05		<0.05		<0.05			
	mg/kg	Sum of Aldrin + Dieldrin			<u> </u>	<u> </u>				<0.05	<0.05		<0.05		<0.05		<0.05			

*CT1 and CT2 refer to NSW EPA Waste Classification Guidelines - Part 1: Classification of Waste

** A confirmed presence of asbestos is pre-classified as Special Waste Asbestos

***These limits apply to Chromium (VI) only. Total Chromium used as a conservative screening level only
***Refers to Chrysotile asbestos detected

Blank cell indicates no screening criterion available
For Limit of Reporting (LOR) refer to laboratory certificates of analysis
--- Indicates sample not analysed
Only compounds with at least one detection are shown.

Concentration in grey box that exceeds the screening value


Concentrations below the LOR noted as <value

RPD = Relative Percent Difference
nc - Not Calculated sinces results < PQL

BOLD identifies where RPD results exceed Ramboll Environ Data Quality Indicators (DQIs) as follows:

OLD Identifies with	ere KPD results exceed Kalliboli Eliviroli Data Qi
Ouplicate	Triplicate
50	>60
75	>85
100	>100
	Absolute Difference>2.5 * POI

Where results are within two of the above ranges the most conservative criteria have been used to assess duplicate performance



RAMBOLL ENVIRON



Figure 2: Proposed depth of excavation. Supplied by CSJ to Ramboll Environ

							006_TP001_0.10	006_TP001_0.50	006_TP001_1.20	006_TP002_0.10	006_TP002_0.70	006_TP002_1.20	006_TP003_0.10	006_TP003_0.30	006_TP003_0.60	006_TP004_0.20	006_TP004_0.40	006_TP004_1.00	006_GW004_0.2	006_GW004_0.5	006_GW004_2.5	006_GW005_0.2	006_GW005_0.6	006_GW005_0.7
	Site	viron Sample ID					Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006
	Compound						Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Sit	e Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site
	Sample Des						FILL; Silty sand, moist, medium grained, uniform, grey/brown, no observed contamination, contains srushed concrete, roots, crushed sandstone	Residual CLAY/highly weathered sandstone; mottled grey/red orange, moist, minor very fine sands, soft- moist, no observed contamination	Residual CLAY/highly weathered sandstone; mottled grey/red orange, moist, minor very fine sands, soft- moist, no observed contamination	FILL; Sity sand, possible backfill sands, grey/orange, saturated, medlum grained, perhaps very slight hydrocarbon odour, loose, no asbestos containing material observed, brick	FILL; Gravelly sandy clay, saturated, orange/brown, ironstone gravels, soft, high plasticity, no observed contamination	odour, opposite wall -	FILL; Silty sand, brown, moist, contains bricks, blue metal, lots of PVC conduits and wire and ag pipe, medium dense, no observed contaminatoin, broken glass	Clayey SAND; highly weathered sandstone, orange/red, medium stiff, ironstone, high plasticity clay, sand is fine grained, no observed contamination	Clayey SAND; highly weathered sandstone, mostly white, medium grained, less dense, NOC, moist pockets	FILL; Gravelly clayey sand, reworked natural with pieces of concrete, sandstone mixed in, orange/brown, medium dense-soft, no observed contamination	Gravelly SILT; orange, slightly moist-moist, gravel is ironstone, no observed contamination	Clayey SAND; highly weathered sandstone, orange and white, high plasticity, medium dense	CLAY; red and grey mottled, low plasticity, moist	CLAY, red and grey mottled, low plasticity, moist	SANDSTONE; light grey/orange mottled	FILL; Clayey sand, black, fine to medium grained, moist	FILL; Sandy clay with gravel, grey, low plasticity, wet (possible staining)	CLAY; red and grey mottled, wet
	Lab Report	ID					ES1609685	ES1609685	ES1609685	ES1609685	ES1609685	ES1609685	ES1609685	ES1609685	ES1609685	ES1609685	ES1609685	ES1609685	ES1610404	ES1610404	ES1610404	ES1610404	ES1610404	ES1610404
	Sampler						AS 0	AS 0	AS 0	AS 0.4	AS 0	AS 0.4	AS 0	AS 0	AS 0	AS 0	AS 0	AS 0	MT	MT	MT	MT 0.5	MT 0.5	MT 0
	PID Value (p Sample date		NSW	EPA (2014) W	aste Classification (Guidelines	4/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	11/05/2016	11/05/2016	11/05/2016	11/05/2016	11/05/2016	11/05/2016
	Units	Analyte	CT1 CT2				CLP2*																	
Asbestos	2020	Ashestos **					No			No	No		No			No	****	****	No	No	***	No	No	No
	none	Asbestos Type					NO	****	****	NO	NO	****	NO	****	****	NO			-	- NO		NO .	-	ino .
Metals																								
	mg/kg	Arsenic	100 400 20 80				<5	<5	<5	46 <1	<5	<5 <1	<5 <1	<5 <1	<5	<5	<5 <1	<5 <1	<1	<5	<5	<5	6 <1	<5
	mg/kg mg/kg	Cadmium Chromium Total***	20 80	100	400		4	4	<2	19	15	2	4	11	4	12	19	8	6	3	<1 14	21	69	2
	mg/kg	Copper					7	<5	<5	20	<5	<5	<5	<5	<5	6	<5	<5	<5	<5	<5	12	24	<5
	mg/kg	Iron	100	4	5005		22			39		9	42		40	10			0.076	0.138	0.640		33	
	mg/kg mg/kg	Lead Nickel	100 400 40 160				22 <2	6 <2	<5	39 4	11 <2	9 <2	13 7	6 <2	10 <2	10	6 <2	6 <2	b <2	5 <2	3	21 11	33 60	10 <2
	mg/kg	Zinc	100	203.			46	<5	<5	228	24	<5	34	<5	<5	14	<5	<5	<5	<5	8	40	76	<5
DTEV	mg/kg	Mercury					<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1
BIEX	mg/kg	Benzene	10 40	18	72		<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
	mg/kg	Toluene	288 1152	518	2073		<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	Ethylbenzene	600 2400	108	4320		<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg mg/kg	meta- & para-Xylene ortho-Xylene	1000 4000	180	7200		<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
	mg/kg	Total Xylenes	1000 4000	100	7200		<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	Sum of BTEX					<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
	mg/kg M 1999)	Naphthalene					<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1
	mg/kg	C6 - C9 Fraction	650 2600	650	2600		<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10
	mg/kg	C10 - C14 Fraction					<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50 <100
	mg/kg mg/kg	C15 - C28 Fraction C29 - C36 Fraction					<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100
	mg/kg	C10 - C36 Fraction (sum)	10000 40000	1000	0 40000		<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50
TRH (NEPA	M Amendmer	nt 2013)					<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10
	mg/kg mg/kg	C6 - C10 Fraction C6 - C10 Fraction minus BTEX (F1)					<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10
	mg/kg	>C10 - C16 Fraction					<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50
	mg/kg	>C16 - C34 Fraction					<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100
	mg/kg mg/kg	>C34 - C40 Fraction >C10 - C40 Fraction (sum)					<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50
	mg/kg	>C10 - C16 Fraction minus Naphthalene (F2)					<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50
PAHs	ma/ka	Naphthalene					<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg mg/kg	Acenaphthylene					<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	Acenaphthene					<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg mg/kg	Fluorene Phenanthrene		-			<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
	mg/kg mg/kg	Anthracene					<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	Fluoranthene					<0.5	<0.5	<0.5	<0.5 <0.5	<0.5	<0.5 <0.5	<0.5	<0.5 <0.5	<0.5 <0.5	<0.5	<0.5	<0.5	<0.5 <0.5	<0.5	<0.5	<0.5 <0.5	<0.5 <0.5	<0.5
	mg/kg mg/kg	Pyrene Benz(a)anthracene					<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
	mg/kg	Chrysene					<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	Benzo(b+j)fluoranthene					<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg mg/kg	Benzo(k)fluoranthene Benzo(a)pyrene	0.8 3.2	10	23		<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
	mg/kg	Indeno(1.2.3.cd)pyrene	5.2	10			<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	Dibenz(a.h)anthracene					<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg mg/kg	Benzo(g.h.i)perylene Sum of polycyclic aromatic hydrocarbons	200 800	200	800		<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
	mg/kg mg/kg	Benzo(a)pyrene TEQ (zero)					<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	Benzo(a)pyrene TEQ (half LOR)					0.6 1.2	0.6	0.6 1.2	0.6 1.2	0.6	0.6 1.2	0.6	0.6 1.2	0.6 1.2	0.6	0.6	0.6	0.6	0.6 1.2	0.6	0.6 1.2	0.6 1.2	0.6
Phenols	mg/kg	Benzo(a)pyrene TEQ (LOR)					1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2
	mg/kg	Phenol	288 1152	518	2073		<0.5			<0.5						<0.5			<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	2-Chlorophenol	4000				<0.5 <0.5			<0.5						<0.5	****		<0.5	<0.5	<0.5	<0.5	<0.5	<0.5 <0.5
	mg/kg mg/kg	2-Methylphenol 3- & 4-Methylphenol	4000 16000	720	28800		<0.5			<0.5				****	****	<0.5 <1	****	****	<0.5 <1	<0.5	<0.5 <1	<0.5 <1	<0.5	<0.5 <1
	mg/kg	2-Nitrophenol					<0.5			<0.5					****	<0.5		****	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5

							006_TP001_0.10	006_TP001_0.50	006_TP001_1.20	006_TP002_0.10	006_TP002_0.70	006_TP002_1.20	006_TP003_0.10	006_TP003_0.30	006_TP003_0.60	006_TP004_0.20	006_TP004_0.40	006_TP004_1.00	006_GW004_0.2	006_GW004_0.5	006_GW004_2.5	006_GW005_0.2	006_GW005_0.6	006_GW005_0.7
	Ramboll Env Site	viron Sample ID					Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006
	Compound						Northcote Street Tuni	el Site Northcote Street Tunnel Si	e Northcote Street Tunnel Si	e Northcote Street Tunnel Sit	te Northcote Street Tunnel Sit	te Northcote Street Tunnel Site	e Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Sit	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	e Northcote Street Tunnel Site	Northcote Street Tunnel Site	e Northcote Street Tunnel Site
	Sample Desc	cription					FILL; Silty sand, m medium grained, uni grey/brown, no obs contamination, con srushed concrete, n crushed sandstor	mottled grey/red orange, most, minor very fine sands, soft	Residual CLAY/highly weathered sandstone; mottled grey/red orange, moist, minor very fine sands, soft moist, no observed contamination	FILL; Silty sand, possible backfill sands, grey/orange saturated, medium grained perhaps very slight hydrocarbon odour, loose, no asbestos containing material observed, brick	saturated, orange/brown, ironstone gravels, soft, hig	h medium grained, slight HC odour, opposite wall -	FILL; Silty sand, brown, moist, contains bricks, blue metal, lots of PVC conduits and wire and agipe, medium dense, no observed contaminatoin, broken glass	Clayey SAND; highly weathered sandstone, orange/red, medium stiff, ironstone, high plasticity clay, sand is fine grained, no observed contamination	Clayey SAND; highly weathered sandstone, mostly white, medium grained, less dense, NOC, moist pockets	FILL; Gravelly clayey sand, reworked natural with pieces of concrete, sandstone mixed in, orange/brown, medium dense-soft, no observed contamination	Gravelly SILT; orange, slightly moist-moist, gravel is ironstone, no observed contamination	Clayey SAND; highly weathered sandstone, orange and white, high plasticity, medium dense	CLAY; red and grey mottled, low plasticity, moist	CLAY; red and grey mottled, low plasticity, moist	SANDSTONE; light grey/orange mottled	FILL; Clayey sand, black, fine to medium grained, moist	FILL; Sandy clay with gravel, grey, low plasticity, wet (possible staining)	
	ab Report I	ID					ES1609685	ES1609685	ES1609685	ES1609685	ES1609685	ES1609685	ES1609685	ES1609685	ES1609685	ES1609685	ES1609685	ES1609685	ES1610404	ES1610404	ES1610404	ES1610404	ES1610404	ES1610404
	Sampler PID Value (p	(mag					AS 0	AS 0	AS 0	AS 0.4	AS 0	AS 0.4	AS 0	AS 0	AS 0	AS 0	AS 0	AS 0	MT 	MT 	MT 	MT 0.5	MT 0.5	MT 0
	Sample date	e:			014) Waste Classification		4/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	11/05/2016	11/05/2016	11/05/2016	11/05/2016	11/05/2016	11/05/2016
	Jnits ng/kg	Analyte 2.4-Dichlorophenol	CT1	CT2	SCC1* SCC2*	TCLP1*	TCLP2* <0.5			<0.5					****	<0.5	****	****	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	ng/kg	2.6-Dichlorophenol					<0.5			<0.5						<0.5			<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	ng/kg	4-Chloro-3-methylphenol 2.4.6-Trichlorophenol	40	160	72 288		<0.5 <0.5			<0.5 <0.5		****			****	<0.5 <0.5		****	<0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
	ng/kg ng/kg	2.4.5-Trichlorophenol	8000		14400 57600		<0.5			<0.5						<0.5			<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	ng/kg	Pentachlorophenol					<2			<2						<2			<2	<2	<2	<2	<2	<2
PCBs	ng/kg	PCBs (Total)	50	50	50 50		0.2			<0.1						<0.1			<0.1	<0.1	<0.1	<0.1	<0.1	<0.1
Pesticides					50																			
	ng/kg	Dichlorvos Demeton-S-methyl					<0.05 <0.05			<0.05 <0.05						<0.05			<0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05
	ng/kg ng/kg	Monocrotophos					<0.2			<0.2						<0.2			<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
	ng/kg	Dimethoate					<0.05			<0.05		****			****	<0.05		****	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
	ng/kg ng/kg	Diazinon Chlorpyrifos-methyl				+	<0.05 <0.05			<0.05 <0.05		****				<0.05 <0.05		****	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05
	ng/kg	Parathion-methyl					<0.2			<0.2						<0.2			<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
	ng/kg	Malathion					<0.05 <0.05			<0.05 <0.05		****				<0.05 <0.05			<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05
	ng/kg ng/kg	Fenthion Chlorpyrifos	4	16	7.5 30		<0.05			<0.05						<0.05			<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
	ng/kg	Parathion					<0.2			<0.2		****				<0.2			<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
	ng/kg	Pirimphos-ethyl Chlorfenvinphos					<0.05 <0.05			<0.05 <0.05						<0.05 <0.05			<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05
	ng/kg ng/kg	Bromophos-ethyl					<0.05			<0.05						<0.05			<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
	ng/kg	Fenamiphos					<0.05			<0.05						<0.05			<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
	ng/kg ng/kg	Prothiofos Ethion					<0.05 <0.05			<0.05 <0.05						<0.05 <0.05			<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05
	ng/kg	Carbophenothion					<0.05			<0.05						<0.05			<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
	ng/kg ng/kg	Azinphos Methyl alpha-BHC					<0.05 <0.05			<0.05 <0.05						<0.05 <0.05			<0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05
	ng/kg	Hexachlorobenzene (HCB)					<0.05			<0.05						<0.05			<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
	ng/kg	beta-BHC					<0.05			<0.05						<0.05			<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
	ng/kg ng/kg	gamma-BHC delta-BHC					<0.05 <0.05			<0.05 <0.05		****				<0.05 <0.05			<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05
	ng/kg	Heptachlor					<0.05			<0.05						<0.05			<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
	ng/kg	Aldrin Heptachlor epoxide					<0.05 <0.05			<0.05 <0.05						<0.05 <0.05			<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05
	ng/kg ng/kg	Total Chlordane (sum)					<0.05			<0.05						<0.05			<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
	ng/kg	trans-Chlordane					<0.05 <0.05			<0.05 <0.05						<0.05 <0.05			<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05
	ng/kg ng/kg	alpha-Endosulfan cis-Chlordane					<0.05 <0.05			<0.05 <0.05						<0.05 <0.05			<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05
	ng/kg	Dieldrin					<0.05			<0.05						<0.05			<0.05	<0.05	<0.05	< 0.05	<0.05	<0.05
	ng/kg	4.4`-DDE Endrin					<0.05 <0.05			<0.05 <0.05						<0.05 <0.05			<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05
	ng/kg ng/kg	Endosulfan (sum)	60	240	108 432		<0.05			<0.05						<0.05			<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
	ng/kg	beta-Endosulfan					<0.05			<0.05						<0.05			<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
	ng/kg ng/kg	4.4`-DDD Endrin aldehyde	 				<0.05 <0.05			<0.05 <0.05						<0.05 <0.05			<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05
	ng/kg	Endosulfan sulfate					<0.05			<0.05						<0.05			<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
	ng/kg	4.4`-DDT Endrin ketone					<0.2 <0.05			<0.2 <0.05						<0.2 <0.05			<0.2 <0.05	<0.2 <0.05	<0.2 <0.05	<0.2 <0.05	<0.2 <0.05	<0.2 <0.05
	ng/kg ng/kg	Methoxychlor					<0.05			<0.2						<0.2			<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
	ng/kg	Sum of DDD + DDE + DDT					<0.05			<0.05						<0.05			<0.05	<0.05	< 0.05	< 0.05	<0.05	<0.05
	ng/kg P)	Sum of Aldrin + Dieldrin					<0.05			<0.05						<0.05			<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
	ng/L	Arsenic				5	20																	
	ng/L	Cadmium Total				1	4																	-
	ng/L ng/L	Chromium, Total Copper																						
	ng/L ng/L	Lead				5	20																	
\vdash	mg/L	Nickel Zinc				2	8																	
PAHTCIP	ng/L	LIIIL																						

									I								T						
	Ramboll Enviro	n Sample ID					006_GW005_4.0 Site 006	006_GW006_0.2	006_GW006_0.5 Site 026	012_GW001_0.2 Site 012	012_GW001_0.5 Site 012	026_TP001_0.10 Site 026	026_TP001_0.50	026_TP001_1.00	026_GW001_0.2	026_GW001_0.5 Site 026	027_TP001_0.20 Site 027	027_TP001_0.50 Site 027	027_TP001_0.80 Site 027	027_TP002_0.25 Site 027	027_TP002_1.30 Site 027	027_GW003_0.2 Site 027	027_GW003_0.5
	Site							Site 026					Site 026	Site 026	Site 026			Northcote Street Tunnel Site N					Site 027
	Compound Sample Descrip	tion					SANDSTONE	FILL; Clayey sand, light brown, moist	CLAY; brown with red (sandstone) mottling, low to medium plasticity,	FILL; sandy clay, brown	CLAY, light brown/grey	FILL; Sandy silty gravel, dark grey/brown, gravel is basalt, moist, medium density, no	FILL; Silty clay, possibly reworked natural, moist, grey/brown with orange and	Silty CLAY; orange with red ironstone pockets, soft, moist, high plasticity, no	FILL; Sandy Clay, light brown, with cobbles, moist,	FILL; Sandy Clay, light brown, with cobbles, moist	FILL; Clayey silt, grey wtih some dark grey pockets, pieces of bricks, medium , plasticity, moist, moderateh	FILL; Clayey silt, grey wtih some dark grey pockets, pieces of bricks, possibly reworked natural, no	Silty CLAY; orange/red,	FILL; Clayey silt, grey/brown, moist-very moist, soft-moist, no	Silty CLAY; orange, moist- very moist, soft, ironstone gravels, no	Sandy CLAY, dark brown low plasticity, wet	CLAY, orange/red/grey mottled, moist, low-me
	Lab Ranast ID						E51610404	ES1610404	moist ES1610404	ES1610404	ES1610404	observed contamination ES1609680	white pockets, sandstone, some charcoal inclusions, no observed contamination ES1609680	observed contamination ES1609680	becoming black ES1610406	becoming black ES1610406	hydrocarbon odour, no ACN observed	anthropogenic inclusions, no observed contamination	no observed contamination	anthropogenic inclusions ES1609682	observed contamination ES1609682	E51610406	plasticity, becoming stif
	Lab Report ID Sampler						MT	MT	MT	MT	MT	AS	AS	AS	MT	MT	AS	AS	AS	AS	AS	MT	MT
	PID Value (ppm)		NCW FDA (2014) W-	-t- Cl f t -	Culdelline	1.1	0.2	0.2	44 (05 (204 5	44 (05 (204 5	04/05/2045	0.4/05/2045	0.4 (0.5 (0.0.4.5	44 (05 (2045	44 (05 (2045	0.4/05/2045	04/05/2045	04/05/2045	04/05/2045	04/05/2045	42/05/2045	42/05/2045
	Sample date: Units	Analyte	CT1	NSW EPA (2014) Wa CT2 SCC1*		TCLP1* TCLP2*	11/05/2016	11/05/2016	11/05/2016	11/05/2016	11/05/2016	04/05/2016	04/05/2016	04/05/2016	11/05/2016	11/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	12/05/2016	12/05/2016
Asbestos																							
	none	Asbestos ** Asbestos Type						No -	No -	No -	No -	No -	No -		No -	No -	No -	No -		No -		No -	No -
Metals																							
		Arsenic Cadmium	100 20	400 500 80 100			<5	13	6	14	21	<5	16	11	<5 <1	<5 <1	9	7 <1	5 <1	12	14 <1	10	<5
		Chromium Total***	20	80 100	400		8	23	26	29	32	12	24	42	9	6	17	20	26	38	15	31	28
	mg/kg	Copper					<5	<5	<5	21	153	80	20	<5	13	<5	28	8	<5	<5	<5	6	<5
		Iron Lead	100	400 1500	6000		0.749	14	12	228	438		75	18	9		158	37	13	14	16	38	
		Nickel	40	160 1050			5	<2	2	5	6	119	2	2	45	<2	6	3	<2	<2	<2	<2	<2
	mg/kg	Zinc Mercury					17 <0.1	10 <0.1	6 <0.1	66 <0.1	420 <0.1	40 <0.1	215 0.1	65 <0.1	22 <0.1	<5 <0.1	239 <0.1	42 <0.1	<5 <0.1	<5 <0.1	<5 <0.1	31 <0.1	<5 <0.1
BTEX	mg/kg	inicicui y					50.1	40.1	50.1	50.1	KU.1	50.1	0.1		40.1	40.1	40.1	V 0.1	V0.1	<0.1		50.1	
		Benzene	10	40 18			<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
	U, U	Toluene Ethylbenzene		1152 518 2400 1080			<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
		meta- & para-Xylene	555		4520		<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	0, 0	ortho-Xylene	1000	4000 1800	7200		<0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5	<0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5	<0.5 <0.5	<0.5	<0.5 <0.5
		Total Xylenes Sum of BTEX					<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.2	<0.5	<0.5	<0.5
	mg/kg	Naphthalene					<1	<1	⊲1	<1	<1	<1	<1	<1	<1	<1	<1	⊲	<1	<1	<1	<1	<1.
	// 1999) mg/kg	C6 - C9 Fraction	650	2600 650	2600		<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10
	mg/kg	C10 - C14 Fraction	030	2000	2000		<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50
		C15 - C28 Fraction C29 - C36 Fraction					<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 140	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100
		C10 - C36 Fraction (sum)	10000	40000 10000	40000		<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	140	<50	<50	<50	<50	<50	<50
TRH (NEPI	A Amendment 2	013)																					
		C6 - C10 Fraction C6 - C10 Fraction minus BTEX (F1)					<10 <10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10
	mg/kg	>C10 - C16 Fraction					<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50
		>C16 - C34 Fraction >C34 - C40 Fraction					<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	120 180	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100
		>C10 - C40 Fraction >C10 - C40 Fraction (sum)					<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	300	<50	<50	<50	<50	<50	<50
DAMe	mg/kg	>C10 - C16 Fraction minus Naphthalene (F2)					<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50
r Al IS		Naphthalene					<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
		Acenaphthylene Acenaphthene					<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
		Fluorene					<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	Phenanthrene Anthracene					<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
		Fluoranthene		+			<0.5	<0.5	<0.5	<0.5	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	Pyrene					<0.5	<0.5	<0.5	<0.5	1.4	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
-	0, 0	Benz(a)anthracene Chrysene					<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	0.8	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
	mg/kg	Benzo(b+j)fluoranthene					<0.5	<0.5	<0.5	<0.5	1.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
		Benzo(k)fluoranthene	0.8	3.2 10	23		<0.5	<0.5 <0.5	<0.5	<0.5	<0.5	<0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5	<0.5 <0.5
	mg/kg mg/kg	Benzo(a)pyrene Indeno(1.2.3.cd)pyrene	0.0	J.E 10	23		<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	Dibenz(a.h)anthracene					<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 0.6	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5
	mg/kg mg/kg	Benzo(g.h.i)perylene Sum of polycyclic aromatic hydrocarbons	200	800 200	800		<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	0.6 6.7	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
	mg/kg	Benzo(a)pyrene TEQ (zero)					<0.5	<0.5	<0.5	<0.5	1.1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
		Benzo(a)pyrene TEQ (half LOR) Benzo(a)pyrene TEQ (LOR)	 				0.6	0.6 1.2	0.6 1.2	0.6 1.2	1.4	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6 1.2	0.6	0.6 1.2
Phenols	G, G				205-													_	·	-			
		Phenol 2-Chlorophenol	288	1152 518	2073		<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5						<0.5 <0.5					<0.5 <0.5	<0.5 <0.5
	mg/kg	2-Methylphenol	4000	16000 7200	28800		<0.5	<0.5	<0.5	<0.5	<0.5						<0.5					<0.5	<0.5
-	mg/kg	3- & 4-Methylphenol 2-Nitrophenol					<1 <0.5	<1 <0.5	<0.5	<1 <0.5	<1 <0.5						<1 <0.5					<0.5	<1 <0.5
<u> </u>		2-Nitrophenol 2.4-Dimethylphenol					<0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5						<0.5 <0.5					<0.5	<0.5 <0.5
	···o/ "b					1 1		1			1	1	1	1	1	1	1	1			1		

				006_GW005_4.0 Site 006	006_GW006_0.2 Site 026	006_GW006_0.5 Site 026	012_GW001_0.2 Site 012	012_GW001_0.5 Site 012	026_TP001_0.10 Site 026	026_TP001_0.50 Site 026	026_TP001_1.00 Site 026	026_GW001_0.2 Site 026	026_GW001_0.5 Site 026	027_TP001_0.20 Site 027	027_TP001_0.50 Site 027	027_TP001_0.80 Site 027	027_TP002_0.25 Site 027	027_TP002_1.30 Site 027	027_GW003_0.2 Site 027	027_GW003_0 Site 027
						ite Northcote Street Tunnel Sit														
				SANDSTONE	FILL; Clayey sand, light brown, moist	CLAY; brown with red (sandstone) mottling, low to medium plasticity, moist	FILL; sandy clay, brown		FILL; Sandy silty gravel, dark grey/brown, gravel is basalt, y moist, medium density, no observed contamination		Silty CLAY; orange with red ironstone pockets, soft, moist, high plasticity, no observed contamination	FILL; Sandy Clay, light brown, with cobbles, moist, becoming black	FILL; Sandy Clay, light brown, with cobbles, moist, becoming black	some dark grey pockets, pieces of bricks, medium plasticity, moist, moderately	pieces of bricks, possibly reworked natural, no anthropogenic inclusions,	ironstone gravels, moist medium-high plasticity,	FILL; Clayey silt, grey/brown, moist-very moist, soft-moist, no anthropogenic inclusions	Silty CLAY; orange, moist- very moist, soft, ironstone gravels, no observed contamination	Sandy CLAY, dark brown low plasticity, wet	
				ES1610404	ES1610404	ES1610404	ES1610404	ES1610404	ES1609680	ES1609680	ES1609680	ES1610406	ES1610406 MT	ES1609682	ES1609682	ES1609682	ES1609682	ES1609682	ES1610406 MT	ES16104 MT
				1.1	0.2	0.2					-							-		
lyte			uidelines TCLP1* TCLP2*		, , , , ,	, , , , , ,	11/05/2016	,	04/05/2016	04/05/2016	04/05/2016	11/05/2016	11/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	,,	12/05/
Dichlorophenol Dichlorophenol				<0.5	<0.5	<0.5	<0.5	<0.5						<0.5					<0.5	<0
nloro-3-methylphenol				<0.5	<0.5	<0.5	<0.5	<0.5						<0.5					<0.5	<0
6-Trichlorophenol 5-Trichlorophenol				<0.5 <0.5	<0.5	<0.5 <0.5	<0.5	<0.5 <0.5						<0.5					<0.5	<0
tachlorophenol				<2	<2	<2	<2	<2						<2					<2	<
s (Total)	50 50 50	50		<0.1	<0.1	<0.1						****		<0.1					****	-
nlorvos				<0.05	<0.05	<0.05								<0.05						-
neton-S-methyl				<0.05	<0.05	<0.05								<0.05						-
ethoate				<0.05	<0.05	<0.05							-	<0.05						-
cinon orpyrifos-methyl				<0.05 <0.05	<0.05 <0.05	<0.05 <0.05								<0.05 <0.05						-
athion-methyl				<0.2	<0.2	<0.2								<0.2						-
athion thion				<0.05	<0.05	<0.05								<0.05						-
orpyrifos athion	4 16 7.5	30		<0.05 <0.2	<0.05 <0.2	<0.05 <0.2								<0.05 <0.2						-
nphos-ethyl				<0.05	<0.05	<0.05								<0.05						
orfenvinphos mophos-ethyl				<0.05 <0.05	<0.05	<0.05								<0.05						-
amiphos thiofos				<0.05 <0.05	<0.05 <0.05	<0.05 <0.05								<0.05 <0.05						
on				<0.05	<0.05	<0.05								<0.05					****	
oophenothion phos Methyl				<0.05 <0.05	<0.05 <0.05	<0.05 <0.05								<0.05 <0.05						
na-BHC				<0.05	<0.05	<0.05								<0.05						
a-BHC				<0.05	<0.05	<0.05								<0.05						
ama-BHC		1		<0.05 <0.05	<0.05 <0.05	<0.05 <0.05								<0.05 <0.05						
tachlor				<0.05	<0.05	<0.05								<0.05						
rin tachlor epoxide				<0.05	<0.05	<0.05								<0.05						
al Chlordane (sum)				<0.05 <0.05	<0.05 <0.05	<0.05 <0.05								<0.05 <0.05						
na-Endosulfan				<0.05	<0.05	<0.05								<0.05					****	
Chlordane drin				<0.05 <0.05	<0.05	<0.05								<0.05 <0.05						
-DDE rin				<0.05										<0.05						
osulfan (sum)	60 240 108	432		<0.05	<0.05	<0.05								<0.05	****			****		
a-Endosulfan -DDD				<0.05 <0.05	<0.05 <0.05	<0.05 <0.05								<0.05 <0.05						
rin aldehyde				<0.05	<0.05	<0.05								<0.05						
-DDT				<0.2	<0.2	<0.2								<0.2						
rin ketone choxychlor			-	<0.05 <0.2	<0.05 <0.2	<0.05 <0.2								<0.05 <0.2						
of DDD + DDE + DDT				<0.05	<0.05	<0.05								<0.05						
				\$0.05	KU.U5	\U.U5								~U.U5						
enic mium		+	5 20 1 4																	
omium, Total			7																	
per d			5 20				-													
kel			2 8										****							
P			0.04 0.16																	
DD D I I I I I I I I I I I I I I I I I	ichlorophenol ichlorophenol pro-3-methylphenol pro-3-methylphenol pro-1-methylphenol pro-1-methylphenol pro-1-methylphenol pro-1-methyl	te	te	Interpretation Inte	NSW PPA 2014 Waster Classification Guidelines 1.1 1	NSW IPA DEVA DEVA Master Classification Utility Devay De	No. No.	No. No.	New Part Deliver 1967 197											

	1	T									П	1	Т	ı			T									
	Ramboll En	viron Sample ID						027_GW003_1.0	028_TP001_0.10	028_TP001_0.50	028_TP001_0.70	028_TP001_0.90	028_TP002_0.20	028_TP002_0.50	028_TP002_1.00	028_TP003_0.40	028_TP003_0.60		136_TP002_0.20			138_TP002_0.20	138_GS001	139_TP001_0.10	139_GS001	140_TP001_0.20
	Site							Site 027	Site 028	Site 028	Site 028	Site 028	Site 028	Site 028	Site 028	Site 028	Site 028	Site 136 Northcote Street	Site 137 Northcote Street	Site 138 Northcote Street	Site 138 Northcote Street	Site 138 Northcote Street	Site 138 Northcote Street	Site 139 Northcote Street	Site 139 Northcote Street	Site 140 Northcote Street
	Compound							Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Sit	e Northcote Street Tunnel Site	Northcote Street Tunnel Site	e Northcote Street Tunnel Si	ite Northcote Street Tunnel Sit	te Northcote Street Tunnel Site	e Northcote Street Tunnel Sit	e Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site
	Sample Des	cription						CLAY, orange/red/grey mottled, moist, low-med plasticity, becoming stiff	FILL, gravelly, silty Clay, dark brown, black staining, pieces of plastic,	FILL, gravelly, silty Clay, dark brown, black staining, pieces of plastic,	Silty CLAY; orange, slightly moist-moist, soft, low plasticity, some ironstone gravels, NOC	Grading to weathered SHALE; light grey and red/brown, ironstone cementing, low plasticity, slightly moist, medium stiff, NOC	FILL; Gravelly dayey silt, gravel is ironstone, reworked natural (?), grey/brown, medium stiff, moist, high gravel content	Silty CLAY; orange, slighth moist-moist, soft, low plasticity, some ironstone gravels, no observed contamination	and red/brown ironstone	slightly moist, grey/brown, roots, pipe near surface, no observed contamination, minor porkets of sand	someironstone gravels, stiff low plasticity,	SILT, brown, low plasticity, contains, brick, glass, plastic,	r FILL; gravelly sandy SILT, brown, moist, soft, contains glass, plastic, timber, brick, wire, concrete, NOC	FILL; Sandy SILT, toposoil, grass, brown, moist, NOC	FILL; Silty CLAY, reworked natural, some pockets of topsoil, yellow/brown, moist, NOC	FILL; gravelly sandy Silt, brown, moist, contains roots, blue metal, pipe, minor, crushed brick and concrete	Two pieces of organic fibre board approximately 50 x 35 x 4mm	FILL; gravelly, sandy SILT, brown, very moist, ironstone, contains brick, plastic, gaffer tape, timber, metal pieces, crushed concrete	One piece of organic fibre board approximately 50 x 50 x 3mm	c FILL; clayey, sandy SILT, brown , contains plastic, irrigation pipe, quartz gravels, NOC
	Lab Report	ID						ES1610406	ES1609686	ES1609686	ES1609686	ES1609686	ES1609686	ES1609686	ES1609686	ES1609686	ES1609686	ES1610867	ES1610867	ES1610867	ES1610867	ES1610867	ES1610867	ES1610867	ES1610867	ES1610867
	Sampler PID Value (p							MT	AS 0.1	AS 0.2	AS	AS	AS	AS	AS	AS 0	AS 0	AS	AS	AS	AS	AS	AS	AS	AS	AS
	Sample date			NSW EPA (201	14) Waste Clas	sification Guidelines		12/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	19/05/2016	19/05/2016	19/05/2016	19/05/2016	19/05/2016	19/05/2016	19/05/2016	19/05/2016	19/05/2016
Achastas	Units	Analyte CT:	1	CT2 S	SCC1*	SCC2* TCLP1*	TCLP2*																			
Asbestos	none	Asbestos **						No	No	No			No			No		No	No	No	No	No	No	No	No	No
		Asbestos Type						-	-	-			-			-		-	-	-	-	-	-	-	-	-
Metals	mg/kg	Arsenic 100	0	400	500	2000		8	13	18	<5	9	6	8	8	9	6	9	11	68	10	341		11		12
	mg/kg	Cadmium 20				400		<1	1	1	<1	<1	<1	<1	<1	<1	<1	<1	<1	2	<1	<1		<1		<1
	mg/kg	Chromium Total***					1	33	25	30	33	33	14	37	19	26	29	18	25	35	20	22		39		23
	mg/kg mg/kg	Copper Iron						<5 	35	32	<5 	<5	18	<5	<5 	<5	<5	16	9	116	<5	29		30		17
	mg/kg	Lead 100			6000		17	141	158	11	17	21	14	19	20	19	151	66	2070	22	290		167		99	
	mg/kg mg/kg	Nickel 40 Zinc)	160	1050	4200		<2	4 226	9 322	<2 6	<2 <5	3 41	<2 <5	<2	<2 <5	<2 <5	3 105	<2 46	8 1390	<2 16	4 455		3 432		3 100
	mg/kg mg/kg	Mercury						<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	0.3	<0.1	0.1		0.1		<0.1
BTEX													<0.2											<0.2		
	mg/kg mg/kg			40 1152	18 518	72 2073		<0.2 <0.5	<0.2	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2	<0.2 <0.5	<0.2	<0.2	<0.2	<0.2	<0.2 <0.5		<0.2		<0.2 <0.5
	mg/kg	Ethylbenzene 60				4320		<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5		<0.5		<0.5
	mg/kg	meta- & para-Xylene	_					<0.5 <0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5		<0.5		<0.5 <0.5
	mg/kg mg/kg	Total Xylenes	00 4	4000	1800	7200		<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5		<0.5 <0.5
	mg/kg	Sum of BTEX						<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2		<0.2		<0.2
TOU (NED	mg/kg	Naphthalene						<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1		<1		<1
IPH (NEP	M 1999) mg/kg	C6 - C9 Fraction 659	0 2	2600	650	2600		<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10		<10		<10
	mg/kg	C10 - C14 Fraction						<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50		<50		<50
	mg/kg mg/kg	C15 - C28 Fraction						<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100	<100	<100 <100	<100 <100	120 <100		<100 <100		<100
	mg/kg		00 4	40000 1	10000	40000		<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	120		<50		<50
TRH (NEP	M Amendmer	nt 2013) C6 - C10 Fraction						<10		-10	***	40	<10	40	-40	40	40	-40	-10	.40	40	-10		<10		<10
	mg/kg mg/kg	C6 - C10 Fraction C6 - C10 Fraction minus BTEX (F1)						<10	<10 <10	<10 <10	<10 <10	<10 <10	<10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10	<10 <10		<10		<10
	mg/kg	>C10 - C16 Fraction						<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50		<50		<50
	mg/kg mg/kg	>C16 - C34 Fraction >C34 - C40 Fraction						<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	170 <100		<100 <100		<100 <100
	mg/kg	>C10 - C40 Fraction (sum)						<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	170		<50		<50
	mg/kg	>C10 - C16 Fraction minus Naphthalene (F2)						<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50	<50		<50		<50
PAHS	mg/kg	Naphthalene						<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5		<0.5		<0.5
	mg/kg	Acenaphthylene						<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	0.6		<0.5		<0.5
-	mg/kg mg/kg	Acenaphthene Fluorene					1	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5		<0.5 <0.5
	mg/kg	Phenanthrene						<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	0.8	<0.5	2.8		<0.5		<0.5
<u> </u>	mg/kg	Anthracene						<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5	<0.5 <0.5	<0.5 <0.5	<0.5	<0.5 <0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	0.8		<0.5		<0.5
-	mg/kg mg/kg	Fluoranthene Pyrene					1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	0.6	<0.5	1.3	<0.5	6		0.6	-	0.8
	mg/kg	Benz(a)anthracene						<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	0.7	<0.5	3.1		<0.5		<0.5
-	mg/kg mg/kg	Chrysene Benzo(b+j)fluoranthene		-				<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5	<0.5 <0.5	0.6	<0.5 <0.5	3.8		<0.5 0.6		<0.5
	mg/kg	Benzo(k)fluoranthene						<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	1.4		<0.5		<0.5
	mg/kg		В	3.2	10	23		<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	0.7	<0.5	3.2		<0.5		<0.5
	mg/kg mg/kg	Indeno(1.2.3.cd)pyrene Dibenz(a.h)anthracene						<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	1.5 <0.5		<0.5 <0.5		<0.5 <0.5
	mg/kg	Benzo(g.h.i)perylene						<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	1.9		<0.5		<0.5
-	mg/kg		0	800	200	800		<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	1.9	<0.5 <0.5	6.1 0.8	<0.5 <0.5	33.9 4.2		1.8		2.2 <0.5
	mg/kg mg/kg	Benzo(a)pyrene TEQ (zero) Benzo(a)pyrene TEQ (half LOR)					1	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	1.2	0.6	4.5		0.6		0.6
	mg/kg	Benzo(a)pyrene TEQ (LOR)						1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.5	1.2	4.7		1.2		1.2
Phenols	mg/kg	Phenol 28	8 1	1152	518	2073		<0.5		<0.5			<0.5			<0.5		<0.5	<0.5	<0.5	<0.5	<0.5		<0.5		<0.5
	mg/kg mg/kg	2-Chlorophenol		1132	310	2073		<0.5		<0.5			<0.5			<0.5		<0.5	<0.5	<0.5	<0.5	<0.5		<0.5		<0.5
	mg/kg	2-Methylphenol 400	00 1	16000	7200	28800		<0.5		<0.5			<0.5			<0.5		<0.5	<0.5	<0.5	<0.5	<0.5		<0.5		<0.5
-	mg/kg mg/kg	3- & 4-Methylphenol 2-Nitrophenol		-				<1 <0.5		<1 <0.5			<1			<1		<0.5	<1 <0.5	<1 <0.5	<0.5	<1 <0.5		<1 <0.5		<1 <0.5
	mg/kg	2.4-Dimethylphenol						<0.5	****	<0.5			<0.5			<0.5		<0.5	<0.5	<0.5	<0.5	<0.5		<0.5		<0.5


iample ID			027_GW003_1.0	028_TP001_0.10	028_TP001_0.50	028_TP001_0.70	028_TP001_0.90	028_TP002_0.20	028_TP002_0.50	028_TP002_1.00	028_TP003_0.40	028_TP003_0.60	136_TP001_0.10	136_TP002_0.20	138_TP001_0.10	138_TP001_0.30	138_TP002_0.20	138_GS001	139_TP001_0.10	139_GS001	140_TP001
			Site 027	Site 028	Site 028	Site 028	Site 028	Site 028	Site 028	Site 028	Site 028	Site 028	Site 136 Northcote Street	Site 137 Northcote Street	Site 138 Northcote Street	Site 138 Northcote Street	Site 138 Northcote Street	Site 138 Northcote Street	Site 139 Northcote Street	Site 139 Northcote Street	Site 14
in			CLAY, orange/red/grey mottled, moist, low-med	FILL, gravelly, silty Clay, darl brown, black staining,		Silty CLAY; orange, slightly moist-moist, soft, low plasticity, some ironstone gravels, NOC	Northcote Street Tunnel Site Grading to weathered SHALE; light grey and red/brown, ironstone cementing, low plasticity, slightly moist, medium stiff, NOC	FILL; Gravelly clayey silt, gravel is ironstone, reworked natural (?), grey/brown, medium stiff, moist, high gravel content	Silty CLAY; orange, slightly moist-moist, soft, low	and red/brown ironstone	FILL; Gravelly clayey silt, gravel is ironstone, stiff, dry- slightly moist, grey/brown, roots, pipe near surface, no observed contamination, minor pockets of sand	- Silty CLAY; orange, dry- slightly moist,	FILL; gravelly, sandy SILT, brown, low plasticity, contains, brick, glass, plastic,	FILL; gravelly sandy SILT, brown, moist, soft, contains glass, plastic, timber, brick,	FILL; Sandy SILT, toposoil, grass, brown, moist, NOC	FILL; Silty CLAY, reworked natural, some pockets of topsoil,	FILL; gravelly sandy Silt, brown, moist, contains roots, blue metal, pipe, minor	Tunnel Site Two pieces of organic fibre board	FILL; gravelly, sandy SILT, brown, very moist, ironstone, contains brick, plastic, gaffer tape, timber, metal pieces,	Tunnel Site One piece of organic fibre board approximately 50 x 3mm	Tunnel FILL; claye SILT, br
			ES1610406	ES1609686	ES1609686	ES1609686	ES1609686	ES1609686	ES1609686	E51609686	ES1609686	ES1609686	ES1610867	ES1610867	ES1610867	ES1610867	ES1610867	ES1610867	ES1610867	ES1610867	ES1610
			MT	AS 0.1	AS 0.2	AS 0	AS 0	AS 0	AS 0	AS 0	AS 0	AS 0	AS	AS	AS	AS	AS	AS	AS	AS 	AS
ashte CT1	NSW EPA (2014) Waste Classification Guidelines	TCI D2*	12/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	05/05/2016	19/05/2016	19/05/2016	19/05/2016	19/05/2016	19/05/2016	19/05/2016	19/05/2016	19/05/2016	19/05/
4-Dichlorophenol	C12 SCC1 SCC2 TCLF1	ICLPZ	<0.5		<0.5		****	<0.5	****		<0.5		<0.5	<0.5	<0.5	<0.5	<0.5		<0.5		<
6-Dichlorophenol Chloro-3-methylphenol			<0.5 <0.5		<0.5 <0.5			<0.5 <0.5			<0.5 <0.5		<0.5 <0.5	<0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5		<
4.6-Trichlorophenol 40 4.5-Trichlorophenol 8000	160 72 288 32000 14400 57600		<0.5		<0.5 <0.5			<0.5 <0.5			<0.5		<0.5	<0.5	<0.5	<0.5	<0.5		<0.5		
entachlorophenol	32000 37000		<2		<2			<2			<2		<2	<2	<2	<2	<2		<2		
EBs (Total) 50	50 50 50				<0.1			<0.1			<0.1		<0.1	<0.1	<0.1	<0.1	<0.1		<0.1	-	
chloryos					<0.05			<0.05			<0.05		<0.05	<0.05	<0.05	<0.05	<0.05		<0.05		
emeton-S-methyl					<0.05			<0.05			<0.05		<0.05	<0.05	<0.05	<0.05	<0.05		<0.05		<1
onocrotopnos methoate					<0.05			<0.05	****		<0.05		< 0.05	<0.05	<0.05	< 0.05	<0.05		< 0.05	1 1	<
azinon olorpyrifos-methyl					<0.05 <0.05			<0.05 <0.05			<0.05 <0.05		<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		
rathion-methyl					<0.2			<0.2			<0.2		<0.2	<0.2	<0.2	<0.2	<0.2		<0.2		
alathion enthion					<0.05			<0.05			<0.05		<0.05 <0.05	<0.05	<0.05 <0.05	< 0.05	<0.05		<0.05		
alorpyrifos 4	16 7.5 30				<0.05			<0.05			<0.05		<0.05	<0.05	<0.05	<0.05	<0.05		<0.05	-	
rimphos-ethyl					<0.05			<0.05			<0.05		<0.05	<0.05	<0.05	< 0.05	<0.05		<0.05		
omophos-ethyl					<0.05 <0.05			<0.05 <0.05			<0.05 <0.05		<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		
enamiphos					<0.05		****	<0.05		****	<0.05		<0.05	<0.05	<0.05	<0.05	<0.05		<0.05		
hion					<0.05			<0.05			<0.05		<0.05	<0.05	<0.05	<0.05	<0.05		<0.05	-	
					<0.05 <0.05			<0.05 <0.05		****	<0.05 <0.05		<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		
pha-BHC					<0.05			<0.05			<0.05		<0.05	<0.05	<0.05	<0.05	<0.05		<0.05	-	
eta-BHC					<0.05			<0.05			<0.05		<0.05	<0.05	<0.05	<0.05	<0.05		<0.05		<
mma-BHC													<0.05 <0.05		<0.05 <0.05	<0.05 <0.05					<1
eptachlor					<0.05			<0.05			<0.05		<0.05	<0.05	<0.05	<0.05	<0.05		<0.05		<(
eptachlor epoxide					<0.05			<0.05			<0.05		<0.05	<0.05	<0.05	<0.05	<0.05		<0.05	1	<
otal Chlordane (sum)							****			****											<(
pha-Endosulfan					<0.05			<0.05			<0.05		<0.05	<0.05	<0.05	<0.05	<0.05		<0.05		
eldrin					<0.05			<0.05			<0.05		< 0.05	<0.05	<0.05	< 0.05	< 0.05		<0.05	1	<
4`-DDE							****	<0.05 <0.05		****	<0.05 <0.05		<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<
ndosulfan (sum) 60	240 108 432				<0.05			<0.05			<0.05		< 0.05	<0.05	<0.05	< 0.05	<0.05		<0.05		<
eta-Endosultan 4'-DDD					0.06			<0.05			<0.05		<0.05	<0.05	<0.05	<0.05	<0.05		<0.05	-	<
ndrin aldehyde					<0.05 <0.05			<0.05 <0.05			<0.05 <0.05		<0.05	<0.05	<0.05	<0.05	<0.05		<0.05 <0.05		
4`-DDT					<0.2			<0.2			<0.2		<0.2	<0.2	<0.2	<0.2	<0.2		<0.2	-	
drin ketone ethoxychlor					<0.05 <0.2			<0.05 <0.2			<0.05 <0.2		<0.05 <0.2	<0.05 <0.2	<0.05 <0.2	<0.05 <0.2	<0.05		<0.05 <0.2		
im of DDD + DDE + DDT					0.06			<0.05			<0.05		<0.05	<0.05	<0.05	<0.05	<0.05		<0.05		<
rsenic admium	5	20 4		<0.1 <0.05	<0.1 <0.05																-
nromium, Total				<0.1	<0.1																
ad	5	20		<0.1	0.2								0.1	<0.1	1.6	<0.1	0.2		<0.1		
	2	8		<0.1 1	<0.1 3.2																
ckel nc																					
446 C 44 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	alyte CTI Dichlorophenol B000 5-Trichlorophenol B000 stachlorophenol B000 stachlorop	NSW EPA (2014) Waste Classification Guidelines	NSW EPA (2014) Waste Classification Guidelines			Pasticity, becoming stiff pieces of pieces, pieces		CAN CONTROLLED CAN	Control Cont	Control Cont	Control Cont	Control Cont		Part		Part	Part			Part	Part

	1									I	1	1	1				1	
	Ramboll Env	riron Sample ID							140_TP002_0.10	141_TP001_0.10	137_TP001_0.10	137_TP001_0.30	137_TP002_0.10	137_TP002_0.40	137_TP002_0.60	137_TP003_0.20	137_TP003_0.90	137_TP003_1.10
	Site								Site 140	Site 141	Site 137	Site 137	Site 137	Site 137	Site 137	Site 137	Site 137	Site 137
	Compound								Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Sit	e Northcote Street Tunnel Sit	e Northcote Street Tunnel Sit	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Sit	e Northcote Street Tunnel Site	Northcote Street Tunnel Sit
	Sample Desc	zription							FILL; sandy Silt, brown, slightly moist, soft, contains roots, minor brick near surface NOC	FILL, sandy silt, minoi ironstone gravels, brown, moist, contains roots, minoi brick and concrete on surface, NOC	FILL; Sandy silt, imported topsoil, dry-slightly moist, brown, roots, no anthropogenic material other than one water pipe, no observed contamination soft, grass on surface	FILL; Sandy silt, imported topsoil, dry-slightly moist, brown, roots, no anthropogenic material other than one water pipe i, no observed contamination soft, grass on surface	on surface, moist-slightly moist, evidence of some building/ demolition rubble throughout fill soil profile	moist, evidence of some building/ demolition rubble throughout fill soil profile (broken pipe, concrete,	Gravelly sandy SILT; dark brown, moist-slightly moist, no observed contamination	FILL; Sandy silt, imported topsoil, dark brown, very moist, roots, high plasticity, minor gravels (ironstone, sandstone <5mm),	Gravelly silty CLAY; highly weathered sandstone, orange, red ironstone cementing, moist, high plasticity, no observed contamination	Gravelly silty CLAY; highly weathered sandstone, orange, red ironstone cementing, moist, high plasticity, no observed contamination
	Lab Report I	D							ES1610867 AS	ES1610867 AS	ES1609681 AS	ES1609681 AS	ES1609681 AS	ES1609681 AS	ES1609681 AS	ES1609681	ES1609681 AS	ES1609681 AS
	Sampler PID Value (p	pm)							AS	AS	AS 0	AS 0	AS 0	AS 0	AS 0	AS 0	AS 0	AS 0
	Sample date			NSW EP	A (2014) Waste	Classification			19/05/2016	19/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016
	Units	Analyte	CT1	CT2	SCC1*	SCC2*	TCLP1*	TCLP2*										
Aspestos	none	Asbestos **							No	No	No	No	No	Yes + Trace		No	No	
		Asbestos Type							-	-	-	-	-	Ch + Am + Cr		-	-	****
Metals																		
	mg/kg	Arsenic Cadmium	100 20	400 80	500 100	2000 400			8 <1	17 <1	7 <1	6 <1	<5 1	12	8 <1	14 2	10	6 <1
-	mg/kg mg/kg	Chromium Total***	20	00	100	400			20	49	22	12	16	40	17	39	25	29
	mg/kg	Copper							60	23	26	10	57	185	30	281	49	<5
	mg/kg	Iron	100	400	1500	6000			151	144	168	76	343	1000	 82	482	241	
	mg/kg mg/kg	Lead Nickel	100 40	160	1500	6000 4200			151 7	3	168 3	76	343 7	1000 14	82 <2	482 7	4	15 2
	mg/kg	Zinc			1000	7200			341	155	86	21	346	1950	293	540	222	42
	mg/kg	Mercury							<0.1	<0.1	<0.1	<0.1	<0.1	0.1	<0.1	0.1	0.1	<0.1
BTEX	mg/kg	Benzene	10	40	18	72			<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
	mg/kg	Toluene	288	1152	518	2073			<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	Ethylbenzene	600	2400	1080	4320			<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	meta- & para-Xylene							<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg mg/kg	ortho-Xylene Total Xylenes	1000	4000	1800	7200			<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
	mg/kg	Sum of BTEX							<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
	mg/kg	Naphthalene							<1	<1	<1	<1	<1	<1	<1	<1	<1	<1
TPH (NEP		C6 - C9 Fraction	650	2600	650	2600			<10	<10	<10	<10	<10	<10	<10	<10	<10	<10
	mg/kg mg/kg	C10 - C14 Fraction	650	2600	650	2600			<50	<50	<10	<50	<50	<50	<50	<50	<50	<10
	mg/kg	C15 - C28 Fraction							<100	<100	<100	<100	<100	<100	<100	<100	<100	<100
	mg/kg	C29 - C36 Fraction							<100	<100	<100	<100	<100	<100	<100	<100	<100	<100
TRH (NED	mg/kg M Amendmen	C10 - C36 Fraction (sum)	10000	40000	10000	40000			<50	<50	<50	<50	<50	<50	<50	<50	<50	<50
1111 (1421	mg/kg	C6 - C10 Fraction							<10	<10	<10	<10	<10	<10	<10	<10	<10	<10
	mg/kg	C6 - C10 Fraction minus BTEX (F1)							<10	<10	<10	<10	<10	<10	<10	<10	<10	<10
	mg/kg mg/kg	>C10 - C16 Fraction >C16 - C34 Fraction							<50 <100	<50 <100	<50 <100	<50 <100	<50 <100	<50 <100	<50 <100	<50 <100	<50 <100	<50 <100
	mg/kg	>C34 - C40 Fraction							<100	<100	<100	<100	<100	<100	<100	<100	<100	<100
	mg/kg	>C10 - C40 Fraction (sum)							<50	<50	<50	<50	<50	<50	<50	<50	<50	<50
PAHs	mg/kg	>C10 - C16 Fraction minus Naphthalene (F2)							<50	<50	<50	<50	<50	<50	<50	<50	<50	<50
PARIS	mg/kg	Naphthalene							<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	Acenaphthylene							<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	Acenaphthene		1			1		<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
	mg/kg mg/kg	Fluorene Phenanthrene		1	+				<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5	<0.5	<0.5 <0.5	<0.5 <0.5	<0.5	<0.5	<0.5 <0.5
	mg/kg	Anthracene							<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	Fluoranthene							<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	0.9	<0.5	<0.5
-	mg/kg mg/kg	Pyrene Benz(a)anthracene		+	+	1			<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	0.8	<0.5 <0.5	<0.5 <0.5
	mg/kg	Chrysene							<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	Benzo(b+j)fluoranthene							<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	0.6	<0.5	<0.5
-	mg/kg mg/kg	Benzo(k)fluoranthene Benzo(a)pyrene	0.8	3.2	10	23			<0.5 <0.5	<0.5	<0.5 <0.5	<0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 0.5	<0.5 <0.5	<0.5
	mg/kg	Indeno(1.2.3.cd)pyrene	0.0	3.2	10	2.5			<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	mg/kg	Dibenz(a.h)anthracene							<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
-	mg/kg	Benzo(g.h.i)perylene	200	000	200	800			<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5 <0.5	<0.5
	mg/kg mg/kg	Sum of polycyclic aromatic hydrocarbons Benzo(a)pyrene TEQ (zero)	200	800	200	800			<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	2.8 0.6	<0.5	<0.5 <0.5
	mg/kg	Benzo(a)pyrene TEQ (half LOR)							0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.9	0.6	0.6
	mg/kg	Benzo(a)pyrene TEQ (LOR)							1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2
Phenols	mg/kg	Phenol	288	1152	518	2073			<0.5	<0.5			<0.5	<0.5				
	mg/kg	2-Chlorophenol	-00	1132	310	20/3			<0.5	<0.5			<0.5	<0.5				
	mg/kg	2-Methylphenol	4000	16000	7200	28800			<0.5	<0.5			<0.5	<0.5				
-	mg/kg	3- & 4-Methylphenol 2-Nitrophenol		1	-	1	1		<0.5	<1 <0.5			<1 <0.5	<1 <0.5				
	mg/kg mg/kg	2.4-Dimethylphenol		1					<0.5	<0.5			<0.5	<0.5				



TABLE 1 Summary of Waste Classification Soil Sampling Results - Northcote Street Compound CSJ M4E WestConnex

Analyte 2.4-Dichlorophenol 2.6-Dichlorophenol 4.ChOro-3-methylphenol	CT1						Site 140 Northcote Street Tunnel Site FILL; sandy Silt, brown, slightly moist, soft, contains roots, minor brick near surface NOC	Site 141 Northcote Street Tunnel Site FILL, sandy silt, mino ironstone gravels, brown, moist, contains roots, mino brick and concrete	FILL; Sandy silt, imported topsoil, dry-slightly moist, brown, roots, no anthropogenic material	Site 137 Northcote Street Tunnel Site FILL; Sandy silt, imported topsoil, dry-slightly moist, brown, roots, no anthropogenic material	FILL; imported topsoil, grass	FILL; imported topsoil, grass on surface, moist-slightly moist, evidence of some	Gravelly sandy SILT; dark	Site 137 Northcote Street Tunnel Site FILL; Sandy silt, imported topsoil, dark brown, very moist, roots, high	Gravelly silty CLAY; highly weathered sandstone,	Gravelly silty CLA weathered san
Analyte 2.4-Dichlorophenol 2.5-Dichlorophenol 4-Chloro-3-methylphenol	CT1						FILL; sandy Silt, brown, slightly moist, soft, contains roots, minor brick	FILL, sandy silt, mino ironstone gravels, brown, moist, contains roots, mino	FILL; Sandy silt, imported topsoil, dry-slightly moist, brown, roots, no anthropogenic material	FILL; Sandy silt, imported topsoil, dry-slightly moist, brown, roots, no	FILL; imported topsoil, grass on surface, moist-slightly moist, evidence of some	FILL; imported topsoil, grass on surface, moist-slightly moist, evidence of some	Gravelly sandy SILT; dark	FILL; Sandy silt, imported topsoil, dark brown, very	Gravelly silty CLAY; highly weathered sandstone,	Gravelly silty CLA weathered san
Analyte 2.4-Dichlorophenol 2.5-Dichlorophenol 4-Chloro-3-methylphenol	ст1	NO.					FILL; sandy Silt, brown, slightly moist, soft, contains roots, minor brick	FILL, sandy silt, mino ironstone gravels, brown, moist, contains roots, mino	topsoil, dry-slightly moist, brown, roots, no anthropogenic material	topsoil, dry-slightly moist, brown, roots, no	on surface, moist-slightly moist, evidence of some	on surface, moist-slightly moist, evidence of some		topsoil, dark brown, very	weathered sandstone,	weathered sa
Analyte 2.4-Dichlorophenol 2.5-Dichlorophenol 4-Chloro-3-methylphenol	ст1	NOW TO					brown, slightly moist, soft, contains roots, minor brick	ironstone gravels, brown, moist, contains roots, mino	topsoil, dry-slightly moist, brown, roots, no anthropogenic material	topsoil, dry-slightly moist, brown, roots, no	on surface, moist-slightly moist, evidence of some	on surface, moist-slightly moist, evidence of some		topsoil, dark brown, very	weathered sandstone,	weathered sa
Analyte 2.4-Dichlorophenol 2.5-Dichlorophenol 4-Chloro-3-methylphenol	CT1	NOW FO					brown, slightly moist, soft, contains roots, minor brick	ironstone gravels, brown, moist, contains roots, mino	brown, roots, no anthropogenic material	brown, roots, no	moist, evidence of some	moist, evidence of some		topsoil, dark brown, very	weathered sandstone,	weathered sa
Analyte 2.4-Dichlorophenol 2.5-Dichlorophenol 4-Chloro-3-methylphenol	CT1	NCW 50					moist, soft, contains roots, minor brick	brown, moist, contains roots, mino	anthropogenic material		building/ demolition rubble	building/domolition rubble				
Analyte 2.4-Dichlorophenol 2.5-Dichlorophenol 4-Chloro-3-methylphenol	СТ1	NGWED					roots, minor brick								orange, red ironstone	orange, red ire
Analyte 2.4-Dichlorophenol 2.6-Dichlorophenol 4-Chloro-3-methylphenol	CT1	NCMED					near surface NOC		other than one water pipe,	other than one water pipe,	throughout fill soil profile		no observed	plasticity, minor gravels	cementing, moist, high plasticity, no observed	cementing, m plasticity, no
Analyte 2.4-Dichlorophenol 2.6-Dichlorophenol 4-Chloro-3-methylphenol	CT1	NCWED						on surface, NOC	no observed contamination,	no observed contamination,	(broken pipe, concrete, plastic, broken tiling, metal	(broken pipe, concrete, plastic, broken tiling, metal	contamination	(ironstone, sandstone <5mm),	contamination	contamin
Analyte 2.4-Dichlorophenol 2.6-Dichlorophenol 4-Chloro-3-methylphenol	CT1	NCWED						on surface, rece	soft, grass on surface	soft, grass on surface	pipe), no ACM observed	pipe), no ACM observed		3,,,,	contamination	Contamina
Analyte 2.4-Dichlorophenol 2.6-Dichlorophenol 4-Chloro-3-methylphenol	CT1	NCW FD														
Analyte 2.4-Dichlorophenol 2.6-Dichlorophenol 4-Chloro-3-methylphenol	CT1	NOWED					ES1610867	ES1610867	ES1609681	ES1609681	ES1609681	ES1609681	ES1609681	ES1609681	ES1609681	ES1609
Analyte 2.4-Dichlorophenol 2.6-Dichlorophenol 4-Chloro-3-methylphenol	CT1	NCW FD					AS	AS	AS 0	AS 0	AS 0	AS 0	AS 0	AS 0	AS 0	AS 0
2.4-Dichlorophenol 2.6-Dichlorophenol 4-Chloro-3-methylphenol	CT1		A (2014) Waste	Classification	Guidelines		19/05/2016	19/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2016	04/05/2
2.4-Dichlorophenol 2.6-Dichlorophenol 4-Chloro-3-methylphenol		CT2	SCC1*	SCC2*	TCLP1*	TCLP2*	13/03/2010	13/03/2010	04/03/2010	04/03/2010	04/03/2010	04/03/2010	04/03/2010	04/03/2010	04/03/2010	04/03/
4-Chloro-3-methylphenol							<0.5	<0.5			<0.5	<0.5				
							<0.5	<0.5			<0.5	<0.5				
							<0.5	<0.5			<0.5	<0.5	****			
2.4.6-Trichlorophenol 2.4.5-Trichlorophenol	40 8000	160 32000	72 14400	288 57600			<0.5 <0.5	<0.5 <0.5			<0.5 <0.5	<0.5 <0.5				
Pentachlorophenol	8000	32000	14400	37600			<2	<2			<2	<2			****	-
- Circumorophicinoi							-	-				\ <u>-</u>				
PCBs (Total)	50	50	50	50			<0.1	<0.1			<0.1	<0.1				
													_		_	
Dichlorvos							<0.05	<0.05			<0.05	<0.05	****		****	
	-	1	-	-												
Monocrotophos Dimethoate	+	 	+			1										
Diazinon	+	1	+			+							***		****	
Chlorpyrifos-methyl							<0.05	<0.05			<0.05	<0.05				
Parathion-methyl							<0.2	<0.2			<0.2	<0.2				
Malathion							<0.05	<0.05			<0.05	<0.05	****			
Fenthion													****		****	-
	4	16	7.5	30		1										-
Parathion Pirimphos-ethyl	1	1	+			+										-
Chlorfenvinphos						1							****		****	-
Bromophos-ethyl							<0.05	<0.05			<0.05	<0.05				-
Fenamiphos							<0.05	< 0.05			<0.05	<0.05				-
Prothiofos							<0.05									-
Ethion																-
																-
																-
Hexachlorobenzene (HCB)								<0.05								
beta-BHC							<0.05	<0.05			<0.05	<0.05				-
gamma-BHC							<0.05	< 0.05			<0.05	<0.05	****		****	-
delta-BHC							<0.05	<0.05			<0.05	<0.05	****		****	-
Heptachlor		1					<0.05	<0.05			<0.05	<0.05	****		****	-
Aldrin		1				1								-		-
	1	1	+			+	<0.05				<0.05 <0.05			****		-
trans-Chlordane		1					<0.05	<0.05			<0.05	0.07				-
alpha-Endosulfan							<0.05	< 0.05			<0.05	<0.05				-
cis-Chlordane							<0.05	<0.05			<0.05	<0.05				
Dieldrin		1	1				<0.05	<0.05			0.14	0.15	****		****	-
4.4`-DDE	1	-	+			1										-
Endrin Endosulfan (sum)	60	240	108	437		+									****	-
beta-Endosulfan	- 00	240	100	734									****			
4.4`-DDD		1					<0.05	<0.05			0.09	0.12				-
Endrin aldehyde							<0.05	< 0.05			<0.05	<0.05	****			-
Endosulfan sulfate							<0.05	<0.05			<0.05	<0.05	****		****	-
4.4`-DDT													****		****	-
Endrin ketone Methovychlor	-	1	-	-												-
	+	 	+			1										-
Sum of Aldrin + Dieldrin						1	<0.05	<0.05			0.14	0.15			****	-
Arsenic					5	20		-								-
Cadmium					1	4							****		****	
·	-	1	-	-												-
Copper Lead					5	20	<0.1	<0.1					****		****	
Nickel					2	8										-
Zinc																-
B(a)P					0.04	0.16		-								
De Modern De Mod	meton-S-methyl monorcrotophos methoate zzinon motorotophos methoate zathion imphos-methyl indifficulty motorotophos motophos motophos motophos sthyl motophos zthiofos inion rbophenothion iniphos Methyl ha-BHC azchiorobenzene (HCB) ta-BHC mma-BHC ta-BHC ta-BHC ta-BHC ptachlor ptachlor epoxide ala Chiordane (sum) ms-Chiordane ha-Endosuffan -Chiordane sidrin -Choo dosuffan (sum) ms-Chiordane dosuffan (sum) ms-Chiordane dosuffan (sum) dosuffan suffate -DDD drin dadefhode dosuffan suffate -DDD drin adehyde dosuffan suffate -DDT drin ketone ethoxychlor m of DDD + DDE + DDT m of Aldrin + Dieldrin senic dminum comium romium, Total pper dd dd de kel kel	meton-S-methyl monorcrotophos methoate zizhon morcrotophos methoate zizhon morcrotophos methoate zizhon morprifis-methyl arathion-methyl alashion withion morprifis 4 a rathion imphos-ethyl morfenvinphos morphos-ethyl manniphos ethyl morfenvinphos morphos-ethyl manniphos withiofos morphos-ethyl manniphos withiofos morphos-ethyl manniphos methophonothion minphos Methyl ma-BHC morprifis morphos-methol morphos-methyl manniphos methyl ma-BHC man-BHC man-BHC man-BHC man-BHC man-BHC manniphos morphos-methyl morphos-methyl manniphos methyl manniphos methyl manniphos m	meton-S-methyl oncorcotophos methoate zizhon orpyrifos-methyl zizhon orpyrifos-methyl zathion-methyl lalathion should be zizhon orpyrifos orpyrifos de 4 16 rathion imphos-ethyl orfenvinphos orpyrifos or 4 16 rathion imphos-ethyl orfenvinphos orpyrifos organization orpyrifos organization orpyrifos organization organi	metons-methyl moncrotophos methoate zainon orcrotophos methoate zainon orcrotophos methoate zainon orgyrifos-methyl atahion-methyl lalathion or allathion orgyrifos de de la 16 7.5 rathion imphos-ethyl lorfenvinphos delivir maniphos delivir maniphos sthiofos orgyrifos delivir maniphos sthiofos orgyrifos delivir maniphos delivir	methos-s-methyl moncrotophos methoate zinon or contephos methoate zinon or compression zinon zinon or compression zinon	methos-methyl methoate	metons-methyl methodate string methodate methodate string methodate methodate string methodate methodate string methodate metho		methor-smethyl	meton-smethyl	metenostrey	meteos-methyl	meteos dendary	meters functionally and the second plane of th	membe sharing	membershely



Client: CSJ

Project No: AS121919

Date: 20 September 2016



Sample ID	Sample Depth (m bgl)	Sampling Date	QC Sample	PID (ppm)	Soil Description
006_GS200	0.5	9/15/2016	-	0.0	Sandtone, very light grey, medium to coarse grained, uniform, dense, moist, no observed contamination (staining, odour or ACM), no anthropogenic inclusions observed
006_GS201	1.0	9/15/2016	-	0.0	Sandtone, very light grey, medium to coarse grained, uniform, dense, moist, no observed contamination (staining, odour or ACM), no anthropogenic inclusions observed
006_GS202	2.0	9/15/2016	-	0.0	Sandtone, very light grey, medium to coarse grained, uniform, dense, moist, no observed contamination (staining, odour or ACM), no anthropogenic inclusions observed
006_GS203	2.0	9/15/2016	-	0.0	Sandtone, very light grey, medium to coarse grained, uniform, dense, moist, no observed contamination (staining, odour or ACM), no anthropogenic inclusions observed
006_GS204	1.0	9/15/2016	٠	0.0	Sandtone, very light grey, medium to coarse grained, uniform, dense, moist, no observed contamination (staining, odour or ACM), no anthropogenic inclusions observed
006_GS205	1.0	9/15/2016	-	0.0	Sandtone, very light grey, medium to coarse grained, uniform, dense, moist, no observed contamination (staining, odour or ACM), no anthropogenic inclusions observed
006_GS206	2.0	9/15/2016	-	0.0	Sandtone, very light grey, medium to coarse grained, uniform, dense, moist, no observed contamination (staining, odour or ACM), no anthropogenic inclusions observed
006_GS207	2.0	9/15/2016	-	0.0	Sandtone, very light grey, medium to coarse grained, uniform, dense, moist, no observed contamination (staining, odour or ACM), no anthropogenic inclusions observed
006_GS208	1.0	9/15/2016	-	0.0	Sandtone, very light grey, medium to coarse grained, uniform, dense, moist, no observed contamination (staining, odour or ACM), no anthropogenic inclusions observed, minor dark grey siltstone cobbles
006_GS209	0.5	9/15/2016	006_QC200	0.0	Sandtone, very light grey, medium to coarse grained, uniform, dense, moist, no observed contamination (staining, odour or ACM), no anthropogenic inclusions observed, minor dark grey siltstone cobbles

m bgl = metres below ground level ppm = parts per million PID = photo ionisation detector QC - quality control ACM = asbestos containing materials



				Sample 1		REG]											
				ALS Sam Sample of	late:	ES1620678001 15/09/2016	ES1620678002 15/09/2016	ES1620678003 15/09/2016	ES1620678004 15/09/2016	ES1620678005 15/09/2016	ES1620678006 15/09/2016	ES1620678007 15/09/2016	ES1620678008 15/09/2016	ES1620678009 15/09/2016	ES1620678010 15/09/2016	ES1620678011 15/09/2016		
				Sample I Project N		006_GS200 WCX M4E	006_GS200 WCX M4E	006_GS201 WCX M4E	006_GS202 WCX M4E	006_GS203 WCX M4E	006_GS204 WCX M4E	006_GS205 WCX M4E	006_GS206 WCX M4E	006_GS207 WCX M4E	006_GS208 WCX M4E	006_GS209 WCX M4E		
				Compour Site:		Northcote 006												
	l vene		Fana attt	Sampling	Metho		Grab											
	VENM Classification ¹	ENM Max Average ^{2,3}	ENM Absolute Maximum ^{2,4}	Sample [Descrip	tion Sandstone	Sandstone	Sandstone	Sandstone	Sandstone	Sandstone	Sandstone	Sandstone	Sandstone	Sandstone	Duplicate of 006_GS209	Average	Maximum
Chemicals and other attributes				Units	LOR													
EA002 : pH (Soils)	_											_						
pH Value	+	5 to 9	4.5 to 10	pH Units	0.1	6.6	6.5	8.6	8.5	6.7	6.5	9.2	8.1	9.3	7.4	7.8	7.7	9.3
EA010: Conductivity Electrical Conductivity @ 25°C		1.5	3	dS/m	1	0.054	0.059	0.118	0.098	0.05	0.053	0.124	0.084	0.143	0.081	0.08	0.09	0.14
EA055: Moisture Content						3.93												
Moisture Content (dried @ 103°C)				%	1	5.3	5.6	6.7	6.3	7.0	5.6	6.8	5.8	6.3	6.8	5.9	6.2	7
EA200: AS 4964 - 2004 Identifica	ation of Asbestos	in Soils																
Asbestos Detected Asbestos Type				g/kg 	0.1	No -												
Sample weight (dry)				g	0.01	51.0 Nisansala	48.0 Nisansala	50.0 Nisansala	54.0 Nisansala	49.0 Nisansala	48.0 Nisansala	67.0 Nisansala	34.0 Nisansala	51.0 Nisansala	48.0 Nisansala		50.0	67
Description APPROVED IDENTIFIER:					-	Maddage.												
EG005T: Total Metals by ICP-AES																		
Arsenic	1-50	20	40	mg/kg	5	<5	<5	<5	<5	<5	<5	<5	<5	<5	<5	<5	<5	<5
Cadmium Chromium (VI)	5-1000	0.5 75	1 150	mg/kg mg/kg	2	<1 8	<1 12	<1 8	<1 8	<1 8	<1 12							
Copper Lead	2-200 2-200	100 50	200 100	mg/kg mg/kg	5	<5 13	<5 12	<5 12	<5 11	<5 13	<5 12	<5 13	<5 14	<5 14	<5 12	22 12	<5 13	<5 14
Nickel Zinc	5-500 10-300	30 150	60 300	mg/kg mg/kg	2	5 25	5 22	5 27	5 27	5 22	5 23	5 25	5 25	5 27	5 22	7 34	5 25	5 27
EG035T: Total Recoverable Merc	•			,g, kg				1	<u> </u>				1 2	<u> </u>				
Mercury	0.03 ⁵	0.5	1	mg/kg	0.1	< 0.1	< 0.1	< 0.1	<0.1	< 0.1	<0.1	< 0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1
EP066: Polychlorinated Biphenyl	s (PCB)																	
Total Polychlorinated biphenyls				mg/kg	0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	< 0.1	<0.1	<0.1	<0.1
EP068A: Organochlorine Pesticio alpha-BHC	les (OC)			mg/kg	0.05	<0.05	<0.05	< 0.05	<0.05	< 0.05	< 0.05	< 0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Hexachlorobenzene (HCB) beta-BHC				mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05										
gamma-BHC				mg/kg	0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05
delta-BHC Heptachlor				mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05										
Aldrin Heptachlor epoxide	+		1	mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05										
Total Chlordane (sum) trans-Chlordane				mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05										
alpha-Endosulfan cis-Chlordane				mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05										
Dieldrin				mg/kg	0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05
4.4`-DDE Endrin				mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05										
Endosulfan (sum) beta-Endosulfan				mg/kg mg/kg	0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05										
4.4`-DDD Endrin aldehyde				mg/kg mg/ka	0.05	<0.05 <0.05	<0.05 <0.05	<0.05 <0.05										
Endosulfan sulfate 4.4`-DDT				mg/kg mg/kg	0.05	<0.05 <0.2	<0.05 <0.2	<0.05 <0.2										
Endrin ketone				mg/kg	0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	< 0.05	<0.05
Methoxychlor Sum of DDD + DDE + DDT				mg/kg mg/kg	0.2	<0.2 <0.05	<0.2 <0.05	<0.2 <0.05										
Sum of Aldrin + Dieldrin				mg/kg	0.05	<0.05	< 0.05	< 0.05	<0.05	< 0.05	< 0.05	< 0.05	<0.05	<0.05	<0.05	< 0.05	<0.05	<0.05
EP075(SIM)B: Polynuclear Aroma Naphthalene	atic Hydrocarbons	s 		mg/kg	0.5	<0.5	< 0.5	< 0.5	<0.5	<0.5	<0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	<0.5	<0.5
Acenaphthylene Acenaphthene				mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5										
Fluorene Phenanthrene				mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5										
Anthracene				mg/kg mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Fluoranthene Pyrene				mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5										
Benz(a)anthracene Chrysene				mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5										
Benzo(b+j)fluoranthene Benzo(k)fluoranthene				mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5										
Benzo(a)pyrene Indeno(1.2.3.cd)pyrene		0.5	1	mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5										
Dibenz(a.h)anthracene				mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Benzo(g.h.i)perylene Sum of polycyclic aromatic hydrocar	bons	20	40	mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5										
Benzo(a)pyrene TEQ (zero) Benzo(a)pyrene TEQ (half LOR)				mg/kg mg/kg	0.5	<0.5 0.6	<0.5	<0.5										
Benzo(a)pyrene TEQ (LOR)				mg/kg	0.5	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2		
EP080/071: Total Petroleum Hyd C6 - C9 Fraction	frocarbons		1	mg/kg	10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10
C10 - C14 Fraction				mg/kg	50	< 50	<50	<50	< 50	< 50	< 50	< 50	< 50	< 50	<50	<50	<50	<50
C15 - C28 Fraction C29 - C36 Fraction				mg/kg mg/kg	100 100	<100 <100	<100 <100	<100 <100										
C10 - C36 Fraction (sum)		250	500	mg/kg	50	<50	<50	<50	<50	<50	<50	<50	< 50	<50	<50	<50	<50	<50
EP080/071: Total Recoverable H	ydrocarbons - NE	PM 2013 Fracti	ions	mg/kg	10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10
C6 - C10 Fraction minus BTEX (F1) >C10 - C16 Fraction				mg/kg mg/kg	10 50	<10 <50	<10 <50	<10 <50										
>C16 - C34 Fraction				mg/kg	100	< 100	<100	< 100	<100	< 100	<100	<100	<100	<100	<100	<100	<100	<100
>C34 - C40 Fraction >C10 - C40 Fraction (sum)				mg/kg mg/kg	100 50	<100 <50	<100 <50	<100 <50										
>C10 - C16 Fraction minus Naphthal	lene (F2)	<u> </u>	<u> </u>	mg/kg	50	<50	<50	<50	<50	< 50	< 50	< 50	< 50	<50	<50	<50	<50	<50
EP080: BTEXN Benzene		N/A	0.5	mg/kg	0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Toluene Ethylbenzene		N/A N/A	65 25	mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5										
meta- & para-Xylene		187.6		mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
ortho-Xylene Total Xylenes		N/A	15	mg/kg mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5										
Sum of RTFX	1		•	ma/ka	0.2	<0.2	< 0.2	< 0.2	<0.2	< 0.2	<0.2	<0.2	<0.2	< 0.2	< 0.2	< 0.2	<0.2	<0.2

Blank Cell indicates no criterion available

--- Indicates sample not analysed
Concentration in _____int fort and grey box exceed VENM Classification
Concentration in red fort and grey box exceed Column 1 - ENM Classification
Concentration in blue font and grey box exceed Column 2 - ENM Classification Concentrations below the LOR noted as <value

bank cell inductors in Criterion available

LOR = Limit of Reporting

Background ranges, taken from the Field Geologist's Manual, compiled by D A Berkman, Third Edition 1989, The Australasian Institute of Mining & Metallurgy.

2 NSW EPA Resource Recovery Order under Part 9, Clause 93 of the Protection of the Environment Operations (Waste) Regulation 2014: The excavated natural material order 2014.

3 Maximum average concentration for site characterisation

⁴ Absolute maximum concentration
⁵ Ramboll Environ notes that the detection limit for mercury exceeds the background concentration as taken from source¹, however no detectable concentrations of mercury were identified, thus this is not considered to be of concern.

Blank cell indicates no screening criterion available

Site Audit Report 278_Northcote
WestConnex Stage 3A Northcote Compound
Area C3a


IAN SWANE & ASSOCIATES

Ramboll (November 2016)
UPSS Remediation & Validation Report

SAR 278_Northcote PAGE 108











UST1 Excavation O06_UST1_002 Tankpit SE base validation sample 3.2 24/05/2016 O06_QC024 1.2 Weathered sandstone, slight h O06_UST1_003 Tankpit NE wall validation sample 2.0 24/05/2016 - 0.0 Weathered sandstone, very sligh h O06_UST1_004 Tankpit SE wall validation sample 2.0 24/05/2016 - 0.0 Weathered sandstone, no obtained to the provided of the provided sandstone o	ne, no observed staining/odour/ACM ydrocarbon odour, no observed staining or ACM hydrocarbon odour, no observed staining or ACM erved contamination (staining, odour or ACM) ydrocarbon odour, no observed staining or ACM
UST1 Excavation O06_UST1_003	hydrocarbon odour, no observed staining or ACM erved contamination (staining, odour or ACM)
UST1 Excavation O06_UST1_004 Tankpit SE wall validation sample 2.0 24/05/2016 - 0.0 Weathered sandstone, no obtained by the control of the con	erved contamination (staining, odour or ACM)
O6_UST1_004	, 5, ,
DOG_UST1_006	/drocarbon odour, no observed staining or ACM
006_UST2_001 Tankpit base validation sample 1.5 10/05/2016 - 16.4 Weathered sandstone / clayey sand, orange an 10/05/2016 006_OC020 11.1 Weathered sandstone / clayey sand, orange an 10/05/2016 006_OC020 11.1 Weathered sandstone / clayey sand, orange an 10/05/2016 1.8 Sand (FILL), cream, loose, uniform, very moist, r beyond sand fill to nature 0.6 UST2_003 Tankpit S wall validation sample 0.8 10/05/2016 - 0.2 Weathered sandstone / clayey sand, very moist 0.6 UST2_004 Tankpit W wall validation sample 0.8 10/05/2016 - 0.1 Weathered sandstone / clayey sand, very moist 0.6 UST2_006 Tankpit W wall validation sample 0.8 24/05/2016 - 0.1 Weathered sandstone, mottled light 0.6 UST2_009 Tankpit wall validation sample 0.8 24/05/2016 - 0.0 Weathered sandstone, mottled light 0.6 UST2_009 Tankpit wall validation sample 0.8 24/05/2016 - 0.0 Weathered sandstone, mottled light 0.6 UST2_006 Fuel line trench and fuel pump base validation sample 0.5 10/05/2016 - 0.0 Weathered sandstone / clayey sand, response 0.5 10/05/2016 - 0.0 Weathered sandstone / clayey sand, response 0.5 10/05/2016 - 0.0 Weathered sandstone / clayey sand, response 0.5 10/05/2016 - 0.0 Weathered sandstone / clayey sand, response 0.5 10/05/2016 - 0.0 Weathered sandstone / clayey sand, response 0.5 10/05/2016 - 0.0 Weathered sandstone / clayey sand, response 0.5 10/05/2016 - 0.0 Weathered sandstone / clayey sand, response 0.5 0.0 Weathered sandstone / clayey sand, response 0.5 0.0	
UST2 Excavation	ydrocarbon odour, no observed staining or ACM
UST2 Excavation	d light grey, moderate hydrocarbon odour, no staining observed
UST2 Excavation UST3 Excavation UST4 Excavation UST4 Excavation UST5 Excavation UST5 Excavation UST5 Excavation UST4 Excavation UST5 Excavation UST5 Excavation UST5 Excavation UST4 Excavation UST5 Excavation UST5 Excavation UST5 Excavation UST6 Excavation UST6 Excavation UST8 Excavation UST8 Excavation UST9 E	d light grey, moderate hydrocarbon odour, no staining observed
Obe_UST2_005	nild hydrocarbon odour, no staining observed. Unable to excavat al on this wall as extends below concrete
O06_UST2_008 Tankpit wall validation sample 0.8 24/05/2016 - 0.0 Wearhered sandstone, mottled light 006_UST2_009 Tankpit wall validation sample 0.8 24/05/2016 - 0.0 Wearhered sandstone, mottled light 006_UST2_006 Fuel line trench and fuel pump base validation sample 006_UST2_006 Fuel line trench and fuel pump base validation sample 006_UST2_007 Fuel line trench base validation sample 0.5 10/05/2016 - 0.0 Weathered sandstone / clayey sand, lights in the properties of th	medium dense, light grey, mild hydrocarbon odour, no staining observed
Tankpit wall validation sample 0.8 24/05/2016 - 0.0 Wearhered sandstone, mottled light 0.8 24/05/2016 - 0.0 Weathered sandstone / clayey sand, light 0.8 Standard Dispensing 0.9 Weathered sandstone / clayey sand, light 0.9 Weathered sandstone / clayey sand, lig	nild hydrocarbon odour, no staining observed
Fuel Lines and Dispensing Pump O6_UST2_006 Fuel line trench and fuel pump base validation sample O6_UST2_007 Fuel line trench base validation sample O6_UST2_007 Fuel line trench base validation sample O5 10/05/2016 - 0.0 Weathered sandstone / clayey sand, lights of sand and clayey sand fill. S1 10/05/2016 - 103.4 mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pip O6_CS005 Backfill Waste Classification O6_CS006 Backfill Waste Classification O6_CS006 Backfill Waste Classification O6_CS006 Backfill Waste Classification O6_CS007 Backfill Waste Classification O6_CS007 Backfill Waste Classification O7 10/05/2016 - 153.7 mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pip O6_CS007 Backfill Waste Classification O7 10/05/2016 - 153.7 mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pip O6_CS007 Backfill Waste Classification O7 10/05/2016 - 14.3 mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pip O6_CS007 Backfill Waste Classification O7 10/05/2016 - 14.3 mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pip O7 10/05/2016 - 14.3 mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pip O7 10/05/2016 - 14.3 mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pip	grey and red/brown, no observed staining/odour/ACM
Fuel Lines and Dispensing Pump O06_UST2_007 Fuel line trench base validation sample O.5 10/05/2016 - O.0 Weathered sandstone / clayey sand, light of sand and clayey sand delayey sand (FILL), saturated, cobbles, timber, roots, PVC pip O06_GS005 Backfill Waste Classification One CS006 Backfill Waste Classification One CS007 Backfill Waste Classification One CS007 Backfill Waste Classification One CS007 One CS008 One CS008 One CS008 One CS009	grey and red/brown, no observed staining/odour/ACM
Puel line trench base validation sample 0.5 10/05/2016 - 0.0 10/05/2016 - 0.0 10/05/2016 - 0.0 10/05/2016 - 0.0 10/05/2016 - 0.0 10/05/2016 - 0.0 10/05/2016 - 0.0 10/05/2016 - 10/05/2016 - 10/05/2016 - 10/05/2016 - 10/05/2016 - 10/05/2016 - 10/05/2016 - 0.5 10/05/2016 - 0.5 10/05/2016 - 0.5 10/05/2016 - 0.5 10/05/2016 - 0.5 10/05/2016 - 10/0	ht grey and orange brown, saturated, soft, no observed aining/odour/ACM
UST1 Excavated Material UST1 Excavated Material Backfill Waste Classification N/a 10/05/2016 N/a 10/05/2016 - 103.4 cobbles, timber, roots, PVC pip mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pip n/a 10/05/2016 - 6.5 mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pip mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pip n/a 10/05/2016 - 153.7 mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pip n/a 10/05/2016 - 14.3 mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pip n/a 10/05/2016 - 14.3 mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pip n/a 10/05/2016 - 14.3 mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pip	ht grey and orange brown, saturated, soft, no observed aining/odour/ACM
UST1 Excavated Material 006_GS006 Backfill Waste Classification 10/05/2016	loose, medium grained, uniform, some bricks, wires, sandstone e, concrete pieces. Moderate hydrocarbon odour
Backfill Waste Classification n/a 10/05/2016 - 153.7 cobbles, timber, roots, PVC pi 006_GS007 Backfill Waste Classification n/a 10/05/2016 - 14.3 mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pi 006_GS007 Backfill Waste Classification n/a 10/05/2016 - 14.3 mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pi 006_GS007 Backfill Waste Classification n/a 10/05/2016 - 14.3 mix of sand and clayey sand (FILL), saturated, cobbles, timber, roots, PVC pi	loose, medium grained, uniform, some bricks, wires, sandstone e, concrete pieces. Moderate hydrocarbon odour
8ackfill Waste Classification n/a 10/05/2016 - 14.3 cobbles, timber, roots, PVC pip	loose, medium grained, uniform, some bricks, wires, sandstone be, concrete pieces. Strong hydrocarbon odour
acceptable in the second secon	loose, medium grained, uniform, some bricks, wires, sandstone e, concrete pieces. Moderate hydrocarbon odour
	loose, medium grained, uniform, some bricks, wires, sandstone be, concrete pieces. Strong hydrocarbon odour
996_GS901 Backfill Waste Classification n/a 10/05/2016 - 7.8 Sand (FILL), cream, medium grained, to	niform, loose, saturated, moderate hydrocarbon odour.
UST2 Excavated Material 806_GS002 Backfill Waste Classification n/a 10/05/2016 - 9.4 Sand (FILL), cream, medium grained, in	iniform, loose, saturated, moderate hydrocarbon odour.
806_GS903 Backfill Waste Classification n/a 10/05/2016 - 15.6 Sand (FILL), cream, medium grained	uniform, loose, saturated, strong hydrocarbon odour.
	cludes some brick, concrete, wires, sandstone, no observed aining/odour/ACM
	cludes some brick, concrete, wires, sandstone, no observed
806_GS911 Backfill Waste Classification n/a 10/05/2016 - 0.0 Silty Sand (FILL), brown, moist, uniform, ir s'	aining/odour/ACM

Notes
ppm = parts per million
m bgl = metres below ground level
ACM - asbestos containing materials
N - north, S - south, E - east, W - west
sample has been excavated and disposed of off-site



											Sample Typ	e:	REG	REG	REG	REG	REG	REG	REG
											ALS Sample	number:	ES1611421001		ES1611421009	ES1611421003	ES1611421004		ES1611421006
											Sample date		24/05/2016	24/05/2016	24/05/2016	24/05/2016	24/05/2016	24/05/2016	24/05/2016
1	NEPM 2013	NEPM 2013	NEPM 2013	NEPM 2013	NEPM 2013	NEPM 2013 EIL	NEPM 2013	NEPM 2013 Management	CRC CARE	CRC CARE	Sample ID:			006_UST1_002	006_QC022	006_UST1_003	006_UST1_004		006_UST1_006
	HIL D	Soil Vapour	Soil Vapour	Soil Vapour	Soil Vapour	Commercial /	ESL ²	Limits	2011 Direct	2011 Direct	Project Nan	ne:	M4E-WCX	M4E-WCX	M4E-WCX Northcote Street	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX
	ommercial /	Intrusion HSL		Intrusion HSL		Industrial	Commercial /		Contact HSL D ⁴	Contact HSL	Compound:		Northcote Street Tunnel Site	Northcote Street Tunnel Site	Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site	Northcote Street Tunnel Site
	Industrial	D Sand '0-1m	D Sand' 1-2m	D Sand ¹ 2-4m	D Sand ¹ 4+m		Industrial	Industrial 3	COMMON TIOL D	for Workers ⁴	Site:		Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006
										-	Sample Des	cription							
											-	-	Validation Sampling UST1	Validation	Duplicate of 006_UST1_002	Validation	Validation	Validation Sampling UST1	Validation
													Sampling UST I	Sampling UST1	006_0311_002	Sampling UST1	Sampling UST1	Sampling UST I	Sampling UST1
Analyte grouping/Analyte											Units	LOR							
EG005T: Total Metals by ICP-AES	2000	I	ı			4/0		I				-	-	-	-	-	_	-	-
Arsenic Cadmium	3000 900					160					mg/kg mg/kg	5	<5 <1	<5 <1	<5 <1	<5 <1	<5 <1	5 <1	<5 <1
Chromium	3600					310					mg/kg	2	4	5	4	4	3	5	2
Copper	240000					25					mg/kg	5	<5	<5	<5	<5	<5	<5	<5
Iron											%	0.005							
Lead	1500					1800					mg/kg	5	6	19	19	5	7	14	10
Nickel	6000					45					mg/kg	2	<2	6	5	<2	2	<2	<2
Zinc	400000					180					mg/kg	5	<5	27	32	12	16	<5	<5
EG035T: Total Recoverable Mercury by FIMS																			
Mercury	730										mg/kg	0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1
	,,,,										grivg	0	10.1	, , , ,	10.1	30.1		30.1	
EP075(SIM)A: Phenolic Compounds							·												
Phenol	240000										mg/kg	0.5		< 0.5					< 0.5
2-Chlorophenol											mg/kg	0.5		< 0.5					< 0.5
2-Methylphenol	25255						1				mg/kg	0.5		< 0.5					<0.5
3- & 4-Methylphenol 2-Nitrophenol	25000						-				mg/kg	1		<1					<1
2-Nitropnenoi 2.4-Dimethylphenol							l				mg/kg mg/kg	0.5		<0.5 <0.5					<0.5 <0.5
2.4-Dirhethylphenol							 				mg/kg mg/kg	0.5		<0.5					< 0.5
2.6-Dichlorophenol											mg/kg	0.5		<0.5					< 0.5
4-Chloro-3-methylphenol											mg/kg	0.5		< 0.5					< 0.5
2.4.6-Trichlorophenol											mg/kg	0.5		< 0.5					< 0.5
2.4.5-Trichlorophenol											mg/kg	0.5		< 0.5					< 0.5
Pentachlorophenol	660										mg/kg	2		<2					<2
EP075(SIM)B: Polynuclear Aromatic Hydrocarbons																			
Naphthalene		NL	NL	NL	NL	370			11000	29000	mg/kg	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	< 0.5
Acenaphthylene		1412	1412	IVL	1902	370			11000	27000	mg/kg	0.5	<0.5	< 0.5	< 0.5	<0.5	<0.5	< 0.5	< 0.5
Acenaphthene											mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Fluorene											mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Phenanthrene											mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Anthracene											mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Fluoranthene											mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Pyrene Benz(a)anthracene											mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Chrysene											mg/kg mg/kg	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Benzo(b+j)fluoranthene											mg/kg	0.5	<0.5	< 0.5	<0.5	< 0.5	<0.5	< 0.5	<0.5
Benzo(k)fluoranthene											mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Benzo(a)pyrene							72				mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Indeno(1.2.3.cd)pyrene											mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Dibenz(a.h)anthracene											mg/kg	0.5	< 0.5	<0.5	< 0.5	< 0.5	<0.5	<0.5	< 0.5
Benzo(g.h.i)perylene	4000						1				mg/kg	0.5	<0.5	<0.5	<0.5	<0.5	< 0.5	<0.5	< 0.5
Sum of polycyclic aromatic hydrocarbons Benzo(a)pyrane TEO (zero)	4000						-				mg/kg	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Benzo(a)pyrene TEQ (zero) Benzo(a)pyrene TEQ (half LOR)							l				mg/kg mg/kg	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6
Benzo(a)pyrene TEQ (Itali EOK) Benzo(a)pyrene TEQ (LOR)	40						1				mg/kg	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2
											., .,,,	·				_			
EP080/071: Total Petroleum Hydrocarbons		T	T			T		T											
C6 - C9 Fraction							1				mg/kg	10	<10	<10	<10	<10	<10	<10	<10
C10 - C14 Fraction C15 - C28 Fraction							-				mg/kg	50	<50	<50	<50	<50	<50	<50	<50
C15 - C28 Fraction C29 - C36 Fraction											mg/kg mg/kg	100 100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100
C10 - C36 Fraction (sum)											mg/kg	50	<50	<50	<50	<50	<50	<50	<50
EP080/071: Total Recoverable Hydrocarbons - NEPM 2013 Fraction	ns	1	1			1													
C6 - C10 Fraction		0/10	0==	/65			0.5-	700	26000	82000	mg/kg	10	<10	<10	<10	<10	<10	<10	<10
C6 - C10 Fraction minus BTEX (F1) >C10 - C16 Fraction		260 NL	370	630 NL	NL NI		215	1000	20000	42000	mg/kg	10 50	<10 <50	<10 <50	<10 <50	<10 <50	<10 <50	<10 <50	<10 <50
>C10 - C16 Fraction >C16 - C34 Fraction (F3)		NL	NL	NL	NL		170 1700	1000 3500	20000 27000	62000 85000	mg/kg mg/kg	100	<50 <100	<50 <100	<50 <100	<50 <100	<50 <100	<50 <100	<50 <100
>C34 - C40 Fraction (F4)							3300	10000	38000	120000	mg/kg mg/kg	100	<100	<100	<100	<100	<100	<100	<100
>C10 - C40 Fraction (sum)							3300	10000	30000	120000	mg/kg	50	<50	<50	<50	<50	<50	<50	<50
>C10 - C16 Fraction minus Naphthalene (F2)		NL	NL	NL	NL						mg/kg	50	<50	<50	<50	<50	<50	<50	<50
FDOOD, RTEVAL																			
EPO80: BTEXN Benzene		3	NL	NL	NL		75		430	1100	mg/kg	0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Toluene		NL	NL NL	NL NL	NL NL		135		99000	120000	mg/kg mg/kg	0.2	<0.2	<0.5	<0.5	<0.5	<0.2	<0.2	<0.2
Ethylbenzene		NL	NL	NL NL	NL		165		27000	85000	mg/kg	0.5	<0.5	<0.5	<0.5	<0.5	< 0.5	<0.5	<0.5
meta- & para-Xylene							95				mg/kg	0.5	< 0.5	< 0.5	<0.5	<0.5	< 0.5	< 0.5	< 0.5
ortho-Xylene	-	-			-			-	-		mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Total Xylenes		230	NL	NL	NL				81000	130000	mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Sum of BTEX		B.::	B**	B**	D."	270	1		11000	20000	mg/kg	0.2	< 0.2	< 0.2	<0.2	< 0.2	< 0.2	< 0.2	<0.2
Naphthalene		NL	NL	NL	NL	370	1	L	11000	29000	mg/kg	1	<1	<1	<1	<1	<1	<1	<1

Blank Cell indicates no criterion available

LOR = Limit of Reporting

CRC Care Technical Report 10, September 2011 Direct Contact (DC) Health Screening Levels 'D' (Commercial/Industrial)

National Environment Protection Council (2013) National Environmental Protection (Assessment of Site Contamination) Amendment Measure 2013 (No. 1) (NEPM).

¹ For soil texture classification undertaken in accord with AS 1726, the classifications of sand, silt and clay may be applied as coarse, fine with liquid limit >50% and fine with liquid limit >50% respectively, as the underlying properties to develop the HSLs may reasonably be selected to be similar. Where there is uncertainty, either a conservative approach may be adopted or laboratory analysis should be carried out.

² The most conservative ESL value has been adopted for all analytes

³ Management limits are applied after consideration of relevant ESLs and HSLs. Separate management limits for BTEX and naphthalene are not available hence these should not be subtracted from the relevant fractions to obtain F1 and F2.

⁴ Direct Contact are applied to surface soils or soils that could result in immediate contact. Health Investigation Levels for chromium based on chromium (VI)

Chromium (III) EIL, based on a low clay content (% clay) of 1%

Site specific EILs for copper in italics are based on the average of soil pH, cation exchange capacity and organic content

Site specific EILs for nickel in Italics are based on the average of soil cation exchange capacity

Site specific EILs for zinc *In Italics* are based on the average of soil pH and cation exchange capacity To obtain F1 subtract the sum of BTEX concentrations from the C6-C10 fraction.

To obtain F2 subtract naphthalene from the >C10-C16 fraction.

Benzo(a)Pyrene ESL adopted values based on Canadian Council of Ministers of the Environment (CCME) 2008 guidelines developed using a species sensitivity distribution (SSD) for eco-toxicity data from five independent studies involving three soil invertebrate taxa and two plant taxa (14 endpoints) in preference to NEPM low reliability data.

Concentration in red font and grey box exceed the adopted health screening value

Concentration in orange font and grey box exceed the adopted acological screening value

Concentration in blue font and grey box exceed the adopted management limits and direct contact screening value

sample has been excavated and disposed of off-site Concentrations below the LOR noted as <value

											REG	REG	REG	REG	REG	REG	REG	REG	REG	REG
										-	ES1610135001	ES1610135002		ES1610135003		ES1610135005		ES1610135007		ES1611421008
											10/05/2016	10/05/2016	10/05/2016	10/05/2016	10/05/2016	10/05/2016	10/05/2016	10/05/2016	24/05/2016	24/05/2016
	NEPM 2013	NEPM 2013	NEPM 2013	NEPM 2013	NEPM 2013	NEPM 2013 EIL	NEPM 2013	NEPM 2013 Management	CRC CARE	CRC CARE	006_UST2_001 M4E-WCX	006_UST2_002 M4E-WCX	006_QC020 M4F-WCX	006_UST2_003 M4E-WCX	006_UST2_004 M4E-WCX	006_UST2_005 M4E-WCX	006_UST2_006 M4E-WCX	006_UST2_007 M4E-WCX	006_UST2_008 M4E-WCX	006_UST2_009 M4E-WCX
	HIL D Commercial /	Soil Vapour Intrusion HSL	Soil Vapour Intrusion HSL	Soil Vapour	Soil Vapour	Commercial /	ESL ²	Limits	2011 Direct	2011 Direct Contact HSL	Northcote Street	Northcote Street	Northcote Street	Northcote Street		Northcote Street				Northcote Street
	Industrial		D Sand ¹ 1-2m			Industrial	Commercial / Industrial			for Workers ⁴	Tunnel Site	Tunnel Site	Tunnel-Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site	Tunnel Site
								Industrial 3		-	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006	Site 006 Validation	Site 006 Validation	Site 006	Site 006
											Validation	Validation	Duplicate of	Validation	Validation	Validation	Sampling Fuel	Sampling Fuel	Validation	Validation
											Sampling UST2	Sampling UST2	006_UST2_002	Sampling UST2	Sampling UST2	Sampling UST2	Lines	Lines	Sampling UST1	Sampling UST1
Analyte grouping/Analyte																				
EG005T: Total Metals by ICP-AES																				
Arsenic	3000					160					<5	13	<5	<5	<5	<5	<5	13	7	<5
Cadmium Chromium	900 3600					310					<1 <2	<1 6	<1	<1 <2	<1 <2	<1 6	<1 5	<1 40	<1 7	<1
Copper	240000					25					<5	<5	₹5	<5	<5	6	<5	<5	<5	<5
Iron											7	5	,	-	6	11	7	10	5	5
Lead Nickel	1500 6000					1800 <i>45</i>					<2		6 <2	<5 <2	<2	++	<2	10 <2	<2	<2
Zinc	400000					180					8	7	₹5	22	<5	65	7	<5	55	23
EG035T: Total Recoverable Mercury by FIMS																				
Mercury	730										< 0.1	<0.1	<0.1	< 0.1	< 0.1	<0.1	< 0.1	< 0.1	< 0.1	< 0.1
EPO75(SIM)A: Phenolic Compounds Phenol	240000	l l									<0.5	<0.5								
2-Chlorophenol	2,3000										< 0.5	<0.5	****							
2-Methylphenol 3- & 4-Methylphenol	25000	1									< 0.5	<0.5 <1								
2-Nitrophenol	∠5000										<1 <0.5	<1 <0.5								
2.4-Dimethylphenol											< 0.5	<0.5								
2.4-Dichlorophenol 2.6-Dichlorophenol											<0.5 <0.5	<0.5 <0.5								
4-Chloro-3-methylphenol											<0.5	<0.5								
2.4.6-Trichlorophenol											< 0.5	<0.5								
2.4.5-Trichlorophenol Pentachlorophenol	660										<0.5 <2	<0.5 <2								
	000										12	12								
EP075(SIM)B: Polynuclear Aromatic Hydrocarbons Naphthalene	T	NL	NL	NL	NL	370			11000	29000	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	< 0.5	<0.5	< 0.5	<0.5
Acenaphthylene		NL	IVL	IVL	IVL	370			11000	29000	<0.5	<0.5 <0.5	<0.5	< 0.5	<0.5	<0.5	< 0.5	<0.5	<0.5	<0.5
Acenaphthene											< 0.5	<0.5	<0.5	< 0.5	< 0.5	<0.5	< 0.5	< 0.5	< 0.5	< 0.5
Fluorene Phenanthrene											<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Anthracene											< 0.5	<0.5	<0.5	< 0.5	< 0.5	<0.5	< 0.5	< 0.5	< 0.5	< 0.5
Fluoranthene											<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Pyrene Benz(a)anthracene											<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	< 0.5	<0.5	<0.5	<0.5
Chrysene											< 0.5	<0.5	<0.5	< 0.5	< 0.5	<0.5	< 0.5	< 0.5	< 0.5	< 0.5
Benzo(b+j)fluoranthene Benzo(k)fluoranthene											<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Benzo(a)pyrene							72				< 0.5	₹0.5	<0.5	< 0.5	< 0.5	<0.5	< 0.5	< 0.5	< 0.5	< 0.5
Indeno(1.2.3.cd)pyrene											< 0.5	<0.5 <0.5	<0.5 <0.5	< 0.5	< 0.5	<0.5	< 0.5	< 0.5	< 0.5	< 0.5
Dibenz(a.h)anthracene Benzo(g.h.i)perylene											<0.5 <0.5	<0.5 <0.5	<0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Sum of polycyclic aromatic hydrocarbons	4000										< 0.5	<0.5	<0.5	< 0.5	< 0.5	<0.5	< 0.5	< 0.5	< 0.5	< 0.5
Benzo(a)pyrene TEQ (zero) Benzo(a)pyrene TEQ (half LOR)											<0.5 0.6	<0.5 0.6	<0.5 0.6	<0.5 0.6	<0.5 0.6	<0.5 0.6	<0.5 0.6	<0.5 0.6	<0.5 0.6	<0.5 0.6
Benzo(a)pyrene TEQ (Idail EOK)	40										1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2
EP080/071: Total Petroleum Hydrocarbons																				
C6 - C9 Fraction	T	1									<10	<10	<10	<10	<10	<10	<10	<10	<10	<10
C10 - C14 Fraction											<50	50	<50	<50	<50	<50	<50	<50	< 50	<50
C15 - C28 Fraction C29 - C36 Fraction											<100 <100	220	<100 <100	<100 <100	<100 <100	240 <100	<100 120	<100 <100	<100 <100	<100 <100
C10 - C36 Fraction (sum)											<50	270	<50	<50	<50	240	120	<50	<50	<50
EP080/071: Total Recoverable Hydrocarbons - NEPM 2013 Frac	otions																			
C6 - C10 Fraction	LIUIIS							700	26000	82000	<10	<10	<10	<10	<10	<10	<10	<10	<10	<10
C6 - C10 Fraction minus BTEX (F1)		260	370	630	NL		215				<10	<10	<10	<10	<10	<10	<10	<10	<10	<10
>C10 - C16 Fraction >C16 - C34 Fraction (F3)		NL	NL	NL	NL		170 1700	1000 3500	20000 27000	62000 85000	<50 <100	120 190	<50 <100	<50 <100	<50 <100	80 210	<50 140	<50 <100	<50 <100	<50 <100
>C34 - C40 Fraction (F4)	<u> </u>						3300	10000	38000	120000	<100	<100	<100	<100	<100	<100	<100	<100	<100	<100
>C10 - C40 Fraction (sum)	1										<50	310	<50	<50	<50	290	140	<50	<50	<50
>C10 - C16 Fraction minus Naphthalene (F2)		NL	NL	NL	NL						<50	120	<50	<50	<50	80	<50	<50	<50	<50
EP080: BTEXN	1																			
Benzene Toluene	1	3 NL	NL NL	NL NL	NL NL		75 135		430 99000	1100 120000	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5	<0.2 <0.5
Ethylbenzene		NL NL	NL NL	NL	NL NL		165		27000	85000	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	< 0.5
meta- & para-Xylene				-			95				< 0.5	<0.5	<0.5	< 0.5	< 0.5	<0.5	< 0.5	< 0.5	< 0.5	< 0.5
ortho-Xylene Total Xylenes	1	230	NL	NL	NL				81000	130000	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Sum of BTEX											< 0.2	<0.2	<0.2	< 0.2	< 0.2	<0.2	< 0.2	< 0.2	< 0.2	< 0.2
Naphthalene	1	NL	NL	NL	NL	370			11000	29000	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1

Blank Cell indicates no criterion available

LOR = Limit of Reporting

CRC Care Technical Report 10, September 2011 Direct Contact (DC) Health Screening Levels 'D' (Commercial/Industrial)

National Environment Protection Council (2013) National Environmental Protection (Assessment of Site Contamination) Amendment Measure 2013 (No. 1) (NEPM).

¹ For soil texture classification undertaken in accord with AS 1726, the classifications of sand, silt and clay may be applied as coarse, fine with liquid limit 50% and fine with liquid limit 50% respectively, as the underlying properties to develop the HSLs may reasonably be selected to be similar. Where there is uncertainty, either a conservative approach may be adopted or laboratory analysis should be carried out.

² The most conservative ESL value has been adopted for all analytes

³ Management limits are applied after consideration of relevant ESLs and HSLs. Separate management limits for BTEX and naphthalene are not available hence these should not be subtracted from the relevant fractions to obtain F1 and F2.

⁴ Direct Contact are applied to surface soils or soils that could result in immediate contact. Health Investigation Levels for chromium based on chromium (VI)

Chromium (III) EIL, based on a low clay content (% clay) of 1%

Site specific EILs for copper in Italics are based on the average of soil pH, cation exchange capacity and organic content

Site specific EILs for nickel in Italics are based on the average of soil cation exchange capacity

Site specific EILs for zinc *in Italics* are based on the average of soil pH and cation exchange capacity To obtain F1 subtract the sum of BTEX concentrations from the C6-C10 fraction.

To obtain F2 subtract naphthalene from the >C10-C16 fraction.

Benzo(a)Pyrene ESL adopted values based on Canadian Council of Ministers of the Environment (CCME) 2008 guidelines developed using a species sensitivity distribution (SSD) for eco-toxicity data from five independent studies involving three soil invertebrate taxa and two plant taxa (14 endpoints) in preference to NEPM low reliability data.

Concentration in red font and grey box exceed the adopted health screening value

Concentration in orange font and grey box exceed the adopted ecological screening value

Concentration in blue font and grey box exceed the adopted management limits and direct contact screening value

sample has been excavated and disposed of off-site Concentrations below the LOR noted as <value

Z:\Projects\LSJH\Deliverables\UPSS\Northcote Street Tunnel Site\Appendix B TablesAppendix B Tables

No.									Sample Type: ALS Sample number: Sample date: Sample ID: Project Name: Compound:	10/05/2016 006_GS001 M4E-WCX Northcote Street Tunnel	10/05/2016 006_GS002 M4E-WCX Northcote Street Tunnel	REG ES1610122003 10/05/2016 006_GS003 M4E-WCX Northcote Street Tunnel	10/05/2016 006_GS004 M4E-WCX Northcote Street Tunnel	10/05/2016 006_GS005 M4E-WCX Northcote Street Tunnel	REG ES1610122006 10/05/2016 006_GS006 M4E-WCX Northcote Street Tunnel	REG ES1610122007 10/05/2016 006_GS007 M4E-WCX Northcote Street Tunnel	10/05/2016 006_GS008 M4E-WCX Northcote Street Tunnel	10/05/2016 006_GS009 M4E-WCX Northcote Street Tunnel	10/05/2016 006_GS010 M4E-WCX Northcote Street Tunnel	REG ES1610122011 10/05/2016 006_GS011 M4E-WCX Northcote Street Tunnel	10/05/2016 006_QC022 M4E-WCX Northcote Street Tunnel
Column										Site 006 Grab Sample	Site 006 Grab Sample	Site 006 Grab Sample	Site 006 Grab Sample	Site 006 Grab Sample	Site 006 Grab Sample	Site 006 Grab Sample	Site 006 Grab Sample	Site 006 Grab Sample	Site 006 Grab Sample	Site 006 Grab Sample	Site 006 Duplicate of
September 1985 1985 1985 1985 1985 1985 1985 1985		General Solid	Restricted	General Solid	Restricted	General Solid	Restricted		Sample Description												
Column	Analyte grouping/Analyte	waste	John Waste	waste	John Waste	waste	John Waste	Units	LOR												
Column	EA055: Moisture Content Moisture Content (dried @ 103°C)							%	1	18	18.7	15.7	14.8	16.2	18.6	17.6	21.9	10.8	9.1	10.4	19.8
Column	Arsenic	100			2000			mg/kg	5	<5	<5	<5	5	6	<5	<5	<5	<5	<5	<5	7
The content of the co	Cadmium Chromium (VI) Copper							mg/kg	2	<2	<2	<2	7	8	6	4	6	5	8	8	11
Series Se	Lead Nickel							mg/kg mg/kg	5 2	<5 <2	<5 <2	<5 <2	2	26 3	18 2	8 <2	2	43	15 2	27 4	36 3
Column		y FIMS						mg/kg	5	53	55	42	59	117	62	46	80	398	//	30	126
Control Cont	Mercury FP066: Polychlorinated Ripheny		16	50	200			mg/kg	0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1
Column	Total Polychlorinated biphenyls	50	50	50	50			mg/kg	0.1			<0.1	<0.1		<0.1		<0.1		<0.1		
Column	EP068A: Organochlorine Pesticio alpha-BHC Hexachlorobenzene (HCB)	des (OC)																			
THE	beta-BHC gamma-BHC							mg/kg mg/kg	0.05 0.05			<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
Second	Heptachlor Aldrin							mg/kg	0.05			< 0.05	< 0.05	****	< 0.05	****	< 0.05		< 0.05		
Control Cont	Heptachlor epoxide Total Chlordane (sum) trans-Chlordane							mg/kg mg/kg	0.05 0.05			<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
Column	alpha-Endosulfan cis-Chlordane							mg/kg mg/kg	0.05 0.05			<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
TRIPLY MAY 18	4.4`-DDE Endrin							mg/kg	0.05			<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
Challed Series 10 10 10 10 10 10 10 1	Endosulfan (sum) beta-Endosulfan 4.4`-DDD	60	240	108	432			mg/kg mg/kg	0.05 0.05			<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
STATE OF THE PROPERTY OF THE P	Endrin aldehyde Endosulfan sulfate							mg/kg mg/kg	0.05 0.05			<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
STATE OF THE COLUMN TOWN THE COLUMN TOWN THE COLUMN TOWN THE COLUMN TOWN THE COLUMN THE	4.4`-DDT Endrin ketone Methoxychlor							mg/kg	0.05			< 0.05	< 0.05		< 0.05		< 0.05		< 0.05		
Figure	Sum of DDD + DDE + DDT Sum of Aldrin + Dieldrin							mg/kg	0.05			< 0.05	< 0.05		< 0.05		< 0.05		< 0.05		
Company Comp	Dichlorvos	ticides (OP)																			
STATE OF THE PROPERTY OF THE P	Demeton-S-methyl Monocrotophos Dimethoate							mg/kg mg/kg	0.05 0.2			<0.05 <0.2	<0.05 <0.2		<0.05 <0.2		<0.05 <0.2		<0.05 <0.2		
Address	Diazinon Chlorpyrifos-methyl							mg/kg mg/kg	0.05 0.05			<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
Service of the property of the	Parathion-methyl Malathion Fenthion							mg/kg	0.05			< 0.05	< 0.05		< 0.05		< 0.05		< 0.05		
Second	Chlorpyrifos Parathion	4	16	7.5	30			mg/kg mg/kg	0.05			<0.05 <0.2	<0.05 <0.2		<0.05 <0.2		<0.05 <0.2		<0.05 <0.2		
Series Continue of the continu	Pirimphos-ethyl Chlorfenvinphos Bromophos-ethyl							mg/kg	0.05			< 0.05	< 0.05		< 0.05		< 0.05		< 0.05		
Company	Fenamiphos Prothiofos							mg/kg mg/kg	0.05 0.05			<0.05 <0.05	<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		<0.05 <0.05		
Target 198 198 199 199 199 199 199 199 199 199	Carbophenothion Azinphos Methyl							mg/kg	0.05			< 0.05	< 0.05		< 0.05		< 0.05		< 0.05		
Company Comp	EP075(SIM)A: Phenolic Compour		1152	518	2073			ma/ka	0.5			<0.5	<0.5		<0.5		<0.5		<0.5		
Figure F	2-Chlorophenol 2-Methylphenol	4000	16000	7200	28800			mg/kg mg/kg	0.5 0.5			<0.5 <0.5	<0.5 <0.5		<0.5 <0.5		<0.5 <0.5		<0.5 <0.5		
Company	2-Nitrophenol 2.4-Dimethylphenol	4000	16000	7200	28800			mg/kg	0.5			< 0.5	< 0.5		< 0.5		<0.5		< 0.5		
2.4 A FORENCIACO 48 160 170 180 180 190 101 100	2.4-Dichlorophenol 2.6-Dichlorophenol							mg/kg	0.5			< 0.5	< 0.5	****	< 0.5	****	< 0.5		< 0.5		
No. Control	2.4.6-Trichlorophenol 2.4.5-Trichlorophenol							mg/kg mg/kg	0.5 0.5			<0.5 <0.5	<0.5 <0.5		<0.5 <0.5		<0.5 <0.5		<0.5 <0.5		
sperimens		atic Hvdrocarb	ons					mg/kg	2			<2	<2		<2		<2		<2		
The second secon	Naphthalene Acenaphthylene							mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	<0.5	< 0.5	< 0.5	<0.5	< 0.5
Segregation	Fluorene Phenanthrene							mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Procedure	Anthracene Fluoranthene							mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	<0.5	< 0.5	< 0.5	< 0.5	< 0.5
Second principal princip	Benz(a)anthracene Chrysene							mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
misend 2 f. allignesses	Benzo(b+j)fluoranthene Benzo(k)fluoranthene Benzo(a)pyrene	0.8	3.2	10	23			mg/kg	0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	<0.5	< 0.5	< 0.5	< 0.5	< 0.5
Sum of proposite semantic hydrocarbox 200 800 200 900	Indeno(1.2.3.cd)pyrene Dibenz(a.h)anthracene							mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Product Prod	Sum of polycyclic aromatic hydrocar Benzo(a)pyrene TEQ (zero)	bo 200	800	200	800			mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
28. C. Friedrich	Benzo(a)pyrene TEQ (half LOR) Benzo(a)pyrene TEQ (LOR)																				
13 - CQB Fraction	C6 - C9 Fraction		2600	650	2600																
Fig. 2 Fraction (sum) 1000 4000 1000 4000 1000 4000 1000 40	C15 - C28 Fraction C29 - C36 Fraction							mg/kg mg/kg	100 100	360 <100	390 <100	420 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100	<100 <100
26 - C10 Fraction	C10 - C36 Fraction (sum)	'			40000																
SC16 - CS4 Fraction	C6 - C10 Fraction C6 - C10 Fraction minus BTEX (F1)		W ZU131	. actions				mg/kg	10	<10	<10	<10	<10	<10	30	<10	49	<10	<10	<10	70
Color - (40 Fraction (sum) Color - (40 Fraction miuro Maphthalere (F2)	>C10 - C16 Fraction >C16 - C34 Fraction >C34 - C40 Fraction							mg/kg	100	280	300	320	<100	<100	<100	<100	<100	<100	<100	<100	<100
Service 10	>C10 - C40 Fraction (sum)	lene (F2)						mg/kg	50	660	700	790	<50	<50	<50	<50	60	<50	<50	<50	<50
Formstrip 198	EP080: BTEXN Benzene																				
Imply Marker Ma	Toluene Ethylbenzene	288	1152	518	2073			mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Maphthalene	ortho-Xylene Total Xylenes	1000	4000	1800	7200			mg/kg mg/kg	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Asbestos Detected	Naphthalene				<u>L</u>	<u> </u>															
Metals TCLP Arsenic 5 20 mg/L 0.15 < 0.1 < 0.1 < 0.1 < 0.1 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.05 < 0.01 < 0.01 < 0.01 < 0.01 < 0.01 < 0.01 < 0.01 < 0.01 < 0.01	Asbestos Detected	ation of Asbes	os in Soils					g/kg	0.1		No	No	No	No	No	No	No	No	No	No	
Arsenic S 20 mg/L 0.1	Metals TCLP									Ch	-	-						-			
Copper mg/L 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 < 0.1 .	Arsenic Cadmium Chromium, Total							mg/L	0.05			< 0.05	< 0.05		< 0.05		< 0.05		< 0.05		
Zinc mg/L 0.1 1.2 0.7 0.6 0.8 1.4	Copper Lead					5		mg/L mg/L	0.1 0.1			<0.1 <0.1	<0.1 <0.1		<0.1 <0.1		<0.1 <0.1		<0.1 <0.1		
	Nickel Zinc Mercury					2	8					1.2							1.4		

Blank Cell indicates no criterion available

LOR = Limit of Reporting

NSW BFA Waste Classification Guidelines - Part 1: Classification of Waste

1 Maximum values of specific contaminant concentration (SCC) for classification without TCLP

2 Maximum values of repectable concentration and specific contaminant concentration when used together

Blank cell indicates no screening retieron available

For Limit of Reporting (LOR) refer to laboratory certificates of analysis

— Indicates ample not analysed

Concentration in red font and grey box exceed CT1 screening value

Concentration in blue font and grey box exceed CT2 screening value

Concentrations below the LOR noted as -value

Z:\Projects\LSJH\Deliverables\UPSS\Northcote Street Tunnel Site\Appendix B TablesAppendix B Tables



Well ID	Easting	Northing	Gauging Date	Total Well Depth	SWL	Groundwater Elevation
wenTD	Lasting	Northing	Gauging Date	(m btoc)	(m btoc)	(mAHD)
006_GW004	326965.04	6250050.50	24/05/2016	10.03	5.03	9.575
006_GW005	326947.55	6250064.53	24/05/2016	10.07	3.07	8.391
006_GW006	326967.92	6250079.60	24/05/2016	10.68	3.77	9.061

Notes

m = Metres

btoc = Below Top of Casing

SWL = Standing Water Level

TOC = Top of Casing

AHD = Australian Height Datum

Easting projection MGA94: Map Grid of Australia 1994



Well ID	Purge Date	Purge Vol (L)	DO (ppm)	EC (µScm-1)	рН	Eh (mV)	Temperature (°C)	Comments
006_GW004	24/05/2016	3.5	1.20	1107	5.16	108	21.0	moderately turbid, brown, no sheen, no odour, no PSH
006_GW005	24/05/2016	2.5	0.62	4350	5.34	136	22.0	slightly turbid, brown, no sheen, no odour, no PSH
006_GW006	24/05/2016	2.5	1.39	2180	5.85	74	22.5	slightly turbid, brown, no sheen, no odour, no PSH

Notes

L = Litre

DO = Dissolved Oxygen

ppm = parts per million

EC = Electrical Conductivity

 $\mu Scm^{-1} = microSiemens per centimetre$

Eh = Redox

PSH = phase seperated hydrocarbons

mV = milli Volts



		– Commo	_	95% Marine Water Protection for Aquatic Ecosystems ^B	Recreational Health (10x ADWG 2011) ^c	Sample Typ ALS Sample Sample dat Sample ID: Project Nar Compound: Site: Sampling N	e number: e: ne:	REG ES1611420001 24/05/2016 006_GW004 M4E-WCX NORTHCOLE STREET TUNNEL SITE GME SITE 006 low flow	REG ES1611420002 24/05/2016 006_GW005 M4E-WCX NORTHCOLE STREET TUNNEL SITE GME SITE 006 low flow	REG ES1611420007 24/05/2016 006_QC100 M4E-WCX NORTHCOLE STREET TUNNEL SITE GME SITE 006 low flow	REG S16-My28529 502339 24/05/2016 006_QC101 M4E-WCX NORTHCOLE STREET TUNNEL SITE GME SITE 006 low flow	REG ES1611420003 24/05/2016 006_GW006 M4E-WCX NORTHCOLE STREET TUNNEL SITE GME SITE 006 low flow
Guidelines	2 to <4m	4m to<8m	8m+							DUPLICATE OF 006_GW005	TRIPLICATE OF 006_GW005	
Analyte grouping/Analyte						Units	LOR					
EG020T: Dissolved Metals by ICP-MS Arsenic				2.3	100	μg/L	1	<1	<1	<1	<1	2
Cadmium Chromium				0.7	20 500	μg/L μg/L	0.1	<0.1	<0.1	<0.1	0.2	0.9 <1
Copper Nickel				1.3	20000	μg/L μg/L	1	2 <1	<1 <1	<1 <1	1 <1	6 <1
Lead				4.4	100	μg/L	1	14	32	33	30	65
Zinc				15		μg/L	1	53	50	52	48	96
EG035F: Dissolved Mercury by FIMS Mercury				0.1	10	μg/L	0.1	<0.1	<0.1	<0.1	<0.1	<0.1
EP066: Polychlorinated Biphenyls (PCB)												
Total Polychlorinated biphenyls						μg/L	1	<1	<1	<1		<1
EPO68A: Organochlorine Pesticides (OC) alpha-BHC						μg/L	0.5	<0.5	<0.5	<0.5		<0.5
Hexachlorobenzene (HCB) beta-BHC						μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5
gamma-BHC delta-BHC					100	μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5
Heptachlor Aldrin				0.0004 0.003	3	μg/L	0.5 0.5	<0.5 <0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5
Heptachlor epoxide				0.003		μg/L μg/L	0.5	<0.5	<0.5	<0.5		<0.5
trans-Chlordane alpha-Endosulfan				0.0002		μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5
cis-Chlordane Dieldrin				0.01		μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5
4.4`-DDE Endrin				0.0005 0.008		μg/L μg/L	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5
beta-Endosulfan 4.4`-DDD				0.007		μg/L μg/L	0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5
Endrin aldehyde						μg/L	0.5	<0.5	< 0.5	<0.5		<0.5
Endosulfan sulfate 4.4`-DDT				0.0004	90	μg/L μg/L	0.5 2	<0.5 <2.0	<0.5 <2.0	<0.5 <2.0		<0.5 <2.0
Endrin ketone Methoxychlor				0.004	3000	μg/L μg/L	0.5 2	<0.5 <2.0	<0.5 <2.0	<0.5 <2.0		<0.5 <2.0
^ Total Chlordane (sum) ^ Sum of DDD + DDE + DDT				0.001	20	μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5
^ Sum of Aldrin + Dieldrin					3	µg/L	0.5	<0.5	<0.5	<0.5		<0.5
EP068B: Organophosphorus Pesticides (Dichlorvos	OP)				50	μg/L	0.5	<0.5	<0.5	<0.5		<0.5
Demeton-S-methyl				4	50	μg/L	0.5	<0.5	<0.5	<0.5		<0.5
Monocrotophos Dimethoate				0.15	70	μg/L μg/L	2 0.5	<2.0 <0.5	<2.0 <0.5	<2.0 <0.5		<2.0 <0.5
Diazinon Chlorpyrifos-methyl				0.01	40	μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5
Parathion-methyl Malathion				0.05	7 700	μg/L μg/L	2 0.5	<2.0 <0.5	<2.0 <0.5	<2.0 <0.5		<2.0 <0.5
Fenthion Chlorpyrifos				0.009	70 100	μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5
Parathion Pirimphos-ethyl				0.004	200	μg/L μg/L	2 0.5	<2.0 <0.5	<2.0 <0.5	<2.0 <0.5		<2.0 <0.5
Chlorfenvinphos					20	μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5 <0.5
Bromophos-ethyl Fenamiphos					5	μg/L	0.5	<0.5	<0.5	<0.5		<0.5
Prothiofos Ethion					40	μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5
Carbophenothion Azinphos Methyl				0.01	300	μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5		<0.5 <0.5
VOCs												
Styrene Isopropylbenzene						μg/L μg/L	5 5	<5 <5	<5 <5			<5 <5
n-Propylbenzene 1.3.5-Trimethylbenzene						μg/L μg/L	5 5	<5 <5	<5 <5			<5 <5
sec-Butylbenzene 1.2.4-Trimethylbenzene						μg/L μg/L	5	<5 <5	<5 <5			<5 <5
tert-Butylbenzene						μg/L	5	<5	<5			<5
p-Isopropyltoluene n-Butylbenzene						μg/L μg/L	5	<5 <5	<5 <5			<5 <5
Vinyl Acetate 2-Butanone (MEK)						μg/L μg/L	50 50	<50 <50	<50 <50			<50 <50
4-Methyl-2-pentanone (MIBK) 2-Hexanone (MBK)	<u> </u>					μg/L μg/L	50 50	<50 <50	<50 <50			<50 <50
Carbon disulfide 2.2-Dichloropropane						μg/L μg/L	5 5	<5 <5	<5 <5			<5 <5
1.2-Dichloropropane cis-1.3-Dichloropropylene						μg/L μg/L	5	<5 <5	<5 <5			<5 <5
trans-1.3-Dichloropropylene 1.2-Dibromoethane (EDB)						μg/L μg/L μg/L	5 5	<5 <5 <5	<5 <5			<5 <5 <5
Dichlorodifluoromethane						μg/L	50	<50	<50			<50
Chloromethane Vinyl chloride					3	μg/L μg/L	50 50	<50 <50	<50 <50			<50 <50
Bromomethane Chloroethane						μg/L μg/L	50 50	<50 <50	<50 <50			<50 <50
Trichlorofluoromethane 1.1-Dichloroethene					300	μg/L μg/L	50 5	<50 <5	<50 <5			<50 <5
Iodomethane trans-1.2-Dichloroethene					-	μg/L μg/L	5	<5 <5	<5 <5			<5 <5
1.1-Dichloroethane						μg/L	5	<5	<5			<5
cis-1.2-Dichloroethene 1.1.1-Trichloroethane						μg/L μg/L	5 5	<5 <5	<5 <5			<5 <5
1.1-Dichloropropylene Carbon Tetrachloride						μg/L μg/L	5 5	<5 <5	<5 <5			<5 <5
1.2-Dichloroethane Trichloroethene					30	μg/L μg/L	5 5	<5 <5	<5 <5			<5 <5
Dibromomethane 1.1.2-Trichloroethane				1900		μg/L μg/L	5	<5 <5	<5 <5			<5 <5
1.3-Dichloropropane				1700	500	μg/L	5	<5	<5			<5
Tetrachloroethene 1.1.1.2-Tetrachloroethane					500	μg/L μg/L	5 5	<5 <5	<5 <5			<5 <5
trans-1.4-Dichloro-2-butene cis-1.4-Dichloro-2-butene 1.1.2.2-Tetrachloroethane						µg/L µg/L µg/L	5 5 5	<5 <5 <5	<5 <5 <5			<5 <5 <5



6												
						Sample Typ	ne:	REG	REG	REG	REG	REG
						ALS Sample		+			S16-My28529	
						ALS Sample	i i i i i i i i i i i i i i i i i i i	ES1611420001	ES1611420002	ES1611420007	502339	ES1611420003
						Sample dat	e:	24/05/2016	24/05/2016	24/05/2016	24/05/2016	24/05/2016
		– Comm				Sample ID:		006_GW004	006_GW005	006_QC100	006_QC101	006_GW006
	I	ndustria	I ^A	95% Marine		Project Nar		M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX	M4E-WCX
				Water	Recreational	Compound	:	NORTHCOLE	NORTHCOLE	NORTHCOLE	NORTHCOLE	NORTHCOLE
				Protection for	Health (10x			STREET TUNNEL SITE GME	STREET TUNNEL SITE GME	STREET TUNNEL SITE GME	STREET TUNNEL SITE GME	STREET TUNNE SITE GME
				Aquatic	ADWG 2011) ^c	Site:		SITE GIVE	SITE GIVE	SITE GIVE	SITE GIVE	SITE GIVE
				Ecosystems ⁸		Sampling N	lethod:	low flow	low flow	low flow	low flow	low flow
	2 to <4m	4m to<8m	8m+			Sumpling in	ictriou.	low now	iow now	DUPLICATE OF	TRIPLICATE OF	low new
Guidelines		to<8m								006_GW005	006_GW005	
Analyte grouping/Analyte						Units	LOR					
	1		1	1		T 1	1	1	1	1		
1.2.3-Trichloropropane						μg/L	5	<5	< 5			<5
Pentachloroethane 1.2-Dibromo-3-chloropropane						μg/L	5 5	<5 <5	<5 <5			<5 <5
Hexachlorobutadiene						μg/L μg/L	5	<5	<5			<5
Chlorobenzene				55	3000	μg/L	5	<5	<5			<5
Bromobenzene						μg/L	5	<5	<5			<5
2-Chlorotoluene				<u></u>		μg/L	5	<5	<5			<5
4-Chlorotoluene						μg/L	5	<5	<5			<5
1.3-Dichlorobenzene				260		μg/L	5	<5	<5			<5
1.4-Dichlorobenzene	ļ		ļ	60	400	μg/L	5	<5	<5			<5
1.2-Dichlorobenzene		1		160	15000	μg/L	5	<5	< 5			<5
1.2.4-Trichlorobenzene	 		 	20	300	μg/L	5	<5	<5			<5
1.2.3-Trichlorobenzene Chloroform	 		 	3	300	μg/L μg/L	5 5	<5 <5	<5 <5			<5 <5
Bromodichloromethane						μg/L μg/L	5	<5 <5	<5 <5			<5 <5
Dibromochloromethane	†		†		1	μg/L μg/L	5	<5 <5	<5 <5			<5 <5
Bromoform						µg/L	5	<5	<5			<5
Naphthalene	1		1	50		μg/L	5	<5	<5			<5
						10						
EP075(SIM)A: Phenolic Compounds												
Phenol				400		μg/L	1	<1.0	<1.0	<1.0		<1.0
2-Chlorophenol				340	3000	μg/L	1	<1.0	<1.0	<1.0		<1.0
2-Methylphenol						μg/L	1	<1.0	<1.0	<1.0		<1.0
3- & 4-Methylphenol						μg/L	2	<2.0	<2.0	<2.0		<2.0
2-Nitrophenol 2.4-Dimethylphenol				2 2		μg/L μg/L	1	<1.0 <1.0	<1.0 <1.0	<1.0 <1.0		<1.0 <1.0
2.4-Dirhettyphenol				120	2000	μg/L μg/L	1	<1.0	<1.0	<1.0		<1.0
2.6-Dichlorophenol				34	2000	μg/L	1	<1.0	<1.0	<1.0		<1.0
4-Chloro-3-methylphenol						µg/L	1	<1.0	<1.0	<1.0		<1.0
2.4.6-Trichlorophenol				3	200	μg/L	1	<1.0	<1.0	<1.0		<1.0
2.4.5-Trichlorophenol				4		μg/L	1	<1.0	<1.0	<1.0		<1.0
Pentachlorophenol				22	100	μg/L	2	<2.0	<2.0	<2.0		<2.0
EP075(SIM)B: Polynuclear Aromatic Hyd												<u> </u>
Naphthalene	arocarbo	ns		50		μg/L	1	<1.0	<1.0	<1.0		<1.0
Acenaphthylene				30		μg/L	1	<1.0	<1.0	<1.0		<1.0
Acenaphthene						μg/L	1	<1.0	<1.0	<1.0		<1.0
Fluorene						μg/L	1	<1.0	<1.0	<1.0		<1.0
Phenanthrene				0.6		μg/L	1	<1.0	<1.0	<1.0		<1.0
Anthracene				0.01		μg/L	1	<1.0	<1.0	<1.0		<1.0
Fluoranthene				1		μg/L	1	<1.0	<1.0	<1.0		<1.0
Pyrene						μg/L	1	<1.0	<1.0	<1.0		<1.0
Benz(a)anthracene						μg/L	1	<1.0	<1.0	<1.0		<1.0
Chrysene Benzo(b+j)fluoranthene	 		 		-	μg/L ug/l	1	<1.0 <1.0	<1.0 <1.0	<1.0 <1.0		<1.0 <1.0
Benzo(k)fluoranthene	 		 		1	μg/L μg/L	1	<1.0	<1.0 <1.0	<1.0		<1.0 <1.0
Benzo(a)pyrene	†		†	0.1	0.1	μg/L	0.5	<0.5	<0.5	<0.5		<0.5
Indeno(1.2.3.cd)pyrene	t		t		†	μg/L	1	<1.0	<1.0	<1.0		<1.0
Dibenz(a.h)anthracene						μg/L	1	<1.0	<1.0	<1.0		<1.0
Benzo(g.h.i)perylene						μg/L	1	<1.0	<1.0	<1.0		<1.0
Sum of polycyclic aromatic hydrocarbons						μg/L	0.5	<0.5	<0.5	<0.5		<0.5
Benzo(a)pyrene TEQ (zero)						μg/L	0.5	<0.5	< 0.5	< 0.5		<0.5
EDOSO (071, Total Batralesses Under the	l one			<u> </u>		H		1	<u> </u>	<u> </u>		
EP080/071: Total Petroleum Hydrocarb	บทร			l		110 ^{//}	20	*20	-20	-20	20	- 20
C10 - C14 Fraction	 		 		1	μg/L μg/L	20 50	<20 <50	<20 <50	<20 <50	20	<20 <50
C15 - C28 Fraction	†		†			μg/L μg/L	100	<100	<100	<100		<100
C29 - C36 Fraction	t		t		†	μg/L	50	<50	<50	<50		<50
C10 - C36 Fraction (sum)						μg/L	50	<50	<50	<50		<50
						i i						
EP080/071: Total Recoverable Hydrocal	rbons - N	EPM 201	3 Fractio	ns								
C6 - C10 Fraction	ļ		ļ		<u> </u>	μg/L	20	<20	<20	<20		<20
C6 - C10 Fraction minus BTEX (F1)	6200	6300	6500		-	μg/L	20	<20	<20	<20		<20
>C10 - C16 Fraction	 		 		1	μg/L	100	<100	<100	<100		<100
>C16 - C34 Fraction >C34 - C40 Fraction	 		 		+	μg/L ug/l	100 100	<100 <100	<100 <100	<100 <100		<100 <100
>C34 - C40 Fraction >C10 - C40 Fraction (sum)	 		 		<u> </u>	μg/L μg/L	100	<100	<100	<100		<100
>C10 - C40 Fraction (sum) >C10 - C16 Fraction minus Naphthalene (F2)	NL	NL	NL			μg/L μg/L	100	<100	<100	<100		<100
2 2 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1	T	†		†	ra, c		1.55	1.55	1.55	 	1.35
EP080: BTEXN				1								
Benzene	4900	5100	5400	500	8000	μg/L	1	<1	<1	<1	<1	<1
Toluene	NL	NL	NL	180	3000	μg/L	2	<2	<2	<2	<1	<2
Ethylbenzene	NL	NL	NL	5	8000	μg/L	2	<2	<2	<2	<1	<2
meta- & para-Xylene				275		μg/L	2	<2	<2	<2	2	<2
ortho-Xylene				350	ļ	μg/L	2	<2	<2	<2	<1	<2
Total Xylenes	NL	NL	NL		6000	μg/L	2	<2	<2	<2	<3	<2
Sum of BTEX Naphthalene	NI	NI	NI	50		μg/L	1 5	<1	<1	<1		<1

Blank Cell indicates no criterion available

All results are in µg/L unless stated LOR = Limit of Reporting

Naphthalene

^A NEPM 2013 HSL 'D' (Commercial/Industrial)

B ANZECC 2000 % Protection Level for Receiving Water Type

ANZECC 2000 % Protection Level for Receiving water type

^c NHMRC Australian Drinking Water Guidelines, 2011

ANZECC guidelines in *Italias* are low level reliability guidelines

ANZECC arsenic guideline based on As (III) for marine and As (V) for fresh, the lowest of presented guidelines.

NHMRC arsenic guidelines are based on total arsenic

ANZECC and NHMRC guidelines for chromium are based on Cr (VI)

NL NL NL

50

ANZECC guidelines for mercury are based on inorganic mercury.

NHMRC guidelines for mercury are based on total mercury.

In instances where there was no marine guideline values, the freshwater guidelines have been adopted In instances where there was no health drinking water guideline value, the aesthetic value has been adopted Concentration in red font and grey box exceed the adopted ecosystem guideline value Concentration in orange font and grey box exceed the adopted recreational drinking water guideline value Concentrations in blue indicate the LOR is greater than the guideline value

Concentrations below the LOR noted as <value

no HSL is presented for recreational use (HSL C) as all these chemicals are not limiting (NL) $\,$



Record Page Page Record Recor													
Semple deficies					REG	REG		REG	REG		REG	REG	
Semple date		ALS Sample	number:										
Sumple failer 100000018 1000000018 100000018 100000018 100000018 100000018 100000018 100000018 100000018 100000018 100000018 100000018 100000018 100000018 100000018 100000018 1000000018 1000000018 1000000018 1000000018 1000000018 1000000018 1000000018 1000000018 10000000000					ES1610122008	ES1610122012		ES1610135002	ES1610135008		ES1610135002	S16-My13432	
Semiple												500403	
Semiple													
Project Name					10/05/2016	10/05/2016		10/05/2016	10/05/2016		10/05/2016	10/05/2016	
Project Name		Sample ID:			006 GS008	006 00022		006 UST2 002	006 00020		006 UST2 002	006 OC021	
Company Comp						_							
Surprise						RPD			RPD			RPD	
Serie Seri		Compound:											
Sample S													
Sample Description													
Sample Description		Sampling M	lethod:		Grab Sample	Grab Sample		Validation					
PRIMARY Depletor of product Depletor of product PRIMARY Depletor of product					Backfill Sands	Backfill Sands		Sampling US12	Sampling US12		Sampling US12	Sampling US12	
Analyte grouping/Analyte		Sample Des	cription										
Processing Memory by FIMS Telestropy of the Control of the Con					PRIMARY			PRIMARY			PRIMARY		
						006_GS008			006_UST2_002			006_UST2_002	
Professional Communication Professional C	Analyte grouping/Analyte		Units	LOR									
Professional Communication Professional C	FCOORT, Tetal Metals by ICD ASS												
Community Comm			ma fluo	-		,		12			12		
Consistent		 										 	
Compare													
Model													
								5				<5	nc
Process							40.0	<2					
BOOSST: Total Recoverable Mercury by FIMS	Zinc				80	126	44.7		<5		7		
Marcary							-						-
Part Post													
Rephthalmene	Mercury		mg/kg	0.1	< 0.1	< 0.1	nc	< 0.1	< 0.1	nc	<0.1		
Rephthalmene													
Reprophtylene			_										
Recomplishmen						<0.5		<0.5	<0.5		<0.5		
Fluerente													
Peneralthrene													
Pubmarkene													
Fluoranthene					< 0.5	< 0.5		< 0.5	< 0.5		< 0.5	< 0.5	
Pyrene			ma/ka										
Bert/Qianthreame						< 0.5		< 0.5	< 0.5		< 0.5	< 0.5	
Chrysme mg/kg	Benz(a)anthracene			0.5	< 0.5	< 0.5	nc	< 0.5	< 0.5	nc	< 0.5	< 0.5	nc
Beartoo(p)Ruoranthene	Chrysene			0.5		< 0.5	nc			nc	< 0.5	< 0.5	nc
Sento(a)pyrene mg/kg 0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5			mg/kg				nc			nc			
Indiano(1 2.3 cd))yrene													
Dibany(an) anthracene mg/kg 0.5 <0.5 <0.5 nc <0.5 <0.5 nc													
Bento(gh 1)perylane mg/kg 0.5 <0.5 <0.5 nc <0.5 nc													
Sum of polycyclic aromatic hydrocarbons													
Benzo(a)pyrene TEQ (1ero)						<0.5							
Benzo(a)pyrene TEQ (LOR)													
Benzo(a)pyrene TEQ (LOR)	Benzo(a)pyrene TEO (balf LOR)									nc			
EP080/071: Total Petroleum Hydrocarbons													
C6 - C9 Fraction mg/kg 10 35 56 46.2 <10 <10 nc <10 nc <20 nc				T									
C6 - C9 Fraction mg/kg 10 35 56 46.2 <10 <10 nc <10 nc <20 nc	EP080/071: Total Petroleum Hydrocarbons												
C15 - C28 Fraction mg/kg 100 <100 <100 nc 220 <100 75.0 220 54 121.2	C6 - C9 Fraction												
C29 - C36 Fraction mg/kg 100 <100 nc <100 <100 nc											25		
EPOBO/071: Total Recoverable Hydrocarbons - NEPM 2013 Fractions mg/kg 50 60 <50 nc 270 50 137.5 270 79 109.5													
EP080/071: Total Recoverable Hydrocarbons - NEPM 2013 Fractions mg/kg 10 49 70 35.3 <10 <10 nc <10 nc <10 \cdot <20 nc <10 Fraction mg/kg 10 49 70 35.3 <10 <10 nc <10 nc <10 \cdot <20 nc <10 Fraction mg/kg 10 49 70 35.3 <10 <10 nc <10 nc <10 \cdot <20 nc <10 Fraction mg/kg 10 dc <10 nc	C29 - C36 Fraction												
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	C10 - C36 Fraction (sum)		mg/kg	50	60	<50	nc	270	50	137.5	270	79	109.5
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	EBORO (071) Total Recoverable Hydrocarbons - NEDM 2012 For	ctions						<u> </u>			<u> </u>		
C6 - C10 Fraction minus BTEX (F1) mg/kg 10 49 70 35.3 <10 <10 ne <10 <20 ne <20 n		CHOIIS	ma/ka	10	40	70	36.3	-10	<10	nc	×10	- 20	nc
SCIO - C16 Fraction mg/kg 50 60 <50 nc 120 <50 82.4 120 <50 82.4 50 62.4													
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$													
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$													
Scilo - C40 Fraction (sum) mg/kg 50 60 <50 nc 310 <50 144.4 310 110 C50 62.4 C50 C5	>C34 - C40 Fraction (F4)												
EPOBL STEXM	>C10 - C40 Fraction (sum)									144.4			
Benzene mg/kg 0.2 <0.2 <0.2 nc <0.2 <0.2 nc <0.2 <0.2 nc <0.2 <0.1 nc nc nc nc nc nc nc n	>C10 - C16 Fraction minus Naphthalene (F2)						nc					< 50	82.4
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$													
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$													
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$													
				0.5	< 0.5	< 0.5		< 0.5	< 0.5		< 0.5	<0.2	
Sum of BTEX mg/kg 0.2 <0.2 <0.2 nc <0.2 <0.2 nc <0.2		—											
		 											
1111/18 1 <1 11													
	respirations	1	mg/kg		< 1	< 1	n.	< 1	< 1	THU .	< 1	<0.5	THU .

mg/kg 0.2 mg/kg 0.5 nc = not calculated since results < LOR LOR = Laboratory Limit of Reporting

BOLD identifies	where RPD exceed	ls
Intralaboratory	Interlaboratory	
>50	>60	where sample results are >10 x PQL
>75	>85	where sample results are > 5 to ≤10 x PQL
>100	>100	where sample results are >2 to ≤5 x PQL
	•	

AD>2.5 * PQL where sample results are \$2 x PQL

Where results are within two of the above ranges the most conservative criteria have been used to assess duplicate performance



Analyte grouping/Analyte EG020T: Dissolved Metals by ICP-MS Arsenic Cadmium Chromium Copper Nickel Lead Zinc EG035F: Dissolved Mercury by FIMS Mercury EP066: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls EP068A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC	ISL D – Cor 2 to <4m	mmercial/ Inc 4m to<8m	dustrial	95% Marine Water Protection for		Sample Typ ALS Sample Sample dat Sample ID: Project Nar Compound: Site: Sampling N Sample Des	e number: e: me:	REG ES1611420002 24/05/2016 006_GW005 M4E-WCX NORTHCOLE STREET TUNNEL SITE GME	REG ES1611420007 24/05/2016 006_QC100 M4E-WCX NORTHCOLE STREET TUNNEL SITE GME	RPD	REG ES1611420002 24/05/2016 006_GW005 M4E-WCX NORTHCOLE STREET TUNNEL SITE GME	REG S16-My28529 502339 24/05/2016 006_QC101 M4E-WCX NORTHCOLE STREET TUNNEL	RPD
Analyte grouping/Analyte EG020T: Dissolved Metals by ICP-MS Arsenic Cadmium Chromium Copper Nickel Lead Zinc EG035F: Dissolved Mercury by FIMS Mercury EP066: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls EP068A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC		ı		Water		Sample ID: Project Nar Compound: Site: Sampling N	ne:	006_GW005 M4E-WCX NORTHCOLE STREET TUNNEL	006_QC100 M4E-WCX NORTHCOLE STREET TUNNEL	RPD	006_GW005 M4E-WCX NORTHCOLE STREET TUNNEL	24/05/2016 006_QC101 M4E-WCX NORTHCOLE STREET TUNNEL	RPD
Analyte grouping/Analyte EGO2OT: Dissolved Metals by ICP-MS Arsenic Cadmium Chromium Copper Nickel Lead Zinc EG035F: Dissolved Mercury by FIMS Mercury EP066: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls EP068A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC		ı		Water		Project Nar Compound: Site: Sampling N	ne:	M4E-WCX NORTHCOLE STREET TUNNEL	M4E-WCX NORTHCOLE STREET TUNNEL	RPD	M4E-WCX NORTHCOLE STREET TUNNEL	M4E-WCX NORTHCOLE STREET TUNNEL	RPD
Analyte grouping/Analyte EGO2OT: Dissolved Metals by ICP-MS Arsenic Cadmium Chromium Copper Nickel Lead Zinc EGO35F: Dissolved Mercury by FIMS Mercury EPO66: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls EPO68A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC		ı		Water	_	Site: Sampling N		STREET TUNNEL	STREET TUNNEL	RPD	STREET TUNNEL	STREET TUNNEL	RPD
Analyte grouping/Analyte EGO20T: Dissolved Metals by ICP-MS Arsenic Cadmium Chromium Copper Nickel Lead Zinc EGO35F: Dissolved Mercury by FIMS Mercury EPO66: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls EPO68A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC		ı		Water		Sampling M					. SITE GIVIE	SITE GME	
Analyte grouping/Analyte EGO20T: Dissolved Metals by ICP-MS Arsenic Cadmium Copper Nickel Lead Zinc EGO35F: Dissolved Mercury by FIMS Mercury EPO66: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls EPO68A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC		ı		Water			lethod:	SITE 006 low flow	SITE 006 low flow		SITE 006 low flow	SITE 006 low flow	
Analyte grouping/Analyte EGO20T: Dissolved Metals by ICP-MS Arsenic Cadmium Chromium Copper Nickel Lead Zinc EGO35F: Dissolved Mercury by FIMS Mercury EPO66: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls EPO68A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC	2 to <4m	4m to<8m	9 ~ .		Recreational Health (10x	Campio Do		PRIMARY	DUPLICATE OF 006_GW005		PRIMARY	TRIPLICATE OF 006_GW005	
Analyte grouping/Analyte EGO20T: Dissolved Metals by ICP-MS Arsenic Cadmium Chromium Copper Nickel Lead Zinc EGO35F: Dissolved Mercury by FIMS Mercury EPO66: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls EPO68A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC	2 to <4m	4m to<6m		Aquatic Ecosystems	ADWG 2011)								
Arsenic Cadmium Cohromium Copper Nickel Lead Zinc EG035F: Dissolved Mercury by FIMS Mercury EP066: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls EP068A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC			0111+			Units	LOR						
Cadmium Chromium Copper Nickel Lead Zinc EG035F: Dissolved Mercury by FIMS Mercury EP066: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls EP068A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC													
Chromium Copper Nickel Lead Zinc EG035F: Dissolved Mercury by FIMS Mercury EP066: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls EP068A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC				2.3 0.7	100 20	μg/L μg/L	1 0.1	<1 <0.1	<1 <0.1	nc nc	<1 <0.1	<1 0.2	nc nc
Nickel Lead Zinc EG035F: Dissolved Mercury by FIMS Mercury EP066: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls EP068A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC				4.4	500 20000	μg/L μg/L	1	<1 <1	<1 <1	nc nc	<1 <1	<1	nc nc
Zinc EG035F: Dissolved Mercury by FIMS Mercury EP066: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls EP068A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC				7	200	μg/L μg/L	1	<1 32	<1 33	nc 3.1	<1 32	<1 30	nc 6.5
Mercury EP066: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls EP068A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC				15	100	µg/L µg/L	1	50	52	3.9	50	48	4.1
EP066: Polychlorinated Biphenyls (PCB) Total Polychlorinated biphenyls EP068A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC													
Total Polychlorinated biphenyls EP068A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC				0.1	10	μg/L	0.1	<0.1	<0.1	nc	<0.1	<0.1	nc
EPO68A: Organochlorine Pesticides (OC) alpha-BHC Hexachlorobenzene (HCB) beta-BHC						μg/L	1	<1	<1	nc	<1		
Hexachlorobenzene (HCB) beta-BHC							0.5	<0.5	<0.5	nc	<0.5		
						μg/L μg/L	0.5	< 0.5	< 0.5	nc	< 0.5		
gamma-BHC					100	μg/L μg/L	0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5		
delta-BHC Heptachlor				0.0004	3	μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5		
Aldrin Heptachlor epoxide				0.003		μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5		
trans-Chlordane alpha-Endosulfan				0.0002		μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5		
cis-Chlordane Dieldrin				0.01		μg/L μg/L	0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5		
4.4`-DDE				0.0005		μg/L	0.5	< 0.5	<0.5	nc	< 0.5		
Endrin beta-Endosulfan				0.008 0.007		μg/L μg/L	0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5		
4.4`-DDD Endrin aldehyde						μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5		
Endosulfan sulfate 4.4`-DDT				0.0004	90	μg/L μg/L	0.5 2	<0.5 2	<0.5 2	nc nc	<0.5 2		
Endrin ketone Methoxychlor				0.004	3000	μg/L μg/L	0.5	<0.5 2	<0.5 2	nc nc	<0.5 2		
^ Total Chlordane (sum) ^ Sum of DDD + DDE + DDT				0.001	20	μg/L	0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5		
^ Sum of Aldrin + Dieldrin					3	μg/L μg/L	0.5	<0.5	<0.5	nc	<0.5		
EP068B: Organophosphorus Pesticides (OP))												
Dichlorvos Demeton-S-methyl				4	50	μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5		
Monocrotophos Dimethoate				0.15	70	μg/L μg/L	2 0.5	2 <0.5	2 <0.5	nc nc	2 <0.5		
Diazinon Chlorpyrifos-methyl				0.01	40	μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5		
Parathion-methyl				0.05	7	μg/L	2	2	2	nc	2		
Malathion Fenthion				0.05	700 70	μg/L μg/L	0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5		
Chlorpyrifos Parathion				0.009 0.004	100 200	μg/L μg/L	0.5	<0.5 2	<0.5 2	nc nc	<0.5 2		
Pirimphos-ethyl Chlorfenvinphos					20	μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5		
Bromophos-ethyl Fenamiphos					5	μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5		
Prothiofos Ethion					40	μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5		
Carbophenothion				0.04		μg/L	0.5	< 0.5	<0.5	nc	< 0.5		
Azinphos Methyl				0.01	300	μg/L	0.5	<0.5	<0.5	nc	<0.5		
Phenol				400		μg/L	1	<1.0	<1.0	nc	<1.0		
2-Chlorophenol 2-Methylphenol				340	3000	μg/L μg/L	1	<1.0 <1.0	<1.0 <1.0	nc nc	<1.0 <1.0		
3- & 4-Methylphenol 2-Nitrophenol				2		μg/L μg/L	2	2 <1.0	2 <1.0	0.0 nc	2 <1.0		
2.4-Dimethylphenol 2.4-Dichlorophenol				2 120	2000	μg/L μg/L	1	<1.0 <1.0	<1.0 <1.0 <1.0	nc nc	<1.0 <1.0 <1.0		
2.6-Dichlorophenol				34	2000	μg/L	1	<1.0	<1.0	nc	<1.0		
4-Chloro-3-methylphenol 2.4.6-Trichlorophenol				3	200	μg/L μg/L	1	<1.0 <1.0	<1.0 <1.0	nc nc	<1.0 <1.0		
2.4.5-Trichlorophenol Pentachlorophenol				4 22	100	μg/L μg/L	2	<1.0 2	<1.0 2	nc 0.0	<1.0 2		
EP075(SIM)B: Polynuclear Aromatic Hydroca	carbons												
Naphthalene Acenaphthylene				50		μg/L μg/L	1	<1.0 <1.0	<1.0 <1.0	nc nc	<1.0 <1.0		
Acenaphthene Fluorene						μg/L μg/L	1	<1.0 <1.0	<1.0 <1.0 <1.0	nc nc	<1.0 <1.0		
Phenanthrene				0.6		μg/L	1	<1.0	<1.0	nc	<1.0		
Anthracene Fluoranthene				0.01 1		μg/L μg/L	1	<1.0 <1.0	<1.0 <1.0	nc nc	<1.0 <1.0		
Pyrene Benz(a)anthracene						μg/L μg/L	1	<1.0 <1.0	<1.0 <1.0	nc nc	<1.0 <1.0		
Chrysene Benzo(b+j)fluoranthene						μg/L μg/L	1	<1.0 <1.0	<1.0 <1.0	nc nc	<1.0 <1.0		
Benzo(k)fluoranthene Benzo(a)pyrene				0.1	0.1	μg/L μg/L	1 0.5	<1.0 <0.5	<1.0 <0.5	nc nc	<1.0 <0.5		
Indeno(1.2.3.cd)pyrene Dibenz(a.h)anthracene					2	μg/L	1	<1.0 <1.0	<1.0 <1.0	nc nc	<1.0 <1.0		
Benzo(g.h.i)perylene						μg/L μg/L	1	<1.0	<1.0	nc	<1.0		
Sum of polycyclic aromatic hydrocarbons Benzo(a)pyrene TEQ (zero)						μg/L μg/L	0.5 0.5	<0.5 <0.5	<0.5 <0.5	nc nc	<0.5 <0.5		
EP080/071: Total Petroleum Hydrocarbons													
C6 - C9 Fraction C10 - C14 Fraction						μg/L μg/L	20 50	20 <50	20 <50	nc nc	20 <50	20	nc
C15 - C28 Fraction C29 - C36 Fraction						μg/L μg/L	100 50	<100 <50	<100 <50	nc nc	<100 <50		
C10 - C36 Fraction (sum)						μg/L	50	<50	<50	nc	<50		
EP080/071: Total Recoverable Hydrocarbon:	ns - NEPM .	2013 Fraction	s				20	20	20	se -	20	 	
	6200	6300	6500			μg/L μg/L	20	20	20 20	nc nc	20		
>C10 - C16 Fraction >C16 - C34 Fraction						μg/L μg/L	100 100	<100 <100	<100 <100	nc nc	<100 <100		
>C34 - C40 Fraction >C10 - C40 Fraction (sum)						μg/L μg/L	100 100		<100 <100				
>C10 - C16 Fraction minus Naphthalene (F2)	NL	NL	NL			μg/L	100		<100				

All units in µg/L except trip spikes (%)
nc = not calculated since results < LOR
LOR = Laboratory Limit of Reporting
BOLD identifies where RPD exceeds
Intralab Interlab

>50	>60	where sample results are >10 x PQL
>75	>85	where sample results are > 5 to ≤10 x PQL
>100	>100	where sample results are >2 to ≤5 x PQL
AD>2.5 * PQL		where sample results are ≤2 x PQL

Site Audit Report 278_Northcote
WestConnex Stage 3A Northcote Compound
Area C3a

IAN SWANE & ASSOCIATES

Appendix B. Figures and Tables from ASBJV Site Work

SAR 278_Northcote PAGE 109

DRAWING FILE LOCATION \ NAME - PLOT DATE \ TIME - PLOT BY

DESIGN MODEL FILE(S) USED FOR DOCUMENTATION OF THIS DRAWING | REV |

:\Users\chris.waite\Documents\WCX\Drawings\ALL SITE\M4M5-RBGP-PRW-CIV-CW02-DRG-1000.dwg-27/06/2022 2:46:15 AM-Chris.Waite

DATE

27.06.22

AMENDMENT / REVISION DESCRIPTION


ISSUED FOR CONSTRUCTION

M4M5 LINK MAIN TUNNEL WORKS

PROJECT WIDE

PACKAGE: M4M5-RBGP-PRW-CIV-CW02-DPK-0001

CONSTRUCTION SITE REINSTATEMENT



LOCALITY PLAN

acciona

DESIGN PACKAGE CODE

CO-ORDINATE SYSTEM

MGA ZONE 56

C.WAITE

SCALES ON THIS A3 SIZE DRAWING

M4M5-RBGP-PRW-CIV-CW02-DPK-0001

HEIGHT DATUM

AHD

DRAWINGS / DESIGN PREPARED BY

DATE

31.03.22

31.03.22

31.03.22

31.03.22

31.03.22

31.03.22

M.ARELLANO

J.SUN

C.WAITE

DRG CHECK

DESIGN MNGR

DESIGN CHECK J.SUN

DESIGN VERIFIER C.WAITE

PROJECT MNGR | C.WAITE

ACCEPTED FOR CONSTRUCTION

M4M5-RBGP-PRW- CIV -CW02-DRG- 1000

M4-M5 LINK MAIN TUNNEL WORKS

PROJECT WIDE
CONSTRUCTION SITE REINSTATEMENT

COVER SHEET

WestConnex

COVER SHEET

RMS REGISTRATION No.

ISSUE STATUS
ISSUED FOR CONSTRUCTION

PAR

1

COVER SHEET

COVER SHEET

PAR

COVER SHEET

COVER SHEET

PAR

COVER SHEET

COVER SHEET

PAR

COVER SHEET

C

© Roads and Maritime Services

0 5 10 15 20 25 30 35 40 45 50mm ON A3 SIZE ORIGINAL	
7	
NE NE	
ON A3 SIZE ORIGI	
m ON A3 SIZE O	
SIZ	
I A3	
6	
шш	
50	
45	
1	
40	
5	
<u></u>	
30	
25	С
20	_
	-
15	-
= =====================================	_
2	ءً ا
0_	_

CW02 Drawing Reference	Temporary works element	Temporary works drawing reference
CW02-DRG-1101	Temporary retaining wall installed by M4East near Northcote street dead end	M4E-EIC-DIC-DG-10-660-925-502
CW02-DRG-1101	Temporary hoarding installed by M4East near Northcote street dead end	M4E-EIC-DIC-DG-10-660-900-435
"CW02-DRG-1101 CW02-DRG-1103 CW02-DRG-1105"	Decline piling structures constructed by M4East	"M4E-MJA-DG-10-280-318-002 M4E-MJA-DG-10-280-318-003 M4E-MJA-DG-10-280-318-100 M4E-MJA-DG-10-280-318-101 M4E-MJA-DG-10-280-318-102 M4E-MJA-DG-10-280-318-150 M4E-MJA-DG-10-280-318-155 M4E-MJA-DG-10-280-318-201 M4E-MJA-DG-10-280-318-301 M4E-MJA-DG-10-280-318-310 M4E-MJA-DG-10-280-318-311 M4E-MJA-DG-10-280-318-320 M4E-MJA-DG-10-280-318-330 M4E-MJA-DG-10-280-318-340 M4E-MJA-DG-10-280-318-340 M4E-MJA-DG-10-280-318-360"
"CW02-DRG-1101 CW02-DRG-1103 CW02-DRG-1105"	Temporary ground slab constructed by M4East	"M4E-AEH-DG-10-660-922-111 M4E-AEH-DG-10-660-922-112 M4E-AEH-DG-10-660-925-411 to 416"
"CW02-DRG-1101 CW02-DRG-1103"	Temporary driveways constructed by M4East	"M4E-AEH-DG-10-660-922-101 M4E-EIC-DG-10-660-925-905 M4E-EIC-DG-10-660-925-911 M4E-EIC-DG-10-660-925-912"

GENERAL ARRANGEMENT NOTES:

- 1. ALL PORTABLE STRUCTURES AND ELECTRICAL EQUIPMENTS ARE TO BE REMOVED AS PART OF THE FINAL REINSTATEMENT PACKAGE.
- 2. PROPOSED DRAINAGE IS DESIGNED FOR MINOR STORM OF 10 YEARS
- 3. WEIGHBRIDGE AND WHEEL WASH TO BE REMOVED AND BACKFILLED AS PER PAVEMENT DETAIL SHOWN M4M5-RBGP-CIV-CW02-DRG-1103.
- 4. REFER TO M4M5-RBGP-PRW-CIV-CW02-DRG-2032 FOR FENCE AND GATE DETAIL.
- 5. FILTER BASKET TO BE INSTALLED IN ALL PROPOSED NEW STORMWATER PITS.
- 6. CLASS D GRATE TO BE PROVIDED OR TO BE INSTALLED FOR ALL PROPOSED STORMWATER PITS.
- 7. ANY EXISTING DRAINS, PITS, DRAINAGE LINES PROPOSED TO BE LEFT IN PLACE ARE REQUIRED TO BE FLUSHED AND CLEARED OF BLOCKAGES AND EVIDENCED AS FIT FOR PURPOSE WITH MEASURES SUCH AS CCTV PRIOR TO HANDOVER.
- 8. BRANDING TO BE DIRECTED AND CONFIRMED WITH TFNSW.

PAVEMENT NOTES:

1. BACKFILL MATERIAL AND SPECIFICATION

FILLING MATERIAL: INORGANIC, NON-PERISHABLE MATERIAL OF THE TYPES SPECIFIED.

SULPHUR CONTENT: DO NOT USE FILLING HAVING A SULPHUR CONTENT EXCEEDING 0.5% WITHIN 500 MM OF CEMENT BOUND ELEMENTS (FOR EXAMPLE CONCRETE STRUCTURES OR MASONRY) UNLESS SUCH ELEMENTS ARE PROTECTED BY IMPERMEABLE MEMBRANES OR EQUIVALENT MEANS.

2. FILLING TYPES GENERAL FILLING: GRADED MATERIAL FROM SITE, MAXIMUM PARTICLE SIZE 50 MM.

SELECTED FILLING: GRANULAR MATERIAL AS FOLLOWS: -MAXIMUM PARTICLE SIZE: 50 MM. -PERCENTAGE PASSING .075 MM SIEVE: 50% MAXIMUM. -PLASTICITY INDEX: NOT GREATER THAN 14% AND NOT LESS THAN -CBR (4 DAY SOAKED): NOT LESS THAN 15%.

FILL SUBGRADES: USE MATERIAL IN THE TOP 150 MM WHICH HAS A MAXIMUM PARTICLE SIZE OF 75 MM.

CO-ORDINATE SYSTEM

MGA ZONE 56

HEIGHT DATUM

AHD

DESIGN VERIFIER C.WAITE

DESIGN MNGR | C.WAITE

PROJECT MNGR | C.WAITE

M.ARELLANO

DATE

31.03.22

31.03.22

31.03.22

31.03.22

31.03.22

31.03.22

31.03.22

Sydney Motorway

ACCEPTED FOR CONSTRUCTION

M4M5-RBGP-PRW- CIV -CW02-DRG- 1100

M4-M5 LINK MAIN TUNNEL WORKS


PROJECT WIDE CONSTRUCTION SITE REINSTATEMENT


NORTHCOTE WestConnex TEMPORARY WORKS DRAWINGS REFERENCE LIST & GENERAL NOTES


RMS REGISTRATION No. ISSUE STATUS SHEET No. ISSUED FOR CONSTRUCTION


CW02-DRG-1100 © Roads and Maritime Services


PRAWING FILE LOCATION \ NAME - PLOT DATE \ TIME -	PLOT	BY			DESIGN PACKAGE CODE	DRAWINGS / DESIG			TITLE	NAME
::\Users\chris.waite\Documents\WCX\Drawings\NORTHCOTE\M4M5-RBGP-PRW-CIV-CW02-DRG-1100.d	dwg-27/06	5/2022 3:53:39 AM-	Chris. Waite		M4M5-RBGP-PRW-CIV-CW02-DPK-0001	WestC	onnex M4-M	15 Link Tunnels	11122	TV WIL
DESIGN MODEL FILE(S) USED FOR DOCUMENTATION OF THIS DRAWING	REV	DATE	AMENDMENT / REVISION DESCRIPTION	APPROVAL	SCALES ON THIS A3 SIZE DRAWING					M.ARELLA
	00	27.05.22	ISSUED FOR CONSTRUCTION	C.WAITE		☆ .	SAMSUNG	BOUYGUES	DRG CHECK	J.SUN
						acciona		CONSTRUCTION	DESIGN	J.SUN
							SAMSUNG C&T	AUSTRALIA	DESIGN CHECK	J.SUN
									DESIGN VERIFIER	C WAITE















00 27.06.22 ISSUED FOR CONSTRUCTION

1.6m



ISOLATION JOINT (IJ) DETAIL SCALE 1:20

DRAWINGS / DESIGN PREPARED BY

WestConnex M4-M5 Link Tunnels

acciona

TITLE

DRG CHECK

DESIGN CHECK J.SUN

DESIGN VERIFIER | C.WAITE

DESIGN MNGR | C.WAITE

PROJECT MNGR | C.WAITE

DESIGN

M.ARELLANO

J.SUN

DATE

31.03.22

31.03.22

31.03.22

31.03.22

31.03.22

31.03.22

31.03.22

Sydney Motorway

DESIGN PACKAGE CODE

CO-ORDINATE SYSTEM

MGA ZONE 56

APPROVAL

C.WAITE

SCALES ON THIS A3 SIZE DRAWING

M4M5-RBGP-PRW-CIV-CW02-DPK-0001

HEIGHT DATUM

AHD

ACCEPTED FOR CONSTRUCTION

M4M5-RBGP-PRW- CIV -CW02-DRG-1115

M4-M5 LINK MAIN TUNNEL WORKS

PROJECT WIDE


ISSUED FOR CONSTRUCTION

CONSTRUCTION SITE REINSTATEMENT NORTHCOTE

WestConnex CIVIL DETAILS SHEET 1 OF 1 RMS REGISTRATION No. ISSUE STATUS

CW02-DRG-1115 © Roads and Maritime Services


SHEET No.





NORTHCOTE STREET CONSTRUCTION ACCESS BACKFILL AND STUB WALLS

PACKAGE: M4M5-PSML-NCS-STR-IS22-DPK-0001



ACCEPTED FOR CONSTRUCTION

M4M5-PSML- NCS - STR - IS22 - DRG - 1000

M4-M5 LINK MAIN TUNNEL WORKS NORTHCOTE STREET

CONSTRUCTION ACCESS BACKFILL AND STUB WALL

COVER SHEET

SSUED FOR CONSTRUCTION

SSUE STATUS

IS22-1000 00

C:\PSM3635 - M4_M5\M4M5-PSML-NCS-STR-IS22-DRG-1000.dwg 9/04/2020 4:34:05 PM ESIGN MODEL FILE(S) USED FOR DOCUMENTATION OF THIS DRAWING REV DATE AMENDMENT / REVISION DESCRIPTION SCALES ON A3 SIZE DRAWING HEIGHT DATUM

DRAWN

DRG CHECK

PKG OWNER

DESIGN CHECK RB DESIGN MNGR TRN

C:\PSM3635 - M4_M5\M4M5-PSML-NCS-STR-IS22-DRG-1001.dwg DESIGN MODEL FILE(S) USED FOR DOCUMENTATION OF THIS DRAWING REV DATE AMENDMENT / REVISION DESCRIPTION

- PLOT DATE \ TIME

9/04/2020 5:06:25 PM

ISSUED FOR CONSTRUCTION

APPROVAL SCALES ON A3 SIZE DRAWING

CO-ORDINATE SYSTEM MGA ZONE 56

HEIGHT DATUM

AHD

DRAWING NUMBER	DRAWING TITLE

M4M5-PSML-NCS-STR-IS22-DRG-1000 COVER SHEET M4M5-PSML-NCS-STR-IS22-DRG-1001 DRAWING SCHEDULE M4M5-PSML-NCS-STR-IS22-DRG-1005 GENERAL NOTES M4M5-PSML-NCS-STR-IS22-DRG-1010 GENERAL ARRANGEMENT

TUNNEL REQUIREMENTS PRIOR TO BACKFILL M4M5-PSML-NCS-STR-IS22-DRG-1020

M4M5-PSML-NCS-STR-IS22-DRG-1025 VT05 TURNING BAYS BACKFILL SECTION M4M5-PSML-NCS-STR-IS22-DRG-1026 TT02 BACKFILL SECTION M4M5-PSML-NCS-STR-IS22-DRG-1027 EXISTING NORTHCOTE DECLINE (M131) - DECLINE TUNNEL BACKFILL

M4M5-PSML-NCS-STR-IS22-DRG-1028 TEMPORARY ADIT (TD02) - DECLINE TUNNEL BACKFILL

M4M5-PSML-NCS-STR-IS22-DRG-1030 BACKFILL BULKHEAD DETAILS M4M5-PSML-NCS-STR-IS22-DRG-1031 BULKHEAD CROWN SHEAR KEY DETAILS

M4M5-PSML-NCS-STR-IS22-DRG-1035 TURNING BAY & SUBSTATION NICHE BACKFILL SEQUENCE

M4M5-PSML-NCS-STR-IS22-DRG-1040 SITE ACCESS RAMP BACKFILL

M4M5-PSML-NCS-STR-IS22-DRG-1041 SITE ACCESS RAMP STRUT REMOVAL SEQUENCE

ACCEPTED FOR CONSTRUCTION

M4M5-PSML- NCS - STR - IS22 - DRG - 1001

M4-M5 LINK MAIN TUNNEL WORKS A3

NORTHCOTE STREET

CONSTRUCTION ACCESS BACKFILL AND STUB WALL

DRAWING SCHEDULE

RMS REGISTRATION No. ISSUE STATUS

TITLE	NAME
DRAWN	NM
DRG CHECK	YB
DESIGN	TRN
PKG OWNER	TRN
DESIGN CHECK	RB
DESIGN MNGR	TRN
PROJECT MNGR	TRN

11/03/202 11/03/2020 11/03/202

SHEET No. REV 00 ISSUED FOR CONSTRUCTION

CONSTRUCTION ACCESS ADIT AND DECLINE BACKFILL

- PRIOR TO BACKFILLING REMOVE ALL ITEMS FROM THE TUNNEL AND DECLINE SUCH AS MOBILE EQUIPMENT, LIQUIDS, MOBILE TRAFFIC BARRIERS AND SOME TUNNEL CONSTRUCTION SERVICES ETC AS SHOWN ON THE DRAWINGS.
- BACKFILL SHALL COMPRISE EITHER IMPORTED OR REUSED EXCAVATED
- REUSED EXCAVATED MATERIAL SHALL COMPRISE FRESH TUNNEL SPOIL WON FROM ROADHEADER OR SURFACE MINER OPERATIONS (HEADING OR BENCHING). DESIGN APPROVAL IS REQUIRED IF MATERIAL OTHER THAN TUNNEL SPOIL IS USED AS BACKFILL. SANDSTONE WON FROM EXCAVATION BY HYDRAULIC ROCK BREAKING SHALL NOT BE USED AS BACKFILL UNLESS PROCESSED TO CONFORM TO TABLE B5.
- BACKFILL SHALL NOT COMPRISE UNSUITABLE MATERIAL AS DEFINED IN AS DEFINED BY CLAUSE 4.3 OF AS3798-2007 'GUIDELINES ON EARTHWORKS FOR COMMERCIAL AND RESIDENTIAL DEVELOPMENTS'
- MATERIAL PROPERTIES FOR BACKFILL MUST COMPLY WITH THE FOLLOWING TABLE. TESTING TO CONFIRM MATERIAL COMPLIANCE SHALL BE IN ACCORDANCE WITH NOTES BF7.

PROPERTY	TEST METHODS	REQUIREMENT
MAXIMUM PARTICLE DIMENSION WITHIN 1000 OF SURFACE	RMS T280	100
MAXIMUM PARTICLE DIMENSION GREATER THAN 1000 FROM SURFACE	RMS T280	200
MATERIAL PASSING 37.5 mm AS SIEVE	RMS T106	MAX 40%
PLASTICITY INDEX	RMS T108 AND T109	≤25%

COMPACTION AND CONDITIONING SHALL CONFORM TO THE FOLLOWING TABLE.

PROPERTY	TEST METHODS	REQUIREMENT
MAXIMUM COMPACTED LAYER THICKNESS WITHIN 4000 OF THE BULKHEAD	N/A	150
MAXIMUM COMPACTED LAYER THICKNESS >4000 OF BULKHEAD	N/A	300
DENSITY RATIO OR HILF DENSITY RATIO (STANDARD)	AS1289.5.4.1, AS1289.5.7.1, AS1289.5.3.1, AS1289.5.8.1	>95%
MOISTURE CONTENT OF THE BACKFILL MATERIAL AT THE TIME OF PLACING	AS1289.2.1.1	OMC +3%

B7. BACKFILL MUST NOT BE PLACED AGAINST CONCRETE MEMBERS UNTIL THEY ACHIEVE THE STRENGTH SPECIFIED IN THE TABLE BELOW.

MEMBER	MINIMUM COMPRESSIVE STRENGTH PRIOR TO BACKFILLING (MPa)
BULKHEAD CONCRETE	N40
MASS CONCRETE PLUG OR BACKFILL	10
FLOWABLE FILL PLUG	1

- CONCRETE MIX FOR MASS CONCRETE PLUG SHALL BE SHRINKAGE COMPENSATED.
- VIBRATING ROLLERS OF MASS EXCEEDING ONE TONNE, OR ANY OTHER EQUIPMENT THAT MAY POTENTIALLY CAUSE DAMAGE TO THE BULKHEAD, ARE NOT TO BE USED TO COMPACT BACKFILL WITHIN 2000 HORIZONTALLY OF THE
- BACKFILL MATERIAL NOT COMPLYING WITH THE NOTES ON THIS DRAWING MUST BE SUBMITTED TO THE DESIGNER FOR APPROVAL.
- CONTAMINATED MATERIAL MUST NOT BE USED FOR BACKFILLING.
- IF MATERIAL OTHER THAN SANDSTONE TUNNEL SPOIL IS USED FOR BACKFILL (I.E. IMPORTED MATERIAL), IT SHALL CONFORM TO RMS B30 CLAUSE 6.2.2 CHEMICAL PROPERTIES AS WELL AS ALL OTHER MATERIAL CRITERIA SET OUT IN

BACKFILL INSPECTION, TESTING & SURVEY

- BF1. THE FREQUENCY OF COMPACTION TESTING SHALL NOT BE LESS THAN THE GREATER OF:
 - i. TEST PER 150 m³ OF MATERIAL PLACED.
 - ii. 2 TESTS PER LAYER.
- BF2. A LAYER SHALL BE DEEMED TO BE IN ACCORDANCE WITH THE SPECIFICATION IF ALL THE TESTS UNDERTAKEN WITHIN THE LAYER ARE IN ACCORDANCE WITH THE SPECIFICATION, I.E. ON A 'NONE TO FAIL' BASIS.
- IF ANY ONE TEST UNDERTAKEN WITHIN A LAYER FAILS, AN APPROPRIATE COURSE OF ACTION (I.E. REWORK AND/OR RETEST) TO BE DETERMINED/AGREED BY CONSTRUCTION TEAM AND DESIGNER
- THE LOCATION OF FIELD DENSITY TESTS SHALL BE RECORDED BY THE CONTRACTOR AND SHOWN ON A PLAN TO AN ACCURACY OF AT LEAST +/-5000 IN PLAN, AND THE ELEVATION SHALL BE SURVEYED TO AN ACCURACY OF +/-100.
- TESTING LOCATIONS SHALL OCCUR OVER THE FULL WIDTH OF THE COMPACTED LOT, NOT ONLY THE CENTRE OF THE TUNNEL.
- THE CONTRACTOR SHALL PRODUCE AT COMPLETION OF FILLING A REPORT PRESENTING THE RESULTS AND LOCATION OF COMPACTION TESTING.
- THE MINIMUM FREQUENCY OF TESTING TO ASSESS CONFORMITY TO THE ITEMS IN TABLE B5 FOR TUNNEL SPOIL SHALL BE AS FOLLOWS:
 - i PRIOR TO FIRST USE
 - ii. EVERY 5000 m³ AFTER FIRST USE.
 - iii. IF THE SOURCE OF THE MATERIAL CHANGES.

FLOWABLE FILL

- F1. SHALL MEET THE FOLLOWING SPECIFICATIONS:
 - i. 28-DAY COMPRESSIVE STRENGTH: fc = 1.0 MPa MIN
 - ii. UNIT WEIGHT: 22 kN/m3 MIN
 - iii. SLUMP: 175 mm MIN
 - iv. BLEED: 5% MAX
- F2. SHALL BE TESTED WITH THE FOLLOWING TEST PROCEDURES AND FREQUENCY:
 - i. UNIT WEIGHT: TO BE TESTED EVERY 150 m3 OR MIX CHANGE ACCORDING TO ASTM 1012 - STANDARD TEST METHOD FOR UNIT WEIGHT, YIELD AND AIR CONTENT (GRAVIMETRIC) OF CONTROLLED LOW STRENGTH MATERIAL
 - ii SLUMP: TO BE TESTED EVERY 150 m3 OR MIX CHANGE ACCORDING TO 1012 3
 - iii. $\,$ BLEED: TO BE TESTED AFTER 2 HOURS, ONE TEST PER SHIFT FOR EACH MIX $\,$ USED ACCORDING TO AS1012.6.
- HEIGHT OF FLOWABLE FILL TOTAL THICKNESS PER CONTRACTOR RECHIREMENTS
- F4 MAXIMUM FLOWABLE FILL LIFT HEIGHT IS 2000.
- THE CONTRACTOR MUST STAGE AND PLACE FLOWABLE FILL IN A MANNER THAT ENSURES COMPLETE ENCAPSULATION OF THE VOID.

FLOWABLE FILL HOLD POINT SCHEDULE				
PROCESS HELD	SUBMISSION DETAILS/RELEASE CRITERIA	RELEASE BY		
PLACEMENT OF FLOWABLE FILL	A WORK METHOD STATEMENT AND APPROPRIATE ITP THAT DETAILS: - STAGING AND METHODOLOGY FOR PLACING FLOWABLE FILL IN A MANNER THAT ENSURES COMPLETE ENCAPSULATION OF THE VOID; AND WITH - AN APPROPRIATE METHOD FOR DEMONSTRATING THAT THE ANNULUS BETWEEN FLOWABLE FILL AND ROCK HAS BEEN COMPLETELY FILLED ALONG THE LENGTH OF THE TUNNEL AND IF A VOID IS FOUND A METHOD OF FILLING THE VOIDS AFTER THE FLOWABLE FILL HAS BEEN PLACED.	IC		

HARDSTAND

H1. HARDSTAND MATERIAL TO BE DGB20 OR APPROVED EQUIVALENT FORMING AN ALL-WEATHER, HEAVY-DUTY CONSTRUCTION GRADE SURFACE.

DRAINAGE PIPES

- SIZED FOR PEAK GROUNDWATER INFLOWS PREDICTED AT THE DECLINE
- TO BE PLACED 100 ABOVE THE TOP OF ADJACENT INVERT TO DISCHARGE IN THE TUNNEL DRAINAGE SYSTEM.
- CONTRACTOR IS RESPONSIBLE FOR ENSURING INTEGRITY OF THE PIPE IS MAINTAINED THROUGHOUT CONSTRUCTION.
- PERFORATED PIPES AND FITTINGS MUST COMPLY WITH RMS M4 EAST D&C
- PIPES CAST INTO CONCRETE BULKHEAD SHALL BE SUITABLY RESTRAINED TO PREVENT FLOTATION OF THE PIPES DURING PLACEMENT.

- SHALL BE CLASSIFIED AS "DRAINAGE ZONE MATERIAL" IN ACCORDANCE WITH TABLE B30.4 TO RMS SPECIFICATION B30: EXCAVATION AND BACKFILL FOR
- TO BE PLACED LOOSE AND ACCORDING TO THE MINIMUM DIMENSIONS AS SHOWN ON THE DRAWINGS.
- CONTRACTOR SHALL ENSURE INTEGRITY OF ROCK FILL DURING COMPACTION OF OVERLYING BACKFILL. USE LIGHTWEIGHT / HAND HELD COMPACTION EQUIPMENT FOR THE FIRST TWO LIFTS ABOVE THE ROCK FILL.

GEOTEXTILE AND GEOGRID

- SUPPLY AND PLACEMENT OF THE GEOTEXTILE AND GEOGRID WILL BE IN ACCORDANCE WITH RMS R63 AND RMS R67 RESPECTIVELY.
- GEOTEXTILE MATERIAL SHALL CONFORM TO RMS 63 GEOTEXTILES:
 - i. GEOTEXTILE STRENGTH CLASS E
 - ii. GEOTEXTILE FILTRATION CLASS I PER TABLE R63/E.1.
- GEOGRID IS INTENDED TO PROVIDE ADDITIONAL PROTECTION AGAINSTPUNCTURE OF GEOTEXTILE FILTER DURING CONSTRUCTION.
- CONTRACTOR IS RESPONSIBLE FOR ENSURING INTEGRITY OF THE GEOTEXTILE IS MAINTAINED THROUGHOUT CONSTRUCTION. IF RUPTURE FROM THE UNDERLYING DRAINAGE LAYER IS OBSERVED, THE GEOTEXTILE SHALL BEREPLACED OR ADDITIONAL LAYERS SHALL BE PLACED.
- MAXIMUM GRID SPACING ON GEOGRID SHALL NOT EXCEED 60% OF THE TYPICAL LARGEST DIMENSION OF DRAINAGE LAYER ROCK

BULKHEAD CONCRETE

- ALL WORKMANSHIP AND MATERIALS SHALL BE IN ACCORDANCE WITH AS5100, AS 3610 AND OTHER RELEVANT AUSTRALIAN STANDARDS.
- CONCRETE SHALL COMPLY WITH THE REQUIREMENTS OF AS 1379
- UNLESS NOTED OTHERWISE CONCRETE SHALL HAVE A MAXIMUM AGGREGATE SIZE OF 20mm AND A STRENGTH GRADE AS TABULATED RFLOWIINO

ELEMENT	STRENGTH GRADE - AS 5100-5
CONCRETE BULKHEAD AND BULKHEAD PLATFORM	N40

- PROJECT ASSESSMENT OF CONCRETE STRENGTH IS NOT REQUIRED. EXCEPT IF THE STRUCTURE IS TO BE LOADED PRIOR TO 28 DAYS AFTER CONCRETE PLACEMENT
- ALL CONCRETE SHALL BE MECHANICALLY VIBRATED IN THE FORM TO GIVE MAXIMUM COMPACTION WITHOUT SEGREGATION OF THE CONCRETE. SELF COMPACTING CONCRETE MIX SHALL BE USED WHEN MECHANICAL VIBRATION IS NOT ACHIEVABLE.
- LOCATION AND DETAILS OF CONSTRUCTION JOINTS SHALL BE TO DETAILS APPROVED BY THE DESIGNER.
- HOLES, CHASES OR PIPES OTHER THAN THOSE SHOWN ON THE STRUCTURAL DRAWINGS SHALL NOT BE PLACED IN CONCRETE MEMBERS WITHOUT PRIOR APPROVAL OF THE DESIGNER.
- PLACE CONCRETE WITH EQUIPMENT AND FROM A HEIGHT THAT ENSURES THAT SEGREGATION OF THE CONCRETE CANNOT OCCUR.
- TO PREVENT EARLY AGE THERMAL CRACKING, ADOPT A CONCRETE MIX THAT LIMITS THE TEMPERATURE DIFFERENCE BETWEEN THE SURFACE AND INTERIOR OF THE BULKHEAD TO LESS THAN 25 DEGREES.
- RESTRICT THE EVAPORATION OF WATER FROM THE CONCRETE SURFACE AND PREVENT PLASTIC SHRINKAGE.
- CONCRETE SHALL NOT BE PLACED WHEN THE AIR TEMPERATURE IN THE SHADE IS BELOW 5°C OR ABOVE 38°C

	CONCRETE HOLD POINT SCHEDULE					
	PROCESS HELD	SUBMISSION DETAILS/RELEASE CRITERIA	RELEASE BY			
	PLACING CONCRETE	CERTIFICATION THAT THE FOLLOWING HAVE BEEN CHECKED AND ARE IN ACCORDANCE WITH THE DRAWINGS: - SET OUT - MEMBER DIMENSIONS - REINFORCEMENT - CONCRETE COVER - SURFACE PREPARATION	SITE ENGINEER			

METHOD TO RESTRICT WATER EVAPORATION AND PREVENT SITE ENGINEER CONCRETE PLASTIC CRACKING. CURING DETAILS BULKHEAD STRENGTH TESTED - DRAINAGE SYSTEM IN PLACE PLACING. SITE ENGINEER BACKFILL AND SURVEYED BULKHEAD MONITORING REVIEWED BACKFILL SURFACE SURVEYED **PLACING** BREATHER TUBES IN PLACE FLOWABLE SITE ENGINEER AND SURVEYED BULKHEAD MONITORING REVIEWED

CONSTRUCTION JOINT (BULKHEAD CONCRETE)

- CONSTRUCTION JOINTS SHALL COMPLY WITH RMS B80.
- THE LOCATION AND DETAILS OF CONSTRUCTION JOINTS SHALL BE AS SHOWN ON THE DRAWINGS.
- THE PLACING OF CONCRETE SHALL PROCEED CONTINUOUSLY FROM JOINT TO JOINT. ANY POINT AT WHICH THE PLACING OF CONCRETE HAS STOPPED AND THE CONCRETE HAS TAKEN ITS INITIAL SET SHALL BE TREATED AS A CONSTRUCTION JOINT.
- BEFORE PLACING NEW CONCRETE AGAINST CONCRETE WHICH HAS SET, THE FORMS (WHERE APPLICABLE) SHALL BE RETIGHTENED.
- CONCRETE AGAINST WHICH NEW CONCRETE IS TO BE PLACED SHALL BE ROUGHENED BY REMOVING ALL LAITANCE AND SUFFICIENT MORTAR TO EXPOSE THE COARSE AGGREGATE TO A DEPTH OF 3 mm. THE ROUGHENED SURFACE SHALL BE CLEANED OF FOREIGN MATTER LAITANCE AND LOOSE OR POROUS MATERIAL. THE SURFACE SHALL BE THOROUGHLY MOISTENED WITH WATER AND ANY EXCESS WATER REMOVED IMMEDIATELY PRIOR TO PLACING OF CONCRETE.

MONITORING

- MONITORING OF THE BULKHEAD IS REQUIRED TO PROVIDE A MEANS OF ASSESSING THE PERFORMANCE OF THE BULKHEAD DURING AND AFTER PLACEMENT OF BACKFILL / FLOWABLE FILL.
- MONITORING SHALL COMPRISE A MIN OF TWO OPTICAL TARGETS PLACED ON THE OUTSIDE OF THE BULKHEAD AND BASELINED PRIOR TO BACKFILLING AGAINST THE BULKHEAD.
- DESIGNER TO BE NOTIFIED IF TOTAL HORIZONTAL MOVEMENT INTO THE VOID (VENT TUNNELS) EXCEEDS 10 MM.

ITEMS TO BE REMOVED

- 11. PRIOR TO BACKFILLING ADITS AND DECLINES REMOVE THE FOLLOWING:
- i. CONCRETE BARRIERS
- ii. ALL FLUIDS
- iii. VENTILATION INFRASTRUCTURE (REFER NOTE 16)
- iv. ALL MACHINERY
- v. TUNNEL CONSTRUCTION CONDUITS FOR SERVICES UNLESS USED TO TREMIE FLOWABLE FILL / CONCRETE (IE MUST BE FULLLY FILLED WITH CEMENTITIOUS MATERIAL)
- ALL TUNNEL SUPPORT SHALL REMAIN IN PLACE FOR BACKFILLING.
- CARE MUST BE TAKEN NOT TO DAMAGE TUNNEL SUPPORT (BOLT HEADS, MESH, SHOTCRETE) DURING BACKFILLING OPERATIONS. ANY ROCK BOLTS DAMAGED DURING BACKFILLING SHALL BE REPAIRED.
- INVERT SLAB SHALL REMAIN IN PLACE.
- ALL MONITORING INCLUDING ENDOSCOPE HOLES SHALL BE DECOMMISSIONED & REMOVED/GROUTED PRIOR TO BACKFILLING.
- STEEL VENTILATION CANS AND ASSOCIATED METALLIC SUPPORTS (CHINAS, ANCHORS ETC) MAY BE LEFT IN THE ZONE OF FLOWABLE FILL. IF KEPT IN PLACE, THEY MUST BE FULLY ENCAPSULATED IN THE FLOWABLE FILL AND A WORK METHOD ESTABLISHED TO PREVENT VOIDS FORMING (METHOD TO BE REVIEWED BY THE DESIGNER).

ACCEPTED FOR CONSTRUCTION

M4M5-PSML- NCS - STR - IS22 - DRG - 1005


M4-M5 LINK MAIN TUNNEL WORKS

NORTHCOTE STREET CONSTRUCTION ACCESS BACKFILL AND STUB WALL

GENERAL NOTES RMS REGISTRATION No


ISSUE STATUS

SSUED FOR CONSTRUCTION IS22-1005 00



NAME DATE DRAWN DRG CHECK YB PKG OWNER 1/03/202 TRN DESIGN CHECK RB 1/03/202 DESIGN MNGR TRN 1/03/202 PROJECT MNGR TRN


© Roads and Maritime Services



© Roads and Maritime Services

NOTES:

- TUNNEL SUPPORT NOT SHOWN FOR CLARITY.
- REFER TO M4M5-PSML-NCS-STR-IS22-DRG-1020 FOR TUNNEL ITEMS TO BE REMOVED PRIOR TO BACKFILLING.



ACCEPTED FOR CONSTRUCTION

M4M5-PSML- NCS - STR - IS22 - DRG - 1025

M4-M5 LINK MAIN TUNNEL WORKS

NORTHCOTE STREET CONSTRUCTION ACCESS BACKFILL AND STUB WALL

TEMPORARY ADIT VT05 TURNING BAY BACKFILL SECTIONS


RMS REGISTRATION No. ISSUE STATUS SHEET No. 1S22-1025 00 ISSUED FOR CONSTRUCTION


© Roads and Maritime Services


ร							
_	DRAWING FILE LOCATION \ NAME - PLOT DATE \ TIME -	PLO	ГВҮ			DESIGN LOT CODE	ſ
Ý	C:\PSM3635 - M4_M5\M4M5-PSML-NCS-STR-IS22-DRG-1025.dwg -			ĺ			
2	DESIGN MODEL FILE(S) USED FOR DOCUMENTATION OF THIS DRAWING	REV	DATE	AMENDMENT / REVISION DESCRIPTION	APPROVAL	SCALES ON A3 SIZE DRAWING	İ
_	-	00	09/04/2020	ISSUED FOR CONSTRUCTION	TRN		İ
2	-						ĺ
	-						ĺ
2	- -						İ
	-						İ
>	-					CO-ORDINATE SYSTEM HEIGHT DATUM	İ
>	-					MGA ZONE 56 AHD	ĺ

DRAWN DRG CHECK YB PKG OWNER TRN DESIGN CHECK RB DESIGN MNGR TRN 11/03/2020

11/03/2020







- PLOT DATE \ TIME C:\PSM3635 - M4_M5\M4M5-PSML-NCS-STR-IS22-DRG-1031.dwg 9/04/2020 5:15:59 PM DESIGN MODEL FILE(S) USED FOR DOCUMENTATION OF THIS DRAWING REV DATE AMENDMENT / REVISION DESCRIPTION SCALES ON A3 SIZE DRAWING APPROVAL SSUED FOR CONSTRUCTION HEIGHT DATUM CO-ORDINATE SYSTEM MGA ZONE 56 AHD

REFER DRAWING M4M5-PSML-NCS-STR-IS22-DRG-1030 FOR SHEARKEY SPACING

OPTION 1

PERMANENT TYPE B ROCK BOLT

TUNNEL CROWN

TUNNEL E-LINE -

TUNNEL CROWN A LINE

CORRUGATED

POLYETHELYNE SHEATHING -

TYPE B ROCKBOLT

BULKHEAD

BOLT HEAD


REMOVED

EXPOSED BAR EMBEDDED IN CONCRETE BULKHEAD

FULLY GROUTED

(NOTES 1 & 2)





NORTHCOTE STREET

NOTES:

1. BOLT/BAR TO BE FULLY ENCAPSULATED.

3. MIN 500 MPa YIELD STRENGTH.

2. BOLTS/BARS TO BE INSTALLED ALONG CENTRELINE OF BULKHEAD. FOR SPACING REQUIREMENTS REFER TABLE 1 ON M4M5-PSML-NCS-STR-IS22-DRG-1030. BOLTS/BARS TO AVOID CLASHING WITH INSTALLED TUNNEL BOLTS.


CONSTRUCTION ACCESS BACKFILL AND STUB WALL TEMPORARY ADIT
BULKHEAD CROWN SHEAR KEY DETAILS

RMS REGISTRATION No.

ISSUE STATUS

ISSUED FOR CONSTRUCTION

SHEET No. 1S22-1031 REV 00 © Roads and Maritime Services





OPTION 2 N24 STAINLESS STEEL BAR NTS

ACCEPTED FOR CONSTRUCTION

M4M5-PSML- NCS - STR - IS22 - DRG - 1031

M4-M5 LINK MAIN TUNNEL WORKS





- PLOT DATE \ TIME

9/04/2020 5:17:30 PM

ISSUED FOR CONSTRUCTION

DESIGN MODEL FILE(S) USED FOR DOCUMENTATION OF THIS DRAWING REV DATE AMENDMENT / REVISION DESCRIPTION


C:\PSM3635 - M4_M5\M4M5-PSML-NCS-STR-IS22-DRG-1041.dwg

NOTES:

- FOR BACKFILL AND LANDSCAPING MATERIAL SPECIFICATIONS REFER TO DRAWING M4M5-PSML-NCS-STR-IS22-DRG-1002.
- TEMPORARY CONCRETE ELEMENTS WITHIN A DISTANCE OF 1 m BELOW THE AGREED FINAL SURFACE LEVEL WILL BE REMOVED. THE EXTENT OF SLAB AND SUBSURFACE BUILT ELEMENTS TO BE REMOVED AT THE END OF THE PROJECT WILL BE SEPARATELY CONSULTED, DISCUSSED AND AGREED WITH WCX/TfNSW WITH THE ACTUAL EXTENT TO BE RECORDED IN WAE DRAWINGS.

LEGEND:





STAGE 1:

1 BACKFILL TO 3000 UNDERSIDE OF STRUT.
BACKFILL MATERIAL AND COMPACTION SHALL BE
AS PER DETAILS ON
M4M5-PSML-NCS-STR-IS22-DRG-1005.

STAGE 2:

APPROVAL SCALES ON A3 SIZE DRAWING

CO-ORDINATE SYSTEM MGA ZONE 56

HEIGHT DATUM

AHD

- ② REMOVE STRUT.
- ③ DEMOLISH CONCRETE MEMBERS (NOTE 2).

DRG CHECK

PKG OWNER TRN DESIGN CHECK RB

DESIGN MNGR TRN

PROJECT MNGR TRN

YB

11/03/202

11/03/202

STAGE 3:

- 4 PLACE BACKFILL TO WITHIN 100 OF FSL.
- 5 TOP WITH 100 HARDSTAND MATERIAL.

NORTHCOTE DECLINE STRUT REMOVAL SEQUENCE SCALE 1:200

ACCEPTED FOR CONSTRUCTION

M4M5-PSML- NCS - STR - IS22 - DRG - 1041

M4-M5 LINK MAIN TUNNEL WORKS

NORTHCOTE STREET CONSTRUCTION ACCESS BACKFILL AND STUB WALL

SITE ACCESS RAMP STRUT REMOVAL SEQUENCE

DECLINE

RMS REGISTRATION No. SHEET No. REV 00 ISSUE STATUS ISSUED FOR CONSTRUCTION

© Roads and Maritime Services

Site Audit Report 278_Northcote
WestConnex Stage 3A Northcote Compound
Area C3a

IAN SWANE & ASSOCIATES

Appendix C. Site Audit Correspondence

SAR 278_Northcote PAGE 110

IAN SWANE & ASSOCIATES P/L

PO Box 359, MORTDALE NSW 2223

Mob: +61 0418 867 112 Email: iswane@bigpond.com

Lendlease Samsung Bouygues Joint Venture WestConnex M4-M5 Link Tunnels Level 7, 189 O'Riordan Street PO Box 63 MASCOT NSW 1460

Attention: - Senior Environmental Coordinator

26/11/2018 IS&A_181126_Interim advice#19 2018_WestConnexStage 3A

Dear

INTERIM ADVICE #19 FOR STATUTORY SITE AUDIT No. 278 BY DR IAN SWANE BASIS FOR SITE AUDIT WORK ON WESTCONNEX STAGE 3A PROJECT

1. Introduction

This letter provides the Lendlease Samsung Bouygues Joint Venture (LSB_JV) with interim advice as part of Statutory Site Audit No. 278 being undertaken by Dr Ian Swane, a NSW EPA Site Auditor accredited under the Contaminated Land Management (CLM) Act. The advice forms part of a statutory site audit for the WestConnex Stage 3A Project (the 'Project').

The purpose of this interim advice is to document the Site Auditor's understanding of the basis for site audit work to be undertaken for the LSB_JV on the Project and the outcomes that the site audit work will need to achieve. This advice should assist the identification of the site audit matters that the LSB_JV will need to meet under their contract with the NSW Government, and identify other site audit matters that may need to be met separately by the NSW Government.

The Site Auditor considers this interim advice is required at this early stage of the Project because statutory site audits can have different objectives, as indicated by the range of options given on the NSW EPA site audit statement proforma, with the objectives required by the LSB_JV being possibly different from those of the NSW Government. The advice provided herein is also limited to site contamination issues and does address any planning or legal matters, which are outside the expertise of the Site Auditor.

This interim advice is considered to be consistent with NSW EPA guidelines and policy and does not preempt conclusions to be drawn at the end of the site audit process. This interim advice does not represent a site audit statement (SAS) or a site audit report (SAR). It is intended that a SAS / SAR will be prepared towards the end of the Project for each part of the Project site where the ground surface is disturbed by construction work undertaken by the LSB_JV.

2. Assumptions

The following assumptions have been made for the purpose of this interim advice and site audit work to be undertaken for the LSB_JV:

- The Department of Planning issued Planning Consent SSI 7485 for the Project on 17/04/18 ('Planning Consent'). The proponent for the Project is Roads and Maritime Services (RMS) from the NSW Government.
- On or about June 2018, the LSB_JV was awarded a contract with the NSW Government to deliver most of the work required by the Project as described in the Planning Consent. Some work required by the Planning Consent may be outside the scope of work to be undertaken by the LSB_JV.

LENDLEASE SAMSUNG BOUYGUES JOINT VENTURE SITE AUDITOR INTERIM ADVICE #19 – BASIS FOR SITE AUDIT WORK WESTCONNEX STAGE 3A PROJECT – SITE AUDIT 278 26/11/2018

IAN SWANE & ASSOCIATES P/L

- 3. With regards to site contamination, the LSB JV is understood to be responsible for:
 - Complying with NSW Government environmental legislation regarding contaminated site and waste management;
 - b) Managing contamination it interferes or disturbs during the course of carrying out its work;
 - c) Not generating contamination at the Project site or generating contamination that may cause an increase in contamination migrating from the Project site; and
 - d) Complying with Environmental Protection Licence 21149.
- 4. With regards to site contamination, the LSB_JV is understood NOT to be responsible for engaging the Site Auditor to determine whether:
 - Any part of the Project site has been remediated and is suitable for a specified use other than as a road construction worksite; and
 - b) Contamination that existed at the Project site prior to the commencement of the Project continues to migrate off-site.
- 5. The Site Auditor engaged by the LSB_JV is understood to be responsible for:
 - a) Reviewing site environmental management plans that deal with contamination at the Project site and whether these plans meet Condition C22 of the Planning Consent.
 - b) Reviewing contamination assessments for the Project site and whether they meet Condition E181 of the Planning Consent.
 - c) Reviewing waste classifications and documentation on the management of waste removed from the Project site¹.
 - d) Reviewing reports on the management of contamination at the Project site throughout the period construction activities are undertaken by the LSB_JV and to determine whether:
 - i. No additional contamination was generated by the construction work;
 - ii. The land was maintained in a condition suitable for a road construction worksite and compliance was achieved with Conditions E182 to E185 of the Planning Consent;
 - iii. Waste generated by construction activities at the Project site was managed in accordance with NSW EPA guidance and Conditions E202 to E204 of the Planning Consent; and
 - iv. The requirements of Conditions O5.10 and O5.11 of EPL 21149 were met.
 - e) Notifying the LSB_JV, RMS and the NSW EPA if the Site Auditor concludes that a part of the Project site should be notified to the EPA under the CLM Act².
 - f) Issuing a Section A1 SAS for each part of the Project site where the ground surface is disturbed by construction work undertaken by the LSB_JV. Each SAS is to be issued at the completion of LSB_JV sitework and needs to determine whether the land is suitable for a road construction worksite at the end of construction period and prior to landscaping by RMS. Each SAS also needs to determine whether:
 - The site auditor reviewed site environmental management plans that dealt with contamination at the site and considered the plans met Condition C22 of the Planning Consent;

¹ A requirement under Section 4.3.7, NSW EPA (October 2017) Site Auditor Guidelines

² A requirement under Sections 3.8.2, 4.3.11 & 4.3.12, NSW EPA (October 2017) Site Auditor Guidelines

LENDLEASE SAMSUNG BOUYGUES JOINT VENTURE SITE AUDITOR INTERIM ADVICE #19 – BASIS FOR SITE AUDIT WORK WESTCONNEX STAGE 3A PROJECT – SITE AUDIT 278 26/11/2018

IAN SWANE & ASSOCIATES P/L

- ii. The site auditor reviewed contamination assessments for the site and considered they met Condition E181 of the Planning Consent;
- iii. The site auditor reviewed reports on the management of contamination at the site throughout construction and considered that:
 - No additional contamination was generated by the construction work,
 - The land was maintained in a condition suitable for a road construction worksite and compliance was achieved with Conditions E182 to E185 of the Planning Consent;
 - Waste generated by construction activities at the site was managed in accordance with NSW EPA guidance and Conditions E202 to E204 of the Planning Consent; and
 - The requirements of Conditions O5.10 and O5.11 of EPL 21149 were met.
- 6. With regards to site contamination, the NSW Government is responsible for engaging the Site Auditor to:
 - a) Determine whether land within the Project site is suitable for a specified use other than as a road construction worksite at the end of construction and prior to landscaping by RMS;
 - b) Review documentation prepared by environmental consultants that determines whether contamination migrating from the Project site is posing an unacceptable risk to off-site receptors and needs to be remediated; and
 - Review work undertaken at the Project site in addition to that required by the NSW EPA under Conditions O5.10 and O5.11 of EPL 21149.

0 - 0 - 0

The Site Auditor requests that the LSB_JV confirms that the assumptions made in this interim advice letter are correct and that the assumptions form the basis for the site audit work to be undertaken for the LSB_JV and the outcomes that the site audit work need to achieve.

Yours sincerely

Dr Ian C Swane (CPEng & CEnvP) EPA Site Auditor NSW, WA & NT Director, Ian Swane & Associates

Phone: 0418 867 112 Email: <u>iswane@bigpond.com</u>

 $C: \label{localized-loca$

Site Audit Report 278_Northcote
WestConnex Stage 3A Northcote Compound
Area C3a

IAN SWANE & ASSOCIATES

Appendix D. Site Auditor Photographs

SAR 278_Northcote PAGE 111

Site Inspection 2 June 2021



Photo 1: Truck wash and eastern laydown area



Photo 2: Operation of truck washdown area

Site Inspection 4 November 2022



Photo 3: Truck washdown area waiting for demolition

IAN SWANE & ASSOCIATES











Photo 4: Eastern laydown area during decommissioning



Photo 5: Acoustic shed during decommissioning looking west to north

IAN SWANE & ASSOCIATES



Photo 6: Acoustic shed during decommissioning looking north to east



Photo 7: Western side of Northcote Compound Showing Demolition of Water Treatment Plant and Laydown Area

Site Audit Report 278_Northcote
WestConnex Stage 3A Northcote Compound
Area C3a

IAN SWANE & ASSOCIATES

Appendix E. Site Audit Statement and Interim Plan

SAR 278_Northcote PAGE 112



NSW Site Auditor Scheme

Site Audit Statement

A site audit statement summarises the findings of a site audit. For full details of the site auditor's findings, evaluations and conclusions, refer to the associated site audit report.

This form was approved under the *Contaminated Land Management Act 1997* on 12 October 2017.

For information about completing this form, go to Part IV.

Part I: Site audit identification

Site audit statement no. 278_Northcote

This site audit is a:

non-statutory audit

within the meaning of the Contaminated Land Management Act 1997.

Site auditor details

(As accredited under the Contaminated Land Management Act 1997)

Name	Dr Ian C Swane	
Company	Ian Swane & Associates	
Address	PO Box 359, Mortdale NSW	Postcode 2223
Phone	0418 867 112	
Email	iswane@bigpond.com	

Site details

Address	The Northcote Compound was part of the WestConnex Stage 3A Project undertaken by the Acciona Samsung Bouygues Joint Venture (refer Figures 1 & 2). The compound consisted of 12 parcels of land comprising: 249-251, 255, 257 and 269 Parramatta Road; 2-4 Wattle Street; part of Northcote Street; 1 and 3 Wolseley Street, 1, 2, 3 and 4 Northcote Street, Haberfield.	

Property description

Phone

Email

(Attach a separate list if several properties are included in the site audit.) - Refer Figure 3
Lots 63, 64, 114 & 115 in DP4612; Lots 1 & 2 in DP239458; Lots 51-54 in DP719977; Lots 56-58 in DP719977; part of Northcote Street; Lot 1 in DP933407; Lot 1 in DP933225; Lots A and B in DP391272
Local government area Inner West Council
Area of site (include units, e.g. hectares) 12,165 m² (1.22 ha)
Current zoning B6 – Enterprise corridor and R2 – Low density residential
Regulation and notification
To the best of my knowledge:
the site is the subject of a declaration, order, agreement, proposal or notice under the Contaminated Land Management Act 1997 or the Environmentally Hazardous Chemicals Act 1985, as follows: (provide the no. if applicable)
→ Declaration no.
□ Order no.
□ Proposal no.
□ Notice no.
★ The site is not the subject of a declaration, order, proposal or notice under the Contaminated Land Management Act 1997 or the Environmentally Hazardous Chemicals Act 1985.
To the best of my knowledge:
the site has been notified to the EPA under section 60 of the Contaminated Land Management Act 1997
the site has not been notified to the EPA under section 60 of the <i>Contaminated Land Management Act 1997</i> .
Site audit commissioned by
Name Environment & Sustainability Manager
Company Acciona Samsung Bouygues Joint Venture (ASBJV) formerly Lendlease Samsung Bouygues Joint Venture
Address 185 O'Riordan Street, Mascot NSW
Postcode 2020

Con Nam	tact details for contact person (if different from above)
Phon	
Ema	
Natu	ure of statutory requirements (not applicable for non-statutory audits)
	Requirements under the Contaminated Land Management Act 1997 (e.g. management order; please specify, including date of issue)
	Requirements imposed by an environmental planning instrument (please specify, including date of issue)
$\overline{\checkmark}$	Development consent requirements under the <i>Environmental Planning and Assessment Act 1979</i> (please specify consent authority and date of issue)
	Department of Planning and Environment (17 April 2018) "Infrastructure Approval, Section 5.19 of the Environmental Planning & Assessment Act 1979, Application No: SSI 7485, Conditions of Approval for WestConnex M4-M5 Link SSI 7485". 76 pages
\checkmark	Requirements under other legislation (please specify, including date of issue)
	NSW EPA (9 October 2018) "Environmental Protection Licence Number 21149". 30 pages (Ref [52])
Purp	pose of site audit
_ ·	A1 To determine land use suitability
	Intended uses of the land:
OR	
0.1	A2 To determine land use suitability subject to compliance with either an active or passive environmental management plan
	Intended uses of the land:
OR	
(Tick	all that apply)
	B1 To determine the nature and extent of contamination
\checkmark	B2 To determine the appropriateness of:
	□ an investigation plan
	□ a remediation plan
	☑ a management plan

Site Audit Statement

	B3 To determine the appropriateness of a site testing plan to determine if groundwater is safe and suitable for its intended use as required by the Temporary Water Restrictions Order for the Botany Sands Groundwater Resource 2017
	B4 To determine the compliance with an approved:
	──voluntary management proposal or
	── management order under the Contaminated Land Management Act 1997
$\overline{\checkmark}$	B5 To determine if the land can be made suitable for a particular use (or uses) if the site is remediated or managed in accordance with a specified plan.
	Intended uses of the land: Road construction worksite at the end of construction and prior to landscaping by Transport for NSW (TfNSW) – Figure 4
Info	rmation sources for site audit
Conc	cultancies which conducted the cite investigations and/or remodiation:

Consultancies which conducted the site investigations and/or remediation:

Ramboll and JM Environmental

Titles of reports reviewed:

- 1. Transport for NSW (August 2017) "M4-M5 Link Environmental Impact Statement, WestConnex"
- 2. Ramboll (19 February 2019) "Northcote Compound, WestConnex M4 East, Phase 2 Environmental Site Assessment". Document No: 318000122_Final prepared for CPB Samsung John Holland
- 3. JM Environmental (4 March 2019) "JME18057-49 Preconstruction Land Condition Assessment, Northcote Street Compound Revision 2". Document No: JME18057-49 prepared for LSBJV
- 4. Ramboll (November 2016) "Underground Petroleum Storage System Validation Report, 269 Parramatta Road, Haberfield". Prepared for CPB Samsung John Holland

Other information reviewed, including previous site audit reports and statements relating to the site:

- 50. Department of Planning and Environment (17 April 2018) "Infrastructure Approval, Section 5.19 of the Environmental Planning & Assessment Act 1979, Application No: SSI 7485, Conditions of Approval for WestConnex M4-M5 Link SSI 7485". 76 pages
- 51. LSBJV (6 June 2018) PowerPoint Presentation "WestConnex Design and Construct, M4 M5 Link Main Tunnel Works, Compounds". 18 pages
- 52. NSW EPA (9 October 2018) 'Environmental Protection Licence Number 21149, WestConnex Stage 3A M4-M5 Mainline Tunnels, WestConnex between M4 East at Haberfield and the New M5 at St Peters, Marrickville NSW 2204'. 30 pages
- 53. Inner West Council (11 November 2016) "Land Zoning Map Sheet LZN_001, Ashfield Environmental Plan 2013 (Amendment No. 3)"
- 54. Higinbotham & Robinson (1889 1894) Map "Fivedock, Parish of Concord". Atlas of the Suburbs of Sydney, https://dictionaryofsydney.org/media/3907

- 55. AECOM (26 February 2019) "Site Audit Report, Northcote Compound, Site 026, WestConnex M4 East". Document No: 60437339 prepared by Brad Eismen for CPB Samsung John Holland JV
- AECOM (26 February 2019) "Site Audit Statement, BE136 for Northcote Compound, Site 026, WestConnex M4 East". Prepared by Brad Eismen for CPB Samsung John Holland JV
- 57. LSBJV (10 October 2018) "Site Establishment Management Plan, M4-M5 Link Mainline Tunnels". Document No: M4M5-LSBJ-PRW-EN-MP01-PLN-0018-07
- 58. LSBJV (23 October 2018) "Appendix B, Contaminated Land Management Sub-plan, M4-M5 Link Mainline Tunnels". Document No: M4M5-LSBJ-PRW-EN-MP01-PLN-0021-01 Rev01
- 59. LSBJV (23 October 2018) "Unexpected Contaminated Land and Asbestos Finds Procedure, M4-M5 Link Mainline Tunnels". Appendix A of Ref [58]
- 60. LSBJV (17 April 2020) "Appendix B5, Soil and Surface Water Management Sub-plan, M4-M5 Link Mainline Tunnels". Document No: M4M5-LSBJ-PRW-EN-MP01-PLN-0005-09 Rev09
- 61. LSBJV (22 June 2020) "Appendix B9, Waste Management Sub-plan, M4-M5 Link Mainline Tunnels". Document No: M4M5-LSBJ-PRW-EN-MP01-PLN-0009-07 Rev08
- 62. LSBJV (28 April 2021) "Appendix B6 Groundwater Management Sub-plan, M4-M5 Link Mainline Tunnels". Document No: M4M5-LSBJ-PRW-EN-MP01-PLN-0006-13 Rev13 (revision 1 dated 17 September 2018)
- 63. ASBJV (27 June 2022) Drawings "M4M5 Link Main Tunnel Works, Package: Project Wide M4M5-RBGP-PRW-CIV-CW02-DPK-0001, Construction Site Reinstatement". 51 drawings prepared for Sydney Motorway Corporation WestConnex
- 64. PSM (9 April 2020) Drawings "M4-M5 Link Main Tunnel Works, Northcote Street Construction Access Backfill and Stub Wall". Document No: M4M5-PSML-NCS-STR-IS22-DPK-0001 comprising 14 drawings prepared for Sydney Motorway Corporation WestConnex

Site audit report details

Title Site Audit Report, Site Audit 278_Northcote by Dr Ian Swane, WestConnex Stage 3A Northcote Compound (Area C3A), Haberfield

Report no. 278 Northcote

Date 28 November 2022

Part II: Auditor's findings

Please complete either Section A1, Section A2 or Section B, not more than one section. (Strike out the irrelevant sections.)

- Use Section A1 where site investigation and/or remediation has been completed and a
 conclusion can be drawn on the suitability of land uses without the implementation of
 an environmental management plan.
- Use Section A2 where site investigation and/or remediation has been completed and a
 conclusion can be drawn on the suitability of land uses with the implementation of an
 active or passive environmental management plan.
- Use Section B where the audit is to determine:
 - o (B1) the nature and extent of contamination, and/or
 - (B2) the appropriateness of an investigation, remediation or management plan¹, and/or
 - (B3) the appropriateness of a site testing plan in accordance with the Temporary Water Restrictions Order for the Botany Sands Groundwater Source 2017, and/or
 - (B4) whether the terms of the approved voluntary management proposal or management order have been complied with, and/or
 - (B5) whether the site can be made suitable for a specified land use (or uses) if the site is remediated or managed in accordance with the implementation of a specified plan.

Section A1

I certify that, in my opinion:

Commercial/industrial

Other (please specify):

The site is suitable for the following uses:

(Tick all appropriate uses and strike out those not applicable.) Residential, including substantial vegetable garden and poultry Residential, including substantial vegetable garden, excluding poultry Residential with accessible soil, including garden (minimal home-grown produce contributing less than 10% fruit and vegetable intake), excluding poultry Day care centre, preschool, primary school Residential with minimal opportunity for soil access, including units Secondary school

Park, recreational open space, playing field

6

¹ For simplicity, this statement uses the term 'plan' to refer to both plans and reports.

OR		
	I certify that, in my opinion, the site is not suitable for any use due to the risk of harm from contamination.	
Ove	rall-comments:	
Sec	etion A2	
l co	rtify that, in my opinion:	
	iect to compliance with the <u>attached</u> environmental management plan ² (EMP), site is suitable for the following uses:	
(Ticl	call appropriate uses and strike out those not applicable.)	
	Residential, including substantial vegetable garden and poultry	
	Residential, including substantial vegetable garden, excluding poultry	
	Residential with accessible soil, including garden (minimal home-grown produce contributing less than 10% fruit and vegetable intake), excluding poultry	
	Day care centre, preschool, primary school	
	Residential with minimal opportunity for soil access, including units	
	Secondary school	
	Park, recreational open space, playing field	
	Commercial/industrial	
	Other (please specify):	
EMI Title	P details	
Auth		
_	Date No. of pages	
EMI	2 summary	
This site.	EMP (attached) is required to be implemented to address residual contamination on the	
The	EMP: (Tick appropriate box and strike out the other option.)	
	requires operation and/or maintenance of active control systems ³	
	requires maintenance of passive control systems only ³ .	

 $^{^2}$ Refer to Part IV for an explanation of an environmental management plan. 3 Refer to Part IV for definitions of active and passive control systems.

Purp	oose of the EMP:		
Desc	Description of the nature of the residual contamination:		
Sum	mary of the actions required by the EMP:		
How	the EMP can reasonably be made to be legally enforceable:		
How	there will be appropriate public notification:		
Ove	rall comments:		
Sec	ction B		
Purp	pose of the plan⁴ which is the subject of this audit:		
	outline the additional work needing to be completed to allow a Section A2 site audit ement to be issued.		
I ce	rtify that, in my opinion:		
(B1)			
	The nature and extent of the contamination has been appropriately determined		
	The nature and extent of the contamination has not been appropriately determined		
AND	VOR (B2)		
$\overline{\checkmark}$	The investigation, remediation or management plan is appropriate for the purpose stated above		
	The investigation, remediation or management plan is not appropriate for the purpose stated above		
AND	VOR (B3)		
	The site testing plan:		
	☐ is appropriate to determine		
	☐ is not appropriate to determine		

⁴ For simplicity, this statement uses the term 'plan' to refer to both plans and reports.

if groundwater is safe and suitable for its intended use as required by the Temporary Water Restrictions Order for the Botany Sands Groundwater Resource 2017

AND/OR (B4)			
	The terms of the approved voluntary management proposal* or management order** (strike out as appropriate):		
	₩	have been complied with	
	₩	have not been complied with.	
	*voluntary management proposal no.		
	**management order no.		
AND	/OR (B	5)	
$\overline{\checkmark}$	The s	ite can be made suitable for the following us	ses:
	(Tick a	all appropriate uses and strike out those not ap	plicable.)
	₩	Residential, including substantial vegetable gar	rden and poultry
	₩	Residential, including substantial vegetable gar	rden, excluding poultry
		Residential with accessible soil, including gardecentributing less than 10% fruit and vegetable i	,
	₩	Day care centre, preschool, primary school	
	₽	Residential with minimal opportunity for soil acc	cess, including units
	₩	Secondary school	
	₩	Park, recreational open space, playing field	
	₽	Commercial/industrial	
) 	Other (please specify): Road construction values of the construction period and prior to landscapin Department of Planning and Environment (1) Approval, Section 5.19 of the Environmenta 1979, Application No: SSI 7485, Conditions (M4-M5 Link SSI 7485" (Ref [50])	g by TfNSW as approved by I7 April 2018) " <i>Infrastructure</i> I Planning & Assessment Act
IF th	e site i	s -remediated/ managed* in accordance with t	the following plan (attached):
*Strik	ke out a	as appropriate	
Plan	title	Interim Management Plan for Contamination WestConnex Stage 3 Project	on at the Northcote Compound,
Plan	author	ASBJV	
Plan	date	28 November 2022	No. of pages 1

SUBJECT to compliance with the following condition(s):

1. The long-term environmental management plan (LTEMP) is prepared by a suitably qualified and experienced environmental consultant in accordance with EPA guidance.

- 2. The LTEMP is to manage the residual contamination risks that remain at the Northcote Compound, as described in the site audit report.
- 3. ASBJV is to provide the Site Auditor with further operational information concerning environmental incidents that occurred at the Northcote Compound during the WestConnex Stage 3A project, chemical storage and operations at the wastewater treatment plant, and operations of the diesel tank and refuelling bay.
- 4. ASBJV is to provide the Site Auditor with further information on the type of fill used to backfill the tunnel dive and other parts of the Site.
- 5. ASBJV is to provide the Site Auditor with further information on demobilisation work and reinstatement of the Northcote Compound demonstrating that the final condition of the Northcote Compound has been achieved.
- 6. Following completion of the minor work and after a written approval of the LTEMP has been issued by the Site Auditor and TfNSW, a Section A2 site audit statement is to be prepared and issued.

Overall comments:

- 1. The site auditor reviewed site environmental management plans that dealt with contamination at the Northcote Compound and considered the plans met Condition C22 of the Planning Consent sufficient for the purpose of this site audit.
- 2. The site auditor reviewed contamination assessments for the Northcote Compound and considered they met Condition E181 of the Planning Consent sufficient for the purpose of this site audit.
- 3. The site auditor reviewed reports on the management of contamination at the Northcote Compound and considered that:
 - a) ASBJV did not interfere or disturb contamination during the course of carrying out its work at the Northcote Compound during the WestConnex Stage 3A project:
 - b) Contamination was not generated by activities undertaken by ASBJV at the Northcote Compound;
 - c) Contamination was not generated at the Northcote Compound that caused an increase in contamination migrating from the Project site;
 - d) The Northcote Compound was returned to a condition suitable for a road construction worksite provided residual contamination risks were managed in accordance with an LTEMP prepared by an experienced environmental consultant that met EPA guidelines and was approved in writing by the Site Auditor and TfNSW; and
 - e) The requirements of Conditions O5.10 and O5.11 of EPL 21149 were met sufficient for the purpose of this site audit.

Part III: Auditor's declaration

I am accredited as a site auditor by the NSW Environment Protection Authority (EPA) under the *Contaminated Land Management Act 1997*.

Accreditation no. 9821

I certify that:

- I have completed the site audit free of any conflicts of interest as defined in the Contaminated Land Management Act 1997, and
- with due regard to relevant laws and guidelines, I have examined and am familiar with the reports and information referred to in Part I of this site audit, and
- on the basis of inquiries I have made of those individuals immediately responsible for making those reports and obtaining the information referred to in this statement, those reports and that information are, to the best of my knowledge, true, accurate and complete, and
- this statement is, to the best of my knowledge, true, accurate and complete.

I am aware that there are penalties under the *Contaminated Land Management Act 1997* for wilfully making false or misleading statements.

Signed

Date 28 November 2022

Part IV: Explanatory notes

To be complete, a site audit statement form must be issued with all four parts.

How to complete this form

Part I

Part I identifies the auditor, the site, the purpose of the audit and the information used by the auditor in making the site audit findings.

Part II

Part II contains the auditor's opinion of the suitability of the site for specified uses or of the appropriateness of an investigation, or remediation plan or management plan which may

enable a particular use. It sets out succinct and definitive information to assist decision-making about the use or uses of the site or a plan or proposal to manage or remediate the site.

The auditor is to complete either Section A1 or Section A2 or Section B of Part II, **not** more than one section.

Section A1

In Section A1 the auditor may conclude that the land is *suitable* for a specified use or uses OR *not suitable* for any beneficial use due to the risk of harm from contamination.

By certifying that the site is *suitable*, an auditor declares that, at the time of completion of the site audit, no further investigation or remediation or management of the site was needed to render the site fit for the specified use(s). **Conditions must not be** imposed on a Section A1 site audit statement. Auditors may include **comments** which are key observations in light of the audit which are not directly related to the suitability of the site for the use(s). These observations may cover aspects relating to the broader environmental context to aid decision-making in relation to the site.

Section A2

In Section A2 the auditor may conclude that the land is *suitable* for a specified use(s) subject to a condition for implementation of an environmental management plan (EMP).

Environmental management plan

Within the context of contaminated sites management, an EMP (sometimes also called a 'site management plan') means a plan which addresses the integration of environmental mitigation and monitoring measures for soil, groundwater and/or hazardous ground gases throughout an existing or proposed land use. An EMP succinctly describes the nature and location of contamination remaining on site and states what the objectives of the plan are, how contaminants will be managed, who will be responsible for the plan's implementation and over what time frame actions specified in the plan will take place.

By certifying that the site is suitable subject to implementation of an EMP, an auditor declares that, at the time of completion of the site audit, there was sufficient information satisfying guidelines made or approved under the *Contaminated Land Management Act 1997* (CLM Act) to determine that implementation of the EMP was feasible and would enable the specified use(s) of the site and no further investigation or remediation of the site was needed to render the site fit for the specified use(s).

Implementation of an EMP is required to ensure the site remains suitable for the specified use(s). The plan should be legally enforceable: for example, a requirement of a notice under the CLM Act or a development consent condition issued by a planning authority. There should also be appropriate public notification of the plan, e.g. on a certificate issued under s.149 of the Environmental Planning and Assessment Act 1979.

Active or passive control systems

Auditors must specify whether the EMP requires operation and/or maintenance of active control systems or requires maintenance of passive control systems only. Active management systems usually incorporate mechanical components and/or require monitoring and, because of this, regular maintenance and inspection are necessary. Most active management systems are applied at sites where if the systems are not implemented an

unacceptable risk may occur. Passive management systems usually require minimal management and maintenance and do not usually incorporate mechanical components.

Auditor's comments

Auditors may also include **comments** which are key observations in light of the audit which are not directly related to the suitability of the site for the use(s). These observations may cover aspects relating to the broader environmental context to aid decision-making in relation to the site.

Section B

In Section B the auditor draws conclusions on the nature and extent of contamination, and/or suitability of plans relating to the investigation, remediation or management of the land, and/or the appropriateness of a site testing plan in accordance with the *Temporary Water Restrictions Order for the Botany Sands Groundwater Source 2017*, and/or whether the terms of an approved voluntary management proposal or management order made under the CLM Act have been complied with, and/or whether the site can be made suitable for a specified land use or uses if the site is remediated or managed in accordance with the implementation of a specified plan.

By certifying that a site *can be made suitable* for a use or uses if remediated or managed in accordance with a specified plan, the auditor declares that, at the time the audit was completed, there was sufficient information satisfying guidelines made or approved under the CLM Act to determine that implementation of the plan was feasible and would enable the specified use(s) of the site in the future.

For a site that *can be made suitable*, any **conditions** specified by the auditor in Section B should be limited to minor modifications or additions to the specified plan. However, if the auditor considers that further audits of the site (e.g. to validate remediation) are required, the auditor must note this as a condition in the site audit statement. The condition must not specify an individual auditor, only that further audits are required.

Auditors may also include **comments** which are observations in light of the audit which provide a more complete understanding of the environmental context to aid decision-making in relation to the site.

Part III

In **Part III** the auditor certifies their standing as an accredited auditor under the CLM Act and makes other relevant declarations.

Where to send completed forms

In addition to furnishing a copy of the audit statement to the person(s) who commissioned the site audit, statutory site audit statements must be sent to

- the NSW Environment Protection Authority: <u>nswauditors@epa.nsw.gov.au</u> or as specified by the EPA AND
- the local council for the land which is the subject of the audit.




Figure 1 Overview of Project Footprint and Construction Ancillary Facilities (Source: Ref [50])



Figure 2 Location Plan for Northcote Compound (Site C3A)



Figure 3 Six Maps 2018 Subdivision Plan for Northcote Compound (Area C3a)



Figure 4 General Arrangement for Reinstatement of Northcote Compound (Source: Drg No: M4M5 -RBGP-PRW- CIV - CW02-DRG- 1101, Ref [63])









Interim Management Plan for Contamination at the Northcote Compound, WestConnex Stage 3 Project

The Purpose of this Interim Management Plan is to outline the additional work that needs to be completed at the Northcote Compound to allow a Section A2 Site Audit Statement (SAS) to be issued. This additional work consists of two parts.

Part 1: Long-term Environmental Management Plan (LTEMP)

An LTEMP is currently being prepared by a suitably qualified and experienced environmental consultant in accordance with EPA guidance; this will facilitate the management of any residual contamination risks that remain at the Northcote Compound, as described in the site audit report, associated with the below items:

- Unknown ACM fragments in fill;
- Unknown buried services/pits remaining at the Site;
- > The possibility of UPSS infrastructure at Site 028; and
- At the former Northcote Street road corridor (site 046): The potential for coal tar to be present in the subbase layer that formed the road pavement and the use of contaminated fill used when Council first constructed the road.

Part 2: Remaining Site Works

Prior to formal handover of the Northcote Compound there are several works that need to be completed to reach the final condition required under the contract. Activities are described below with the risk of contamination to be managed in accordance with the existing environmental management plan.

Demolition of Acoustic Shed

This work is scheduled to occur over the last four weeks of 2022 and be completed in the first quarter of 2023 at the latest. Shed removal will continue by hand along Parramatta Rd during night shift and at adjacent the Northcote Street houses during standard hours.

Pedestrian Access at Northcote Street

Northcote Street will be closed to traffic with pedestrian access created between Northcote Street and Parramatta Road in the first quarter of 2023. Sections of hoarding will be removed whilst new pedestrian fencing, pathways and a turfed verge bounded by planter boxes will be provided.

<u>Demolition of Decline and Support Structures</u>

Decline retaining walls, piles and capping beam will be removed along with support structures for the construction office starting in the last month of 2022, to be completed by the end of the first quarter in 2023. Contamination in this area was managed during site establishment thus little risk remains.

Removal of LV switchyard

The LV switchyard area is to be removed in early 2023 and completed by the end of the quarter. This area presents little contamination risk following its removal will be capped by way of chip sealing.

Decommission Water Management System

Concrete settlement ponds and associated plumbing will be decommissioned for removal in the first quarter of 2023 and any exposed or damaged areas of site will be leveled and sealed for handover.